



$\hat{\ell}$ - Λ regime map — THERMAL test (regime read from the final dynamic damage profile; numbers = crack/fragment count)


$\eta = 0.001$



$\eta = 0.01$



$\eta = 0.05$



$\eta = 0.1$

