


CONTRACTOR. <b>MANCHESTER GEOTECHNICAL LTD.</b>		DATE OF DRILLING <b>13/11/84</b>	DRILLING METHOD. <i>Rotary openhole with water flush.</i>	BOREHOLE NO <b>2</b>
GROUND LEVEL. <b>136.7 m.o.d. APPROX.</b>	ORIENTATION. <b>-90°</b>	CO-ORDINATES. <b>/</b>	SITE. <b>SITE A HUTHWAITE, NOTTS.</b>	PAGE 1 OF 3
TOTAL CORE RECOV % <b>100</b>	SOLID CORE RECOV % <b>100</b>	R. Q. D. <b>100</b>	FRACTURE LOG	STRATA DESCRIPTION <b>SK45NE61 4681 58785</b>
<p><b>TOPSOIL</b></p> <p><i>Sandy, yellow CLAY</i></p> <p><b>OPENHOLE DRILLED</b></p> <p><i>Yellow and grey, fissured MUDSTONE/SILTSTONE</i></p> <p><i>Light grey, fissured MUDSTONE/SILTSTONE with occasional iron-stained bands.</i></p> <p>KEY.</p> <p>REMARKS. <i>OPENHOLE DESCRIPTIONS AS PER DRILLER'S LOGS.</i></p>				
LOGGED BY. <b>MANCHESTER GEOTECHNICAL LTD.</b>		SCALE 1/50 METRES	CLIENT. <b>KYLE STEWART LTD.</b>	JOB No. <b>3756/1</b>



SITE				PAGE 3 OF 3		BOREHOLE No.
TOTAL CORE RECOV %	TOTAL CORE RECOV %	R G D	FRACTURE LOG	STRATA	DESCRIPTION	SK45NE61 46181 58785
				22.		22.
				23.	Light grey, fissured MUDSTONE	23.
23.00				24.		24.
				25.		25.
				26.		26.
				27.		27.
				28.		28.
				29.		29.
				30.		30.
				31.		31.
				32.		32.
				33.		33.
				34.		34.
WARDELL ARMSTRONG				CLIENT	KYLE STEWART LTD.	JOB No. 3756/1