



Section of:

MARKHAM NOS. 16 (UP) AND 17 (DOWN) UNDERGROUND BOREHOLES COMMERC

Purpose:

COAL EXPLORATION

(Nat. Grid, Sheet & Qtr.) B/H REGD. NO.

Exact Site:

NATIONAL GRID CO-ORDINATES

SK 46 NE

55 a **(No.**16) 55 b **(No.**17)

E445744 ) Both holes

N368403 )

Level at which bore commenced relative to

O.D.: 376.1 m

(Zero: floor of Clay Cross Soft)

Date of Boring: 1980-81

Borer: NATIONAL COAL BOARD

Cores examined by D.J. Green, N.C.B. Geologist

		THICK	NESS	DEPT	H
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	m	cm	m	cm
	Top of borehole at			146	54
Siltstone	coarse, vaguely greenish; occasional siltstone medium layers; poorly laminated; rare roots throughout	0	84+	145	70
Siltstone	medium with occasional siltstone coarse layers (strong); common ironstone bands; poorly laminated	0	90	144	80
Siltstone	fine, poorly laminated; common plant debris	0	54	144	26
Siltstone	coarse, unlaminated; rare plant debris	0,5	61	143	65
Siltstone	medium with occasional siltstone fine and muddy layers, poorly laminated; occasional ironstone bands; rare plant debris	1	50	142	15
Siltstone	fine, poorly laminated; common ironstone nodules; occasional plant debris	0	75	141	40



COMMERCIAL IN CONFIDENCE 2 SK /46 /NE /44+
MARKHAM NOS. 16 (UP) AND

Section of:

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP.	ſH
CLASSIFICATION		M	CM	m	cm
Mudstone	silty, laminated; occasional ironstone bands. passage	0	28	141	12
Siltstone	medium, laminated; occasional plant debris	0	61	140	51
ludstone	silty, laminated; rare ironstone bands; common plant remains including <u>Calamites</u>	0	91	139	60
duds tone	silty, poporly laminated; common listric surfaces; common plant debris; common roots; occasional <u>Pinnularia</u> Sharp	000	37	139	23
ands tone	fine and siltstone fine; locally common load and pouch structures; occasional dune sets; common ripples and minor erosion surfaces; common micaceous planty planes	1	81	137	42
andstone	medium; common micaceous planty planes above 134.50; common ripples above 134.80	5	14	132	28
iltstone	medium and sandstone fine; locally vaguely rippled; sub-vertical, calcite-mineralized joint throughout	0	12	132	16
iltstone	medium, poorly laminated; sub-vertical, unmineralised joint throughout passage	0	10	132	06
iltstone	fine, poorly laminated; common ironstone bands passage	0	72	131	34
udstone	silty, poorly laminated; common thin ironstone bands passage	1	94	129	40
ludstone	dark, laminated; common ironstone bands; common worm tracks on some bedding planes	0	34	129	06



·	•	COMMERCIAL IN CONFIDENCE	5K/40	NE	144	+ +
		CORE ANALYSED 129.06 to 126.08				
	Mudstone	silty, ironstone bands; non-marine JIN   lamellibranchs	<sup>0</sup> ርጻን	25	128	81
	Mudstone	shaly, carbonaceous; non-marine lamellibranch impressions detached	0	13	128	68
	SECOND WATERLOO	Upper (Coal, bright 15) (Coal, banded 24) fragments (Coal, mostly bright 38)	8			
		Mudstone, laminated, rootlets 32 cylinders	3			
		Middle (Cannel 7)  Leaf (Coal and dirty coal 18)  pragmen	ts			
		Seatearth; mudstone, grey 20) Lower Leaf (Coal mostly bright 48) 202 cm				
		Dip less than 2°, recovery 75%	2	02	126	66
	Seatearth Mudstone	silty, grey, listric	0	18	126	48
	Siltstone	fine, grey, with fine sandstone laminae, commoner in basal 0.14; ironstone root- nodules and common roots	0	40	126	08
	Sandstone	fine with common siltstone medium laminae (60:40); local slump structures between 125.98 and				
		126.04; abundant roots	0	30	125	78
	Siltstone	fine to medium; poorly laminated; common roots	0	54	125	24
	Siltstone	fine to medium, occasional muddy layers, unlaminated; sporadic roots throughout passage	1	39	123	85
	Sandstone	medium to fine, (strong), with occasional siltstone laminae; common poorly developed ripples; occasional micaceous planty planes	0	47	123	38
	Siltstone	coarse, poorly laminated; common slurried layers; common plant debris including Neuropteris	1	04	122	34




Section of:

### COMMERCIAL IN CONFIDENCE


MARKHAM NOS. 16 (UP) AND 17 (DOWN) UNDERGROUND BOREHOLES \* SK/46/NE/44+

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP1	Ή
CLASSIFICATION	NATURE OF STRAIN	m	cm	m	cm
Siltstone	fine with occasional sandstone fine laminae and thin layers (80:20) towards base; common load casts in basal 0.05; occasional plant debris including Calamites and Neuropteris	1	16	121	18
Mudstone	locally slightly silty; poorly laminated; rare ironstone bands; common non-marine lamellibranchs in basal 0.10; very rare plant debris	2	89	118	29
Mudstone	carbonaceous, shaly	0	09	118	20
COAL	bright (cylinder)	0	02	118	18
Seatearth Mudstone	silty, unlaminated, brownish; abundant listric surfaces; abundant roots passage	1	28	116	90
Mudstone	silty, unlaminated, greenish; abundant irregular listric surfaces; occasional ironstone nodules; abundant roots	2	97	113	93
Siltstone	medium, unlaminated, greenish; common roots, becoming less common to base	1	15	112	78
Sandstone	fine to medium, locally vaguely greenish; rare discontinuous micaceous planty planes; rare comminuted plant debris	1 9	48	111	30
Siltstone	fine and sandstone fine, interlaminated; locally well developed ripples passage	0	20	111	10
Siltstone	fine to medium, poorly laminated	0	50	110	60
Siltstone	medium with common thin sandstone fine laminae (70:30); locally vaguely ripple bedded; occasional comminuted plant debris	0	30	110	30



Section of:

COMMERCIAL IN SI MEIDENCE



GEOLOGICAL	NATURE OF STRATA		NATURE OF STRATA THICKNESS		KNESS	DEPTH	
CLASSIFICATION	MATURE OF STRAIN	W	CM	M	CM		
iltstone	medium, poorly laminated; common slurried layers	0	54	109	76		
iltstone	fine, poorly laiminated; common plant debris	2	20	107	56		
iltstone	fine and sandstone fine; occasional micaceous planty planes; rare ripples and minor erosion surfaces	0	86	106	70		
andstone	medium, generally massive; rare discontinuous micaceous carbonaceous planes	0 3	62	106	08		
iltstone	fine with common thin sandstone fine laminae (60:40); occasional ripples; rare plant debris	0	23	105	85		
iltstone	fine, poorly laminated, with rare wispy thin sandstone fine laminae near the base; rare plant debris	0	30	105	55		
andstone	medium, occasional micaceous carbonaceous planes; rare poorly developed ripples; rare plant remains erosional	3	27	102	28		
ludstone	silty, poorly laminated; rare plant debris	0	80	101	48		
OAL eatearth	bright (fragments)	0	24	101	24		
udstone	silty, unlaminated; abundant irregular listric surfaces; abundant roots	0	48	100	76		
andstone	fine to medium; occasional micaceous planty planes; occasional poorly developed ripples; occasional roots including Stigmaria	0	81				



MARKHAM NOS. 16 COMPLEAND

6 X SIC/46/NE/44+

Section of:	MARKHAM NOS. 16 (DW) AND 17 (DOWN) UNDERGROUND BUREHOLES				
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	M	NESS cm	DEP1	H cm
Seatearth Mudstone	silty, unlaminated, greenish; occasional fine siltstone passages; common roots	1	31	98	64
Siltstone	fine, unlaminated, greenish; common ironstone nodules; abundant roots	0	88	97	76
Siltstone	medium, unlaminated, grey; common ironstone nodules; coalified <u>Stigmaria</u> , abundant roots	0	40	97	36
Mudstone	silty, unlaminated, greenish; occasional irregular listric surfaces; common roots	0	32	97	04
Siltstone	fine to medium, unlaminated, greenish; ironstone nodules; common roots	1	04	96	00
Siltstone	coarse, unlaminated, greenish, abundant roots	0	74	95	26
Siltstone	fine to medium, unlaminated; common roots, occasional root nodules near the base	0	38	94	88
Mudstone	silty, poorly laminated; common irregular listric surfaces; occasional iron-filled roots near base, occasional carbonaceous roots near top; occasional coalified plant remains, common well preserved Neuropteris leaves near top		18	93	70
Siltstone	fine to medium, poorly laminated; rare sandstone fine laminae in basal 0.50; occasional iron-rich patches; occasional sub-vertical unmineralised joints; occasional comminuted plant debris; occasional plant remains including Calamites and Pinnularia above 90.80 passage	5	00	88	70
Siltstone	fine to medium with occasional sandstone fine laminae and lenses (80:20); locally vaguely rippled; 45 degree fracture at 88.43	0	65	88	05



SK/46/NE/50+

Section of:

MARKHAM NOS. 16 (UP) AND


17 (DOWN) UNDERGROUND BOREHOLES

	17 (DOWN) UNDERGROUND BUREHOLES	= Jlin to	Øn		
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THICKN	ess cm	DEPT m	em H
Siltstone	fine, locally muddy, laminated passage	0	50	87	55
Mudstone	silty with rare sandy laminae near the base; occasional iron-rich layers; occasional thin wormy ironstone bands; rare small non-marine lamellibranchs; rare plant remains	3	32	84	23
Siltstone	fine with occasional wispy thin sandstone fine laminae (95:5); occasional plant remains including <u>Neuropteris</u> towards the top		39	83	84
Siltstone	fine, locally muddy, poorly laminated; rare vague sandy laminae; occasional iron-rich patches	1	04	82	80
Mudstone	silty, poorly laminated	0	95	81	85 .
Siltstone	fine, unlaminated; common iron-rich patches. short passage	0	85	81	00
Mudstone	slightly silty, laminated passage	1	54	79	46
Mudstone	silty, slightly carbonaceous, laminated, shaly; becoming less carbonaceous towards top; occasional shelly ironstone bands up to 0.05 thick passage	0	74	78	72
Mudstone	highly carbonaceous, shaly, occasional ostracods; common non-marine lamellibranchs in basal 0.05, rare above	0	15	78	57
COAL	and dirt (fragments)	0	30	78	27
Seatearth Mudstone	locally silty, laminated; common listric surfaces, core completely fragmented; locally slightly carbonaceous; occasional rootlets sharp	2	13	76	14




## COMMERCIAL IN CONFIDER IN

8



Section of:

			/		
GEOLOGICAL	NATURE OF STRATA		THICKNESS		TH
CLASSIFICATION		m	CM	m	cm
Siltstone	fine with common thin sandstone fine laminae (70:30); common micaceous carbonaceous planes	0	75	75	39
Sandstone	fine with rare siltstone fine laminae; vaguely ripple bedded; micaceous carbonaceous planes; occasional comminuted plant debris	1	92	73	47
Sandstone	fine and siltstone fine; common lenticular ripples; common micaceous planes; rare sandfilled burrows		52	71	95
Siltstone	fine to medium with common thin sandstone fine laminae (70:30); common plant debris	1	37	70	58
Siltstone	muddy, poorly laminated passage	0	58	70	00
Mudstone	silty, laminated, dark; common non-marine lamellibranchs in basal 0.10; scattered non- marine lamellibranch fragments throughout	2	66	67	34
Ironstone	shelly	0	06	67	28
Siltstone	fine, unlaminated; common <u>roots</u> in top 0.10, rare below		58	65	70
Siltstone	fine with common sandstone fine laminae and layers (60:40); slump structures at 63.70, 65.40; common rootlets 64.20 to 64.60; common plant fragments including Neuropteris 64.60 to 64.75	3	70	62	00
Siltstone	muddy, laminated passage	0	30	61	70
Muds tone	silty, laminated; abundant non-marine lamellibranchs including <u>Naiadites</u> and <u>Anthracosia</u>	0	90	60	80



SK/46/N F/444

Section of:

	17 (DOWN) UNDERGROUND BUREHOLES				
GEOLOGICAL	NATURE OF STRATA		KNESS	DEP m	TH cm
CLASSIFICATION		m	cm		CIII
Mudstone	carbonaceous, shaly; detached <u>Spirorbis</u> at 60.05; common non-marine lamellibranch fragments including Naiadites	1	01		
	CORE ANALYSED 59.79 TO 58.27			59	79
Mudstone	silty; a few ironstone nodules	0	53	59	26
SECOND ELL	Coal, bright 80) fragments Coal, inferior bright $\frac{14}{94}$ cm				
	<u>Dip</u> less than 2°. <u>Recovery</u> 60% (based on borehole recorder)	0	94		
Seatearth				<u>58</u>	32
Siltstone	medium, with a few bright coal laminae	0	05	58	27
Siltstone	muddy, poorly laminated, dark; common plant fragments including <u>Lepidodendron</u>	0	07	58	20
				<del>20</del>	0
Seatearth Siltstone	muddy, unlaminated, abundant rootlets	0	20	58	00
Siltstone	fine, poorly laminated, thin irregular sandstone fine laminae in top 0.30, rootlets above 57.25	1	25	56	75
Siltstone	fine with common thin sandstone fine laminae (70:30); burrows up to 0.08 deep; comminuted plant debris	0	45	56	30
Siltstone	fine, poorly laminated; common faultlets in basal 0.50 passage	0	57	55	73
Siltstone	muddy with irregular thin sandstone fine laminae 55.43 to 55.53	1	92	53	81
Siltstone	fine with sandstone fine (70:30) slurried in parts	0	25	53	56
Siltstone	muddy, laminated, dark; isolated non-marine lamellibranch fragment at 53.40	0	18	53	<i>3</i> 8
				<u> </u>	<del></del>



COMMERCIAL N JANFIDENCE

SK/46/NE/44+

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP	ГH
CLASSIFICATION	HATONE OF STRAIN	m	cm	m	СM
				53	38
Geatearth Giltstone	muddy, unlaminated, cheesy texture, ironstone nodules in top 0.10; abundant rootlets	0	73	52	65
iltstone	fine with common sandstone fine laminae in basal 0.30; rare rootlets	0	37	52	28
Sandstone	fine with thin siltstone laminae; slurried in parts, common load casts throughout; contact inclined at 20 degrees	4	91	47	37
Siltstone	muddy to fine with common thin sandstone fine laminae in top 0.15 passage	0	47	46	90
<b>l</b> udstone	silty laminated; common shelly ironstone to 43.02 passage	5	75	41	15
Siltstone	muddy, laminated, dark; common non-marine lamellibranchs passage	1	50	39	65
CLAY CROSS MARINE BAND	mudstone, silty, completely fragmented; cone-in-cone, canky ironstone 36.14 to 36.36; Lingula and Dunbarella fragments towards base; isolated Lingula at 37.46 (core from 34.65 to 36.14 broken, part lost)	5	00	34	65
Siltstone	muddy, cheesy texture	0	10	34	55
Siltstone	muddy to fine with common thin sandstone fine laminae, 33.65 to 34.05	1	10	33	45
<b>l</b> udstone	silty, laminated; wormy	1	91	31	54
ludstone	silty, dark; common non-marine lamellibranch fragments; common <u>Geisina</u> in basal 0.02	0	25	31	29
Siltstone	muddy to fine; thin sandstone laminae 29.90 to 30.08; poorly laminated; ironstone nodules in top 0.30; plant remains in top 0.30	2	19	29	10




COMMERCIAL TO LINE DENCE

SK/46/NE /48+

Section of:

GEOLOGICAL	NATURE OF STRATA		NATURE OF STRATA THICKNESS		Н
CLASSIFICATION		m	cm	m	CM
Mudstone	silty, laminated	0	75	28	35
Siltstone	muddy, becoming siltstone fine upwards with rare sandstone fine laminae passage	0	65	27	70
1udstone	silty, laminated, dark; shelly ironstone 27.00 to 27.12; abundant <u>Geisina</u> in basal 0.01	0	77	26	93
Geatearth Mudstone	silty, dark, unlaminated, listric; abundant rootlets	0 6	02	26	91
Siltstone	fine with irregular thin sandstone fine laminae; cheesy texture; abundant rootlets	0	46	26	45
Siltstone	fine with common thin sandstone fine laminae; sandstone layer 24.58 to 24.83; common rootlets above 26.25	3	30	23	15
Siltstone	muddy, poorly laminated passage	1	05	22	10
Mudstone	silty, laminated, wormy passage	0	80	21	30
Mudstone	silty, dark, abundant thick shelled non- marine lamellibranchs including <u>Carbonicola</u> ; abundant <u>Geisina</u>	00	75	20	55
COAL	(cylinder)	0	02	20	53
Seatearth Siltstone	fine, poorly laminated; common ironstone nodules; common rootlets	0	73	19	80
Siltstone	fine with common thin sandstone fine laminae; sporadic rootlets above 18.50	3	32	16	48
Mudstone	silty, laminated	1	18	15	30



5K/46/NE /44 55 RE-1101-

Section of:

MARKHAM NOS. 16 (UP) AND

17	(DOWN)	UNDERGROUND	<b>BOREHOLES</b>
----	--------	-------------	------------------

	NATURE OF STRATA					
GEOLOGICAL	NATURE OF STRATA	182 THIC	787 THICKNESS		ŤH	
CLASSIFICATION		m	cm	m	CM	
Mudstone	silty, laminated, dark; shelly ironstone band 15.25 to 15.30; abundant thick shelled non-marine					
	lamellibranchs	0	61	14	69	
COAL	and dirt (completely fragmented)	0	10	14	59	
Geatearth Mudstone	silty, dark, unlaminated, cheesy texture; abundant rootlets (core fragmented)	0	39	14	20	
udstone	silty, poorly laminated, common rootlets	0	33	13	87	
iltstone	muddy, laminated; common rootlets above 13.20 passage	1	27	12	60	
udstone	silty, laminated passage	0	65	11	95	
udstone	carbonaceous, shaly; <u>Geisina</u> at 11.65; common <u>Naiadites</u> fragments at 11.68 passage	0	40	11	55	
udstone	silty, laminated; abundant non-marine lamellibranchs 10.50 to 10.70	1	50	10.	05	
arkham No. 16 upbore)	Start of coring in upbore: 10.05 m	(BGG	)	<u>.</u>		
RIGIN	Base of Clay Cross Soft Seam			0	00	
arkham No. 17 downbore)	Start of coring in downbore; 4.00 m			4.	00	
iltstone	fine with common thin sandstone fine laminae 70:30; common ripple sets, occasional minor erosion surfaces; rare comminuted plant debris	0	44	4	44	
iltstone	fine and sandstone fine; interlaminated and interlayered. Ripple bedded throughout, minor erosion surfaces	0	19	4	63	



5K/46/NE / 44+

Section of:

	WATER OF GTRATA	TUZO	KNESS	DEF	TU
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	W	CM	M	CM
Sands tone	fine to medium with rare siltstone fine laminae; common micaceous planty plane Local vague ripples		25	5	88
Siltstone	fine with common sandstone fine lamina 70:30; becoming 60:40 towards base. Poorly developed ripples throughout Passage	e, O	31	6	19
Sandstone Siltstone	fine with common siltstone fine lamina 70:30. Common ripple sets; occasiona ripple drift, common micaceous planes fine and sandstone fine, complexly		51	6	70
31100 00110	interlaminated and interlayered; rippledded throughout, occasional minor erosion surfaces. Locally developed minor load structures. Common micaceo planty planes. Rare iron-rich patches Sharp		08	7	78
Sandstone	fine to medium; core broken into 1 cm pieces though no sign of bedding sharp, erosional	0	20	7	98
Mudstone	silty, laminated. Common ironstone ba rare worm tracks; rare plant debris  Detached	nds; 1	12	9	10
DEEP SOFT (part)	Coal (fragments) 0. Detached Seatearth, silty mudstone, coal laminae (fragments) 0.				
	Detached  Coal and dirt (fragments)  Detached  O.	0 <u>8</u> 43 <u>0</u>	43	9	53
Seatearth Mudstone	silty, occasional coaly laminae. Abundant roots	0	56	10	09
COAL	and dirt (fragments and broken cylinde	rs) <u>0</u>	43	<u>10</u>	52



TOWMER THE WINDENCE

5K/46/NE/44+

Section of:

OCCUPATON.	NATURE OF CTRATA	4.	KNESS	DEP	TU
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	W	CM KNE 33	m	CM
Seatearth Mudstone	silty, occasional coaly laminae; common roots	1	22	11	74
Siltstone	fine to medium, unlaminated, granular texture. Occasional roots	0	79	12	53
Ironstone		0	12	12	65
Siltstone	fine to medium, poorly laminated, becoming muddy towards base. Occasional iron-rich patches; O.ll ironstone band at base. Rare plant debris	0	83	13	48
Mudstone	silty, poorly laminated. Rare plant debris	0	13	13	61
Siltstone	medium, locally siltstone fine. Slurried texture near top. Poorly laminated; occasional faultlets. Occasional plant remains	0	54	14	15
Siltstone Mudstone	fine, unlaminated with occasional siltstone medium passages. Slurried texture in basal 0.20. Common faultlets. Common plant remains including Neuropteris; common comminuted plant debris	0	43	14	58
Muastone	laminated	0	UG	14	64
Siltstone	fine, locally muddy, unlaminated; abundant faultlets. Common ironstone bands. Single <u>Naiadites</u> at 15.97. Occasional plant debris	2	29	16	93
Siltstone	medium with common sandstone fine laminae, 70:30. Occasional ironstone patches. Occasional faultlets. Sub-vertical unmineralised joint in basal 0.20	0	40		
	Occasional plant debris	U	40	17	33



COMMERCIAL & LANGENCE

SK/46/Nt/

44† 50

Section of:


GEOLOGICAL	NATURE OF STRATA		THICKNESS		'TH
CLASSIFICATION		m	CM	m	cm
Siltstone	fine, locally muddy, unlaminated	0	72	18	05
Siltstone	coarse, poorly laminated	0	48	18	53
CORE LOST		0	47	19	00
Mudstone	laminated, becoming slightly carbonaceous in basal 0.10. Core completely fragmented. Occasional ironstone bands; rare non-marine lamellibranch fragments. Rare guilielmites. Common worm tracks on some bedding planes	3	96		
	Sommer world crucks on some beduring prairies	000	70	22	96
COAL	(fragments)	<u>0</u>	15	23	11
Seatearth Mudstone	core completely fragmented	0	29	23	40
Siltstone	coarse, unlaminated; abundant roots	0	25	23	65
Sandstone	fine with rare wispy thin siltstone fine laminae, becoming more common towards base. Common micaceous carbonaceous planes. Common sand-filled roots passage	0	35	24	00
Siltstone	fine to medium with rare sandstone fine laminae. Occasional iron-rich patches. Common comminuted plant debris	03(5)	40	24	40
Mudstone	silty, poorly laminated; common ironstone bands. Occasional roots	0	25	24	65
Siltstone	fine with occasional wispy sandstone fine microlenses, 90:10; occasional ironstone bands. Common comminuted plant debris. Rare roots in top 0.10 Passage	. 0	60	25	25
				1	



SK/46/NE/44+ 50 \*\*

Section of:

GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THIC	KNESS cm	DEP m	TH
Siltstone	fine, laminated; occasional thin ironstone bands. Occasional plant fragments passage	0	35	25	60
Mudstone	silty, laminated sharp	0	29	25	89
Sandstone	fine with rare siltstone fine laminae; vaguely ripple bedded. Common micaceous planty planes. Common comminuted plant debris	0	09	25	98
Muds tone	silty, laminated, core fragmented. Occasional ironstone bands. Occasional worm tracks; abundant burrows in top 0.05 Detached		64	27	62
DEEP HARD (Upper Leaf)	Coal (fragments) Detached	0	27	27	89
Geatearth Giltstone	fine to muddy, grey; common ironstone nodules; common roots	0	51	28	40
Giltstone	fine to medium, unlaminated; common ironstone bands and nodules, becoming rare below 29.20; common roots	1	30	29	70
Siltstone	medium with occasional sandstone fine laminae. Occasional iron-rich patches. Rare roots, rare plant debris	0 5	20	29	90
Siltstone	fine with common thin sandstone fine laminae and layers, variously inclined. Common plant debris	2	20	32	10
luds tone	silty, laminated. Common worm tracks on some bedding planes	0	90	33	00
Siltstone	fine, locally muddy, laminated; iron-rich layers in basal 0.10	0	37	33	37



5K/46/NE/44+

Section of:

	17 (DOWN) UNDERGROUND BOKEHOLES				
GEOLOGICAL	NATURE OF STRATA	THICKNESS		DEPTH	
CLASSIFICATION		m	CM	m	cm
Mudstone	laminated. Occasional plant debris	0	09	33	46
Siltstone	fine, poorly laminated, occasional medium siltstone passages. Occasional iron-rich layers. Rare plant debris	0	44	33	90
Mudstone	silty, laminated, fining downwards. Occasional ironstone bands. Common worm tracks. passage	1	10	35	00
luds tone	laminated; core fragmented. Rare plant remains	0,50	48	35	48
Siltstone	fine, poorly laminated. Occasional iron- rich layers. Rare plant remains including Lepidostrobus. Vague worm tracks, locally common small burrows	0	94	36	42
Muds tone	CORE ANALYSED, 36.42 to 38.04 silty, light grey	0	31	36	73
DEEP HARD (Main Leaf)	Coal, mostly bright 40) Coal, inferior bright, pyritic 19)cyl Coal, bright 32)ind Coal, inferior bright, pyritic 3) Coal, mostly bright 21)				
	Dip less than 2° Recovery 100%	L.S.	15	<u>37</u>	88
Seatearth Mudstone	light grey	0	16	38	04
Mudstone	silty, grey, common roots	0	26	38	30
Siltstone	coarse, unlaminated. Common roots	0	15	38	45



50140/NE/44+

Section of:

•	17 (BOMY GROENANDOND BUNEROLES	0	<i></i>		
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THIC	KNESS cm	DÉF m	TH cm
	· · · · · · · · · · · · · · · · · · ·				
Siltstone	fine with common thin sandstone fine laminae, 70:30. Common roots	0	57		
				<u>39</u>	02
Seatearth					
Sandstone	fine with occasional root-disturbed siltstone fine laminae. Common micaceous planty planes.	0	78		
-	Common iron-rich patches. Occasional roots	U	70	39	80
Siltstone	fine with common thin sandstone fine laminae, 70:30. Common small load and pouch structures.				
	Occasional roots	0	15	39	95
Siltstone	fine with rare sandstone fine laminae and lenses. Occasional roots. Occasional plant				
	remains	0	10	40	05
Siltstone	fine, poorly laminated. Occasional roots passage	0	35	40	40
Mudstone	laminated; occasional ironstone bands	0	20	40	60
Siltstone	fine with common, variously inclined sandstone fine laminae and layers, 60:40. Ripple-bedded throughout. Common micaceous				
	planty planes. Common sand-filled burrows	0	60	41	20
Siltstone	fine with occasional muddy passages; 0.18 slurried layer at 41.47. Common plant	CG	)		
	debris. Occasional small burrows. passage	2	30	43	50
Mudstone	silty, poorly laminated passage	0	30	43	80
Siltstone	fine, poorly laminated. Occasional iron- rich layers. Common worm tracks	0	67	, ,	
				44	47
Mudstone	laminated; common ironstone bands Detached	1	43	45	90



19

5K/46/NE/44+

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

-- JUN 1982

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP	TH
CLASSIFICATION		m	cm	m	CM
IST PIPER (Part)	Coal, dirty (fragments) Detached	0	29	46	19
Seatearth Mudstone	Core fragmented	0	91	47	10
Siltstone	fine, grey; common ironstone nodules Common roots	0	44	47	54
Mudstone	Core fragmented	0	57	48	11
Siltstone	fine with occasional muddy layers. Occasional ironstone nodules. Occasional roots. Common <u>Neuropteris</u> leaves below 48.50	O O	59	48	70
Siltstone	fine, poorly laminated; rare ironstone nodules. Abundant plant remains including Mariopteris; Calamites; Neuropteris and Pinnularia	2	66	51	36
Siltstone	medium, poorly laminated. Abundant burrows in top 0.10; rare plant debris passage	0	84	52	20
Siltstone	medium with common thin sandstone fine laminae, 70:30; occasional ripples and minor erosion surfaces, common micaceous planty planes passage		55	53	75
Sandstone	fine with common siltstone fine laminae, 70:30. Common ripples and minor erosion surfaces. Common micaceous planty planes	1	37	55	12
Siltstone	fine with common thin sandstone fine laminae, 60:40. Common ripples. Common micaceous planty planes	0	28	55	40



### COMMERCIAL IN CONFIDENCE

20

\$ /46 |NE /44+

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

\_\_ JIJN 1982

GEOLOGICAL	NATURE OF STRATA		THICKNESS		?TΗ
CLASSIFICATION		m	cm	M	cm
Sandstone	fine with common siltstone fine laminae. Vaguely ripple bedded. Common micaceous planty planes	0	50		
				55	90
Sands tone	medium, generally massive, rare discontinuous micaceous planty planes showing vague dune bedding; conglomerate between 61.75 and 61.82. Occasional thin fine siltstone layers.				
	Common sub-vertical mineralised joints sharp	6	87	62	77
::14-4	fine and condature fine interlayand				
Siltstone	fine and sandstone fine, interlayered. Common ripples and minor erosion surfaces	0	81	63	58
Sandstone	medium, massive. Common sub-vertical unmineralised joints	1	05	64	63
Giltstone	fine and sandstone fine; interlayered; common mineralised joints. Common ripples, common micaceous planty planes passage	1	57	66	20
iltstone	fine, poorly laminated, common listric surfaces. Common sub-vertical joints. Rare horizons with thin sandstone fine laminae.				
	Rare plant debris. passage	2	90	69	10
iltstone	medium, poorly laminated	1	10	70	20
andstone	fine with common siltstone fine laminae, 70:30. Occasional ripples. Detached	0	86	71	06
OAL	and dirt (broken cylinders)	0	34	71	40
eatearth udstone	unlaminated; grey; rare coal streaks				
	Detached	0	13	71	53



COMMERCIAL NEW NEWFINCE

21

SK/46/NE 44+

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEF	TH
CLASSIFICATION		m	cm	m	cm
COAL AND DIRT	Coal, bright 0.05 (cylinder) Coal and dirt 0.14 (broken cylinders 0.19 and fragments)				
	Detached	0	19	<u>71</u>	72
Seatearth Mudstone	unlaminated, grey; abundant listric				
14000110	surfaces; abundant roots	0	29	72	01
Siltstone	fine, poorly laminated; abundant roots	0	57	72	58
Siltstone	fine, poorly laminated; rare ironstone nodules; rare roots; common plant debris	0	42	73	00
Muds tone	silty, poorly laminated, common listric surfaces; common roots	0	82	<u>73</u>	82
Seatearth Mudstone	grey, common coal streaks, abundant roots	0	17	73	99
2.)				1)	
Siltstone	medium, grey; occasional ironstone nodules, common roots	0	45	74	44
Sandstone	fine with common siltstone fine laminae, 60:40. Occasional ironstone nodules. Common roots in top 0.05; rare below.				
	passage	0	21	74	65
Siltstone	fine, unlaminated; rare plant remains	1	06	75	71
Siltstone	fine with common sandstone fine laminae, 70:30. Common vague ripples. Common	_	<b>4</b> -		
	micaceous planty planes Sharp	0	35	76	06
Muds tone	silty, laminated; rare non-marine lamellibranchs	0	14		(BC
				76	20



CAMMENON IN A ME HACE

22


SK/46/NE/44+

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

			/		
GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEPTH	
CLASSIFICATION		m	cm	m	cm
Siltstone	fine, poorly laminated; rare plant debris passage	0	60	76	80
Mudstone	silty, poorly laminated; rare plant debris	0	19	76	99
Siltstone	fine, poorly laminated; occasional muddy passages; common small burrows	1	99	78	98
Mudstone	very weak, core completely fragmented; occasional ironstone bands	3	65	82	63
Mudstone	carbonaceous, shaly. Common ostracods. Rare plant remains including Lepidodendron and Neuropteris Attached	0	26	82	89
COAL	and dirt (cylinder) Attached	0	04	82	93
Mudstone	carbonaceous, shaly. Locally common ostracods. Locally common fish scales. Detached	0	06	82	99
Mudstone	and <u>Coal</u> . Abundant plant fragments (cylinder) Detached	0	12	83	<u>11</u>
Seatearth					
Mudstone	silty, unlaminated, grey, occasional irregular listric surfaces, abundant roots	0	31	83	42
Siltstone	fine, muddy, unlaminated, grey; occasional ironstone bands; common roots	0	36	83	78
Mudstone	silty with local muddy siltstone passages; core completely fragmented; common roots, becoming rare towards base sharp	1	34	85	12
Sands tone	medium; common micaceous planty planes; rare roots	0	31	85	43



COMMERCIAL SEA NECENCE 23

SK/46 INE /44 +

Section of:

	17 (DOWN) UNDERGROUND BOREHOLES			M
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	2	(NESS cm	DEPTH m cm
Mudstone	laminated, fissile, core locally completely fragmented; occasional ironstone bands up to 0.04 thick; locally common worm tracks sharp	0	77	86 20
Mudstone	highly carbonaceous, shaly; core completely fragmented in top 0.22; common ostracods including <u>Geisina</u>	0	40	86 60
CORE LOST  Mudstone	carbonaceous, poorly laminated in top 0.30,	0	60	87 20
Mudstone	becoming shaly below; locally very weak. Locally common non-marine lamellibranchs, some with mineralised shells. Locally common ostracods including Geisina; occasional ironstone bands up to 0.04 thick passage	2	91	90 11
induscone	laminated, very weak, occasional ironstone bands; occasional non-marine lamellibranchs near top  CORE ANALYSED 91.07 TO 93.07	0	96	91 07
Mudstone	shaly with non-marine lamellibranch fragments	0	11	91 18
TUPȚON	Coal, inferior bright Coal, mostly bright 28) Mudstone, grey 3) Coal, bright 10)cylinders Mudstone, dark grey 3) Coal, bright 96) Coal, bright 3 fragments Core lost, assumed coal 22 176 cm	ed		
	Pull-out at 92.68. Dip less than 20 Recovery 85% (Based on borehole recorder)	1	76	92 94
Seatearth Mudstone	silty, light grey; ironstone nodules	0	13	93 07



24

SK/46/NE/44+ --JUN 1982

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES


	OUN 176Z		- M -		
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THIC	KNESS cm	DEP m	TH cm
Siltstone	medium, unlaminated, grey; abundant roots becoming common below 94.50; occasional root nodules below 94.70	1	83		
	(4)	_	-	94	90
Siltstone	medium with occasional root-disturbed sandstone fine laminae 80:20, becoming 70:30 below 95.40; common root nodules; common roots	1	14		
	sharp			96	04
Siltstone	medium, slurried texture	0	30	96	34
Siltstone	medium with rare sandstone fine wisps and micro-lenses; strong; rare root nodules; locally abundant small burrows towards base; rare plant debris passage	2	01	98	35
Siltstone	fine to medium with common sandstone fine laminae and lenses, 70:30; occasional micaceous planty planes; occasional minor erosion surfaces; occasional small load casts; common comminuted plant debris sharp	0	87	99	22
Mudstone	laminated, fissile, weak; occasional ironstone nodules; locally common worm tracks	0	52	99	74
Siltstone	fine with common sandstone fine laminae, 80:20 sharp	0,5	08	99	82
Mudstone	laminated, shaly, weak; occasional ironstone bands; locally common worm tracks	0	42	100	24
	CORE ANALYSED 100.24 to 101.40				
Mudstone	light grey	0	28	100	52
THREEQUARTER	Coal, bright 72 cylinders Coal, bright 4 fragments 76 cm				
	Dip less than 2°, Recovery (based on borehole recorder) 99%.	0	76	<u>101</u>	28



· Cr	IMMERCIAL IN - 25	sk /4	t6/N	$\epsilon/4$	4
Section of:	MARKHAM NOS. 16 (DENCED  17 (DOWN) UNDERGROUND BOREHOLES	1787	)	ال ' چ	?' * *
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THICK	(NESS cm	DEPT m	H
Seatearth Mudstone	silty, grey	0	10	101	38
Siltstone	fine, grey	0	02	101	40
Siltstone	fine with common root-disturbed sandstone fine laminae, 60:40; abundant roots	0	14	101	54
Sandstone	fine with occasional discontinuous micaceous planty planes; common roots	0	28	101	82
Siltstone	medium with common sandstone fine laminae and layers, 70:30; common roots	0	33	102	15
Mudstone	with occasional ironstone bands. Core completely fragmented; occasional roots	0	60	102	75
Siltstone	fine, unlaminated; common roots sharp	0	41	103	16
Sandstone	fine to medium with rare siltstone fine laminae; locally vaguely ripple bedded, well developed ripple sets in basal 0.20; common micaceous planty planes; occasional iron-rich patches; rare roots in top 0.50 sharp	1	68	104	84
Siltstone	fine to medium with rare wispy thin sandstone fine laminae in top 0.30; common worm tracks and small burrows; single non-marine lamellibranch at 105.63	PG <sup>G</sup>	04	105	88
Siltstone	fine and sandstone fine; variously interlayered and interlaminated; occasional ripples; rare minor erosion surfaces; common micaceous planty planes	0	36	104	2.4
				106	24



Section of:	MARKHAM NUS. 16 (UP) AND		6/NE	150 W
	17 (DOWN) UNDERGROUND BOREHOLES		)	
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THIC	KNESS cm	DEPTH m cm
Sandstone	fine with rare siltstone fine laminae; occasional iron-rich patches; occasional large load-and-pouch structures	0	86	
	Targo Toda-ana-poden Gerdebaros	ŭ	55	107 10
Siltstone	medium with occasional sandstone fine laminae, 90:10; common minor load structures and isolated sandstone pouches in top 0.50	1	40	108 50
Sandstone	fine and siltstone fine, interlayered and			
	interlaminated; locally developed ripples with ripple sets, occasional minor erosion surfaces; common micaceous planty planes; occasional large load—and—pouch structures	(4 <sup>C</sup>	70	1,10 20
Sandstone	fine with rare siltstone fine laminae; occasional discontinuous micaceous planty planes; vague ripple bedding throughout; occasional sand-filled burrows passage	2	60	112 80
Siltstone	fine with common sandstone fine laminae; 60:40, becoming 80:20 below 113.10; locally ripple-bedded; occasional sand-filled burrows; common micaceous planes passage	0	40	113 20
Siltstone	fine with rare sandstone fine laminae and isolated lenses; occasional sandstone dominant layers up to 0.03 thick; occasional sand-filled burrows; common comminuted plant debris in sand-dominant layers; single non-marine lamellibranch at 113.25. passage	000	80	114 00
Siltstone	fine to medium, poorly laminated; occasional plant debris; abundant burrows throughout. passage	0	80	114 80
Siltstone	fine, muddy, laminated; occasional thin ironstone bands, rare plant debris, common burrows	0	26	115 06



27

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

IIIN 1982


	, a JUIV 1				
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THICKNESS m cm		DEPTH m cm	
CLASSIF ICATION		111			ÇIII
Siltstone	fine with rare sandstone fine laminae and isolated lenses; occasional iron-rich patches; common sand-filled burrows sharp	0	26	115	32
Muds tone	silty, laminated; core completely fragmented below 117.00; occasional thin ironstone bands; common worm tracks on some bedding planes; locally common small burrows sharp	2	23	<u>117</u>	55
Siltstone	medium and sandstone fine, interlaminated and interlayered; strong; common micaceous planty planes; rare <u>roots</u>	000	45	118	00
Siltstone	fine, poorly laminated with rare sandstone fine wisps near the base; rare root nodules; rare <u>roots</u>	0	67	118	67
Sands tone	fine with rare siltstone fine laminae; common iron-rich layers; common micaceous planes; locally poorly developed ripples; common sand-filled burrows towards the base short passage	0	68	119	35
Siltstone	fine with common sandstone fine laminae and ripple marked lenses, 80:20; occasional iron-rich patches sharp	0	27	119	62
Sandstone	fine with occasional siltstone fine laminae and layers, 90:10; occasional small load structures; sub-vertical mineralised joint throughout	0	45	120	07
Siltstone	medium to fine, laminated; common burrows in top 0.05	0	83	120	90



SK/46/NE/44+ 28

Section of:

					1
GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP	TH
CLASSIFICATION		m	CM	m	CM
Sandstone	fine with occasional siltstone fine laminae and layers 90:10; occasional discontinuous micaceous planty planes.			· · · · · · · · · · · · · · · · · · ·	
	Inclined, erosional contact	٥	52	121	42
Siltstone	medium to coarse with occasional sandstone fine pouches and layers 90:10; strong. sharp	0	54	121	96
Mudstone	silty, laminated; occasional thin ironstone bands, rare comminuted plant debris; locally common small burrows; single non-marine lamellibranch at 122.08 passage	0	34	. 122	30
iltstone	fine, poorly laminated; occasional iron-rich patches; occasional small burrows near the base	1	35	123	65
Siltstone	medium with rare sandstone fine laminae and lenses; common burrows	0	22	123	87
Siltstone	coarse with occasional irregular sandstone fine laminae, strong	0	25	124	12
iltstone	fine, locally muddy, poorly laminated; occasional ironstone bands; 45 degree polished break at 125.43; rare plant remains	_			
	including <u>Calamites</u>	2	26	126	38
luds tone	silty, laminated, occasional ironstone bands; locally common worm tracks		54	127	92
luds tone	laminated, weak, core completely fragmented in parts	0	53	128	45
Muds tone	dark, slightly carbonaceous, shaly; rare fish remains including scales	0	11	128	56



Siltstone

5K/46/ COMMERCIAL NO , TO DENCE MARKHAM NOS. 16 (UP) AND Section of: 17 (DOWN) UNDERGROUND BOREHOLES DEPTH THICKNESS NATURE OF STRATA GEOLOGICAL cm m CLASSIFICATION M 0 19 laminated, core completely fragmented Muds tone 128 75 0 04 Mudstone carbonaceous, shaly 79 128 Muds tone laminated, dark; occasional thin ironstone bands 1 34 130 13 CORE ANALYSED 130.13 TO 131.91 **Mudstone** grey 0 10 130 23 5 cylinders Coal, inferior bright YARD Mudstone, grey, listric 14 fragments 5) Mudstone, dark grey Coal, inferior bright and dull Coal, bright 14) cylinders 51) 29) Core lost, assumed coal 1<u>18</u>cm Dip less then 2°. Recovery (based on borehole recorder) 75%. Pull-out at 130.68 18 131 Seatearth Siltstone fine, light grey; a few ironstone lenses 0 50 91 131 fine, unlaminated, grey; occasional Siltstone 29 ironstone nodules; abundant roots 20 132 medium, unlaminated; common roots becoming Siltstone rare to base; occasional root nodules. 50 132 70 passage fine, poorly laminated; common comminuted Siltstone 0 40 plant debris; rare roots 133 10 passage

> fine, muddy, laminated; rare roots and root nodules in top 0.10; 0.04 ironstone at base

134

28

1

18



Section of:

	17 (DOWN) BINDERGROUND BURETICES			- / 1	
GEOLOGICAL	NATURE OF STRATA	THICKNESS		DEPTH	
CLASSIFICATION		M.	cm	m	cm
Mudstone	dark, laminated; common worm tracks	0	18	134	46
Mudstone	carbonaceous, poorly laminated; occasional fish remains including spines and scales. detached, fitting	0	04	134	50
BLACKSHALE 4TH LEAF Seatearth	Coal, dirty 5 cylinder Coal, bright 9 cylinder detached, inclined	0	14	134	64
Mudstone	silty, unlaminated; common inclined listric surfaces; common roots	0	05	134	69
Siltstone	fine, iron-rich; abundant roots	0	20	134	89
CORE LOST		0	35	135	24
Mudstone	laminated, very weak; occasional ironstone bands; common worm tracks sharp	0	65	135	89
Siltstone	fine, locally muddy, poorly laminated; occasional ironstone bands; rare roots in top 0.20; locally vaguely wormy. passage	1	11	137	00
Siltstone	medium, unlaminated, barren	0	60	137	60
Siltstone	fine, locally muddy, poorly laminated; barren	1	50	139	10
Siltstone	medium, poorly laminated; occasional slurried layers; barren passage	1	20	140	30
Siltstone	fine, poorly laminated with occasional siltstor medium passages, very rare comminuted plant debris	ne 2	60	142	90



# sk/46/NE/44

### COKRETCIAL IN CONFIDENCE

31

Section of:

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP	TH
CLASSIFICATION		m	CM	m	cm
Siltstone	fine with common thin sandstone fine laminae, 80:20 becoming 90:10 towards the base; occasional iron-rich layers; rare minor erosion surfaces; 0.04 ironstone band at				6
	base; common small sand-filled burrows	0	76	143	66
Mudstone	silty, laminated, very weak	0	11	143	77
Siltstone	fine, muddy, laminated; occasional ironstone bands up to 0.08 thick sharp	1	18	144	95
Mudstone	laminated, very weak; common worm tracks	0	17	145	12
	CORE ANALYSED 145.12 TO 146.67				
Mudstone	shaly	0	08	145	20
BLACKSHALE LEAVES 1 to 3	Coal, bright 39 cylinders Coal, bright 7 fragments Coal, bright 14 cylinders Coal, bright 9 fragments Coal, bright; with 50° dip slickensided breaks ) 46 cylinders 115 cms				
	Dip less than 2°. Recovery (based on borehole recorder) 90%. Pull-out at 145.88		15	146	35
Seatearth Mudstone	dark grey	0	01	146	36
Siltstone	fine, light grey	0	31	146	67
Mudstone	silty, very weak, unlaminated, grey; abundant roots	0	07	146	74
Siltstone	medium to coarse, strong; unlaminated, grey; abundant roots	0	22	146	. 96
Siltstone	fine to medium, unlaminated, grey; abundant roots including <u>Stigmaria</u> becoming common towards base; occasional root nodules below 147.25	n.C	54		



Section of:

MARKHAM NOS. 16 (UP) AND 17 (DOWN) UNDERGROUND BOREHOLES

三二,四河 1982

GEOLOGICAL	NATURE OF STRATA	THICKNESS		DEPTH	
CLASSIFICATION		m	cm	m	cm
Siltstone	medium, unlaminated, with rare, diffuse siltstone coarse layers, strong; occasional roots in top 0.25; 0.04 septarian ironstone at base	1	04	148	54
Siltstone	fine with occasional siltstone medium passages, unlaminated; rare plant remains including Neuropteris sharp	1'	17	149	71
Sandstone	fine with occasional irregular siltstone fine laminae, 90:10. Common large load-and-pouch structures	0	42	150	13
Siltstone	medium, unlaminated; barren	0	19	150	32
Sandstone	fine with common discontinuous micaceous planty planes; ripple bedded throughout with well developed ripple sets; occasional minor erosion surfaces inclined	0	25	150	57
Siltstone	fine with rare sandstone fine laminae and disconnected lenses	0	38	150	95
Sands tone	fine with rare highly disturbed siltstone fine laminae; complex load—and—pouch structures throughout	0	46	151	41
Siltstone	medium with occasional complex, isolated siltstone and sandstone pouches	0	28	151	69
Sands tone	fine with rare siltstone fine laminae; highly contorted bedding; common large load structures	0	12	151	81
Siltstone	fine to medium, laminated; common micaceous bedding planes	0	73	152	54



COMMEDMIL


5K/46/NE

33

Section of:

MARKHAM NOS. 16 (UP) AND

Section of:	17 (DOWN) UNDERGROUND BOREHOLES				
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THICK m	(NESS cm	DEP m	TH cm
Siltstone	fine with common sandstone fine laminae				
	and layers 70:30 becoming 60:40 towards base; locally well developed ripples; locally common ripple lenses below 156.00; common small scale load-and-pouch structures; common micaceous planty planes; rare minor				
	erosion surfaces; mineralised joint between 155.34 and 155.58 Inclined, sharp	5	56	158	10
Sandstone	medium, generally massive; occasional siltstone fine laminae in top 0.50; occasional iron-rich layers showing vague dune bedding; sub-vertical mineralised joint in top 0.70; rare burrows towards base	(3G)	64		
	sharp		- '	169	74
Siltstone	and sandstone interlaminated and inter- layered; common vague ripples; abundant plant debris; occasional sand-filled				
	burrows	0	50	170	24
Mudstone	slightly silty, poorly laminated ; dark; slightly carbonaceous, occasional plant debris	0	33	170	57
Mudstone	carbonaceous, shaly, cleated; locally abundant coalified plant debris	0	26	170	83
COAL	and dirt	0	04	<u>170</u>	87
Mudstone	dark, slightly carbonaceous, poorly laminated; common irregular listric surfaces; abundant plant debris in top 0.04	0	36		
				171	23
Mudstone	carbonaceous, laminated; common guilielmites in top 0.10; rare <u>Naiadites</u> fragments; rare coalified plant fragments sharp; inclined	0	27	171	.50
Sandstone	fine with rare siltstone fine laminae, vague ripple bedding	0	05	171	55




· 一种文化器

SK/46/NE/44+
50

34

Section of:	MARKHAM NOS. 16 (UP) AND 17 (DOWN) UNDERGROUND BOREHOLES			*		
GEOLOGICAL CLASSIFICATION	TATIONE OF CHANNE		DEPT m	H em		
Siltstone	fine and sandstone fine; ripple bedded throughout with well developed ripple sets; occasional minor erosion surfaces; common micaceous planty planes.	0	21	171	76	
Siltstone	fine with occasional siltstone - with - sandstone layers; load structures within sandy layers	0	20	171	96	
Siltstone	fine and sandstone fine, interlaminated and interlayered; common ripples through—out; common small sand-filled burrows.	0	39	172	35	
Siltstone	fine with rare sandstone fine micro- lenses; occasional ironstone patches; sub-vertical mineralised joint below 172.80 rare plant debris	1	12	173	47	
Sandstone	medium with common micaceous planty planes; vague ripple bedding.	0	13	173	60	
Siltstone	fine with occasional sandstone fine laminae and lenses 90:10; occasional iron-rich patches	0	70	174	30	
Siltstone	fine, laminated; occasional ironstone bands	0	55	174	85	
Mudstone	laminated, common worm tracks	0	55	175	40	
Mudstone	highly carbonaceous, shaly; barren	0	68	<u>176</u>	08	
Seatearth Siltstone	medium with occasional highly disturbed					
	sandstone fine laminae, 80:20, abundant roots	0	57	176	65	
Siltstone	fine to medium, poorly laminated; common roots becoming rare to base; occasional root nodules; 0.05 "oolitic" ironstone band at base	1	26	177	91	



35

SK/46/NE/44/

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

>	*
DEP	Н
m	CM

GEOLOGICAL	NATURE OF STRATA	THICK	NESS	DEPT	Н
CLASSIFICATION		· m	CM	m	cm
Siltstone	fine to muddy, laminated; occasional ironstone patches; occasional plant debris including <u>Calamites</u>	0	47	178	38
Auds tone	laminated; core completely fragmented; 0.08 ironstone at base sharp	0	52	178	90
<b>d</b> udstone	silty, laminated; core completely fragmented	0	60	179	50
1uds tone	dark, laminated; core completely fragmented	0	78	180	28
CANNEL		0	36	180_	64
Mudstone	laminated; occasional ironstone bands; core completely fragmented	0	76	181	40
Siltstone	fine, laminated; common ironstone bands	0	50	181	90
Siltstone	fine with common sandstone fine laminae and lenses, 80:20 becoming 70:30 in basal 0.20; local ripple bedding; rare minor erosion surfaces; rare sand-filled burrows; rare plant debris	0	88	182	78
Siltstone	fine with rare wispy thin sandstone fine laminae and disconnected lenses passage	2	02	184	80
Mudstone	silty laminated;	0	32	185	12
Siltstone	fine laminated; occasional ironstone bands	0	61	185	73
Mudstone	dark, laminated	0	26	185	99
Mudstone	highly carbonaceous, sub-canneloid; rare fish scales	0	14	186	13
				=	



SK146 [NE] 44

36

Section of:

MARKHAM NOS. 16 (UP) AND

17 (DOWN) UNDERGROUND BOREHOLES

--JUN 1982

_	
	111/
	W.
_	.v
_	2
_	∵ <b>∧</b> `
	V N

				- "
GEOLOGICAL CLASSIFICATION	NATURE OF STRATA	THICK	VESS cm	ĎEPTH m cm
COAL	bright (fusain in top 0.01)	0	05	<u> 186 18</u>
Seatearth Mudstone	core completely fragmented	0	02	186 20
Sandstone	fine with rare highly disturbed siltstone fine laminae; abundant roots; occasional root nodules	1	09	187 29
Siltstone	fine to medium, poorly laminated; common roots and occasional root nodules sharp		35	187 64
Sandstone Siltstone	fine with rare, locally highly disturbed siltstone fine laminae and thin layers; common micaceous planty planes; occasional large load-and-pouch structures; vague ripples below 88.40; rare roots in top 0.10 Sharp, slightly erosional	2	80	190 44
0223000	fine laminae, 80:20; occasional small load structures; locally common small burrows passage	0	36	190 80
Siltstone	medium, poorly laminated	1	02	191 82
Mudstone	laminated	0	16	191 98
COAL AND DIRT	Coal, bright 3 Mudstone 1 Coal 4 Coal and dirt 2	<u>0</u>	10	192 08
Seatearth Mudstone	core completely fragmented	0	12	192 20



CHOMMEN CHAIL COMMITTING

5K/46/NE/40+

37

Section of:

MARKHAM NOS. 16 (UP) AND 17 (DOWN) UNDERGROUND BOREHOLES E-JUL MAZ


11//	

GEOLOGICAL	NATURE OF STRATA	THIC	KNESS	DEP	ſН
CLASSIFICATION		m	cm	m	CM
Siltstone	fine with common highly disturbed sandstone fine laminae 70:30; common roots	0	25	192	45
Sandstone	fine with rare siltstone fine laminae; bedding highly disturbed by large load structures and occasional roots	0	38	192	83
Siltstone	fine with occasional sandstone fine laminae; 90:10 becoming 80:20 below 193.30; vague ripple bedding, rare minor erosion surfaces; common diffuse ironstone bands; rare roots; common comminuted plant debris in basal 0.30		22	194	05
Siltstone	medium, poorly laminated, occasional diffuse ironstone bands; rare thin sandstone fine layers below 195.00 showing minor load and pouch structures; occasional faultlets;				
	rare worm tracks and burrows	3	51+	197	56

Base of borehole at 197.56









Section of:

Bolsover No. 20 Underground

Borehole

Purpose:

Coal Exploration

Exact Site:

E.445 957

N.369 940 (D23 Main Gate) SK46NE

SK46 NR

50

Nat. Grid, Sheet & Qtr. B/H REGD. NO.

Level at which bore commenced relative to O.D.:

530.5 m below 0.D.

(origin in Tupton Seam workings)

Date of Boring: January 1982

Borer: National Coal Board

Cores examined by: P.K. Boam, N.C.B. Geologist


GEOLOGICAL	NATURE OF STRATA	THICK	NESS	DÉP	TH
CLASSIFICATION	NATURE OF STRATA	m	cm	m	cm
2 lin1-	ORIGIN: FLOOR OF TUPTON SEAM		52	0	00
pen Hole	00071/0 5001/1 50	1	72	1	52
6	CORING FROM 1.52				
Siltstone	medium, occasional rootlets	1	00	2	52
CORE LOST		0	69	7	0.1
				3	21
Sandstone	medium, micaceous planty planes; vertical breaks with oil	0	30		
				3	51
Sandstone	fine with siltstone fine, variously inclined laminae; micaceous planty				
	planes, rare plant debris	0	53	4	04
Siltstone	medium, slurried; plant debris	0	27		
				4	31
Sandstone	medium with rare silty laminae; micaceous planty planes; sub-vertical				
	breaks sharp	2	00	6	31
iltstone	fine, laminated; wormy; vertical crinkled				
	breaks	0	15	6	46
				J	70



•	2	Ę	SKYLON	1E) 149	}
Sandstsone	medium, rare discontinuous siltstone laminae, rare coal laminae, micaceous planty planes	0	69	7	15
Siltstone	fine laminated, rare disconnected sandstone fine ripples, iron rich patches passage	1	57	8	72
Mudstone	dark; vaguely wormy, rare planty material	0	30	9	02
Mudstone	CORE ANALYSED, 9.02 TO 10.31 light grey	0	13	9	02 15
THREEQUARTER	Coal mostly bright, clean (part core and fragments) Recovered 85% Dip 4°	0.0	87	10	02
Seatearth Siltstone	fine to medium, becoming coarse downwards with fine sandstone laminae	0	29	10	31
Siltstone	fine, rare sandy laminae; rootlets	0	25	10	56
Siltstone	and sandstone fine; abundant rootlets	0	33	10	89
Mudstone	laminated; rootlets	Ü	13	11	02
COAL	bright	0	02	11	04
Seatearth Siltstone	fine and sandstone fine; ironstone nodules	0	97+	12	01
Core not seen		0	06	12	07

Base of hole at 12.07

PKB/90272/Z73/PH.XI





SKAPHE/19

### SURVEY DEPARTMENT

#### BOREHOLE DATA AND HISTORY

BOREROLE NAME: BOLSOVER Nº20 UNDERGROUND BORE HOLE (D23 M.9. JUNCTION)
Approximate Location: 1,150 METRES S 41/2 W OF BOLSOVER SHAFT.

National Grid Reference: E 445957 N 369940

6 inch sheet:

SK 46NE.

Level of Origin:

530.5 M BELOW. O. b.

Date of Drilling:

Commenced 8. 1. 82

Finished 14. 1.82

NCB.

Name of Boremaster: DRILLER IN CHARGE J. MOTTRAM.

Th Depth (fil)	MAN Diameter of Core (in)	ीत्स Diameter of Hole (अंग)
0 10 1.52	OPEN HOLR FOR 'EX' COZR EAREEL	60 mm.
1.52 70 /2.07	CORING WITH BY CORREMEREC.	48. 41
RE-DRIL	LED SEAM WITH TES CRAELIUS	OPERMICEL.
9.14/10/033.	T 65 BARREL 661414	Sol- In in.

Drilling Difficulties: FAILED TO RECOVER COAL SERRY WITH BY BARREL SO REAMED BOWN TO SRAM, THEN USED T 65 BARREL TO RECOURT 3/4 SEAM.

Method of Scaling Off Borehole: BORE HOLE CEMENT PILLED WITH 127. SAY SHALLOW OIL WELL CEMENT MIXED WITH 68 LITERS OF PIRE MAIN WATER - BOREHOLE FILLED RIGHT TO THE TOP

Purpose fulfilled by Borehole:

OBTAINED A CORR OF 3/4 SEAM

AS REQUIRED

Official Responsible for above Report:

