

Calibration results

=====

Camera-system parameters:

cam0 (/my_camera/pylon_ros2_camera_node/image_raw):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [-0.25824021 0.11037541 0.0004633 0.00061452] +- [0.00166808 0.00407996 0.00013565 0.00011853]

projection: [1763.16255846 1766.35573712 958.12806019 588.90354437] +- [2.39266375 2.25484717 2.44948602 2.21825571]

reprojection error: [-0.000000, -0.000000] +- [0.300643, 0.244253]

Target configuration

=====

Type: aprilgrid

Tags:


Rows: 6

Cols: 6



Size: 0.088 [m]

Spacing 0.02639999999999996 [m]



cam0: estimated poses





cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

cam0

