

HARDNESS TEST REPORT

CLIENT : EXXONMOBIL ASIA PACIFIC PTE LTD (EM)
 OWNER : SHING LECK ENGINEERING SERVICE PTE LTD
 LOCATION : PAC S4 SITE
 PROJECT TITLE : TAID-4V0794 D-4603 Nozzle 3N Encapsulation Repair Work
 WO NO : 20475872
 SIZE / THK : 10" / 40
 PROCEDURE : MSE-HT-0711-Rev.10
 MATERIAL : CARBON STEEL

METHOD : IMPACT HARDNESS GAUGE

EQUIPMENT USED

MODEL : EQUOTIP®550
 SERIAL NO : UP01-011-0299
 MEASUREMENT TYPE : Digital Read - Out
 IMPACT DEVICE : UCI / ET50-013-0313
 BLOCK HARDNESS : 791 HLDL
 SPECIFIED HARDNESS : 200 HB


SCOPE OF EXAMINATION : HARDNESS TEST WAS CARRIED OUT ON SELECTED PORTIONS OF PARENT METAL ,HEAT-AFFECTED ZONE AND WELD ZONE
 TOTAL NO OF JOINTS : 01
 TOTAL NO OF POINTS : 25
 SMOOTH GRINDING AREA



PM : PARENT METAL
 HAZ : HEAT AFFECTED ZONE
 WELD : WELD ZONE
 HB : HARDNESS BRINELL

NOTE : ALL HARDNESS TEST READING IN HB [BRINELL HARDNESS VALUE]

ACCEPTANCE REFERENCE : GP 18-10-01 (NACE MR0103-2016 : Para 13.1.4 Table-2)



Tested & Reported by	Reviewed by :	Reviewed by QA/QC	Reviewed by Client
M.KAJENDRAN NDT LEVEL II 	R.VIJIPILLAI NDT LEVEL II 		
SIGNATURE DATE : 18.04.2026	SIGNATURE: DATE : 19.04.2026	DATE :	DATE :

The report is issued under the following terms and conditions:

- The report shall not be reproduced in part or in full unless approved in writing has been given by MASTERSCAN
- MASTERSCAN agrees to use reasonable diligence in the manner of performing the tests, inspections or services but no warrants are given, and none may be implied directly or indirectly relating to the product or material tested.
- MASTERSCAN shall under no circumstances be liable for collateral, special or consequential damage.
- This is a test report and not a MASTERSCAN certificate of quality. The significance of the report is subject to the adequacy and representative character of the sample(s) and to the comprehensiveness of the tests, examinations or survey requested or made.
- The test report is prepared based on the test(s) requested and on the specific items submitted / sampled to MASTERSCAN for testing. MASTERSCAN assumes no responsibility for variations in quality or other characteristics of product produced on supplied under conditions over which MASTERSCAN has no control. MASTERSCAN Engineering' testing does not constitute a recommendation for, or endorsement of the product or material tested.



MASTERSCAN ENGINEERING

INSPECTION WITH INTEGRITY

+65 6261 4766 +65 6261 4768 www.masterscan.com.sg sales@masterscan.com.sg

GST/Co. Reg. No.: 200506867D 29 Benoi Road, Pioneer Lot, Singapore 629922

HARDNESS TEST REPORT

REPORT No : MSE-SLE-TA-WON-20475872-F-HT-007

PAGE : 2 OF 3

S.NO	DRAWING NO. / SHT NO.	JOINT NO	SIZE (Inch)	SCH (THK)	SPOT	READINGS					AVE-HB	REMARKS
						1	2	3	4	5		
1	20475872-DRW-001 / SHT NO-1	FW2	10"	40	PM1	149.0	152.1	145.4	153.4	146.9	149.4	
					HAZ1	173.9	163.8	173.8	169.1	179.6	172.0	
					WELD	164.2	162.0	160.5	158.6	159.7	161.0	
					HAZ2	172.6	169.1	172.9	182.7	175.8	174.6	
					PM2	176.2	172.6	186.1	179.5	180.4	179.0	

REMARKS : ALL HARDNESS TEST READING IN HB [BRINELL HARDNESS VALUE] WAS ACCEPTABLE

Tested and Reported By :	Reviewed by :	Reviewed by QA/QC	Reviewed by Client
M.KAJENDRAN NDT LEVEL II 	R.VIJIPILLAI NDT LEVEL II 		
SIGNATURE: DATE : 18.04.2026	SIGNATURE: DATE : 19.04.2026	DATE :	DATE :

PAGE NO: 3 OF 3



Shing Lee Engineering Services Pte Ltd
30 Duan Lay Viny Trade hub 21, #02-175 Singapore
600040
Tel: 6318 4450 / 6360 880 0900 6266 1776
Fax: 6318 2342
E-mail: shinglee@shinglee.com.sg
Web Site: www.shinglee.com.sg