



SafeYelli.in  
SafeYelli in Bengaluru?



## *Report on Working Condition of Streetlights and Sidewalks Near and Under the Hebbala Flyover*

Date of audit: 18, 19 November 2022


Date of publishing: 24 December 2022

We mapped the **conditions of the streetlights and sidewalks near the Hebbala Flyover**. These are particularly **unsafe roads for women under dark conditions**. Some areas **don't have sidewalks especially on the opposite side of Esteem mall**. High resolution interactive maps are available at [safeyelli.in/mapping-hebbala](https://safeyelli.in/mapping-hebbala)

Content	Pg Number
1 Map of Streetlight conditions	3
2 Map of Sidewalk conditions	4
3 Particular problem areas	5










**Level Crossing with no protection,**  
Hundreds of people cross these tracks which is not  
manned.




**Lack of sidewalk and lighting near the Hebbal Lake leading to Esteem Mall Bus Stand**

On the day of the audit, all lighting on the side of the lake was off while advertisement bill boards were on.



**Lighting and space under the flyover leading to the bustands on the ORR**

Lighting on the green spaces and path from the track to the BusStand is very low and women avoid these spaces after sundown



**Lighting and sidewalk width leading to Bhoopsandra road**

Both sides of the road are filled with large, unused complexes, this combined with spotty lighting and tiny sidewalks make it dangerous. The only light on the road is from vehicles