

Fig. 5 Inter-arrival ECDF on the Raspberry Pi 5 host. Radar frame loss: 0 of 8,363 and 0 of 1,091 (frame-number gaps).