



B0 previous versus repaired propagation | context and morphology now have separate views


superseded: +/-5 mm and 0--100 mm



repaired full-field context to 180 mm



repaired fixed +/-0.5 mm detail



repaired HWHM radius; invalid values remain NaN

