
Fabric Defect Inspection Report

Company Name:	ijo	**Date:**	2026-08-08 10:42:43
Operator Name:	akjdk	**Inspection ID:**	INSP-CE588B94
Roll ID:	7898	**Batch ID:**	8484
Fabric Type:	coja	**Final Verdict:**	REWORK

Inspection Image:



Quality Score: 57.0/100

Detected Defects:

Type	Confidence	Dimensions (cm)	Area (cm2)	Severity	Suggestion
Stain	0.99	7.4 x 4.55	33.67	Moderate	Spot Clean and Reprocess
Stain	0.63	3.2 x 2.95	9.44	Minor	Chemical Wash
Stain	0.57	1.95 x 1.45	2.83	Minor	Chemical Wash
Stain	0.55	1.1 x 1.5	1.65	Minor	Chemical Wash
Stain	0.54	1.7 x 1.6	2.72	Minor	Chemical Wash
Stain	0.53	1.0 x 1.5	1.5	Minor	Chemical Wash
Stain	0.53	3.05 x 0.45	1.37	Minor	Chemical Wash
Stain	0.52	1.0 x 0.9	0.9	Minor	Chemical Wash
Stain	0.52	0.55 x 2.05	1.13	Minor	Chemical Wash

Stain	0.51	0.7 x 0.75	0.53	Minor	Chemical Wash