WEBSITE AUDIT REPORT

setmiindia.com

Technical, SEO, performance, security and UX audit - prepared for the website developer

Audit date	7 October 2026
Site / stack	WordPress 7.1.2, WooCommerce 11.1.2, Elementor 4.3.3, Astra theme, Yoast SEO, LiteSpeed Cache, Site Kit, Google Listings & Ads, Trustindex. Hostinger / LiteSpeed. PHP 8.2.33.
Scope	Homepage in a real browser (desktop 1366px and mobile 390px), plus HTTP-level checks of all 847 unique URLs in the Yoast sitemaps (52 pages, 567 products, 169 product categories, 59 blog posts). Public, non-intrusive checks only - no logins, no form submissions, no load testing.
Findings	**5 High** **9 Medium** **8 Low / Info** (22 total)

How to read this report

- Every finding has an ID, severity, **where** it was seen, the **evidence** (what was actually measured), the **impact**, **how to fix** and, where useful, a **re-test** command so you can confirm the fix.
- **High** = fix first (security exposure, broken business-critical behaviour, or large visible defect). **Medium** = clear SEO / speed / UX loss. **Low / Info** = hardening and polish.
- Performance numbers come from a synthetic test run from a cloud data centre, not from India and not from real users. Treat them as relative signals and confirm with PageSpeed Insights and Search Console (Core Web Vitals) before and after changes.
- Plugin menu names can differ slightly between versions; the intent of each setting is described so you can find the equivalent.

1. Executive summary

The site is fundamentally healthy: HTTPS with HSTS, clean redirects, brotli compression, a working sitemap, canonical tags, valid robots rules, product structured data, and **all 847 sitemap URLs return HTTP 200** with no broken links or JavaScript errors found. The problems are concentrated in five areas:

- **First paint looks empty.** LiteSpeed "delay JS" plus lazy-loading of above-the-fold images means the logo, hero banner and menu icons stay blank until the visitor moves the mouse or scrolls. Lab CLS on desktop was 0.687 (good is under 0.1).
- **Security exposure on WordPress.** XML-RPC is live, the REST API lists administrator usernames (one of them an email address), and the login page is public.
- **Broken SEO titles.** 16 product pages show unresolved template text such as "%%sitename%%" in the title/description Google will display. Another 288 titles are too long and 78 are cut with "…".
- **Broken WhatsApp link** in the footer (the URL contains a second, nested api.whatsapp.com address) and no clickable phone/email on the homepage.
- **Heavy pages.** ~2 MB of resources on first load, 3,448 DOM elements, 300-470 KB of HTML on every page (even the 404 page), and slow WooCommerce pages (cart 5.9 s, checkout 4.7 s in test).

Area	Status	Summary
Security	**Needs work**	XML-RPC enabled, usernames exposed, version disclosure, no CSP
Performance	**Needs work**	Delayed JS/lazyload blanks first view, 2 MB initial load, heavy DOM, slow Woo pages
SEO - technical	**Good base**	Sitemap, canonicals, robots, schema OK; duplicate category URLs and metadata errors
SEO - content/meta	**Needs work**	Broken titles, long/truncated titles, missing alt text, thin homepage title
Functionality	**Needs work**	Footer WhatsApp link broken; no contact form; phone/email not clickable
Accessibility	**Fair**	Skip link and ARIA labels present; small tap targets, empty links, missing alt
Availability / links	**Good**	847/847 sitemap URLs return 200; 96 of 99 homepage links OK (3 social sites block bots)

Recommended order of work

Priority	Items	Est. effort
Do first (same day)	H2 disable XML-RPC, H3 lock down user enumeration, H5 fix WhatsApp link, H4 fix 16 broken product titles	1-3 hours
This week	H1 exclude above-the-fold items from lazyload/JS-delay and fix layout shift; M2 compress hero images	0.5-1 day
Next 2 weeks	M1 lighter menu/DOM, M3 server/Woo speed, M4-M7 metadata, duplicate categories, alt text, schema, M8 contact form + click-to-call	2-4 days
Backlog	Low items: headers/CSP, fonts, cache lifetimes, accessibility polish, consent review	1-2 days

All findings at a glance


H1	HIGH	Above-the-fold content hidden until user interaction (delayed JS + lazyload); CLS 0.687
H2	HIGH	XML-RPC enabled (system.listMethods responds)
H3	HIGH	Administrator usernames exposed via REST API and author redirect; public login
H4	HIGH	16 product pages with unresolved Yoast variables in title/meta
H5	HIGH	Footer WhatsApp link malformed (nested URL)
M1	MEDIUM	Very heavy DOM/HTML on every page (3,448 elements, 300-470 KB HTML)
M2	MEDIUM	Oversized hero/images (909 KB + 513 KB), unused preload

M3	MEDIUM	Slow server response and slow cart/checkout/account/category pages
M4	MEDIUM	Weak homepage title; 288 long titles, 78 truncated with "…", separators missing, duplicates
M5	MEDIUM	24 category pages indexable at two URLs (/slug/ and /product-category/slug/)
M6	MEDIUM	23% of product-page images lack alt text
M7	MEDIUM	21 products without Product schema; schema incomplete
M8	MEDIUM	No contact form; phone and email not clickable
M9	MEDIUM	Metadata/description errors: SMB/SMA mix-ups, duplicate descriptions
L1	LOW	Version disclosure and public readme.html / license.txt
L2	LOW	Security headers: no CSP, odd Permissions-Policy, HSTS without includeSubDomains
L3	LOW	Multiple Google tags (3 gtag IDs + GTM); analytics fires only after interaction
L4	LOW	Fonts/CSS: Font Awesome CDN, 7 font files (444 KB), duplicate Trustindex CSS
L5	LOW	Static asset cache only 7 days
L6	LOW	Navigation wraps to two rows at 1366px; accessibility polish
L7	LOW	Heading structure and keyword-stuffed product headings on homepage
I1	INFO	Consent notice and REST CORS behaviour - review


2. High priority findings

HIGH H1 Above-the-fold content stays blank until the visitor interacts

Where	Homepage (and every page that uses the same header). Header logo, hero slider, menu thumbnails.
Evidence	In a real browser the page loads, but the logo (class `custom-logo lazyload`, still a 1x1 placeholder after 8 s) and the hero banner do not render until the first mouse movement/touch/key press. 16 inline scripts are rewritten to `type="litespeed/javascript"` (JS delay) and 48 images carry the `lazyload` class, including the logo and hero. Layout also shifts while content arrives: lab **CLS = 0.687** on desktop (mobile 0). Lab FCP 2.0-2.2 s, TTFB ~1.1 s. A 909 KB image (IMG_1387-scaled.jpg) is preloaded but never used (browser console warning).
Impact	Visitors on slow phones see an empty header and banner; crawlers and PageSpeed tools that do not interact with the page see an empty page above the fold, hurting LCP and CLS and therefore rankings and conversions. Because Google Analytics/Ads tags are also delayed, sessions of visitors who leave before interacting are never counted.
How to fix	- LiteSpeed Cache > Page Optimization > Tuning: add the theme logo, header/menu scripts and Elementor hero scripts to the **JS Delayed Includes exclusion** list, or switch "Delay JS" off and use "Load JS Deferred" instead. - LiteSpeed Cache > Page Optimization > Media: exclude the logo and the first hero image(s) from lazy load (`Lazy Load Image Excludes` / "exclude first N images"), or add `data-no-lazy="1"`. - Mark the real LCP image `fetchpriority="high"` and preload only that image; remove the preload of IMG_1387-scaled.jpg if it is not the LCP element. - Give the hero slider and the Trustindex review widget a fixed height / `aspect-ratio` placeholder so nothing jumps while loading. - Keep analytics (gtag/GTM) outside the delay list so page views are recorded on arrival.
Re-test	Run PageSpeed Insights (mobile) before/after. Target: CLS < 0.1, LCP < 2.5 s, logo and hero visible in a screenshot taken with no interaction.



Initial load (before any mouse/scroll): logo and hero missing



After first mouse movement: logo and hero appear

HIGH H2 XML-RPC is enabled

Where	https://setmiindia.com/xmlrpc.php
Evidence	A POST of the standard `system.listMethods` call returns HTTP 200 with the full method list (including `system.multicall`). robots.txt disallows the path but that does not block access.
Impact	XML-RPC allows password guessing in bulk (many attempts per request via multicall) and can be abused for pingback-based DDoS. It is a common entry point for WordPress compromises.

How to fix	Disable it unless an integration needs it (Jetpack, old mobile apps - none detected). Either of:
	`# .htaccess (LiteSpeed honours this)`
	`<Files xmlrpc.php>`
	`  Require all denied`
	`</Files>`
	`// functions.php / mu-plugin`
	`add_filter('xmlrpc_enabled', '__return_false');`
	The .htaccess rule is preferable because requests never reach PHP.

Re-test	`curl -s -o /dev/null -w "%{http_code}" -X POST https://setmiindia.com/xmlrpc.php  # expect 403`

HIGH H3 Administrator usernames exposed; login page is public and unprotected

Where	https://setmiindia.com/wp-json/wp/v2/users , https://setmiindia.com/?author=1 , https://setmiindia.com/wp-login.php
Evidence	The REST users endpoint returns, without authentication, two accounts: id 2 **"Sankalp"** (login slug `sankalpsuri`) and id 1 whose display name **and** login slug are a full email address (`vishu@setmiindia.com` / `vishusetmiindia-com`). Both are flagged `is_super_admin: true`. `?author=1` 301-redirects to /author/<login>/ and also reveals the login name. wp-login.php is reachable and the form markup shows no CAPTCHA or 2FA field (server-side rate limiting, if any, cannot be seen from outside).
Impact	Attackers get half of the credentials for free, then only need the password. An email-address login also leaks a real mailbox to spammers and phishing.

How to fix	- Block unauthenticated user listing:
	`add_filter('rest_endpoints', function($e){`
	`  unset($e['/wp/v2/users'], $e['/wp/v2/users/(?P<id>[\d]+)']);`
	`  return $e;`
	`});`
	- Redirect or 404 author archives (Yoast: Settings > Advanced > Author archives off) so ?author=N no longer discloses the login.
	- Change the administrator login names and set a different public "Display name" / nickname. Do not use an email as the username.
	- Add login protection: 2FA for all administrators, Cloudflare Turnstile / reCAPTCHA on wp-login.php, and login-attempt limiting (LiteSpeed server-level or a security plugin). Optionally move the login URL.
	- Review whether both accounts really need administrator rights.

Re-test	`curl -s https://setmiindia.com/wp-json/wp/v2/users  # expect 401/404, no usernames` `curl -sI "https://setmiindia.com/?author=1" | grep -i location  # expect no /author/<login>/`

HIGH H4 16 product pages show unresolved template text in the SEO title / description

Where	Product pages listed in Appendix A (16 URLs): 25MM 4/5/6/7/8/12-pin circular connectors, GX16 and GX20 aviation connectors, "5-pin / 6-pin / 7-pin circular connector" and LP24 / RJ45 sockets.
Evidence	The `<title>` contains fragments such as `%%sitename%`, `%%sitename` and `%%site` - the Yoast variable appears to have been typed incorrectly (one % instead of %%...%%) or cut off. Example: "25MM Circular Connector 4 Pin | Aviation Plug & Connector- %%sitename - Sol...". Five products (2-, 4-, 5-, 6- and 7-pin) share the same "RP Type Aviation Connector | 2- pin 16mm RP Reverse Plug GX16" title text.
Impact	Google shows the raw "%%sitename" text in search results, which looks broken and lowers click-through; the titles are also wrong for the actual product (different pin counts share the same title).
How to fix	Edit each product in Yoast SEO > "SEO title": remove the stray variables, use the variable picker (`%%title%% %%sep%% %%sitename%%`) or write a plain unique title containing the pin count. Save, purge LiteSpeed cache, then request re-indexing of the URLs in Google Search Console. Add a QA step: after bulk edits/imports search the site for "%%".
Re-test	`curl -s URL | grep -o '<title>[^<]*' | grep '%%'  # expect no output`

HIGH H5 Footer WhatsApp link is malformed

Where	Footer social icons on every page (Astra footer builder > social).
Evidence	The link on the WhatsApp icon is: `https://api.whatsapp.com/send?phone=https://api.whatsapp.com/send?phone=918586878111&text=` The URL was pasted into a field that already prepends the base URL, so `phone=` receives a full URL instead of a number. WhatsApp will not open a valid chat from this.
Impact	The main one-tap contact route for Indian B2B buyers fails; every footer visit with this click is a lost enquiry.
How to fix	Customizer / Footer Builder > Social icons > WhatsApp: set the URL to `https://wa.me/918586878111` (optionally `?text=Hello%20Setmi%20India`). The number matches the "Enquiry: +91 85868 78111" shown in the top bar.
Re-test	Click the footer icon on desktop and mobile - the chat with 91 85868 78111 should open.

3. Medium priority findings

MEDIUM M1 Very heavy DOM and HTML on every page

Where	All templates, including the 404 page.
Evidence	Homepage: **3,448 DOM elements**, **347 links** (116 unique), 90 images, 17 inline scripts, the logo markup repeated 9 times. HTML is ~450 KB uncompressed (~91 KB brotli). The 404 page is 303 KB; every category/product page is 335-475 KB of HTML (e.g. /xlr-connectors/ 474 KB with 62 images, /bnc-connectors/ 450 KB with 54 images). The header mega-menu (desktop + mobile versions) is printed in full on each page.
Impact	Large DOM slows rendering and interaction on low-end phones (INP/LCP) and inflates server time.
How to fix	- Shorten the mega-menu (limit to top-level + key children), or load child menus on demand; avoid printing separate desktop and mobile copies of the same menu where the theme allows. - Remove hidden/duplicated sections and unused Elementor widgets; use the Elementor "Optimized DOM" / flexbox container experiments. - Give the 404 template a minimal layout.
Re-test	Target under ~1,500 DOM elements on the homepage and under ~250 KB HTML (raw) on templates; verify in Lighthouse "Avoid an excessive DOM size".

MEDIUM M2 Oversized, unconverted images

Where	Homepage hero and banners; wp-content/uploads/2025/11/IMG_1387-scaled.jpg, uploads/2025/08/pexels-photo-164572-164572-scaled.jpg
Evidence	Initial load transferred ~2.0 MB (desktop) / 2.1 MB (mobile) in 27-28 requests; 13-14 images = 1.47-1.57 MB. IMG_1387-scaled.jpg is 909 KB, the pexels hero is 513 KB. Many images are WordPress "-scaled" 2560 px originals (e.g. 2560x1280 and 2560x1350) and PNG banners.
Impact	Slow LCP on Indian mobile networks, wasted data, lower rankings.
How to fix	- Use LiteSpeed Image Optimization (or ShortPixel/Imagify) to convert to WebP/AVIF and generate responsive sizes; serve ~1600 px max for hero banners (1366 px is the typical desktop width). - Re-export IMG_1387 and the pexels hero at 100-200 KB; replace large PNG banners with WebP. - Set explicit width/height on all images (6 homepage images lack dimensions).
Re-test	Target: under 1 MB total above-the-fold weight.

MEDIUM M3 Slow server response and slow WooCommerce pages

Where	Server response on homepage; /cart/, /checkout/, /my-account/, category pages.
Evidence	Homepage TTFB (cache HIT) measured 0.8 s, 1.4 s and 2.3 s over three consecutive requests (1.06 s in the browser). Fully loaded page fetches: /cart/ 5.9 s, /checkout/ 4.8 s (one redirect), /my-account/ 3.6 s, /30mm-circular-connectors/ 3.4 s, /16mm-circular-connectors/ 2.8 s. Measured from a remote data centre, so absolute values include network latency.
Impact	Cart and checkout are the highest-value pages; delays there directly reduce orders.
How to fix	- Confirm the Hostinger plan has enough PHP workers/RAM; enable LiteSpeed **object cache** (Redis/Memcached) if the plan supports it. - Profile the slow pages with Query Monitor: look for heavy product-category queries (500+ products), plugins running on every request, expired transients, autoloaded options. - Exclude cart/checkout/my-account from page cache (already uncached by Woo) and make sure no unnecessary scripts load on them. - Re-measure from an Indian location (PageSpeed Insights / WebPageTest Mumbai) for a fair baseline.

MEDIUM

M4 SEO titles: weak homepage title, many long or truncated titles

Where	Homepage + product/category titles (847 URLs crawled).
Evidence	Homepage title is **"Home - Setmi India"** (18 characters, no keywords) although the H1 is "Connectors, Cables & RF Components Online in India". Across 847 URLs: **288 titles are over 60 characters** (105 over 70), **78 are cut mid-word with "…"** (e.g. "Push-Type fuse And Switch For Male Conne… | Setmi India"), **4 are missing the separator** (e.g. "HDMI CablesSetmi India"), 20 meta descriptions exceed 160 characters, and 1 blog title is 113 characters. Many category/page titles are very short (22-30 characters) and underuse the space.
Impact	Truncated or generic titles lower click-through and relevance. Missing separators and "…" look unprofessional in search results.
How to fix	- Homepage title suggestion: **Connectors, Cables & RF Components Online in India | Setmi India** (60 chars). - Set Yoast title templates: Product `%%title%% | %%sitename%%`, Category `%%term_title%% Buy Online | %%sitename%%`; keep 50-60 characters and descriptions 120-155. - Fix the 4 missing-separator titles (Appendix A) and the 78 product titles that were manually truncated with "…" - write a short real title instead. - Page-type "category" pages (e.g. /sma-connectors/) average only 22-33 title characters: add the keyword and benefit.

MEDIUM

M5 Duplicate category pages: two indexable URLs for the same category

Where	24 slugs, e.g. /dvi-couplers/ and /product-category/dvi-couplers/ (full list in Appendix A).
Evidence	Both URLs return 200, are self-canonical, "index, follow", appear in the sitemaps (page-sitemap and product_cat-sitemap) and use different titles (e.g. "DVI Couplers - Setmi India" vs "DVI Couplers - Buy Online | Setmi India").
Impact	Two pages compete for the same keyword (cannibalisation), splitting links and rankings and wasting crawl budget.
How to fix	- Choose the preferred URL per category (the richer, Elementor-built page is usually the better one) and 301-redirect the other, or canonical/noindex the duplicate and remove it from the sitemap. - Update menu and internal links to point only to the preferred URL; re-submit sitemaps in Search Console.

MEDIUM

M6 Many images have no alt text

Where	Homepage and all product pages.
Evidence	Homepage: 29 of 90 images have no alt (the Trustindex review widget alts are fine; the missing ones are hero banners, series images, category icons). Product pages: **2,838 of 12,427 images (23%)** missing alt across 567 products; 5-6 per page are sitewide menu/footer images, the rest are product galleries.
Impact	Lost image-search traffic and an accessibility failure (screen readers). Decorative images may keep empty alt, but product and banner images need descriptions.
How to fix	- Fix the sitewide menu/footer images once in the header/footer builder (fixes 5-6 images on every page). - Add alt text to product gallery images: describe type, size and pin count, e.g. "25mm 4-pin waterproof circular connector, solder type". Bulk-edit via the media library or an alt-text plugin.

MEDIUM

M7 Product structured data: 21 products missing, others incomplete

Where	Product pages; list of 21 in Appendix A.
Evidence	40 sampled products had Product schema; across the full crawl **21 products have none** (e.g. /product/computer-male-cable-type/, /product/bnc-plug-2-pin/). Existing schema is thin: no `brand`, no GTIN/MPN, no `aggregateRating`/`review`, no `shippingDetails` or `hasMerchantReturnPolicy`, and the `description` field glues labels together without spaces ("...Hdmi MaleCategory: DVI CouplersIndustry: ..."). `valueAddedTaxIncluded` is false - confirm it matches the displayed prices (GST).
Impact	Missing rich-result eligibility (price/availability/stars) and Merchant Center warnings (the site runs Google Listings & Ads).

How to fix	- Find out why the 21 products lack schema (often a missing SKU, short description or custom template) and fix the cause. - Add brand (Setmi India), SKU/MPN, shipping and return policy (the site already has /shipping-policy/ and /refund_returns/ pages). - Fix the product short-description template so fields are separated by periods or line breaks. - Validate with Google Rich Results Test.

MEDIUM M8 No contact form; phone and email are plain text

Where	/contact/ and homepage top bar / footer.
Evidence	The Contact page contains the address, four phone numbers and info@setmiindia.com but no form - the only forms on the page are the search box and the (hidden) login. No `tel:` or `mailto:` link exists anywhere on the homepage, so "Enquiry: +91 85868 78111" cannot be tapped on mobile. The only 1-tap channel (WhatsApp) is broken (H5).
Impact	B2B buyers browsing products cannot send an enquiry or call in one tap, so leads are lost. An unprotected form would also attract spam, so protection matters.
How to fix	- Add an enquiry/contact form (WPForms/Contact Form 7/Elementor Form) with Cloudflare Turnstile or reCAPTCHA and an email to info@setmiindia.com. - Add "Request a quote" / "Enquire on WhatsApp" buttons on product pages with the product name pre-filled. - Make phone numbers `tel:+918586878111` and the email a `mailto:` link; add a sticky mobile call/WhatsApp button.

MEDIUM M9 Metadata copy errors in product descriptions

Where	Product pages.
Evidence	**SMA vs SMB mix-up:** two SMA products have an SMB meta description - "Shop SMB Male Straight Panel Mount Connector..." and "High-quality SShop SMB Male Crimp Connector for RG Cable..." (typo "SShop"). **Identical meta description** on 4 different BNC products ("BNC Male Plug with 2 Screw Terminal for secure, st..."). URLs are listed in Appendix A.
Impact	Wrong specs in snippets mislead buyers searching for exact connector types and can reduce trust; identical descriptions give no distinguishing information.
How to fix	Rewrite the affected meta descriptions so they match the product (SMA vs SMB are different connectors), fix the "SShop" typo and give each BNC product a unique description.

4. Low priority findings and information

LOW L1 Version disclosure and public default files

Where	Page source, HTTP headers, /readme.html, /license.txt
Evidence	Generator meta tags expose WordPress 7.1.2, WooCommerce 11.1.2, Elementor 4.3.3 and Site Kit 1.188.0; the header `X-Powered-By: PHP/8.2.33` is sent; /readme.html and /license.txt are publicly readable (HTTP 200). Sensitive files (.env, .git/config, debug.log, wp-config backup) correctly return 403.
Impact	Helps attackers match known vulnerabilities to the exact versions. Keep every component updated; hiding versions is only defence in depth.
How to fix	Delete readme.html and license.txt (re-created by core updates, so add a deny rule), remove generator tags (`remove_action('wp_head','wp_generator')`), and remove X-Powered-By in the server config. Confirm WordPress, WooCommerce, Elementor and all plugins are on the latest patch release and remove unused plugins/themes.

LOW L2 Security headers

Where	All responses.
Evidence	Present: HSTS (max-age 1 year), X-Content-Type-Options, X-Frame-Options SAMEORIGIN, Referrer-Policy. Missing or weak: no real Content-Security-Policy (only `upgrade-insecure-requests`), the Permissions-Policy only lists private-state-token entries and does not restrict camera/microphone/geolocation, HSTS has no includeSubDomains/preload.
Impact	Reduces protection against XSS and third-party script abuse.
How to fix	Add a report-only CSP first (allow Google tag/analytics, Trustindex, fonts) and tighten gradually; add `Permissions-Policy: camera=(), microphone=(), geolocation=()`; add includeSubDomains once all subdomains are HTTPS.

LOW L3 Multiple Google tags and delayed analytics

Where	Homepage .
Evidence	Three gtag loaders (G-85SC6YV2T1, GT-WRDQNFR2, AW-16705509694) plus GTM container GTM-MWBFLP7X appear in the markup. Some of the analytics hits were aborted in the test (they fire only after the delayed scripts run).
Impact	Risk of double-counted page views/conversions and extra script weight; delay JS can undercount traffic.
How to fix	Audit which tags are required (Site Kit, Google Listings & Ads, GTM). Keep one path per product (e.g. GA4 via GTM or via Site Kit, not both) and exclude tag scripts from JS delay.

LOW L4 Fonts and CSS

Where	Homepage requests.
Evidence	7 font files = 444 KB, including Font Awesome 6.6 loaded from use.fontawesome.com (154 KB) although Elementor is set to inline SVG icons; the Trustindex stylesheet `trustindex-google-widget.css` is linked twice.
Impact	Extra requests and render-blocking resources.
How to fix	Self-host only the font weights/glyphs in use (WOFF2, `font-display: swap`), drop Font Awesome if SVG icons are used, preload the main font, and remove the duplicate stylesheet.

LOW L5 Static asset cache lifetime

Where	Images, JS, CSS.
Evidence	Cache-Control is `public, max-age=604800` (7 days) for images and core JS.
Impact	Repeat visitors re-validate assets weekly.
How to fix	Use max-age=31536000 for versioned/hashed assets and images (LiteSpeed Cache > Browser > Browser Cache TTL).

LOW

L6 Layout and accessibility polish

Where	Header navigation and generic UI.
Evidence	At 1366 px the main menu wraps to two rows with "Other Products" alone on row two. 14 links on the homepage use `href="#"`. 36 interactive elements (desktop) / 32 (mobile) are smaller than 24 px; the smallest body text on mobile is ~10.9 px. Positive: skip link and 106 aria-labels present, no horizontal scroll on mobile, no unlabeled form fields.
Impact	Harder navigation on small screens, lower accessibility score.
How to fix	Tighten menu spacing or merge items so the primary menu fits one row; give parent menu items real URLs or buttons with ARIA; enlarge tap targets to at least 24x24 px (ideally 44 px on mobile) and raise the minimum mobile font size to 12 px.

LOW

L7 Heading structure

Where	Homepage.
Evidence	One H1 (good), 33 H2 and 15 H3 but no H4. Product names are H2s with very long keyword-stuffed text (e.g. "MC4 Connector for Solar Panels | Waterproof Solar Panel Wire Connectors (Male & Female Pair)"), and blog post titles use H3. The visible hero slides show their own headings, so the H1 text is not the first thing users see.
Impact	Muddled hierarchy dilutes topical focus and hurts screen-reader navigation.
How to fix	Use H2 for sections ("Top-Rated BNC Connector Series") and H3 for product names with short readable titles; make sure the H1 matches the visible hero message.

INFO

I1 Consent notice and REST CORS behaviour

Where	Site-wide.
Evidence	No cookie/consent banner was visible although Google Analytics, Google Ads remarketing and a third-party review widget (Trustindex, images from Google) run. Separately, the WordPress REST API echoes any `Origin` with `Access-Control-Allow-Credentials: true` - this is the default WordPress behaviour; authenticated actions still need a nonce.
Impact	Possible privacy-compliance gap (India DPDP Act and Google consent mode requirements for ads); CORS is informational.
How to fix	Have the owner decide on a consent notice (e.g. Complianz/CookieYes) wired to Google consent mode; this is a business/legal decision, not just a developer task. No change required for CORS unless a stricter API policy is wanted.

5. What is already working

- HTTPS everywhere; http:// and www redirect with a single 301 to https://setmiindia.com/; HSTS enabled.
- All 847 URLs in the sitemaps return HTTP 200; no broken internal links; 96 of 99 homepage links OK (LinkedIn/Instagram returned 999/429 which is bot-blocking, not a defect).
- Brotli compression, LiteSpeed page-cache HIT on HTML, no JavaScript errors and no failed first-party requests.
- Canonical tags on every URL, no accidental noindex, 1 H1 on every page, robots.txt blocks cart/checkout/account, filters and feeds; Yoast sitemap submitted via robots.txt.
- Open Graph and Twitter card tags, JSON-LD (WebPage, Organization, Breadcrumb); product schema on 546 of 567 products.
- Mobile viewport configured, no horizontal scroll at 390 px, skip link and ARIA labels present.
- Policy pages exist (shipping, refund/returns, data/privacy, terms); address and phone shown on the contact page; copyright year current.
- Sensitive file probes (.env, .git/config, debug.log, wp-config backup) are blocked with 403.

Appendix A - Affected URLs

H4 - product pages with unresolved %% template text (16)

/product/25mm-12-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/25mm-4-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/25mm-5-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/25mm-6-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/25mm-7-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/25mm-8-pins-circular-connector-soldered-wire-ip67-waterproof-threaded-lock/
/product/5-pin-circular-connector-high-quality-5-pin-set/
/product/gx-20mm-aviation-connector-10-pin-male-female-plug-panel-mount-adapter-nickel-plated-brass-body/
/product/gx-20mm-aviation-connector-9-pin-male-female-plug-panel-mount-adapter-nickel-plated-brass-body/
/product/gx16-4-pin-16-mm-aviation-connector-16-mm-metal-plug-nickel-plated-male-connector-solder-type-pins/
/product/gx16-5-pin-16-mm-aviation-connector-16-mm-metal-plug-nickel-plated-male-connector-solder-type-pins/
/product/gx16-6-pin-16-mm-aviation-connector-16-mm-metal-plug-nickel-plated-male-connector-solder-type-pins/
/product/gx16-7-pin-16-mm-aviation-connector-16-mm-metal-plug-nickel-plated-male-connector-solder-type-pins/
/product/high-quality-6-pin-circular-connector-built-to-last/
/product/high-quality-7-pin-circular-connector-built-to-last/
/product/lp24-rj45-cat5e-female-socket-ip67-waterproof-ethernet-connector/

M4 - titles missing the separator (4)

/product/xlr-female-mount-with-cap/
/product/hdmi-male-to-2-hdmi-female-y-cable/
/product/sb50-anderson-power-connector-600v-50-amp/
/product/australia-2-pin-multiplug/

M5 - slugs that exist both as /slug/ and /product-category/slug/ (24)

/led-wall-power-connectors/
/21mm-waterproof-connectors/
/17mm-waterproof-connectors/
/13mm-waterproof-connectors/
/computer-power-connectors/
/dvi-couplers/
/bnc-couplers/
/multimedia-tweeters/
/schuko-plugs/
/audio-video-couplers/
/terminal-push-terminal/
/audio-video-cables/
/computer-cables/
/usb-cables/
/power-cables/
/dvi-cables/
/hdmi-cables/
/rj-45-jointer/
/paging-horn-speakers/
/sma-connectors/
/circular-connectors/
/f-connectors/
/bnc-connectors/
/uhf-connectors/

M7 - products without Product schema (21)

/product/computer-male-cable-type/
/product/computer-female-cable-type/
/product/bnc-plug-sdi-compatible-full-metal-gold-plated/
/product/bnc-plug-2-pin/
/product/bnc-plug-clamp-rg213/
/product/bnc-socket-2-pin/
/product/bnc-plug-high-voltage-5000v/
/product/bnc-socket-to-banana-terminal-2/
/product/bnc-socket-to-2-banana-pin/
/product/best-and-high-quality-connector-f3-connector-2-pin-cable-connector-setmi-india/
/product/dvi-male-hdmi-male-coupler/
/product/m12-6-pin-connector-male-female/
/product/m12-4-pin-connector-male-female/
/product/m12-5-pin-connector-male-female/
/product/m12-5-pin-male-a-coded-ethernet-field-wireable-connector/
/product/m12-2-pin-connector-male-female/
/product/m12-3-pin-connector-male-female/
/product/bnc-plug-soldering-chassis-type/
/product/bnc-socket-chassis-mount/

/product/bnc-plug-crimp-rg-58-right-angle/
/product/bnc-socket-pcb-type-right-angle-2/

M9 - SMA products with SMB meta description

/product/sma-male-straight-panel-mount-connector/
/product/sma-male-straight-crimp-connector-for-rg-cable/

M9 - four BNC products sharing one meta description

/product/bnc-socket-chasisi-mount/
/product/bnc-plug-full-metal-soldering-type-taiwan-make/
/product/best-performance-bnc-plug-bnc-plug-with-2-screw-setmi-india/
/product/bnc-socket-pcb-type-right-angle/

Appendix B - Measurements

Metric	Desktop 1366x768	Mobile 390x844
TTFB (browser)	1,081 ms	1,061 ms
First contentful paint	2,152 ms	1,960 ms
Largest contentful paint (lab)	2,152 ms	2,324 ms
Cumulative layout shift (lab)	0.687	0
Load event	3.0 s	3.1 s
Requests on load	27	28
Transferred (images / fonts / CSS / JS)	~2.0 MB (1.47 / 0.44 / 0.13 / 0.01)	~2.1 MB (1.57 / 0.44 / 0.13 / 0.01)
DOM elements	3,448	3,448
Interactive elements under 24 px	36	32
Smallest text	13 px	10.9 px
Horizontal scroll	none	none

Tested with headless Chromium, no throttling, from a cloud data centre, so absolute timings will differ from users in India. Analytics beacons were aborted by the test environment and are not counted.

Crawl statistics (847 sitemap URLs)

Check	Result
HTTP status	847 x 200
Titles over 60 / over 70 chars	288 / 105
Titles truncated with "..."	78
Meta descriptions over 160 chars	20
Missing meta description	0
Duplicate titles	0
Duplicate meta descriptions	1 group (4 URLs)
Unresolved %% variables	16 URLs
Missing canonical / noindex	0 / 0
Pages with not exactly one H1	0
Product pages without Product schema	21 of 567
Product-page images without alt	2,838 of 12,427

Appendix C - Scope and limitations

- Only publicly reachable pages were tested. Admin area, plugin settings, server logs, the checkout payment flow and order emails were not inspected.
- Component versions come from the page source; they were not checked against vulnerability databases. Please confirm all components are on the latest releases.
- Sample sizes: homepage in-browser tests on desktop and mobile; metadata, schema and alt checks across all 847 sitemap URLs; the full list of 16 broken titles and 21 schema gaps is exact because every product URL was crawled.
- Search rankings, Search Console coverage, Core Web Vitals field data and Merchant Center diagnostics were not available; check them to prioritise further.
- No security exploitation was attempted: the XML-RPC and REST checks used the same harmless read-only calls any visitor can make.