


— Before (2011-Nov 2014) — During construction — After opening (Jun 2022-)

(a) Mawa rating curve by era



(b) Specific-gauge change (90% CI)

