
# SIGNAL ANALYSIS REPORT (AC)

DUT: AC_DETECTOR | Timestamp: 31/10/2026, 10:09:46 am

*Hardware Capacitive Antenna [Channel: 230V] → Active Filtration → ADC → 10 kHz DSP*

## Asset Location (GPS)


| | |
|---|---|
| **Latitude:** | 17.41492 °N |
| **Longitude:** | 78.37073 °E |
| **Source:** | Live Phone GPS |
| **Address:** | Manikonda, Telangana, India |





## BLC (Core Antenna) - Pure AC Waveform

| | |
|---|---|
| **Wave Type:** | Complex / Noisy |
| **DC Bias:** | 1645 mV |
| **True RMS:** | 30 mV |
| **Peak-to-Peak:** | 144 mV |
| **Dom. Freq:** | 50.0 Hz |
| **THD:** | 96.96% |

**[HIGH DISTORTION]**




## ALC (After Filter) - Pure AC Waveform

| | |
|---|---|
| **Wave Type:** | Complex / Noisy |
| **DC Bias:** | 1643 mV |
| **True RMS:** | 14 mV |
| **Peak-to-Peak:** | 53 mV |
| **Dom. Freq:** | 50.0 Hz |
| **THD:** | 21.53% |

**[HIGH DISTORTION]**

