

COKE CAN INSPECTION GATEWAY REPORT

PoC Gateway Gateway ID: INSPECT_20260719_SIMULATED

INSPECTION METADATA

DEFECT STATISTICS

Date: 2026-07-19

Total Scratches: 1

Time: 04:35:12

Total Dents: 1

Duration: 0.42 sec

Avg Confidence: 93.0%

RESULT

FAIL

3D DIGITAL TWIN DEFECT MAPPING

Cameras: 2 Active


Max Severity: Major

CLICK HERE TO OPEN INTERACTIVE 3D DIGITAL TWIN IN CHROME

Launches WebGL 3D cylinder. Supports orbit rotation, manual defect injection, and deletion.

DEFECT DETAIL LOGS (PAGE 1/1)

High-resolution camera crops and spatial surface coordinate mappings.



SCR_001 C

[SCRATCH] SCR_001

Length: 15.4 mm

Width: 0.65 mm

Area: 10.0 mm²

Orientation: 0.0°

Confidence: 91%

Camera: Camera_1

Angle: 45.0°

Height: -0.020 m



DENT_001 C

[DENT] DENT_001

Diameter: 8.2 mm

Depth: 1.74 mm

Area: 52.8 mm²

Severity: Major

Confidence: 95%

Camera: Camera_1 + Camera_2


Angle: 121.0°

Height: 0.030 m

ANNOTATED CAMERA CAPTURES

Synchronized dual-camera views showing localized bounding boxes for all active detections.

CAMERA 1 (TOP-RIGHT VIEW) - ANNOTATED FEED



CAMERA 2 (TOP-LEFT VIEW) - ANNOTATED FEED

