

PRELIMINARY SURVEY REPORT**August 13, 2025**

Your Ref.	:		Our Ref.	:	25-116868
Date of Assignment	:	August 5, 2025	Inspected by	:	<surveyor name>
Date of Survey	:	August 6 and 12, 2025	Place of Survey	:	<survey location>
Vessel/Carrier	:	<vessels name>	Voyage	:	<voyage number>
Port of Discharge	:	<port name>	Date of Discharge	:	August 6, 2025
Consignment	:	1360 boxes of "Frozen Cherries, 18,509.60kg" from 40ft refrigerated container TEMU9238382 transloaded in route (Panama) to MSDU9734453			
Shipper Delivering Carrier	:	Shipper details	Consignee	:	<consignee details>
	:		Waybill No.	:	<way bill number>
Date of Delivery	:	August 7, 2025	Cargo Exceptions:	:	Alleged Damage to Cargo

Further to the request of XXX, we did attend survey of above shipment.

SURVEYOR'S FINDINGS:

Surveyor attended Lineage facility on August 6, 2025, however, the container had not been delivered. Surveyor was further advised that the container was to be inspected in presence of FDA inspector. Container was reportedly delivered to Lineage on August 7, 2025. Due to FDA inspector availability, survey was conducted on August 12, 2025.

In attendance were <people in attendance>

FDA inspector arrived and had brief discussion with Ms. Dunn but took no part in the unload and inspection of the cargo.

The container MSDU9734453 was 11/2004 mfd. 40ft high cube refrigerated container. No exceptions were observed (normal wear and tear excepted). Reefer unit was operational with set point temperature at -20degC and return air temperature at -20.1degC prior to opening the doors. High security bolt seal #AIR13256 was on the doors and removed in presence of all attending parties. Slight frost at the doors was observed. Cargo was palletized, with pallets stowed in two columns without any blocking and bracing. No shift in stow was observed. Cartons were stacked 7 high on the pallets and were poly wrapped. Warehouse crew used a forklift to devann all the pallets. Three temp recorders were recovered and readout provided by Lineage

- #1 Serial # PAVYN08H3V at rear of container on top of cartons
- #2 Serial # PAVYN8HWV at center of container on top of cartons
- #3 Serial # PAVYN08HXV at front of container on top of cartons

Cartons appeared crisp and showed no signs of exposure to moisture. Surveyor opened nine cartons from various pallets for inspection. Cartons showed no sign of leakage or water damage. Product had slight frosting on surface and appeared consistent in all cartons. No signs of product thawing and leaking or malodor were observed. Overall, the cargo appeared to be in apparent good condition.

Silver nitrate test on three pallets was negative for chlorides
Container floor was dry and clean.

NATURE/CAUSE OF LOSS:

No apparent damages to shipment were observed.

PACKING:

Merchandise was packaged in unsealed yellow plastic bags, placed in cardboard cartons, with flaps closed and taped. Packing appeared adequate and customary.

SN TEST:

Salinity test on wooden pallets was negative for chlorides.

RECOMMENDATIONS FOR MITIGATION OF LOSS:

n/a

EXTENT OF LOSS / RECOMMENDED LOSS RESERVE:

n/a

ADDITIONAL COMMENTS:

This report is based on the facts presently known to us and is submitted without prejudice to the rights of whom it may concern. All our findings and comments are subject to the underlying insurance policy conditions and/or provisions of the law. The right to amend or supplement this report at any time is reserved.

Limited Liability

It is expressly understood that all our services are rendered solely on behalf of the person or entity requesting same. Under no circumstances shall <surveyor company> be neither liable for any indirect or consequential losses, howsoever arising, nor to any person or entity other than the person or entity requesting such services.

It is expressly understood and agreed that in any event, the liability of <surveyor company> and of its employees, officers, or subcontractors is limited to the fee charged for all services rendered to subject assignment, but not to exceed \$1000.00. Any claim against <surveyor company> shall be submitted to commercial arbitration in accordance with the rules of the American Arbitration Association of New York and has to be submitted within 60 days of date of survey report or be time barred. The laws of the State of New Jersey shall govern all disputes and claims arising from the services of <surveyor company> under this agreement.

Very truly yours,



2.

Seal on the container



3.

Temperature display prior to opening the doors



4.

Paper seal on the doors



5.

Paper seal on the doors



6.

Slight frosting near the doors




7.

View of cargo inside the container



8.

View of cargo inside the container




9.

View of cargo inside the container



10.

Empty container



11.

Pallets staged on warehouse floor



12.

Pallets staged on warehouse floor



13.

Typical labels




14.

Typical label



15.

Typical label



16.

One sample carton



17.

Sample carton



18.

Product in sample carton



19.

Temperature recorder #1



20.

Temperature recorder #2



21.

Temperature recorder #3



22.

Product in #2 carton



23.

Product in #3 carton



24.

Product in #4 carton



25.

Product in #5 carton



26.

Product in #6 carton



27.

Product in #7 carton



28.

Product in #8 carton



29.

Product in #9 carton



30.

Silver nitrate test on pallet was negative

