
San Diego Exploit Team presents



Cha Cha... Choppin down the China Chopper webshell (say it fast 3*)

Official malware report

China Chopper CnC | caidao.exe

SAN DIEGO EXPLOIT TEAM. PROPRIETARY INFORMATION

The information in this document is proprietary to Rick Flores. It may not be used, reproduced, disclosed, or distributed without the written approval of Rick Flores. 

Figure 0xFFF: Figured I'd get this out of my system ;)

Procedure Summary				
Procedure:	Malware reverse engineering (dynamic/static analysis)			
Author:	Rick Flores			
Approved By:				
Effective Date:	08/07/2013			
Source File Location:	-TBD			

Revision Summary				
Rev	Description of changes	Changes by:	Review / Approval by:	Date
1.0	Rough DRAFT	Flores, Rick	N/A	08/07/2013

	Report Details		
Infected user	Computer Name	Malware Analyst	Date
INFECTED	XEN-00xFFFFF_F.anon.local	Flores, Rick	08/07/2013

Table of Contents

1.	Scope	<i>6</i>
2.	Investigation goals	7
3.	Malware sample analyzed	8
4.	Malware variant history, timeline, and special features	8
5.	General function and functionality of the malware	13
6.	Network behavior (including hosts, domains and ip's accessed)	14
7.	Time and local system dependant features	19
8.	Snort signature to detetct China Chopper CnC malicious traffic	19
9.	References	19



1. SCOPE

1.1 Detection Operations created this malware report in an effort to track, categorize, contain, understand root cause and infection vector of said malware sample, user account/s, networked equipment and or computer/s.



2. INVESTIGATION GOALS

- 2.1 Determine extent of infection, uncover actual business risk, data exposure, network weakness, and figure out infection vector and propogation methods.
- 2.2 More importantly this report should uncover host based indicators that can be used to detect infection, and include network signatures used to alert/prevent potential infection (*McAfee HIPS, Snort, DNS sinkhole...* etc).



3. MALWARE SAMPLE ANALYZED

China Chopper CnC | BackDoor.Chopper.1

Filename: caidao.exe (the client interface)

MD5: md5sum caidao.exe 5001ef50c7e869253a7c152a638eab8a caidao.exe

SHA1: sha1sum caidao.exe 056a60ec1f6a8959bfc43254d97527b003ae5edb caidao.exe

SHA256: be24561427d754c0c150272cab5017d5a2da64d41bec74416b8ae363fb07fd77 caidao.exe

SSDEEP: ssdeep,1.1--blocksize:hash:hash,filename

6144:SsTPvGm5RJ5DbeigL9Phruwz1nverLgCBUtePdo:S03GAJ5DbeNZImEP/BUtn,"/root/Desktop/malware/caidao/caida o.exe"

PACKER USED: caidao.exe: PE32 executable (GUI) Intel 80386, for MS Windows, UPX compressed

MD5	5001ef50c7e869253a7c152a638eab8a
SHA1	056a60ec1f6a8959bfc43254d97527b003ae5edb
SHA256	be24561427d754c0c150272cab5017d5a2da64d41bec74416b8ae363fb07fd77
ssdeep	6144:SsTPvGm5RJ5DbeigL9Phruwz1nverLgCBUtePdo:S03GAJ5DbeNZImEP/BUtn
File size	215.5 KB (220672 bytes)
File type	Win32 EXE

Figure 0x: VirusTotal submission details.



- 3.1 Location C:\Documents and Settings\sandb0x\Local Settings\Temp\caidao.exe
- 3.2 Moving forward, and for brevity I will be referring to "caidao.exe" simply as the malware sample. When you read 'malware sample' or simply 'sample' in the remainder of this report, safely assume I am referring to caidao.exe which is the malicious sample used as the basis of this malware report.



4. MALWARE VARIANT HISTORY, TIMELINE, AND SPECIAL FEATURES

- 4.1 Fisrt publicly documented <u>blog</u> post on the China chopper webshell (Friday, November 16, 2012).
- 4.2 Fireeye researchers released a part 1 of 2 blog post and new information on the chinese malware (August 7, 2013). Part 1 included a quick surface level analysis of the sample.
- 4.3 Part 2 promises deeper analysis on its delivery mechanisms, traffic analysis and detection. FireEye also plans to release regular expressions that can be used to find instances of this Web shell.
- 4.4 Because the strings are not encoded, examining the printable strings in the unpacked binary provides insight into how the backdoor communicates. We were intrigued to see a reference to google.com.hk using the Chinese (simplified) language parameter (Figure 3) as well as references to the text "Chopper" (Figure 4).



```
C:\WINDOWS\system32\cmd.exe

X-Forwarded-For: Xs
User-Agent: Xs
Content-Type: application/x-www-form-urlencoded

Pafanan: Xc
http://www.google.com.hk/search?hl=zh-CN&q=

IYFE:GUSIUMIZE
Please enter the URL address!
.com/
http://www.
CMyWindow
Right Bar
xs\system32
Shortcut Name
LIMIT
SkinScrollBarFrame
Tip: The default view can not be deleted!
[Alt+K]
[Alt+J]
CUiewCrack
.php.asp.aspx.html.jsp.txt
xs,200;xs.60
(crack) (url:http://xs/xxs/) (flag:successfully) (dict:list.txt)
(crack) (url:http://xs/admin/) (flag:!!HTTP/1.1 200) (dict:list.txt)
(spider) (url:http://xs/damin/) (flag:!!TTP/1.1 200) (dict:list.txt)
```

Figure 1: Printable strings refer to www.google.com.hk



```
MS Sans Serif
MS Sans Serif
WebRun
Exexute
Load
Save
Clear
Down
MS Sans Serif
SysListUiew32
List1
MS Sans Serif
5Chopper
Chopper
Chopper
Chopper
Chopper
Chopper
Document
Chopper
Weady
Open the document
```

Figure 4: Strings references to the text "Chopper".



5. GENERAL FUNCTION AND FUNCTIONALITY OF THE MALWARE

This is a very tiny and feature packed malware sample. It can be used as a RAT, and has several CnC features. Some of the features include:

5.1 Security scanner, spider, password bruteforcer, File Management (File explorer) Database Management (DB client) and Virtual Terminal (Command shell).




Figure 5: Virtual terminal tabbed (similar to Armitage).



6. NETWORK BEHAVIOR (INCLUDING HOSTS, DOMAINS AND IP'S ACCESSED)

6.1 WHOIS can be seen below as having a Beijing, China origin. Domain can be clearly seen as recently updated from this:

```
Registered through: GoDaddy.com, LLC (http://www.godaddy.com)
Domain Name: MAICAIDAO.COM
  Created on: 16-May-09
  Expires on: 16-May-15
  Last Updated on: 30-Jul-11
Registrant:
maicaidao
FangXinYuan
BeiJing
BeiJing, FenTaiQu 100072
China
Administrative Contact:
  caidao, mai root@maicaidao.com
  maicaidao
  FangXinYuan
  BeiJing
  BeiJing, FenTaiQu 100072
  China
  +86.01086886789
Technical Contact:
  caidao, mai root@maicaidao.com
  maicaidao
  FangXinYuan
  BeiJing
  BeiJing, FenTaiQu 100072
  China
  +86.01086886789
Domain servers in listed order:
  NS25.DOMAINCONTROL.COM
  NS26.DOMAINCONTROL.COM
```



To this:

Domain Name: MAICAIDAO.COM

Registrar URL: http://www.godaddy.com

Updated Date: 2013-05-04 01:53:31

Creation Date: 2009-05-16 07:17:54

Registrar Expiration Date: 2015-05-16 07:17:54

Registrar: GoDaddy.com, LLC

Registrant Name: mai caidao

Registrant Organization: maicaidao

Registrant Street: FangXinYuan

Registrant Street: BeiJing

Registrant City: BeiJing

Registrant State/Province: FenTaiQu

Registrant Postal Code: 100072

Registrant Country: China



Admin Name: mai caidao

Admin Organization: maicaidao

Admin Street: FangXinYuan

Admin Street: BeiJing

Admin City: BeiJing

Admin State/Province: FenTaiQu

Admin Postal Code: 100072

Admin Country: China

Admin Phone: +86.01086886789

Admin Fax:

Admin Email: root@maicaidao.com

Tech Name: mai caidao

Tech Organization: maicaidao

Tech Street: FangXinYuan

Tech Street: BeiJing

Tech City: BeiJing

Tech State/Province: FenTaiQu



Tech Postal Code: 100072

Tech Country: China

Tech Phone: +86.01086886789

Tech Fax:

Tech Email: root@maicaidao.com

Name Server: NS25.DOMAINCONTROL.COM

Name Server: NS26.DOMAINCONTROL.COM

Name Server: NS31.DOMAINCONTROL.COM

6.2 The malicious POST can be seen below.

∃ Hypertext Transfer Protocol

■ POST /code.asp HTTP/1.1\r\n

■ [Expert Info (Chat/Sequence): POST /code.asp HTTP/1.1\r\n]

Request Method: POST
Request URI: /code.asp
Request Version: HTTP/1.1
Cache-Control: no-cache\r\n

X-Forwarded-For: 88.120.198.202\r\n Referer: http://172.16.0.10\r\n

Content-Type: application/x-www-form-urlencoded\r\n

User-Agent: Mozilla/4.0 (compatible; MSIE 6.0; Windows NT 5.1)\r\n

Host: 172.16.0.10\r\n

User-Agent: User-Agent: Mozilla/4.0 (compatible; MSIE 6.0; Windows NT 5.1)



Host: 172.16.0.10

Figure 6: User-Agent and malicious host.

6.1 The malicious pages accessed can be seen below.

- [+] POST http://www.maicaidao.com/server.asp
- [+] POST http://www.maicaidao.com/server.aspx
- [+] POST http://www.maicaidao.com/server.php

Figure 7: Different pages accessed.

6.2 The malicious server details can be found below.




Figure 8: Malicious IP/Host.



7. TIME AND LOCAL SYSTEM DEPENDANT FEATURES

7.1 This malware sample requires a valid internet connection, and execution to activate its payload, and send/receive its instructions.



8. SNORT SIGNATURE TO DETECT CHOPPER CNC TRAFFIC

Below are examples of rough snort sigs that look for specific Chopper traffic.

- 1. alert tcp any any -> any 80 (msg:"China Chopper PHP/Backdoor Detected"; content:"|62 61 73 65 36 34 5f 64 65 63 6f 64 65|"; rawbytes; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.html; classtype:trojan-activity; sid:500007; rev:1)
- 2. alert tcp any any -> any 80 (msg:"China Chopper PHP/Backdoor Detected"; content: "|63 61 69 64 61 6f 3d|"; content:"|62 61 73 65 36 34 5f 64 65 63 6f 64 65|"; rawbytes; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.html; classtype:trojan-activity; sid:500008; rev:1)
- 3. alert tcp any any -> any any (msg: "China Chopper with first ASPX Payload Command (z1 = cmd shell access) Detected"; flow:to_server,established; content: "FromBase64String"; content: "z1"; content: "POST"; nocase;http_method; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-ii.html; classtype:web-application-attack; sid: 900000101;)
- 4. alert tcp any any -> any any (msg: "China Chopper with *all ASPX Payload Commands (z1 = cmd shell access, & z2 = directory listing/whoami command) Detected"; flow:to_server,established; content: "FromBase64String"; content: "z"; pcre: "/Z\d{1,3}/i"; content: "POST"; nocase;http_method; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-ii.html; classtype:web-application-attack; sid: 900000102;)
- 5. alert tcp any any -> any 80 (msg:"China Chopper with first ASP Payload Command (z1 = cmd shell access) Detected"; content: "|52 65 73 70 6f 6e 73 65 2e 45 6e 64|"; content: "|49 73 4e 75 6d 65 72 69 63|"; content: "|7a 31|"; rawbytes; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.html; classtype:trojan-activity; sid:500066; rev:1)
- 6. alert tcp any any -> any 80 (msg:"China Chopper with *all ASP Payload Commands (z1 = cmd shell access, & z2 = directory listing/whoami command) Detected"; content: "|42 52 65 73 70 6f



6e 73 65 2e 45 6e 64|"; content:"|45 6e 63 6f 64 69 6e 67 2e 47 65 74|"; content:"|7a 31|"; content:"|7a 32|";rawbytes; reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.html; classtype:trojan-activity; sid:500067; rev:1)

Src IP	SPort	Dst IP	DPort	Pr	Event Message
172.16.0.129	1300	172.16.0.10	80	6	China Chopper with first
207.35.251.172	2243	192.168.1.102	21	6	GPL FTP SITE EXEC atte
192.168.1.102	21	207.35.251.172	2243	6	GPL ATTACK_RESPONSE
192.168.1.102	23	217.156.93.166	61216	6	ET MALWARE Suspicious
207.35.251.172	4031	192.168.1.102	5920	6	ET SCAN Potential VNC S
192.168.1.102	23	217.156.93.166	61200	6	GPL TELNET Bad Login
210.114.220.46	653	192.168.1.102	111	17	GPL RPC portmap statu
207.35.251.172	4981	192.168.1.102	5807	6	ET SCAN Potential VNC S
207.35.251.172	2850	192.168.1.102	5432	6	ET POLICY Suspicious in
207.35.251.172	3066	192.168.1.102	1521	6	ET POLICY Suspicious in
207.35.251.172	1134	192.168.1.102	4333	6	ET POLICY Suspicious in
207.35.251.172	4095	192.168.1.102	3306	6	FT POLICY Suspicious in

✓ Show Packet Data ✓ Show Rule

alert tcp any any -> any 80 (msg:"China Chopper with first ASP Payload Command (z1 = cmd shell access) Detected"; content: "|52 65 73 70 6f 6e 73 65 2e 45 6e 64|"; content: "|49 73 4e 75 6d 65 72 69 63|"; content: "|7a 31|"; rawbytes;

reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breakingdown-the-china-chopper-web-shell-part-i.html; classtype:trojan-activity; sid:500066; rev:1) /nsm/server_data/securityonion/rules/bug-hunter-eth1-1/local.rules: Line 36

Figure 9: All above sigs have been tested and verified to fire.






Figure 10: Updated Snort sigs have been tested and verified to fire.



Dst IP	DPort	Pr	Event Message
172.16.0.10	80	6	China Chopper with first ASPX Payload Command (z1 = cmd shell access) Detected
192.168.1.102	21	6	GPL FTP SITE EXEC attempt
207.35.251.172	2243	6	GPL ATTACK_RESPONSE id check returned root
217.156.93.166	61216	6	ET MALWARE Suspicious FTP 220 Banner on Local Port (-)
192.168.1.102	5920	6	ET SCAN Potential VNC Scan 5900-5920
217.156.93.166	61200	6	GPL TELNET Bad Login
192.168.1.102	111	17	GPL RPC portmap status request UDP
192.168.1.102	5807	6	ET SCAN Potential VNC Scan 5800-5820
192.168.1.102	5432	6	ET POLICY Suspicious inbound to PostgreSQL port 5432
192.168.1.102	1521	6	ET POLICY Suspicious inbound to Oracle SQL port 1521
192.168.1.102	4333	6	ET POLICY Suspicious inbound to mSQL port 4333
192.168.1.102	3306	6	ET POLICY Suspicious inbound to mySQL port 3306

▼ Show Packet Data ▼ Show Rule

alert tcp any any -> any 80 (msg:"China Chopper with first ASPX Payload Command (z1 = cmd shell access) Detected"; content: "|52 65 73 70 6f 6e 73 65 2e 45 6e 64|"; content: "|49 73 4e 75 6d 65 72 69 63|"; content: "|7a 31|"; rawbytes;

reference:url,http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.ht ml; classtype:trojan-activity; sid:500027; rev:1)

/nsm/server_data/securityonion/rules/bug-hunter-eth1-1/local.rules: Line 36

Figure 11: Updated Snort sigs have been tested and verified to fire.



9. REFERENCES

- 1. http://informationonsecurity.blogspot.com/2012/11/china-chopper-webshell.html
- 2. http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-i.html
- 3. http://www.fireeye.com/blog/technical/botnet-activities-research/2013/08/breaking-down-the-china-chopper-web-shell-part-ii.html
- 4. https://www.virustotal.com/en/file/be24561427d754c0c150272cab5017d5a2da64d41 bec74416b8ae363fb07fd77/analysis/