



# Relationship between Land Surface Temperature (LST) and Foliar Water Stress Index (NDMI) for brick kilns and bare soil controls, León, Guanajuato (March-May)


**(a) LST vs NDMI — All years combined (2024-2026)**




**(b) 2024 | kiln  $\rho = -0.59$  | ctrl  $\rho = -0.57$**



**(c) 2025 | kiln  $\rho = -0.44$  | ctrl  $\rho = -0.52$**



**(d) 2026 | kiln  $\rho = -0.38$  | ctrl  $\rho = -0.49$**



Brick kiln Bare soil control