



Checked scene routes vs. recorded robot motion

— A* feasibility route — not sent to policy Recorded success Recorded failure


Furniture 4001 | A* route 6.04 m
success seed 9 · failure seed 0




Furniture 4002 | A* route 11.25 m
success seed 2 · failure seed 8



Mixed clutter 5001 | A* route 5.70 m
success seed 14



Mixed clutter 5002 | A* route 10.96 m
failure seed 12



A = nominal start B = goal. Shaded shapes show projected obstacle geometry.
Blue routes check a 0.23 m-radius root cylinder over $z = 0.35\text{--}1.05$ m; they do not certify limb clearance.