Bengaluru (Whitefield): regional check


Bengaluru (Whitefield) | Before - Sentinel-2 - 2019-02-18 to After - Sentinel-2 - 2025-02-06

What we found

We found 272 real changes covering 68.58 hectares. The biggest and strongest (rank 1) is new construction: 2.88 ha at 13.0020, 77.7370.

By priority: 1 Critical, 15 High, 67 Medium, 189 Low.

The detector first flagged 6,117 candidate areas. The rest were removed as false alarms: seasonal crop and vegetation cycles, change types this analysis does not track, tiny specks and noise, cloud and cloud shadow.



Numbers = rank of the 10 highest-priority changes. Outline colour = priority.

Changes by priority

Critical	1
High	15
Medium	67
Low	189

Totals

Area changed: 68.58 ha

Cropland affected: 14.03 ha (upper bound)

Built-up land affected: 31.30 ha

How to read this report

Rank	Every change has a number. Rank 1 is the highest priority: the largest and strongest change. Priority = size x strength of the change.
Priority colour and shape	Critical (octagon): score 20,000 or more (about 2 ha of strong change); High (diamond): score 5,000 or more; Medium (square): score 1,500 or more; Low (circle): score below 1,500 (small or weak).
Confidence	How sure the system is that the change is real, from 0 to 100 %. Changes marked 'needs a human check' sit between 50 % and 70 %.
What changed	New construction, vegetation cleared, vegetation growth, new water / flooding, water receded, or unexplained change. These come from rules on the satellite colours, not from knowing what is actually on the ground.
Raw detections	Everything the detector first flagged. Most are not real (clouds, crop seasons, shadows, specks), so only changes that pass the filters are listed here.

The 10 highest-priority changes

Start here. Each card says where the change is, how big it is, why it was flagged and what to do.


1

New construction

Rank 1 of 272 | Critical priority

Size	2.88 ha (28,750 m2), about 4 football pitches
Confidence	96 %
Location	13.00204, 77.73703 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.20), vegetation index fell (-0.15), water index rose (+0.26), SWIR/blue ratio (paved surfaces are flatter) fell (-2.81)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




2

New construction

Rank 2 of 272 | High priority

Size	1.35 ha (13,550 m2), about 2 football pitches
Confidence	97 %
Location	13.00260, 77.72576 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.24), vegetation index fell (-0.16), water index rose (+0.23), SWIR/blue ratio (paved surfaces are flatter) fell (-2.60)
What to do	Check soon. A substantial change that is probably real.

Before



After



3

New construction

Rank 3 of 272 | High priority

Size	1.38 ha (13,800 m2), about 2 football pitches
Confidence	94 %
Location	12.99063, 77.75521 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	water index rose (+0.08), SWIR/blue ratio (paved surfaces are flatter) fell (-0.79)
What to do	Check soon. A substantial change that is probably real.

Before



After




4

New construction


Rank 4 of 272 | High priority

Size	1.37 ha (13,700 m2), about 2 football pitches
Confidence	94 %
Location	12.96646, 77.74367 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.13), vegetation index fell (-0.14), water index rose (+0.20), SWIR/blue ratio (paved surfaces are flatter) fell (-1.75)
What to do	Check soon. A substantial change that is probably real.

Before



After



5

Water receded

Rank 5 of 272 | High priority

Size	0.93 ha (9,300 m2)
Confidence	98 %
Location	12.95280, 77.75216 (open in Google Maps)
What it is	Water that was there before has gone.
Why flagged	built-up index rose (+0.08), vegetation index rose (+0.70), water index fell (-0.76), SWIR/blue ratio (paved surfaces are flatter) rose (+4.62)
What to do	Check soon. A substantial change that is probably real.

Before



After



6

New construction

Rank 6 of 272 | High priority

Size	0.99 ha (9,950 m2)
Confidence	98 %
Location	12.97396, 77.72569 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.17), vegetation index fell (-0.07), water index rose (+0.09), SWIR/blue ratio (paved surfaces are flatter) fell (-0.70)
What to do	Check soon. A substantial change that is probably real.

Before



After



7

New construction

Rank 7 of 272 | High priority

Size	0.83 ha (8,300 m2)
Confidence	98 %
Location	13.01758, 77.76296 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.20), water index rose (+0.05), SWIR/blue ratio (paved surfaces are flatter) fell (-0.87)
What to do	Check soon. A substantial change that is probably real.

Before



After




8

New construction

Rank 8 of 272 | High priority

Size	0.94 ha (9,400 m2)
Confidence	97 %
Location	13.01201, 77.77170 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index rose (+0.34), vegetation index fell (-0.10), SWIR/blue ratio (paved surfaces are flatter) rose (+1.43)
What to do	Check soon. A substantial change that is probably real.

Before



After



9

New construction

Rank 9 of 272 | High priority

Size	1.39 ha (13,850 m2), about 2 football pitches
Confidence	92 %
Location	12.98746, 77.75130 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.13), vegetation index fell (-0.06), water index rose (+0.22), SWIR/blue ratio (paved surfaces are flatter) fell (-2.99)
What to do	Check soon. A substantial change that is probably real.

Before



After




10

New construction

Rank 10 of 272 | High priority

Size	1.26 ha (12,650 m2), about 2 football pitches
Confidence	92 %
Location	13.01447, 77.76394 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.09), vegetation index fell (-0.12), water index rose (+0.22), SWIR/blue ratio (paved surfaces are flatter) fell (-2.28)
What to do	Check soon. A substantial change that is probably real.

Before



After



All 272 changes found

Every change that survived the false-alarm filters, in priority order (rank 1 is the highest). A * after the confidence means it needs a human check. The CSV and GeoPackage downloads hold the same list with every attribute.

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
1	Critical	New construction	2.88	96 %	13.00204	77.73703
2	High	New construction	1.35	97 %	13.00260	77.72576
3	High	New construction	1.38	94 %	12.99063	77.75521
4	High	New construction	1.37	94 %	12.96646	77.74367
5	High	Water receded	0.93	98 %	12.95280	77.75216
6	High	New construction	0.99	98 %	12.97396	77.72569
7	High	New construction	0.83	98 %	13.01758	77.76296
8	High	New construction	0.94	97 %	13.01201	77.77170
9	High	New construction	1.39	92 %	12.98746	77.75130
10	High	New construction	1.26	92 %	13.01447	77.76394
11	High	New construction	0.75	98 %	12.96729	77.72364
12	High	New construction	0.94	96 %	12.96055	77.74813
13	High	New construction	0.95	95 %	13.01916	77.72265
14	High	New construction	1.09	92 %	12.98884	77.78912
15	High	New construction	0.64	98 %	12.98309	77.74443
16	High	New construction	0.62	98 %	12.98758	77.79432
17	Medium	New construction	0.60	98 %	12.95490	77.75093
18	Medium	New construction	0.64	97 %	12.99266	77.72051
19	Medium	New construction	0.66	95 %	13.00448	77.73340
20	Medium	New construction	0.58	96 %	13.00114	77.72636
21	Medium	New construction	0.69	94 %	12.98228	77.77368
22	Medium	New construction	0.50	97 %	12.98574	77.73806
23	Medium	New construction	0.59	95 %	12.98980	77.78904
24	Medium	New construction	0.47	98 %	12.97721	77.75843
25	Medium	New construction	0.52	96 %	13.01414	77.76264
26	Medium	New construction	0.64	94 %	12.98756	77.72085
27	Medium	New construction	0.72	91 %	12.97390	77.75717
28	Medium	New construction	0.40	98 %	13.00168	77.72443
29	Medium	New construction	0.59	94 %	13.01427	77.72807
30	Medium	New construction	0.42	98 %	12.97884	77.72939
31	Medium	New construction	0.56	93 %	12.97201	77.76465
32	Medium	New construction	0.47	96 %	12.98839	77.72038
33	Medium	New construction	0.56	93 %	13.00045	77.72709
34	Medium	New construction	0.49	94 %	12.99323	77.79835
35	Medium	New construction	0.36	98 %	12.97095	77.73607
36	Medium	New construction	0.62	89 %	12.99351	77.78232
37	Medium	New construction	0.48	94 %	12.99897	77.72124
38	Medium	New construction	0.40	96 %	12.96894	77.73342
39	Medium	New construction	0.45	95 %	13.01585	77.75620
40	Medium	New construction	0.30	98 %	12.98954	77.72761
41	Medium	New construction	0.33	97 %	12.98181	77.75623
42	Medium	New construction	0.34	97 %	13.01369	77.72281
43	Medium	New construction	0.43	93 %	12.99125	77.73000
44	Medium	New construction	0.32	97 %	12.98261	77.78432
45	Medium	New construction	0.37	95 %	12.98478	77.73042
46	Medium	New construction	0.38	94 %	12.97697	77.77950
47	Medium	New construction	0.39	94 %	12.96655	77.73976
48	Medium	New construction	0.40	93 %	12.98526	77.75002

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
49	Medium	New construction	0.42	92 %	12.96257	77.74212
50	Medium	New construction	0.38	94 %	12.98649	77.78832
51	Medium	New construction	0.28	97 %	12.98581	77.73414
52	Medium	New construction	0.39	93 %	13.00872	77.74002
53	Medium	New construction	0.28	96 %	13.00214	77.74242
54	Medium	New construction	0.34	93 %	12.95035	77.75813
55	Medium	New construction	0.24	98 %	12.99883	77.73395
56	Medium	New construction	0.20	99 %	12.97482	77.74141
57	Medium	New construction	0.38	91 %	12.95283	77.72119
58	Medium	New construction	0.32	94 %	12.96315	77.73461
59	Medium	New construction	0.24	98 %	12.95545	77.72867
60	Medium	New construction	0.31	94 %	13.00404	77.73527
61	Medium	New construction	0.33	93 %	12.96906	77.72465
62	Medium	New construction	0.28	96 %	12.95005	77.74702
63	Medium	New construction	0.29	95 %	12.98971	77.78611
64	Medium	New construction	0.28	95 %	12.99084	77.79724
65	Medium	New construction	0.34	92 %	12.98552	77.72901
66	Medium	New construction	0.38	89 %	12.96583	77.76878
67	Medium	New construction	0.30	93 %	12.96808	77.73540
68	Medium	New construction	0.30	93 %	12.98515	77.73466
69	Medium	New construction	0.21	98 %	12.97335	77.72302
70	Medium	New construction	0.29	93 %	12.97563	77.73061
71	Medium	New construction	0.24	96 %	12.98456	77.73320
72	Medium	New construction	0.27	94 %	12.96263	77.72304
73	Medium	New construction	0.20	98 %	12.97763	77.72389
74	Medium	New construction	0.24	95 %	13.01514	77.72344
75	Medium	New construction	0.23	96 %	13.01900	77.76041
76	Medium	New construction	0.23	96 %	12.98913	77.79396
77	Medium	New construction	0.23	96 %	12.97446	77.73110
78	Medium	New construction	0.27	94 %	12.98568	77.73934
79	Medium	New construction	0.21	97 %	12.99804	77.75452
80	Medium	New construction	0.25	94 %	12.97277	77.72207
81	Medium	New construction	0.21	97 %	12.97227	77.72232
82	Medium	New construction	0.17	98 %	13.00662	77.72925
83	Medium	New construction	0.21	96 %	12.97155	77.76546
84	Low	New construction	0.17	98 %	13.01233	77.76211
85	Low	New construction	0.21	96 %	12.99283	77.74785
86	Low	New construction	0.16	98 %	12.97484	77.72303
87	Low	New construction	0.20	96 %	12.97777	77.72284
88	Low	New construction	0.17	98 %	12.98119	77.72313
89	Low	New construction	0.17	98 %	12.98176	77.72312
90	Low	New construction	0.24	94 %	12.99916	77.72477
91	Low	New construction	0.33	86 %	12.97424	77.72363
92	Low	New construction	0.15	99 %	12.99679	77.76155
93	Low	New construction	0.17	98 %	12.97201	77.72334
94	Low	New construction	0.15	99 %	12.99006	77.78257
95	Low	New construction	0.17	97 %	12.97254	77.76302
96	Low	New construction	0.29	88 %	13.02039	77.72378
97	Low	New construction	0.24	93 %	12.97377	77.74389
98	Low	New construction	0.16	98 %	12.98234	77.72289
99	Low	Water receded	0.28	89 %	12.98593	77.80014

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
100	Low	New construction	0.20	95 %	12.99925	77.73239
101	Low	New construction	0.20	95 %	12.98620	77.74792
102	Low	New construction	0.15	98 %	12.97929	77.72433
103	Low	New construction	0.20	95 %	12.98963	77.72039
104	Low	New construction	0.18	96 %	12.99497	77.72802
105	Low	New construction	0.27	88 %	13.01291	77.73224
106	Low	New construction	0.18	96 %	12.97825	77.72383
107	Low	New construction	0.21	93 %	12.97594	77.72576
108	Low	New construction	0.12	99 %	12.99307	77.74562
109	Low	New construction	0.23	91 %	12.99996	77.72584
110	Low	New construction	0.20	94 %	13.01557	77.76673
111	Low	New construction	0.16	96 %	12.97125	77.77209
112	Low	New construction	0.21	92 %	12.98513	77.73687
113	Low	New construction	0.12	99 %	12.98942	77.79145
114	Low	New construction	0.20	93 %	12.99489	77.72721
115	Low	New construction	0.15	97 %	12.97446	77.72860
116	Low	New construction	0.20	93 %	12.99041	77.72804
117	Low	New construction	0.24	89 %	12.96398	77.73125
118	Low	New construction	0.21	92 %	12.98908	77.72112
119	Low	New construction	0.16	96 %	12.98427	77.76446
120	Low	New construction	0.18	94 %	12.97534	77.72564
121	Low	New construction	0.12	98 %	13.00531	77.77979
122	Low	New construction	0.21	91 %	12.99457	77.72959
123	Low	New construction	0.23	88 %	12.98977	77.74780
124	Low	New construction	0.16	96 %	12.99527	77.72961
125	Low	New construction	0.15	96 %	12.97701	77.72670
126	Low	New construction	0.24	87 %	12.97969	77.77670
127	Low	New construction	0.16	95 %	12.98121	77.72246
128	Low	New construction	0.18	93 %	12.99512	77.72878
129	Low	New construction	0.20	91 %	12.99210	77.79459
130	Low	New construction	0.18	93 %	12.97913	77.75703
131	Low	New construction	0.18	93 %	13.00098	77.77042
132	Low	New construction	0.14	96 %	12.96562	77.72506
133	Low	New construction	0.21	88 %	12.97409	77.76653
134	Low	New construction	0.14	96 %	12.97882	77.74971
135	Low	New construction	0.12	98 %	12.99028	77.79151
136	Low	New construction	0.12	97 %	13.01581	77.73076
137	Low	New construction	0.21	88 %	12.95040	77.77416
138	Low	New construction	0.15	94 %	13.00846	77.75154
139	Low	New construction	0.12	97 %	12.96566	77.72413
140	Low	New construction	0.14	95 %	12.99186	77.72826
141	Low	New construction	0.17	91 %	13.01322	77.73042
142	Low	New construction	0.21	86 %	12.95139	77.77445
143	Low	New construction	0.15	94 %	12.95326	77.73623
144	Low	New construction	0.17	91 %	12.97558	77.73148
145	Low	New construction	0.12	97 %	13.01142	77.76986
146	Low	New construction	0.15	93 %	12.99325	77.72862
147	Low	New construction	0.14	94 %	13.00893	77.72968
148	Low	New construction	0.12	96 %	12.99942	77.73500
149	Low	New construction	0.10	98 %	13.00108	77.71994
150	Low	New construction	0.12	96 %	12.97217	77.76574

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
151	Low	New construction	0.12	96 %	12.98486	77.76202
152	Low	New construction	0.15	93 %	12.95186	77.79863
153	Low	New construction	0.15	93 %	12.95729	77.72980
154	Low	New construction	0.12	96 %	12.96975	77.77290
155	Low	New construction	0.12	96 %	12.96646	77.74247
156	Low	New construction	0.15	92 %	13.01048	77.76106
157	Low	New construction	0.09	98 %	12.97560	77.72300
158	Low	New construction	0.18	88 %	13.00473	77.74952
159	Low	New construction	0.12	96 %	12.98384	77.79420
160	Low	New construction	0.12	96 %	12.98201	77.73698
161	Low	New construction	0.12	96 %	12.96531	77.72238
162	Low	New construction	0.15	91 %	12.96220	77.73464
163	Low	New construction	0.14	92 %	13.01224	77.72314
164	Low	New construction	0.12	95 %	12.97489	77.75702
165	Low	New construction	0.12	95 %	12.98739	77.74901
166	Low	New construction	0.12	95 %	12.97409	77.72063
167	Low	New construction	0.12	95 %	13.01428	77.75580
168	Low	New construction	0.15	90 %	12.99476	77.76480
169	Low	New construction	0.14	92 %	13.01403	77.72348
170	Low	New construction	0.12	95 %	13.01427	77.72273
171	Low	New construction	0.09	98 %	12.99834	77.73412
172	Low	New construction	0.09	98 %	12.99141	77.73229
173	Low	New construction	0.09	98 %	13.00125	77.75838
174	Low	New construction	0.12	94 %	13.01632	77.76398
175	Low	New construction	0.09	98 %	12.97826	77.72791
176	Low	New construction	0.12	94 %	12.95944	77.73070
177	Low	New construction	0.09	98 %	13.00233	77.75811
178	Low	New construction	0.14	91 %	12.98946	77.73367
179	Low	New construction	0.12	94 %	13.01802	77.72673
180	Low	New construction	0.09	98 %	13.00506	77.76477
181	Low	New construction	0.09	97 %	12.97926	77.73649
182	Low	New construction	0.12	94 %	12.97337	77.72081
183	Low	New construction	0.12	94 %	12.96390	77.76215
184	Low	New construction	0.14	90 %	13.01699	77.76266
185	Low	New construction	0.09	97 %	13.00082	77.72143
186	Low	New construction	0.09	97 %	12.97472	77.72990
187	Low	New construction	0.12	93 %	12.97726	77.72840
188	Low	New construction	0.09	97 %	12.98195	77.72039
189	Low	New construction	0.10	95 %	13.01617	77.75580
190	Low	New construction	0.09	97 %	12.96556	77.75862
191	Low	New construction	0.12	93 %	13.01027	77.76363
192	Low	New construction	0.09	97 %	13.00605	77.73088
193	Low	New construction	0.12	92 %	12.98657	77.72786
194	Low	New construction	0.12	92 %	13.00485	77.72912
195	Low	New construction	0.12	92 %	13.01699	77.79010
196	Low	New construction	0.09	97 %	12.97226	77.77417
197	Low	New construction	0.09	97 %	12.97980	77.73677
198	Low	New construction	0.12	92 %	12.99196	77.72723
199	Low	New construction	0.12	92 %	12.95166	77.74512
200	Low	New construction	0.12	92 %	12.99331	77.75276
201	Low	New construction	0.12	92 %	12.98708	77.72681

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
202	Low	New construction	0.09	96 %	12.95040	77.75754
203	Low	New construction	0.12	92 %	12.98497	77.74696
204	Low	New construction	0.12	92 %	12.99571	77.74380
205	Low	New construction	0.09	96 %	12.99639	77.72239
206	Low	New construction	0.12	91 %	12.98950	77.79666
207	Low	New construction	0.09	96 %	13.00882	77.75081
208	Low	New construction	0.09	96 %	13.00449	77.75086
209	Low	New construction	0.09	96 %	12.97933	77.72912
210	Low	New construction	0.14	87 %	12.98033	77.75680
211	Low	New construction	0.09	96 %	12.95936	77.72973
212	Low	New construction	0.12	91 %	13.00701	77.76005
213	Low	New construction	0.09	96 %	12.98755	77.72138
214	Low	New construction	0.09	96 %	12.99308	77.72798
215	Low	New construction	0.12	91 %	12.96559	77.73477
216	Low	New construction	0.09	96 %	12.97679	77.73885
217	Low	New construction	0.12	90 %	12.98218	77.77143
218	Low	New construction	0.09	96 %	12.98758	77.76099
219	Low	New construction	0.12	90 %	12.99928	77.74808
220	Low	New construction	0.09	95 %	12.98326	77.78443
221	Low	New construction	0.12	90 %	12.95323	77.71976
222	Low	New construction	0.09	95 %	12.98074	77.72443
223	Low	New construction	0.09	95 %	12.96501	77.75144
224	Low	New construction	0.09	95 %	13.00121	77.74520
225	Low	New construction	0.09	95 %	12.99549	77.73095
226	Low	New construction	0.12	89 %	12.95087	77.73433
227	Low	New construction	0.12	89 %	12.96239	77.75537
228	Low	New construction	0.09	95 %	13.00569	77.73134
229	Low	New construction	0.12	89 %	12.99723	77.75386
230	Low	New construction	0.09	94 %	12.98327	77.77568
231	Low	New construction	0.09	94 %	13.01590	77.72279
232	Low	New construction	0.09	94 %	12.96626	77.74445
233	Low	New construction	0.09	94 %	12.99522	77.75554
234	Low	New construction	0.09	94 %	12.98342	77.75311
235	Low	New construction	0.09	94 %	12.96555	77.72602
236	Low	New construction	0.09	94 %	12.99297	77.75487
237	Low	New construction	0.09	94 %	12.96828	77.74088
238	Low	New construction	0.09	94 %	13.00833	77.73772
239	Low	New construction	0.09	94 %	12.99074	77.78617
240	Low	New construction	0.09	94 %	12.99478	77.75499
241	Low	New construction	0.09	94 %	13.00232	77.73416
242	Low	New construction	0.09	94 %	12.97124	77.76873
243	Low	New construction	0.09	93 %	12.96644	77.76094
244	Low	New construction	0.09	93 %	12.97598	77.72180
245	Low	New construction	0.09	93 %	12.97849	77.75757
246	Low	New construction	0.12	86 %	13.00811	77.75002
247	Low	New construction	0.09	93 %	13.00687	77.79003
248	Low	New construction	0.09	93 %	13.01410	77.77280
249	Low	New construction	0.09	93 %	12.95926	77.72282
250	Low	New construction	0.09	93 %	12.99015	77.72251
251	Low	New construction	0.09	93 %	13.00168	77.72595
252	Low	New construction	0.09	93 %	12.95444	77.74220

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
253	Low	New construction	0.09	92 %	12.97075	77.77232
254	Low	New construction	0.09	91 %	13.01921	77.72578
255	Low	New construction	0.09	91 %	13.00626	77.72867
256	Low	New construction	0.09	91 %	12.97513	77.74270
257	Low	New construction	0.09	91 %	12.95357	77.73952
258	Low	New construction	0.09	91 %	12.97586	77.75883
259	Low	New construction	0.09	90 %	12.98126	77.75226
260	Low	New construction	0.09	90 %	13.01377	77.72765
261	Low	New construction	0.09	90 %	13.01616	77.73228
262	Low	New construction	0.09	90 %	12.99127	77.76213
263	Low	New construction	0.09	89 %	13.01632	77.76821
264	Low	New construction	0.09	89 %	13.00825	77.72824
265	Low	New construction	0.09	89 %	12.96999	77.74136
266	Low	New construction	0.09	88 %	12.99245	77.72788
267	Low	New construction	0.09	87 %	12.98937	77.78809
268	Low	New construction	0.09	87 %	12.99393	77.74180
269	Low	New construction	0.09	86 %	13.01365	77.73060
270	Low	New construction	0.09	86 %	12.99096	77.78286
271	Low	New construction	0.09	86 %	13.01464	77.73033
272	Low	New construction	0.09	86 %	12.95263	77.73435

Data sources

- Copernicus Sentinel-2 L2A (ESA), via the Element84 Earth Search COG bucket
- ESA WorldCover 2021 v200 (10 m), CC-BY 4.0

Limits - what this report cannot tell you

- Optical imagery cannot see through cloud; flagged areas with cloud are removed, not analysed.
- Change type comes from spectral index rules (no training); check critical changes on the ground.
- 10 m pixels cannot resolve single small buildings or people.
- Rivers, sandbars and lake edges move between dates and can be flagged as change; bare soil in dry regions can look like construction. Check flagged areas near water.
- Land cover is ESA WorldCover 2021, newer than the before image (2019): land already cleared or under construction can be mislabelled as cropland, so treat cropland as an upper bound
- Buildings and road segments need OpenStreetMap, which was not reachable when this result was built: shown as unknown, not zero
- This report points to where to look. Confirm important changes on the ground before acting.