Delhi NCR (Noida): regional check

Delhi NCR (Noida) | Before - Sentinel-2 - 2019-01-05 to After - Sentinel-2 - 2025-01-23

What we found

We found 290 real changes covering 125 hectares. The biggest and strongest (rank 1) is new construction: 6.68 ha at 28.5162, 77.3444.

By priority: 8 Critical, 27 High, 71 Medium, 184 Low.

The detector first flagged 5,082 candidate areas. The rest were removed as false alarms: seasonal crop and vegetation cycles, tiny specks and noise, change types this analysis does not track.



Numbers = rank of the 10 highest-priority changes. Outline colour = priority.

Changes by priority

Critical	8
High	27
Medium	71
Low	184

Totals

Area changed: 125 ha

Cropland affected: 10.24 ha (upper bound)

Built-up land affected: 39.35 ha

How to read this report

Rank	Every change has a number. Rank 1 is the highest priority: the largest and strongest change. Priority = size x strength of the change.
Priority colour and shape	Critical (octagon): score 20,000 or more (about 2 ha of strong change); High (diamond): score 5,000 or more; Medium (square): score 1,500 or more; Low (circle): score below 1,500 (small or weak).
Confidence	How sure the system is that the change is real, from 0 to 100 %. Changes marked 'needs a human check' sit between 50 % and 70 %.
What changed	New construction, vegetation cleared, vegetation growth, new water / flooding, water receded, or unexplained change. These come from rules on the satellite colours, not from knowing what is actually on the ground.
Raw detections	Everything the detector first flagged. Most are not real (clouds, crop seasons, shadows, specks), so only changes that pass the filters are listed here.

The 10 highest-priority changes

Start here. Each card says where the change is, how big it is, why it was flagged and what to do.


1

New construction


Rank 1 of 290 | Critical priority

Size	6.68 ha (66,800 m2), about 9 football pitches
Confidence	98 %
Location	28.51616, 77.34440 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.34), water index rose (+0.08), SWIR/blue ratio (paved surfaces are flatter) fell (-0.89)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After



2

New construction

Rank 2 of 290 | Critical priority

Size	7.61 ha (76,050 m2), about 11 football pitches
Confidence	96 %
Location	28.53688, 77.33090 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	water index rose (+0.07), SWIR/blue ratio (paved surfaces are flatter) fell (-0.79)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




3

New construction


Rank 3 of 290 | Critical priority

Size	4.64 ha (46,450 m2), about 7 football pitches
Confidence	98 %
Location	28.50084, 77.35288 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.27), vegetation index fell (-0.05), water index rose (+0.10), SWIR/blue ratio (paved surfaces are flatter) fell (-0.82)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After



4

New construction

Rank 4 of 290 | Critical priority

Size	3.36 ha (33,600 m2), about 5 football pitches
Confidence	96 %
Location	28.55684, 77.38202 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	SWIR/blue ratio (paved surfaces are flatter) fell (-0.42)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




5

New construction


Rank 5 of 290 | Critical priority

Size	3.28 ha (32,800 m2), about 5 football pitches
Confidence	96 %
Location	28.52108, 77.34108 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index rose (+0.31), vegetation index rose (+0.15), water index fell (-0.20), SWIR/blue ratio (paved surfaces are flatter) rose (+1.16)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




6

New construction


Rank 6 of 290 | Critical priority

Size	2.52 ha (25,200 m2), about 4 football pitches
Confidence	98 %
Location	28.50434, 77.35242 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.10), water index rose (+0.08), SWIR/blue ratio (paved surfaces are flatter) fell (-0.61)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




7

New construction


Rank 7 of 290 | Critical priority

Size	2.62 ha (26,250 m2), about 4 football pitches
Confidence	98 %
Location	28.50738, 77.35043 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.25), water index rose (+0.08), SWIR/blue ratio (paved surfaces are flatter) fell (-0.80)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After



8

New construction

Rank 8 of 290 | Critical priority

Size	2.90 ha (29,000 m2), about 4 football pitches
Confidence	96 %
Location	28.54656, 77.31492 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.14), SWIR/blue ratio (paved surfaces are flatter) fell (-0.43)
What to do	Check first. A large, strong change; send someone or review recent imagery now.

Before



After




9

Water receded


Rank 9 of 290 | High priority

Size	2.02 ha (20,250 m2), about 3 football pitches
Confidence	98 %
Location	28.55040, 77.31640 (open in Google Maps)
What it is	Water that was there before has gone.
Why flagged	built-up index fell (-0.27), vegetation index rose (+0.72), water index fell (-0.64), SWIR/blue ratio (paved surfaces are flatter) rose (+1.18)
What to do	Check soon. A substantial change that is probably real.

Before



After




10

New construction

Rank 10 of 290 | High priority

Size	2.21 ha (22,100 m2), about 3 football pitches
Confidence	96 %
Location	28.53321, 77.33138 (open in Google Maps)
What it is	Land that was open (vegetation or bare soil) now looks built-up: roofs, roads or concrete.
Why flagged	built-up index fell (-0.05), water index rose (+0.09), SWIR/blue ratio (paved surfaces are flatter) fell (-0.71)
What to do	Check soon. A substantial change that is probably real.

Before



After



All 290 changes found

Every change that survived the false-alarm filters, in priority order (rank 1 is the highest). A * after the confidence means it needs a human check. The CSV and GeoPackage downloads hold the same list with every attribute.

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
1	Critical	New construction	6.68	98 %	28.51616	77.34440
2	Critical	New construction	7.61	96 %	28.53688	77.33090
3	Critical	New construction	4.64	98 %	28.50084	77.35288
4	Critical	New construction	3.36	96 %	28.55684	77.38202
5	Critical	New construction	3.28	96 %	28.52108	77.34108
6	Critical	New construction	2.52	98 %	28.50434	77.35242
7	Critical	New construction	2.62	98 %	28.50738	77.35043
8	Critical	New construction	2.90	96 %	28.54656	77.31492
9	High	Water receded	2.02	98 %	28.55040	77.31640
10	High	New construction	2.21	96 %	28.53321	77.33138
11	High	New construction	2.29	95 %	28.54002	77.32176
12	High	New construction	1.61	98 %	28.53666	77.32385
13	High	New construction	1.83	96 %	28.51062	77.38483
14	High	New construction	1.45	98 %	28.53056	77.33329
15	High	New construction	2.02	91 %	28.56428	77.37990
16	High	New construction	1.39	96 %	28.51204	77.34671
17	High	New construction	1.55	94 %	28.55007	77.39067
18	High	New construction	1.52	94 %	28.52799	77.31675
19	High	New construction	1.92	89 %	28.51725	77.31454
20	High	New construction	1.20	97 %	28.51771	77.37359
21	High	New construction	1.24	96 %	28.51256	77.37190
22	High	New construction	1.41	94 %	28.55709	77.38672
23	High	New construction	1.29	95 %	28.53707	77.32629
24	High	New construction	1.16	96 %	28.50958	77.31423
25	High	Water receded	1.11	97 %	28.56554	77.31049
26	High	New construction	1.19	95 %	28.52086	77.31244
27	High	New construction	0.78	99 %	28.52384	77.33690
28	High	New construction	0.95	96 %	28.52711	77.36052
29	High	New construction	0.78	97 %	28.52273	77.31210
30	High	New construction	0.83	96 %	28.55113	77.34612
31	High	New construction	0.91	95 %	28.53762	77.38529
32	High	New construction	0.82	96 %	28.55291	77.38992
33	High	New construction	1.20	88 %	28.51738	77.32587
34	High	New construction	0.96	91 %	28.56857	77.38340
35	High	New construction	0.69	96 %	28.55107	77.32952
36	Medium	New construction	0.84	92 %	28.55033	77.32732
37	Medium	New construction	0.56	98 %	28.50854	77.38666
38	Medium	New construction	0.56	97 %	28.52359	77.31101
39	Medium	New construction	0.73	94 %	28.50069	77.37809
40	Medium	Water receded	0.65	96 %	28.55712	77.31736
41	Medium	New construction	0.73	93 %	28.50163	77.31577
42	Medium	New construction	0.48	98 %	28.51748	77.34490
43	Medium	New construction	0.67	94 %	28.54123	77.33328
44	Medium	New construction	0.80	90 %	28.55798	77.38856
45	Medium	New construction	0.60	96 %	28.52471	77.31402
46	Medium	New construction	0.70	93 %	28.54318	77.37743
47	Medium	New construction	0.55	96 %	28.54577	77.33094
48	Medium	New construction	0.64	92 %	28.53621	77.31304

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
49	Medium	New construction	0.51	96 %	28.55250	77.32687
50	Medium	New construction	0.47	97 %	28.56477	77.33182
51	Medium	New construction	0.41	98 %	28.54666	77.37698
52	Medium	Water receded	0.57	94 %	28.50283	77.35275
53	Medium	New construction	0.68	90 %	28.53344	77.31204
54	Medium	Water receded	0.39	98 %	28.53374	77.33255
55	Medium	New construction	0.66	88 %	28.56301	77.38054
56	Medium	New construction	0.45	96 %	28.54449	77.31254
57	Medium	New construction	0.55	91 %	28.56946	77.38675
58	Medium	New construction	0.49	93 %	28.54155	77.32001
59	Medium	Water receded	0.32	98 %	28.54805	77.31363
60	Medium	New construction	0.45	94 %	28.50961	77.37036
61	Medium	New construction	0.47	93 %	28.55428	77.38307
62	Medium	New construction	0.33	98 %	28.55000	77.37891
63	Medium	New construction	0.42	94 %	28.50822	77.37665
64	Medium	New construction	0.47	92 %	28.53645	77.31413
65	Medium	New construction	0.41	95 %	28.55924	77.39036
66	Medium	New construction	0.40	95 %	28.50603	77.36976
67	Medium	New construction	0.31	98 %	28.54248	77.37436
68	Medium	New construction	0.29	98 %	28.51025	77.34885
69	Medium	New construction	0.47	90 %	28.53011	77.38353
70	Medium	New construction	0.31	97 %	28.55485	77.35850
71	Medium	New construction	0.41	92 %	28.49988	77.34121
72	Medium	New construction	0.40	93 %	28.55872	77.37787
73	Medium	New construction	0.38	93 %	28.55745	77.38927
74	Medium	New construction	0.39	92 %	28.51732	77.37796
75	Medium	New construction	0.39	92 %	28.50000	77.34452
76	Medium	New construction	0.32	96 %	28.52270	77.35186
77	Medium	New construction	0.42	90 %	28.50179	77.38672
78	Medium	New construction	0.28	97 %	28.51207	77.32285
79	Medium	New construction	0.38	92 %	28.53275	77.32885
80	Medium	New construction	0.34	94 %	28.55561	77.38536
81	Medium	New construction	0.28	97 %	28.51000	77.34763
82	Medium	New construction	0.43	88 %	28.52812	77.38236
83	Medium	New construction	0.35	93 %	28.54281	77.38624
84	Medium	New construction	0.31	95 %	28.51124	77.37332
85	Medium	New construction	0.41	89 %	28.53262	77.34704
86	Medium	New construction	0.37	91 %	28.55365	77.38532
87	Medium	New construction	0.32	94 %	28.50393	77.31561
88	Medium	New construction	0.41	88 %	28.51881	77.31352
89	Medium	Water receded	0.26	97 %	28.55560	77.31641
90	Medium	New construction	0.41	87 %	28.53210	77.33041
91	Medium	New construction	0.28	95 %	28.54582	77.32843
92	Medium	New construction	0.39	88 %	28.54501	77.34767
93	Medium	New construction	0.24	97 %	28.56071	77.36680
94	Medium	New construction	0.23	97 %	28.55307	77.38322
95	Medium	New construction	0.32	93 %	28.50519	77.36507
96	Medium	New construction	0.42	84 %	28.51210	77.32475
97	Medium	New construction	0.33	91 %	28.51407	77.32097
98	Medium	New construction	0.20	98 %	28.54232	77.36643
99	Medium	New construction	0.28	94 %	28.51521	77.34623

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
100	Medium	New construction	0.24	96 %	28.50048	77.38421
101	Medium	New construction	0.33	90 %	28.52346	77.31435
102	Medium	Water receded	0.21	97 %	28.54713	77.31219
103	Medium	New construction	0.31	90 %	28.50981	77.37741
104	Medium	New construction	0.21	97 %	28.55163	77.32833
105	Medium	New construction	0.23	96 %	28.54989	77.32884
106	Medium	New construction	0.30	90 %	28.53112	77.36400
107	Low	New construction	0.33	86 %	28.51626	77.31509
108	Low	New construction	0.27	91 %	28.52153	77.31620
109	Low	New construction	0.22	94 %	28.54481	77.34167
110	Low	New construction	0.20	96 %	28.55984	77.35145
111	Low	New construction	0.18	97 %	28.54692	77.32120
112	Low	Water receded	0.18	97 %	28.54311	77.31757
113	Low	New construction	0.24	92 %	28.56973	77.38104
114	Low	New construction	0.21	95 %	28.53689	77.32504
115	Low	New construction	0.18	97 %	28.56061	77.39056
116	Low	New construction	0.25	91 %	28.54706	77.38298
117	Low	New construction	0.22	94 %	28.53965	77.34020
118	Low	New construction	0.25	91 %	28.50934	77.33117
119	Low	New construction	0.15	98 %	28.51259	77.34775
120	Low	New construction	0.15	98 %	28.50549	77.35108
121	Low	New construction	0.14	98 %	28.53155	77.33263
122	Low	New construction	0.15	98 %	28.53768	77.37839
123	Low	New construction	0.28	86 %	28.51931	77.31512
124	Low	New construction	0.26	88 %	28.51596	77.33515
125	Low	New construction	0.28	86 %	28.56918	77.37511
126	Low	New construction	0.20	94 %	28.53774	77.38830
127	Low	New construction	0.22	92 %	28.53450	77.31423
128	Low	New construction	0.26	88 %	28.50139	77.37709
129	Low	New construction	0.14	98 %	28.51125	77.34832
130	Low	New construction	0.20	94 %	28.56677	77.38385
131	Low	New construction	0.14	98 %	28.55056	77.32567
132	Low	New construction	0.21	92 %	28.55365	77.38897
133	Low	New construction	0.20	93 %	28.52591	77.31566
134	Low	New construction	0.24	88 %	28.49982	77.37977
135	Low	New construction	0.24	88 %	28.51232	77.32840
136	Low	New construction	0.20	92 %	28.53927	77.32552
137	Low	New construction	0.21	91 %	28.51457	77.32888
138	Low	New construction	0.22	90 %	28.53896	77.37080
139	Low	New construction	0.23	89 %	28.50414	77.38517
140	Low	New construction	0.21	91 %	28.52077	77.36034
141	Low	New construction	0.18	94 %	28.56098	77.38990
142	Low	New construction	0.24	87 %	28.50688	77.37259
143	Low	New construction	0.21	90 %	28.51737	77.33404
144	Low	New construction	0.12	98 %	28.52610	77.38012
145	Low	New construction	0.12	98 %	28.51955	77.36562
146	Low	New construction	0.15	96 %	28.51572	77.31652
147	Low	New construction	0.15	96 %	28.53459	77.35891
148	Low	New construction	0.20	90 %	28.52248	77.31370
149	Low	New construction	0.12	98 %	28.51032	77.37236
150	Low	New construction	0.16	95 %	28.49901	77.38217

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
151	Low	New construction	0.17	93 %	28.55778	77.33902
152	Low	New construction	0.20	88 %	28.56031	77.35444
153	Low	New construction	0.20	89 %	28.53393	77.31427
154	Low	New construction	0.15	94 %	28.51135	77.36207
155	Low	New construction	0.12	97 %	28.53218	77.34982
156	Low	New construction	0.17	91 %	28.49890	77.38653
157	Low	New construction	0.18	90 %	28.56095	77.37582
158	Low	New construction	0.16	93 %	28.52549	77.36627
159	Low	New construction	0.20	87 %	28.50777	77.34468
160	Low	New construction	0.15	94 %	28.55771	77.34512
161	Low	New construction	0.15	93 %	28.51596	77.37814
162	Low	New construction	0.09	99 %	28.52471	77.33601
163	Low	New construction	0.18	89 %	28.50172	77.38938
164	Low	New construction	0.09	99 %	28.53476	77.32826
165	Low	New construction	0.12	96 %	28.54590	77.33392
166	Low	New construction	0.14	94 %	28.53465	77.31076
167	Low	New construction	0.09	99 %	28.51115	77.37861
168	Low	Water receded	0.09	99 %	28.53323	77.33344
169	Low	New construction	0.14	94 %	28.53404	77.32082
170	Low	New construction	0.15	93 %	28.53805	77.38351
171	Low	New construction	0.15	92 %	28.51977	77.31268
172	Low	New construction	0.12	96 %	28.53356	77.35868
173	Low	New construction	0.15	92 %	28.49931	77.38539
174	Low	New construction	0.14	94 %	28.55480	77.35928
175	Low	New construction	0.09	99 %	28.54568	77.31246
176	Low	New construction	0.15	92 %	28.51292	77.36548
177	Low	New construction	0.14	94 %	28.54444	77.33458
178	Low	New construction	0.18	87 %	28.52275	77.32090
179	Low	New construction	0.12	96 %	28.50728	77.36545
180	Low	New construction	0.09	98 %	28.53556	77.35014
181	Low	New construction	0.17	88 %	28.51546	77.32720
182	Low	Water receded	0.17	87 %	28.50682	77.38840
183	Low	New construction	0.12	95 %	28.51337	77.32115
184	Low	New construction	0.12	95 %	28.51929	77.31229
185	Low	New construction	0.15	91 %	28.50002	77.35467
186	Low	New construction	0.18	86 %	28.53799	77.38407
187	Low	New construction	0.15	90 %	28.52257	77.35362
188	Low	New construction	0.15	90 %	28.55646	77.34662
189	Low	New construction	0.15	90 %	28.51142	77.33735
190	Low	New construction	0.12	94 %	28.52643	77.31413
191	Low	New construction	0.09	98 %	28.50967	77.38113
192	Low	New construction	0.12	94 %	28.51335	77.38178
193	Low	New construction	0.09	98 %	28.55619	77.37268
194	Low	New construction	0.09	98 %	28.55522	77.33495
195	Low	New construction	0.14	91 %	28.54346	77.33831
196	Low	New construction	0.12	94 %	28.54161	77.37036
197	Low	New construction	0.09	98 %	28.55029	77.37980
198	Low	New construction	0.09	98 %	28.55077	77.37817
199	Low	New construction	0.15	89 %	28.54551	77.32513
200	Low	New construction	0.14	91 %	28.54852	77.32359
201	Low	New construction	0.12	94 %	28.51387	77.37311

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
202	Low	New construction	0.12	94 %	28.52496	77.36048
203	Low	New construction	0.15	88 %	28.52726	77.34455
204	Low	New construction	0.09	97 %	28.49984	77.38061
205	Low	New construction	0.12	93 %	28.51474	77.37246
206	Low	New construction	0.12	93 %	28.51724	77.32394
207	Low	New construction	0.12	93 %	28.55354	77.38973
208	Low	New construction	0.12	93 %	28.55599	77.34247
209	Low	New construction	0.12	93 %	28.54729	77.32088
210	Low	New construction	0.14	89 %	28.51852	77.31445
211	Low	New construction	0.12	93 %	28.56786	77.37856
212	Low	New construction	0.09	97 %	28.51149	77.37515
213	Low	New construction	0.12	92 %	28.52141	77.35979
214	Low	New construction	0.15	86 %	28.56164	77.38051
215	Low	New construction	0.12	92 %	28.51008	77.37568
216	Low	New construction	0.10	95 %	28.50961	77.37561
217	Low	New construction	0.14	88 %	28.51743	77.32019
218	Low	New construction	0.09	97 %	28.54499	77.36323
219	Low	New construction	0.12	92 %	28.52924	77.31348
220	Low	Water receded	0.09	96 %	28.54944	77.31428
221	Low	New construction	0.12	91 %	28.50637	77.38898
222	Low	New construction	0.09	96 %	28.51958	77.36092
223	Low	New construction	0.12	91 %	28.52443	77.36502
224	Low	New construction	0.12	91 %	28.51830	77.31498
225	Low	New construction	0.14	87 %	28.52164	77.31333
226	Low	New construction	0.12	90 %	28.53282	77.30988
227	Low	New construction	0.09	96 %	28.54168	77.38737
228	Low	New construction	0.14	86 %	28.50175	77.37599
229	Low	New construction	0.12	90 %	28.54793	77.39073
230	Low	New construction	0.12	90 %	28.55125	77.35555
231	Low	New construction	0.12	90 %	28.52202	77.31092
232	Low	New construction	0.09	95 %	28.54480	77.38417
233	Low	New construction	0.09	95 %	28.56978	77.35367
234	Low	New construction	0.12	89 %	28.50892	77.37759
235	Low	Water receded	0.09	95 %	28.54854	77.31416
236	Low	New construction	0.12	89 %	28.54166	77.35968
237	Low	New construction	0.09	94 %	28.54508	77.38387
238	Low	New construction	0.12	88 %	28.55596	77.38080
239	Low	New construction	0.09	94 %	28.55150	77.32546
240	Low	New construction	0.12	88 %	28.52013	77.31349
241	Low	New construction	0.09	94 %	28.51591	77.33357
242	Low	New construction	0.09	94 %	28.54344	77.31681
243	Low	New construction	0.09	94 %	28.53488	77.36321
244	Low	New construction	0.09	94 %	28.54875	77.32315
245	Low	New construction	0.09	94 %	28.51615	77.34563
246	Low	New construction	0.09	94 %	28.55143	77.31923
247	Low	New construction	0.09	94 %	28.54366	77.36167
248	Low	New construction	0.09	94 %	28.54534	77.35353
249	Low	New construction	0.09	93 %	28.51525	77.32467
250	Low	New construction	0.09	93 %	28.53855	77.34418
251	Low	New construction	0.09	93 %	28.51726	77.33339
252	Low	New construction	0.09	93 %	28.54834	77.38282

Rank	Priority	What changed	Size (ha)	Confidence	Latitude	Longitude
253	Low	New construction	0.09	93 %	28.51146	77.31897
254	Low	New construction	0.09	93 %	28.50877	77.36538
255	Low	New construction	0.12	84 %	28.51992	77.31512
256	Low	New construction	0.09	92 %	28.54222	77.35080
257	Low	New construction	0.09	92 %	28.52070	77.31140
258	Low	New construction	0.12	83 %	28.51914	77.31587
259	Low	New construction	0.09	91 %	28.54362	77.34297
260	Low	New construction	0.09	91 %	28.51215	77.36811
261	Low	New construction	0.09	91 %	28.56249	77.33214
262	Low	New construction	0.09	91 %	28.51685	77.32052
263	Low	New construction	0.09	91 %	28.51554	77.31814
264	Low	New construction	0.09	91 %	28.52070	77.38485
265	Low	New construction	0.09	91 %	28.53894	77.38414
266	Low	New construction	0.09	90 %	28.51421	77.33752
267	Low	New construction	0.09	90 %	28.55329	77.32131
268	Low	New construction	0.09	90 %	28.55118	77.34446
269	Low	New construction	0.09	90 %	28.56807	77.36916
270	Low	New construction	0.09	90 %	28.54329	77.38260
271	Low	New construction	0.09	90 %	28.51303	77.32237
272	Low	New construction	0.09	89 %	28.54550	77.35456
273	Low	New construction	0.09	88 %	28.50245	77.38628
274	Low	New construction	0.09	88 %	28.50820	77.33544
275	Low	New construction	0.09	88 %	28.54672	77.32536
276	Low	New construction	0.09	88 %	28.50906	77.36927
277	Low	New construction	0.09	88 %	28.55862	77.38826
278	Low	New construction	0.09	88 %	28.55222	77.32017
279	Low	New construction	0.09	88 %	28.54106	77.33453
280	Low	New construction	0.09	88 %	28.55185	77.38862
281	Low	New construction	0.09	88 %	28.53180	77.34853
282	Low	New construction	0.09	88 %	28.51588	77.32478
283	Low	New construction	0.09	87 %	28.51248	77.36965
284	Low	New construction	0.09	87 %	28.51451	77.32527
285	Low	New construction	0.09	87 %	28.51845	77.31667
286	Low	New construction	0.09	87 %	28.54796	77.38394
287	Low	New construction	0.09	85 %	28.50862	77.33198
288	Low	New construction	0.09	85 %	28.53800	77.38116
289	Low	New construction	0.09	84 %	28.50272	77.34472
290	Low	New construction	0.09	82 %	28.55051	77.30981

Data sources

- Copernicus Sentinel-2 L2A (ESA), via the Element84 Earth Search COG bucket
- ESA WorldCover 2021 v200 (10 m), CC-BY 4.0

Limits - what this report cannot tell you

- Optical imagery cannot see through cloud; flagged areas with cloud are removed, not analysed.
- Change type comes from spectral index rules (no training); check critical changes on the ground.
- 10 m pixels cannot resolve single small buildings or people.
- Rivers, sandbars and lake edges move between dates and can be flagged as change; bare soil in dry regions can look like construction. Check flagged areas near water.
- Land cover is ESA WorldCover 2021, newer than the before image (2019): land already cleared or under construction can be mislabelled as cropland, so treat cropland as an upper bound
- Buildings and road segments need OpenStreetMap, which was not reachable when this result was built: shown as unknown, not zero
- This report points to where to look. Confirm important changes on the ground before acting.