GEOAI 04 flood report: Assam 2016 (radar)

Brahmaputra flood, Assam, India | Sentinel-1 radar 2016-08-12 | expert labels: Sen1Floods11



Totals

Raw detections: 3490
Real changes after filters: 37
Area changed: 139.04 ha
Cropland affected: unknown
Built-up land affected: unknown
critical: 0
high: 6
medium: 3
low: 28

Open this result: /scene/assam-flood-2016

Top 10 changes

#	Tier	Type	Area (ha)	Conf.	Reason
1	high	water_gain	24.42	0.99	open-water flood: radar backscatter -19.9 dB, 5.9 dB below the event water thres
2	high	water_gain	23.37	0.99	open-water flood: radar backscatter -19.0 dB, 4.9 dB below the event water thres
3	high	water_gain	21.15	0.99	open-water flood: radar backscatter -18.1 dB, 4.0 dB below the event water thres
4	high	water_gain	12.48	0.99	open-water flood: radar backscatter -19.8 dB, 5.7 dB below the event water thres
5	high	water_gain	11.63	0.99	open-water flood: radar backscatter -19.3 dB, 5.2 dB below the event water thres
6	high	water_gain	10.73	0.93	open-water flood: radar backscatter -17.5 dB, 3.4 dB below the event water thres
7	medium	water_gain	6.97	0.89	open-water flood: radar backscatter -17.1 dB, 3.1 dB below the event water thres
8	medium	water_gain	3.61	0.82	open-water flood: radar backscatter -16.6 dB, 2.6 dB below the event water thres
9	medium	water_gain	3.44	0.96	open-water flood: radar backscatter -17.7 dB, 3.7 dB below the event water thres
10	low	water_gain	1.74	0.73	open-water flood: radar backscatter -15.9 dB, 1.8 dB below the event water thres

Sources and limits

- Copernicus Sentinel-1 IW GRD (dB) and Sentinel-2, via Sen1Floods11 v1.1 (CC-BY 4.0)
- JRC Global Surface Water (permanent water mask)
- Open-water flood extent estimate: flooded crops and streets can look bright on radar and may be missed.
- Single date shown; the full M8 compares before/after radar scenes.
- Impact layers are not computed for this 2016 test chip