
Oil Spill Incident Report #5


Generated 2026-10-08 05:18 UTC. Status: **detected**. Priority: **Critical** (80.3).

Satellite image	S1B_IW_GRDH_1SDV_20211003T014927_20211003T014952_028965_0374DA_3EE4.zip
Acquisition time (UTC)	2021-10-03T01:49:27+00:00
Location	33.56454, -117.91562
Area	4.2765 sq km
Length / width	3.907 km / 1.769 km (elongation 2.21)
Detection	unet (resnet34), confidence 0.907
Estimated volume	1.28–213.82 m³ (8.1–1344.9 barrels)

Satellite image with detection



Situation map



Suspected vessels

Rank	Vessel	MMSI	Type	Score	Closest (km)	Review
1	ALLURE	338392038	Pleasure craft	0.39	0.079	pending
2	CLAUDE-II	367770240	Pleasure craft	0.38	0.232	pending
3	LANI KAI	368051830	Pleasure craft	0.38	0.054	pending
4	KITE	338310229	Pleasure craft	0.38	0.087	pending
5	FUSION	338236803	Pleasure craft	0.37	0.05	pending
6	PURITAN	338324182	Pleasure craft	0.37	0.207	pending
7	REEL NOYES	338382138	Pleasure craft	0.37	0.079	pending
8	INCOGNITO	338326507	Pleasure craft	0.37	0.088	pending
9	SEACLUSION	338354382	Pleasure craft	0.36	0.09	pending
10	JANICE O	338181008	Pleasure craft	0.36	0.056	pending

#1 ALLURE: Passed 0.1 km from the spill's back-tracked position 1.6 h before the satellite image. 76% of the spill axis lies on this vessel's path. Slowed down sharply near the spill. Loitered for 2.4 h at low speed.

#2 CLAUDE-II: Passed 0.2 km from the spill's back-tracked position 4.5 h before the satellite image. Its course matches the spill's long axis (typical of a discharge while underway). 72% of the spill axis lies on this vessel's path. Slowed down sharply near the spill. Loitered for 3.1 h at low speed.

#3 LANI KAI: Passed 0.1 km from the spill's back-tracked position 7.0 h before the satellite image. Its course matches the spill's long axis (typical of a discharge while underway). 64% of the spill axis lies on this vessel's path. Slowed down sharply near the spill. Loitered for 2.5 h at low speed.

Drift forecast

After	Centre (lat, lon)	Beached
6 h	33.5699, -117.9183	0%
12 h	33.5718, -117.9321	0%
24 h	33.5917, -117.9407	20%
48 h	33.6193, -117.9771	48%
72 h	33.6381, -118.0144	60%

Impact

First landfall: 17.5 h. Coastline affected: 24.25 km. Severity score: 80.3/100.

Site	Type	Arrives in	Sensitivity
Newport Beach	public beach	0.0 h	3
Huntington State Beach	public beach	19.0 h	4
Talbert Marsh	wetland	19.5 h	5
Huntington Beach Pier	public beach	37.5 h	3
Bolsa Chica Ecological Reserve	wetland	55.0 h	5

Recommended actions

Urgency	Action	Detail
high	Notify authorities	Send this incident report to the coast guard pollution response centre and the port state control office.
high	Protect Newport Beach	Deploy containment booms before the oil arrives (oil is already within reach - deploy immediately; site type: public beach).
high	Protect Huntington State Beach	Deploy containment booms before the oil arrives (estimated in 19 h; site type: public beach).
high	Protect Talbert Marsh	Deploy containment booms before the oil arrives (estimated in 20 h; site type: wetland).
medium	Protect Huntington Beach Pier	Deploy containment booms before the oil arrives (estimated in 38 h; site type: public beach).
medium	Protect Bolsa Chica Ecological Reserve	Deploy containment booms before the oil arrives (estimated in 55 h; site type: wetland).
high	Dispatch recovery vessel	Send a skimmer vessel to the predicted slick centre at 33.5917, -117.9407 (24 h forecast).
high	Shoreline response	Prepare beach clean-up teams; first landfall predicted after about 18 h along ~24.25 km of coast.
medium	Investigate ALLURE	Inspect MMSI 338392038 at its next port call and collect oil samples for fingerprint comparison with the slick.
medium	Sample the slick	Collect oil samples from the slick for laboratory fingerprinting (evidence).

Volume uses a 0.3–50 µm thickness range because SAR cannot measure thickness. Vessel scores indicate where to investigate; they are not proof of liability.