Used Car Inspection Report

ID: 3022
Engineer: MD SADDAM HUSSAIN
Customer Name: AYON ROY

Generated: 2026-02-21 15:22:33

STEP 1 — BOOKING DETAILS

Booking ID: 3022

Engineer Name: MD SADDAM HUSSAIN

Customer Name: AYON ROY

Customer Phone: 7890950986

OBD Scanning: NO

Car: GRAND I10 NIOS

Lead Owner: 1

STEP 2 — EXPERT DETAILS

Taking Payment: NO

Your photo with car's number plate

Latitude: 22.562886

Longitude: 88.323235

Full Location Address: AVANI RIVERSIDE, 32, JAGAT BANNERJEE GHAT ROAD, HOWRAH, KOLKATA METROPOLITAN AREA, □□□□□□, WEST BENGAL, 711102, INDIA

Date: 21-02-2026

Time: 02:22 PM

STEP 3 — CAR DETAILS

Car Company: HYUNDAI

Car Registration Number: WB12BP0584

Car Registration Year (YYYY): 2023

Car Variant: 1,2, MTKAPPASPORTZ

Car Registered State: HOWRAH

Fuel Type: PETROL

Engine Capacity (in CC): 1197

Transmission: MANUAL

Car Colour: SPARK GREEN PEARL

Car KM Current Reading: 29703

Number of Car Keys Available: 1

Chassis Number: MALB351CLPM464714

Engine Number: G4LAPM522487

Car KM Reading Photo

Chassis No Plate

STEP 4 — CAR DOCUMENTS

Registration Certificate: AVAILABLE

Car Insurance: NOT AVAILABLE

Car Finance NOC: NOT REQUIRED

STEP 5 — BODY FRAME ACCIDENTAL CHECKLIST

Radiator Core Support: OK

Match Chassis No Plate with Real Body: MATCHING

Driver Side Strut Tower Apron: OK

Passenger Strut Tower Apron: OK

Front Bonnet UnderBody: OK

Boot Floor: OK

Radiator Core Support



Driver Side Strut Tower Apron

Passenger Strut Tower Apron



Front Bonnet UnderBody



Boot Floor

STEP 6 — EXTERIOR BODY

Front Bumper: REPAINTED

Front Bumper

Rear Bumper: REPAINTED

Rear Bumper

Bonnet: SCRATCHES

Bonnet

Roof: OK

Windshield: OK

STEP 7 — ENGINE (BEFORE TEST DRIVE)

Car Start: OK

Wiring: OK

Wiring



Engine Oil Quality: CLEAN AND COMPLETE

Engine Oil Quality



Engine Oil Cap: CLEAN

Engine Mounting and Components: OK

Coolant Level: OK

Coolant Quality: OK

Smoke Emission: OK

Smoke Emission

Battery: OK

STEP 8 — OBD SCAN

Any Fault Codes Present?: NO

OBD Scan Photo

STEP 9 — ELECTRICAL AND INTERIOR

Central Lock Working: OK

Ignition Switch / Push Button: OK

Driver – Front Indicator: WORKING

Passenger – Front Indicator: WORKING

Driver Headlight: WORKING

Driver Headlight Highbeam: WORKING

Passenger Headlight: WORKING

Passenger Headlight Highbeam: WORKING

Front Number Plate Light: NOT AVAILABLE

Driver Back Indicator: WORKING

Passenger Back Indicator: WORKING

Back Number Plate Light: WORKING

Brake Light Driver: WORKING

Brake Light Passenger: WORKING

Driver Tail Light: WORKING

Passenger Tail Light: WORKING

Steering Wheel Condition: OK

Steering Mounted Controls: WORKING

Back Camera: WORKING

Reverse Parking Sensor: WORKING

Multi Function Display: WORKING

Multi Function Display

In Car Start: OK

Car Horn: WORKING

Entertainment System: WORKING

Cruise Control: WORKING

Interior Lights: WORKING

Sun Roof: WORKING

Bonnet Release Operation: WORKING

Fuel Cap Release Operation: WORKING

Check Onboard Computer AdBlue Level – Diesel Cars: WORKING

Window Safety Lock: WORKING

Driver ORVM Controls: OK

Passenger ORVM Controls: OK

Glove Box: OK

Wiper: OK

Rear View Mirror: OK

Dashboard Condition: OK

Car Roof From Inside: OK

Car Roof From Inside

Seat Adjustment Driver Side: WORKING

Seat Adjustment Driver Rear Side: WORKING

Front Driver Side Seat Condition: OK

Front Driver Side Floor: OK

Front Driver Side Seat Belt: OK

Front Passenger Side Seat Condition: OK

Front Passenger Side Floor: OK

Front Passenger Side Seat Belt: OK

Seat Adjustment Passenger Side: WORKING

Window Driver Side: WORKING

Window Passenger Side: WORKING

Window Passenger Rear Side: WORKING

Window Driver Rear Side: WORKING

Back Driver Side Floor: OK

Back Driver Side Seat Belt: OK

Back Driver Side Seat Condition: OK

Seat Adjustment Passenger Rear Side: NOT APPLICABLE

Back Passenger Side Floor: OK

Back Passenger Side Seat Condition: OK

Back Passenger Side Seat Belt: OK

Rear Side Floor – 7 Seater: NOT APPLICABLE

Rear Seat Condition – 7 Seater: NOT APPLICABLE

Rear Seat Belt – 7 Seater: NOT APPLICABLE

Child Safety Lock: WORKING

STEP 10 — WARNING LIGHTS

Check Engine: PRESENT

Power Steering Problem: NOT PRESENT

ABS Sensor Problem: NOT PRESENT

Airbag Sensor Problem: NOT PRESENT

Battery Problem: NOT PRESENT

Low Engine Oil: NOT PRESENT

Low Coolant / Overheating: NOT PRESENT

Brake System Warning: NOT PRESENT

Any Other Lights Found?: NOT PRESENT

STEP 11 — AIR CONDITIONING

Air Conditioning Turning On: OK

AC Cool Temperature: 17

AC Hot Temperature: 27.0

Air Conditioning Direction Mode Working: OK

Defogger Front Vent Working: OK

Defogger Rear Vent Working: OK

Air Conditioning All Vents: OK

AC Abnormal Vibration: NOT PRESENT

AC Cool Mode Temperature

AC Hot Mode Temperature



STEP 12 — TYRES

Tyre Size: 175/60R15

Tyre Type: TUBELESS

Rim Type: NORMAL

Driver Front Tyre Depth Check: GOOD

Driver Front Tyre Manufacturing Date: 2623

Driver Front Tyre Shape: OK

Driver Back Tyre Depth Check: GOOD

Driver Back Tyre Manufacturing Date: 2623

Driver Back Tyre Shape: OK

Passenger Back Tyre Depth Check: GOOD

Passenger Back Tyre Manufacturing Date: 2723

Passenger Back Tyre Shape: OK

Passenger Front Tyre Depth Check: GOOD

Passenger Front Tyre Manufacturing Date: 2723

Passenger Front Tyre Shape: OK

Stepney Tyre Depth Check: GOOD

Stepney Tyre Manufacturing Date: 2823

Stepney Tyre Shape: OK

Driver Front Tyre

Driver Back Tyre



Passenger Back Tyre

Passenger Front Tyre

Stepney Tyre

Signs of Camber Issue: NOT PRESENT

STEP 13 — TRANSMISSION & CLUTCH PEDAL

Check Gear Box / Transmission Shifting: OK

Check 4x4 Shifting: NOT APPLICABLE

Clutch Pedal: OK

Clutch Engagement - RPM Downgrade: OK

Clutch Engagement - RPM Upgrade: OK

Clutch Engagement - RPM With Acceleration: OK

STEP 14 — AXLE

Left Axle: OK

Right Axle: OK

Abnormal Noise: NOT PRESENT

STEP 15 — ENGINE (AFTER TEST DRIVE)

Check for Oil Leaks Near Engine: NOT PRESENT

Oil Leak Near Engine

Radiator Fan: WORKING

Radiator Condition: OK

Smoke from Dipstick Point: NOT PRESENT

Transmission Oil Leakage: NOT PRESENT

Engine Noise: NOT PRESENT

Engine Vibration: NOT PRESENT

Hoses: OK

Exhaust Sound: NOT PRESENT

STEP 16 — BRAKES

Brake Pads Front Driver Side: OK

Brake Discs Front Driver Side: OK

Brake Pads Front Passenger Side: OK

Brake Discs Front Passenger Side: OK

Brake Pads Back Passenger Side: OK

Brake Discs Back Passenger Side: OK

Brake Pads Back Driver Side: OK

Brake Discs Back Driver Side: OK

Brake Fluid Reservoir: OK

Brake Fluid Cap: OK

Parking Hand Brake: OK

STEP 17 — SUSPENSION

Shocker Bounce Test: OK

Driver Side Suspension Assembly: OK

Driver Side Shocker Leakage: NOT PRESENT

Passenger Side Suspension Assembly: OK

Passenger Side Shocker Leakage: NOT PRESENT

Driver Side Front Shocker

Passenger Side Front Shocker

Driver Side Rear Shocker

Passenger Side Rear Shocker

STEP 18 — BRAKES & STEERING (TEST DRIVE)

Brake Pedal: OK

Steering Rotating Smoothly: OK

Steering Coming Back While Driving: OK

Steering Weird Noise: NOT PRESENT

Alignment: OK

Bubbling: NOT PRESENT

Steering Vibration: NOT PRESENT

STEP 19 — UNDERBODY

Driver Side Body Chasis: OK

Passenger Side Body Chasis: OK

Rear Subframe: NOT OK

Engine Damage UnderBody: OK

Under Trays: OK

Front Protection Cover: OK

Rear Protection Cover: OK

Silencer: OK

Fuel Tank: OK

Any Fluid Leaks Under Body: NOT PRESENT

Underbody Left

Underbody Rear

Underbody Right

Underbody Front

STEP 20 — EQUIPMENTS

Tool Kit: PRESENT

STEP 21 — FINAL CAR RESULT

Any Issues Found in the Car?: EXCEPT ROOF, BONET AND LEFT REAR DOOR PANELS ARE REPAINTED
REAR DOOR OR TRUNK REPLACED
DASHBOARD SIDE LIGHT BURNED

Issues Photo 1

Issues Photo 2

STEP 22 — CAR IMAGES FROM ALL DIRECTIONS

Front

Corner Front - Driver

Driver Side

Corner Back - Driver

Back

Corner Back - Passenger

Passenger Side

Corner Front - Passenger

Front Interior



Rear Interior



4 Way Switch Driver Side

Trunk Open



Car KM Reading



Car Inspection Expert System

⚠ **IMPORTANT NOTE:**
While inspecting the vehicle, our boy will be responsible as long as he is at the inspection site, after that he will not be responsible even if anything happens to the vehicle.

Report generated on 2026-02-21 15:22:33