
## Results of full image denoising using MMSE estimation on patches with GMM prior

## Tal Amir and Haggai Maron April 8, 2013


We ran our implementaion of MMSE denoising on the tiger image (GMM prior, no EPLL) and compared the results to those of Daniel's code (with EPLL). The noise added was white Gaussian noise with STD 25/255.




Original image



Noisy image PSNR: 20.17



Our denoised image PSNR: 29.00



Daniel's denoised image PSNR: 29.16