## LABORATORIO DI LANDRO

**Materials Analysis & Testing** 

**Customer Ref.:** 

Laboratory Ref.:



PΝ

LABORATORIO CHIMICO DI LANDRO SAS - Via A. Toscanini 18 - 26013 - CREMA - CR - Italy - Phone: +39 0373-202906 - VAT N. IT01231610195 - info@dilandrolab.it

**TEST REPORT** 

**Report No.:** 53691

**Date:** 30/09/2022

Customer(#):

**EMMEGI ZINCATURA SRL** 

via Enrico da Fiume 16

33080 FIUME VENETO

ΙT

Test Requested: HUMIDITY TEST

Sample Descr. (#): UNALLOYED ZINC COATED PART CODE 17825030000+KTL - BASE MAT. S420MC 4 mm THK-3 WELDING COMPONENTS

VW 13750-Ofl x632

Sampling: Performed by the customer

DDT N°396

220957

**Date of receipt:** 04/08/2022

Date of testing: Start: 05/09/2022 End: 15/09/2022

**Test Method:** ISO 2409:2020

Ref. Documents: VW TL227:2016

# **HUMIDITY TEST**

#### **TEST DATA**

Test Period = 240h

Temperature = 40±3°C

Relative Humidity = 100% Formation of condensate on the specimens

Chamber Capacity = 1500 l

## **RESULTS**

No blistering, no zinc corrosion, no base metal corrosion; Cross cut test ISO 2409 rating <=1

Required :No blistering, no zinc corrosion, no base metal corrosion; Cross cut test ISO 2409 rating <=1

Note: Compliant with VW TL227:2022-02

Date: 06/04/2023

Simone Di Landro 📈

NS= Not Specified / NA= Not Applicable

www.dilandrolab.i

#: Data provided by the customer. The laboratory disclaims all responsibility for the information provided by the customer.

Unless otherwise required by standards and technical specifications or agreed with the customer, statements of conformity based on the comparison between results and reference values are reported without taking into account the uncertainty of measurement. In the case of sampling performed by the customer, the results reported in this test report apply to the sample as received.

The results reported in this test report refer only to the tested sample.

This test report cannot be partially reproduced without a written approval of the laboratory.

Digitally signed by:

Dr. Umberto Di Landro

Laboratory Manager

Materials Analysis & Testing




LABORATORIO CHIMICO DI LANDRO SAS – Via A.Toscanini 18- 26013 CREMA (CR) Italy - Phone: +39 0373202906 - VAT No. 01231610195 - EMail: info@dilandrolab.it

# **TEST REPORT**

**Report N°:** 53691 **Date:** 30/09/2022



SAMPLE AFTER THE HUMIDITY TEST



CROSS CUT PHOTO