



Neer Vazhvu

India's Water Intelligence

contact@neervazhvu.org - neervazhvu.org

Bengaluru Lakes Snapshot, monsoon 2026

Every lake on the Greater Bengaluru custody lists, read from Sentinel-2 as relative, uncalibrated readings, with an order of priority for restoration funding. Reading window: **monsoon (Jun-Sep) 2026** for 173 of 180 assessed lakes (each lake's own window is named in the list). Archive 28 March 2017 to 30 August 2026; observed passes only, nothing interpolated. A post-monsoon edition follows in November 2026 on the same method.

What this snapshot is for

Greater Bengaluru lists 210 lakes in the care of four agencies. Each is monitored in its own way, and no single reading covers all of them on the same footing, so a funder, a custodian or a lake group has no common basis on which to decide where the next rupee of restoration money does the most good.

This snapshot reads every listed lake the same way, from free satellite imagery going back to 2017: how much of each lake is open water, vegetation or exposed bed, how green the water is, how much of its usual extent it holds, whether it is built over, and how it compares with its own past. It sets these beside the regulator's June 2026 classification and the works already on record, and orders the lakes by a published rule into classes a funder can act on: Fund now, Co-fund, Design first, and the rest.

It is a starting point, not a verdict. Every reading carries its uncertainty and a confidence class, nothing is estimated where there is no observation, and the order improves with each edition, with ground sampling, and with surveyed boundaries.

Custody lakes on the KTCDA lists

210

BBMP, BDA, Forest Department,
BMRCCL

Assessed from satellite

180

30 unassessed: no usable boundary
at 10 m, or too few clear readings

Condition D or E

68

973 of 2,259 ha of assessed footprint

Fundable now

38

Fund now 23 and Co-fund 15; Design
first 44

How to read a number in this report

Each value is a seasonal median of clear satellite passes, shown as **value ± band** with **n** passes and a confidence class **H / M / L**. The band is the reading's own uncertainty (sampling and classification for shares, spread across passes for indices). A Health Card band is assigned only where the band is wider than the error; otherwise both candidate bands are listed. Where the evidence is too thin, the value reads "insufficient".

Why nothing reads High. A class is the weakest of six components, and two cannot reach High from a 10 m satellite and a mapped boundary: closeness to shore (only lakes over about 100 ha escape it) and boundary provenance (High needs a surveyed boundary). Medium is the ceiling for now; a surveyed boundary and a field calibration unlock High.

What this snapshot cannot say

Dissolved oxygen, BOD, COD, nutrients, coliform, metals and toxins have no optical signature; the regulator's Use Based Class (KSPCB, June 2026) is shown beside the satellite reading for 101 lakes and is never recomputed. Chlorophyll and turbidity are relative indices until a field calibration exists; no calibrated concentration appears here. The vegetation share includes floating mats and emergent reeds inside the footprint, and water under a mat is invisible: "no open water" on a sewage-fed lake means a covered surface, not a dry bed. Built share is read at 10 m inside the satellite footprint, which is the mapped boundary united with the observed water, not the survey area; encroachment against the cadastral boundary needs that boundary, and the footprint area is not the revenue-record area. A class rests on condition and the works on record, not on why a lake is in its state or what was done before the record.

The first ten in the order


1. **Yelahanka Amani kere** (BBMP, 244 acres): Fund now; Algal bloom on the open water; KSPCB class E
2. **Puttenahalli Lake** (Forest Department, 22 acres): Fund now; 100% covered by vegetation; KSPCB class E
3. **Kannalli kere** (BBMP, 56 acres): Fund now; 93% covered by vegetation; KSPCB class E
4. **Hosakerahalli Lake** (BBMP, 37 acres): Fund now; 91% covered by vegetation; KSPCB class E
5. **Rachenahalli Lake** (BBMP, 92 acres): Fund now; Algal bloom on the open water; KSPCB class E
6. **Gangondanahalli Lake** (BBMP, 39 acres): Fund now; 99% covered by vegetation; KSPCB class E
7. **Dasarahalli (Chokkasandra) Lake** (BBMP, 15 acres): Fund now; Holds 17% of its usual open water; KSPCB class E
8. **Byrasandra Melina Kere** (BBMP, 16 acres): Fund now; 38% covered by vegetation; holds 27% of its usual open water; froth seen about 34 times a year
9. **Bhoganahalli Lake** (BBMP, 9 acres): Fund now; Almost no open water this season; KSPCB class E
10. **Chinnappanahalli** (BBMP, 9 acres): Fund now; 31% covered by vegetation; algal bloom on the open water; froth seen about 27 times a year; KSPCB class E

Lakes are ordered within the city as the funding unit; custodians are not compared.


The city in one view

■ Fund now
 ■ Co-fund
 ■ Design first
 ■ Other classes


Numbers mark the first ten in the ordered list; lakes under 20 ha are drawn as dots.



Beyond the frame: Bheemanakuppa Lake (Watch / verify). Fixed footprints of the 180 assessed lakes on the five 2025 corporation outlines, coloured by Need class. Footprint = mapped boundary united with the observed water extent since 2017.



Condition A (best) to E (worst) is the worse of the median and the worst repeated input over six readings: share of its usual water held, built share, vegetation cover, algae in the water, froth events and the regulator's class.



Need class by Neer Vazhvu's published rules: Condition D or E with a tractable boundary and no works on record reads Fund now (a budget line alone does not change it); with works on record, Co-fund; with a boundary or built-up question, or no water held in the window, Design first; a single severe input against an otherwise sound reading is a flag for a closer read (Watch / verify), not a verdict.

The regulator's view, June 2026: KSPCB classed 68 monitored lakes D (wildlife and fisheries) and 62 E (irrigation and industrial cooling), none A to C; 101 of those stations join a custody lake here.

Lakes with no open water observed in nine years: B. Channasandra, Chikka Begur Lake, Chikkakalasandra Lake, Mallasandra gudde Lake, Mylasandra (Sunnakallu palya) lake, Pattandur agrahara lake-124, Pattangere/Kenchenahalli lake, Sadaramangala Lake, Srinivasapura Lake, Vasanthapura Kere / Janardhana Kere. These read as dry, vegetated or built over at 10 m and are listed with Low boundary confidence.

The ordered list, fundable now first

Open water and vegetation cover (mats, reeds, scum) are shares of the lake's footprint in its reading window (percent $\pm$ points). Algae in the water is read from the greenness of the open water on five levels: clear water, some algae, algae-rich water, heavy algae, algal bloom (the satellite index behind it is shown small). n = clear passes with a value. H / M / L = confidence class. Rows shaded orange are Fund now and Co-fund. Condition A (best) to E (worst) is the worse of the median and the worst repeated input over storage, built share, vegetation, chlorophyll, froth and the regulator's class. The reason under each Need class names the inputs that drive it; every input per lake, with its band, is in the appendix at the end.

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
1	Yelahanka Amani kere BBMP - North - 98.6 ha (244 acres)	Fund now Algal bloom on the open water; KSPCB class E; no works on record	E	95 $\pm$ 5 n18 M	4 $\pm$ 5 n18 M	algal bloom 0.42 $\pm$ 0.07 n18 M	E		M
2	Puttenahalli Lake Forest Department - North - 8.7 ha (21.6 acres)	Fund now 100% covered by vegetation; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	100 $\pm$ 5 n5 M	no open water to read	E		M
3	Kannalli kere BBMP - outside the 2025 ward layer - 22.5 ha (56 acres)	Fund now 93% covered by vegetation; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	93 $\pm$ 6 n5 M	no open water to read	E		M
4	Hosakerahalli Lake BBMP - West - 15.0 ha (37 acres)	Fund now 91% covered by vegetation; KSPCB class E; no works on record	E	2 $\pm$ 6 n5 M	91 $\pm$ 7 n5 M	no open water to read	E		M
5	Rachenahalli Lake BBMP - North - 37.1 ha (92 acres)	Fund now Algal bloom on the open water; KSPCB class E; no works on record	E	85 $\pm$ 6 n6 M	14 $\pm$ 6 n6 M	algal bloom 0.44 $\pm$ 0.11 n6 L	E		L
6	Gangondanahalli Lake BBMP - outside the 2025 ward layer - 15.6 ha (39 acres)	Fund now 99% covered by vegetation; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	99 $\pm$ 6 n5 M	no open water to read	E		M
7	Dasarahalli (Chokkasandra) Lake BBMP - West - 6.0 ha (14.8 acres)	Fund now Holds 17% of its usual open water; KSPCB class E; no works on record	E	15 $\pm$ 8 n6 M	28 $\pm$ 9 n6 M	no open water to read	E		M
8	Byrasandra Melina Kere BBMP - Central - 6.6 ha (16.4 acres)	Fund now 38% covered by vegetation; holds 27% of its usual open water; froth seen about 34 times a year; no works on record	E	19 $\pm$ 9 n8 M	38 $\pm$ 10 n8 M	algae-rich water 0.13 $\pm$ 0.13 n7 L			L
9	Bhoganahalli Lake BBMP - East - 3.7 ha (9.2 acres)	Fund now Almost no open water this season; KSPCB class E; no works on record	E	4 $\pm$ 7 n8 L	8 $\pm$ 8 n8 M	algae-rich water 0.19 $\pm$ 0.08 n5 L	E		L
10	Chinnappanahalli BBMP - East - 3.6 ha (8.9 acres)	Fund now 31% covered by vegetation; algal bloom on the open water; froth seen about 27 times a year; KSPCB class E; no works on record	E	49 $\pm$ 12 n5 L	31 $\pm$ 11 n5 M	algal bloom 0.48 $\pm$ 0.13 n5 L	E		L
11	Chelekere BBMP - East - 3.0 ha (7.5 acres)	Fund now 58% covered by vegetation; KSPCB class E; no works on record	E	22 $\pm$ 12 n7 L	58 $\pm$ 13 n7 M	some algae 0.09 $\pm$ 0.04 n4 L	E		L
12	Veerasandra Lake BMRCL - outside the 2025 ward layer - 4.1 ha (10.0 acres)	Fund now 58% covered by vegetation; froth seen about 19 times a year; no works on record	E	0 $\pm$ 6 n9 L	58 $\pm$ 12 n9 M	no open water to read			L
13	Devarakere (ISRO Layout Lake) BBMP - South - 1.8 ha (4.3 acres)	Fund now 47% covered by vegetation; heavy algae on the open water; KSPCB class E; no works on record	E	15 $\pm$ 12 n6 L	47 $\pm$ 14 n6 M	heavy algae 0.27 $\pm$ 0.09 n5 L	E		L
14	Kogilu Lake BBMP - North - 24.3 ha (60 acres)	Fund now 40% covered by vegetation; holds 30% of its usual open water; KSPCB class E; no works on record	D	20 $\pm$ 7 n4 M	40 $\pm$ 7 n4 M	no open water to read	E		M

Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
15 Begur Lake BBMP - South - 43.3 ha (107 acres)	Fund now 42% covered by vegetation; heavy algae on the open water; KSPCB class D; no works on record	D	53 ±7 n17 M	42 ±7 n17 M	heavy algae 0.26 ±0.09 n17 L	D		L
16 Kaikondrahalli Lake BBMP - South - 31.8 ha (78 acres)	Fund now Holds 44% of its usual open water; heavy algae on the open water; froth seen about 26 times a year; KSPCB class D; no works on record	D	41 ±7 n8 M	17 ±7 n8 M	heavy algae 0.23 ±0.18 n8 L	D		L
17 J.P Park (Mathikere Lake) BBMP - North - 4.6 ha (11.5 acres)	Fund now 84% covered by vegetation; froth seen about 8 times a year; KSPCB class D; no works on record	D	2 ±7 n6 L	84 ±10 n6 M	no open water to read	D		L
18 Kammagondanahalli Lake BBMP - North - 7.5 ha (18.5 acres)	Fund now 78% covered by vegetation; heavy algae on the open water; KSPCB class D; no works on record	D	10 ±7 n6 M	78 ±8 n6 M	heavy algae 0.32 ±0.12 n4 L	D		L
19 Byrasandra Lake BBMP - Central - 4.4 ha (10.8 acres)	Fund now Holds 32% of its usual open water; heavy algae on the open water; froth seen about 32 times a year; no works on record	D	28 ±11 n7 L	18 ±10 n7 M	heavy algae 0.20 ±0.07 n7 L			L
20 Nayandahalli Lake BBMP - West - 4.2 ha (10.3 acres)	Fund now Holds 28% of its usual open water; froth seen about 7 times a year; KSPCB class D; no works on record	D	25 ±10 n4 L	12 ±9 n4 M	no open water to read	D		L
21 Konappana Agrahara Lake (Karabu Kere/Konappana agrahara lake) BBMP - South - 1.4 ha (3.4 acres)	Fund now 31% covered by vegetation; holds 39% of its usual open water; heavy algae on the open water; KSPCB class D; no works on record	D	29 ±15 n9 L	31 ±15 n9 L	heavy algae 0.25 ±0.15 n6 L	D		L
22 Yediyur Lake BBMP - West - 4.2 ha (10.5 acres)	Fund now 36% covered by vegetation; holds 43% of its usual open water; heavy algae on the open water; KSPCB class D; no works on record	D	41 ±10 n6 L	36 ±10 n6 M	heavy algae 0.31 ±0.11 n6 L	D		L
23 Avalahalli BBMP - outside the 2025 ward layer - 3.9 ha (9.7 acres)	Fund now 92% covered by vegetation; froth seen about 6 times a year; no works on record	D	0 ±5 n5 L	92 ±8 n5 M	no open water to read			L
24 Hulimavu Lake BBMP - South - 41.2 ha (102 acres)	Co-fund 76% covered by vegetation; 11% built over; KSPCB class E; works under way	E	9 ±6 n6 M	76 ±6 n6 M	algae-rich water 0.11 ±0.05 n6 M	E	works underway	M
25 Kalkere Lake BBMP - East - 49.2 ha (122 acres)	Co-fund 89% covered by vegetation; heavy algae on the open water; KSPCB class E; budget line on record	E	6 ±6 n7 M	89 ±6 n7 M	heavy algae 0.23 ±0.14 n7 L	E	proposed	L
26 Kacharakanahalli BBMP - North - 6.0 ha (14.9 acres)	Co-fund Holds 15% of its usual open water; built over; works under way	E	2 ±6 n6 M	2 ±6 n6 M	algae-rich water 0.10 ±0.08 n4 L		works underway	L
27 Bellanduru Lake BDA - East - 316.8 ha (783 acres)	Co-fund 64% covered by vegetation; KSPCB class E; works under way	E	6 ±2 n4 M	64 ±3 n4 M	algae-rich water 0.12 ±0.02 n4 M	E	works underway	M
28 Shivapura Old Lake BBMP - West - 1.7 ha (4.1 acres)	Co-fund 50% covered by vegetation; built over; KSPCB class D; budget line on record	E	1 ±7 n6 L	50 ±15 n6 M	no open water to read	D	proposed	L

Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
29 Kengeri Lake BBMP - West - 9.8 ha (24.2 acres)	Co-fund 44% covered by vegetation; KSPCB class E; budget line on record	E	25 ±8 n7 M	44 ±8 n7 M	algae-rich water 0.12 ±0.03 n6 L	E	proposed	L
30 Ullal Lake BBMP - West - 9.9 ha (24.4 acres)	Co-fund 96% covered by vegetation; 12% built over; KSPCB class E; budget line on record	E	0 ±5 n6 M	96 ±6 n6 M	no open water to read	E	proposed	M
31 Munekolala Lake BBMP - East - 7.5 ha (18.6 acres)	Co-fund 32% covered by vegetation; holds 39% of its usual open water; algal bloom on the open water; froth seen about 26 times a year; KSPCB class E; budget line on record	E	39 ±9 n5 M	32 ±9 n5 M	algal bloom 0.46 ±0.13 n5 L	E	proposed	L
32 Ambalipura Upper Lake BBMP - South - 4.9 ha (12.1 acres)	Co-fund 72% covered by vegetation; froth seen about 24 times a year; budget line on record	E	4 ±7 n8 L	72 ±10 n8 M	no open water to read		proposed	L
33 Singapura Lake BBMP - North - 3.1 ha (7.6 acres)	Co-fund Holds 6% of its usual open water; KSPCB class E; budget line on record	E	6 ±8 n5 L	27 ±11 n5 M	no open water to read	E	proposed	L
34 Ambalipura Lower Lake BBMP - South - 2.2 ha (5.4 acres)	Co-fund 64% covered by vegetation; heavy algae on the open water; KSPCB class E; budget line on record	E	10 ±10 n8 L	64 ±13 n8 M	heavy algae 0.29 ±0.10 n5 L	E	proposed	L
35 Panathur lake BBMP - East - 4.5 ha (11.1 acres)	Co-fund 41% covered by vegetation; heavy algae on the open water; KSPCB class E; budget line on record	E	32 ±10 n6 L	41 ±10 n6 M	heavy algae 0.33 ±0.09 n6 L	E	proposed	L
36 Mangammana Palya Kere (ITI Layout Lake) BBMP - South - 4.9 ha (12.2 acres)	Co-fund Holds 11% of its usual open water; froth seen about 26 times a year; KSPCB class D; budget line on record	E	11 ±9 n6 L	6 ±8 n6 M	some algae 0.07 ±0.06 n6 L	D	proposed	L
37 Dore Kere BBMP - South - 9.1 ha (22.5 acres)	Co-fund 48% covered by vegetation; heavy algae on the open water; KSPCB class D; budget line on record	D	45 ±9 n6 M	48 ±9 n6 M	heavy algae 0.23 ±0.18 n6 L	D	proposed	L
38 Sompura Govt.lake BBMP - South - 7.3 ha (18.1 acres)	Co-fund 49% covered by vegetation; 17% built over; KSPCB class D; budget line on record	D	8 ±7 n4 M	49 ±9 n4 M	some algae 0.08 ±0.01 n4 L	D	proposed	L
39 Sankey Lake BBMP - West - 14.3 ha (35 acres)	Intervene early getting worse against its own past; no works on record	C	52 ±8 n4 M	15 ±7 n4 M	algae-rich water 0.10 ±0.03 n4 L	D		L
40 Nagaraesh Nagenahalli Lake BBMP - East - 2.2 ha (5.4 acres)	Intervene early getting worse against its own past; no works on record	C	49 ±13 n7 L	3 ±8 n7 M	heavy algae 0.22 ±0.08 n6 L			L
41 Mahadevapura Lake-1 BBMP - East - 29.8 ha (74 acres)	Design first Holds 19% of its usual open water; heavy algae on the open water; froth seen about 35 times a year; KSPCB class E; no works on record	E	19 ±7 n7 L	21 ±7 n7 M	heavy algae 0.30 ±0.16 n7 L	E		L
42 Vibhuthipura kere (Lal Bahadur Shastri Nagar Lake) BBMP - East - 13.2 ha (33 acres)	Design first 56% covered by vegetation; heavy algae on the open water; 11% built over; KSPCB class E; no works on record	E	16 ±7 n9 L	56 ±8 n9 M	heavy algae 0.27 ±0.13 n9 L	E		L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
43	Iblur Lake BBMP - South - 6.7 ha (16.6 acres)	Design first Holds 7% of its usual open water; froth seen about 32 times a year; KSPCB class D; no works on record	E	6 ±8 n6 L	21 ±10 n6 M	algae-rich water 0.18 ±0.07 n5 L	D		L
44	Konanakunte Lake BBMP - South - 2.0 ha (5.0 acres)	Design first 96% covered by vegetation; 30% built over; no works on record; boundary or built-up question	E	2 ±7 n6 L	96 ±8 n6 M	no open water to read			L
45	Vasanthapura Kere / Janardhana Kere BBMP - South - 1.8 ha (4.5 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n4 L	98 ±8 n4 M	no open water to read			L
46	B Channasandra Lake BBMP - Central - 1.7 ha (4.2 acres)	Design first 96% covered by vegetation; built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	96 ±9 n6 M	no open water to read			L
47	Garudacharpalya Lake BBMP - East - 1.7 ha (4.2 acres)	Design first Holds 32% of its usual open water; froth seen about 12 times a year; KSPCB class E; no works on record; boundary or built-up question	E	27 ±15 n9 L	20 ±14 n9 L	some algae 0.09 ±0.11 n7 L	E		L
48	Uttarahalli Lake BBMP - South - 4.4 ha (10.9 acres)	Design first 57% covered by vegetation; heavy algae on the open water; 19% built over; KSPCB class E; no works on record	E	23 ±10 n7 L	57 ±10 n7 M	heavy algae 0.20 ±0.10 n7 L	E		L
49	Beratenahalli Lake BBMP - South - 2.7 ha (6.7 acres)	Design first 52% covered by vegetation; built over; no works on record; boundary or built-up question	E	0 ±6 n10 L	52 ±12 n10 M	no open water to read			L
50	Gubbalala Kere BBMP - South - 2.0 ha (4.9 acres)	Design first 93% covered by vegetation; 17% built over; KSPCB class E; no works on record	E	0 ±5 n5 L	93 ±9 n5 M	no open water to read	E		L
51	Lingadeeranahalli BBMP - South - 1.8 ha (4.3 acres)	Design first 98% covered by vegetation; 32% built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	98 ±7 n6 M	no open water to read			L
52	Kembathahalli kere BBMP - South - 1.7 ha (4.3 acres)	Design first 51% covered by vegetation; 49% built over; KSPCB class D; no works on record; boundary or built-up question	E	3 ±8 n5 L	51 ±15 n5 M	no open water to read	D		L
53	Pattangere / Kenchenahalli lake (Kenchanahalli Lake) BBMP - West - 1.6 ha (3.8 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n7 L	99 ±7 n7 L	no open water to read			L
54	Chokkanahalli Lake BBMP - North - 0.9 ha (2.2 acres)	Design first 35% covered by vegetation; almost no open water this season; froth seen about 37 times a year; budget line on record; boundary or built-up question	E	4 ±13 n8 L	35 ±26 n8 L	no open water to read		proposed	I
55	Mestripalya Lake BBMP - South - 2.3 ha (5.7 acres)	Design first 99% covered by vegetation; 69% built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	99 ±7 n6 M	no open water to read			L
56	Chikkalasandra lake BBMP - South - 2.2 ha (5.4 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n9 L	62 ±13 n9 M	no open water to read			L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
57	Bheemanakatte Lake BBMP - West - 1.0 ha (2.5 acres)	Design first 64% covered by vegetation; froth seen about 14 times a year; no works on record; boundary or built-up question	E	8 ±13 n6 l	64 ±19 n6 L	no open water to read			I
58	Panathur Chikka Kere BBMP - East - 0.9 ha (2.3 acres)	Design first Holds 17% of its usual open water; KSPCB class E; no works on record; boundary or built-up question	E	14 ±14 n6 l	19 ±15 n6 L	algae-rich water 0.14 ±0.06 n4 l	E		I
59	Junnasandra lake BBMP - South - 0.8 ha (2.0 acres)	Design first Almost no open water this season; froth seen about 35 times a year; no works on record; boundary or built-up question	E	2 ±12 n9 l	0 ±5 n9 l	no open water to read			I
60	Kalyanikunte (Near Saibaba Temple) (Vasantapura Temple Kalyani) BBMP - South - 0.4 ha (1.1 acres)	Design first Holds 12% of its usual open water; froth seen about 14 times a year; no works on record; boundary or built-up question	E	9 ±18 n6 l	24 ±24 n6 L	no open water to read			I
61	Shivanahalli Lake BBMP - North - 0.4 ha (1.1 acres)	Design first Almost no open water this season; froth seen about 36 times a year; no works on record; boundary or built-up question	E	2 ±12 n7 l	0 ±5 n7 l	no open water to read			I
62	Narasappanahalli kere BBMP - West - 17.6 ha (43 acres)	Design first 92% covered by vegetation; 20% built over; KSPCB class D; no works on record	D	1 ±5 n4 M	92 ±6 n4 M	no open water to read	D		M
63	Chikka Begur Lake BBMP - South - 9.8 ha (24.3 acres)	Design first No open water seen since 2017; budget line on record	D	0 ±5 n7 L	81 ±8 n7 M	no open water to read		proposed	L
64	Hoodi kere BBMP - East - 9.2 ha (22.8 acres)	Design first 84% covered by vegetation; 18% built over; KSPCB class D; no works on record	D	1 ±6 n12 M	84 ±8 n12 M	algae-rich water 0.11 ±0.04 n5 L	D		L
65	Pattandur agrahara lake-124 BBMP - East - 4.5 ha (11.2 acres)	Design first No open water seen since 2017; no works on record	D	0 ±5 n8 L	92 ±8 n8 M	no open water to read			L
66	Kodigehalli lake BBMP - outside the 2025 ward layer - 3.3 ha (8.1 acres)	Design first 38% covered by vegetation; holds 49% of its usual open water; 18% built over; no works on record	D	25 ±11 n7 L	38 ±11 n7 M	algae-rich water 0.18 ±0.12 n5 L			L
67	Garvebhavipalya lake BBMP - South - 7.4 ha (18.3 acres)	Design first 84% covered by vegetation; 11% built over; no works on record	D	0 ±5 n6 M	84 ±8 n6 M	no open water to read			M
68	Garudachar Palya (Goshala) Lake (Goshala Lake) BBMP - East - 2.7 ha (6.6 acres)	Design first Holds 34% of its usual open water; heavy algae on the open water; froth seen about 23 times a year; KSPCB class D; no works on record; boundary or built-up question	D	31 ±14 n8 L	12 ±11 n8 M	heavy algae 0.29 ±0.14 n7 L	D		L
69	Mallasandra Lake BBMP - North - 4.4 ha (10.9 acres)	Design first No open water seen since 2017; no works on record	D	0 ±5 n6 L	100 ±5 n6 M	no open water to read			L
70	Venkateshapura Lake BBMP - North - 0.5 ha (1.1 acres)	Design first 74% covered by vegetation; no works on record; boundary or built-up question	D	0 ±5 n7 l	74 ±25 n7 L	no open water to read			I

Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
71 Gunjuru Lake BBMP - East - 20.6 ha (51 acres)	Design first 35% covered by vegetation; almost no open water this season; works under way	C	0 ±5 n10 M	35 ±7 n10 M	some algae 0.09 ±0.03 n4 L		works underway	L
72 Nelagadiranahalli Hosakere BBMP - West - 5.9 ha (14.5 acres)	Design first Holds 5% of its usual open water; budget line on record	C	4 ±7 n6 M	23 ±9 n6 M	no open water to read		proposed	M
73 Chikkabettahalli Lake BBMP - North - 2.0 ha (5.0 acres)	Design first Almost no open water this season; no works on record	C	0 ±6 n6 L	29 ±13 n6 M	no open water to read			L
74 Vaderahalli BBMP - outside the 2025 ward layer - 2.4 ha (6.0 acres)	Design first Holds 28% of its usual open water; 11% built over; no works on record	C	16 ±11 n6 L	23 ±11 n6 M	algae-rich water 0.19 ±0.05 n6 L			L
75 Swarnakunte Gudda Kere (Chandrasekhar Layout Lake) BBMP - South - 1.6 ha (3.8 acres)	Design first 38% covered by vegetation; almost no open water this season; no works on record	C	1 ±7 n19 L	38 ±15 n19 M	algae-rich water 0.14 ±0.07 n7 L			L
76 Bande Mahadevapura kere BBMP - East - 1.6 ha (4.0 acres)	Design first Holds 27% of its usual open water; froth seen about 7 times a year; no works on record; boundary or built-up question	C	26 ±16 n8 l	12 ±14 n8 L	algae-rich water 0.13 ±0.04 n7 l			I
77 Sadaramangala Lake BBMP - East - 0.1 ha (0.2 acres)	Design first No open water seen since 2017; no works on record	C	insufficient	insufficient	no open water to read	E		I
78 Mylasandra (Sunnakallu palya) lake BBMP - West - 0.7 ha (1.8 acres)	Design first No open water seen since 2017; no works on record	C	0 ±5 n5 l	62 ±54 n5 l	no open water to read			I
79 Srinivasapura Lake BBMP - North - 0.3 ha (0.8 acres)	Design first No open water seen since 2017; no works on record	C	2 ±14 n5 l	1 ±13 n5 l	no open water to read			I
80 Hebbal Lake Forest Department - North - 46.6 ha (115 acres)	Design first Almost no open water this season; budget line on record	B	2 ±5 n5 M	18 ±6 n5 M	algae-rich water 0.13 ±0.07 n4 L		proposed	L
81 Chikka Bellanduru Lake BBMP - East - 20.1 ha (50 acres)	Design first Almost no open water this season; budget line on record	B	0 ±5 n8 M	12 ±7 n8 M	no open water to read		proposed	M
82 Nagawara Lake Forest Department - North - 30.3 ha (75 acres)	Design first Holds 18% of its usual open water; budget line on record	B	13 ±6 n7 M	16 ±6 n7 M	some algae 0.07 ±0.01 n7 L		proposed	L
83 B. Channasandra BBMP - East - 2.9 ha (7.2 acres)	Design first No open water seen since 2017; no works on record	B	0 ±5 n8 L	95 ±8 n8 M	no open water to read			L
84 Ramagondanahalli Lake BBMP - outside the 2025 ward layer - 11.3 ha (28 acres)	Design first Holds 23% of its usual open water; no works on record	A	19 ±7 n6 M	2 ±6 n6 M	some algae 0.05 ±0.02 n6 L			L
85 Doddakalasandra Lake BBMP - South - 5.8 ha (14.4 acres)	Watch / verify 99% covered by vegetation; one warning sign, to be checked	C	0 ±5 n18 M	99 ±6 n18 M	no open water to read	D		M
86 Kundalahalli Lake BBMP - East - 11.4 ha (28 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	48 ±9 n8 M	19 ±8 n8 M	heavy algae 0.36 ±0.07 n8 L	D		L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
87	Nallurahalli Lake BBMP - East - 9.4 ha (23.3 acres)	Watch / verify 52% covered by vegetation; one warning sign, to be checked	C	37 ±8 n9 M	52 ±9 n9 M	algae-rich water 0.14 ±0.08 n9 L	D		L
88	Varthur Lake BDA - East - 155.0 ha (383 acres)	Watch / verify works under way	C	21 ±6 n5 M	61 ±6 n5 M	algae-rich water 0.14 ±0.02 n5 M	D	works underway	M
89	Madiwala Lake Forest Department - South - 91.0 ha (225 acres)	Watch / verify 55% covered by vegetation; one warning sign, to be checked	C	29 ±6 n4 M	55 ±6 n4 M	algae-rich water 0.10 ±0.07 n4 L	D		L
90	Bheemanakuppa Lake BBMP - outside the 2025 ward layer - 39.8 ha (98 acres)	Watch / verify steady; keep watching	C	58 ±7 n7 M	22 ±6 n7 M	algae-rich water 0.10 ±0.04 n7 L			L
91	Chikkabanavara lake BDA - outside the 2025 ward layer - 33.9 ha (84 acres)	Watch / verify steady; keep watching	C	54 ±7 n6 M	37 ±7 n6 M	algae-rich water 0.16 ±0.04 n6 L	D		L
92	Allalasandra lake BBMP - North - 16.0 ha (39 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	59 ±8 n6 M	17 ±7 n6 M	heavy algae 0.21 ±0.11 n6 L	E		L
93	Mallathahalli lake BBMP - West - 13.9 ha (34 acres)	Watch / verify 66% covered by vegetation; one warning sign, to be checked	C	26 ±8 n4 M	66 ±8 n4 M	algae-rich water 0.10 ±0.04 n4 L	D		L
94	Kudlu Anekal & Doddakere (Hosakere) BBMP - South - 13.2 ha (33 acres)	Watch / verify steady; keep watching	C	70 ±8 n9 L	21 ±7 n9 M	algae-rich water 0.20 ±0.13 n9 L	D		L
95	Herohalli Lake Bangalore North BBMP - West - 10.3 ha (25 acres)	Watch / verify steady; keep watching	C	66 ±8 n4 M	30 ±8 n4 M	heavy algae 0.35 ±0.06 n4 L	D		L
96	Haralur kere BBMP - South - 8.6 ha (21.2 acres)	Watch / verify steady; keep watching	C	68 ±9 n7 M	29 ±8 n7 M	algae-rich water 0.17 ±0.06 n6 L	D		L
97	Doddakannelli Lake BBMP - East - 8.0 ha (19.9 acres)	Watch / verify steady; keep watching	C	58 ±9 n7 M	10 ±7 n7 M	heavy algae 0.28 ±0.10 n7 L	D		L
98	Amruthalli Lake BBMP - North - 7.7 ha (19.1 acres)	Watch / verify 40% covered by vegetation; one warning sign, to be checked	C	30 ±9 n7 M	40 ±9 n7 M	algae-rich water 0.18 ±0.09 n5 L	E		L
99	Kempambudhi Lake BBMP - West - 7.7 ha (19.0 acres)	Watch / verify steady; keep watching	C	71 ±9 n6 M	27 ±9 n6 M	heavy algae 0.36 ±0.16 n6 L	D		L
100	Kowdenahalli lake BBMP - East - 5.9 ha (14.6 acres)	Watch / verify 32% covered by vegetation; one warning sign, to be checked	C	59 ±10 n7 M	32 ±9 n7 M	heavy algae 0.24 ±0.12 n7 L	E		L
101	Horamavu Lake BBMP - East - 5.0 ha (12.5 acres)	Watch / verify steady; keep watching	C	34 ±10 n11 L	19 ±9 n11 M	algae-rich water 0.11 ±0.08 n10 L			L
102	Parappana Agrahara BBMP - South - 4.6 ha (11.4 acres)	Watch / verify 100% covered by vegetation; one warning sign, to be checked	C	0 ±5 n4 L	100 ±5 n4 M	no open water to read	D		L
103	Subrayana Lake BBMP - South - 1.1 ha (2.6 acres)	Watch / verify 100% covered by vegetation; one warning sign, to be checked	C	0 ±5 n20 I	100 ±5 n20 L	no open water to read			I
104	Kommagatta Lake BDA - outside the 2025 ward layer - 11.6 ha (29 acres)	Watch / verify steady; keep watching	C	43 ±8 n8 M	38 ±8 n8 M	algae-rich water 0.13 ±0.10 n6 L			L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
105	Abbigere Lake BBMP - North - 9.5 ha (23.4 acres)	Watch / verify 76% covered by vegetation; one warning sign, to be checked	C	11 ±7 n6 M	76 ±8 n6 M	algae-rich water 0.19 ±0.05 n5 L	D	proposed	L
106	K R Puram (BEML) / Benniganahalli Lake (Benniganahalli Lake) BBMP - East - 8.0 ha (19.8 acres)	Watch / verify holds 46% of its usual open water; one warning sign, to be checked	C	43 ±9 n8 M	17 ±8 n8 M	heavy algae 0.24 ±0.11 n8 L	E		L
107	H Gollahalli kere (Hemmigepura Kere) BBMP - outside the 2025 ward layer - 5.7 ha (14.2 acres)	Watch / verify steady; keep watching	C	49 ±10 n6 M	33 ±10 n6 M	algae-rich water 0.16 ±0.06 n6 L			L
108	Narsipura Lake BBMP - North - 5.5 ha (13.5 acres)	Watch / verify steady; keep watching	C	57 ±11 n9 L	4 ±7 n9 M	algae-rich water 0.11 ±0.03 n9 L	D		L
109	Kothanuru Lake (Krishna Nagara Lake) BBMP - South - 4.6 ha (11.3 acres)	Watch / verify steady; keep watching	C	35 ±10 n6 L	11 ±8 n6 M	algae-rich water 0.13 ±0.06 n6 L	D		L
110	Dubasi Palya Kere BBMP - West - 4.2 ha (10.4 acres)	Watch / verify 54% covered by vegetation; one warning sign, to be checked	C	31 ±10 n7 L	54 ±11 n7 M	algae-rich water 0.13 ±0.04 n7 L		proposed	L
111	Seetharampalya Lake BBMP - East - 4.1 ha (10.0 acres)	Watch / verify 38% covered by vegetation; one warning sign, to be checked	C	49 ±11 n9 L	38 ±10 n9 M	heavy algae 0.39 ±0.18 n9 L	E		L
112	Andrahalli Lake BBMP - West - 3.7 ha (9.1 acres)	Watch / verify holds 50% of its usual open water; one warning sign, to be checked	C	46 ±11 n5 L	24 ±10 n5 M	some algae 0.08 ±0.04 n5 L	E		L
113	Puttenhalli Lake BBMP - South - 3.5 ha (8.6 acres)	Watch / verify steady; keep watching	C	27 ±10 n10 L	36 ±11 n10 M	algae-rich water 0.11 ±0.08 n10 L	D		L
114	Kudlu Chikka Kere (Haraluru Lake) BBMP - South - 3.3 ha (8.2 acres)	Watch / verify steady; keep watching	C	73 ±11 n7 L	23 ±10 n7 M	algae-rich water 0.17 ±0.08 n7 L	D		L
115	Kodige Singasandra Lake (Begur Kere) BBMP - South - 3.1 ha (7.7 acres)	Watch / verify 85% covered by vegetation; one warning sign, to be checked	C	0 ±5 n7 L	85 ±10 n7 M	no open water to read	D		L
116	Halagevader Halli Lake BBMP - West - 2.9 ha (7.1 acres)	Watch / verify 61% covered by vegetation; one warning sign, to be checked	C	16 ±10 n7 L	61 ±12 n7 M	some algae 0.05 ±0.03 n6 L			L
117	Basapura Lake-2 BBMP - South - 2.7 ha (6.7 acres)	Watch / verify steady; keep watching	C	49 ±12 n6 L	25 ±11 n6 M	heavy algae 0.22 ±0.08 n6 L	D		L
118	Singasandra Lake South Bangalore South BBMP - South - 2.6 ha (6.4 acres)	Watch / verify holds 42% of its usual open water; one warning sign, to be checked	C	38 ±13 n9 L	29 ±12 n9 M	algae-rich water 0.14 ±0.09 n9 L	D		L
119	Basapura Lake-1 BBMP - South - 2.3 ha (5.7 acres)	Watch / verify algal bloom on the open water; one warning sign, to be checked	C	70 ±12 n6 L	30 ±12 n6 M	algal bloom 0.45 ±0.14 n6 L	D		L
120	Carmelaram Lake BBMP - East - 2.1 ha (5.2 acres)	Watch / verify works under way	C	0 ±5 n7 L	69 ±13 n7 M	no open water to read		works underway	L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
121	Annappanakere / Yelchenahalli Lake (Yelachenahalli Kere) BBMP - South - 2.1 ha (5.2 acres)	Watch / verify 50% covered by vegetation; one warning sign, to be checked	C	9 ±10 n7 L	50 ±13 n7 M	algae-rich water 0.16 ±0.11 n5 L	D		L
122	Ramasandra Lake BDA - outside the 2025 ward layer - 2.0 ha (5.0 acres)	Watch / verify steady; keep watching	C	21 ±12 n6 L	28 ±12 n6 M	heavy algae 0.21 ±0.16 n4 L			L
123	Lakshmipura Lake BBMP - North - 1.9 ha (4.7 acres)	Watch / verify steady; keep watching	C	32 ±14 n5 L	27 ±13 n5 M	heavy algae 0.28 ±0.11 n4 L			L
124	Basavanapura Pond BBMP - South - 1.7 ha (4.3 acres)	Watch / verify 68% covered by vegetation; one warning sign, to be checked	C	7 ±10 n6 L	68 ±14 n6 M	no open water to read	D		L
125	Vijinapura Lake BBMP - East - 1.7 ha (4.3 acres)	Watch / verify 36% covered by vegetation; one warning sign, to be checked	C	56 ±14 n8 L	36 ±14 n8 M	heavy algae 0.25 ±0.17 n8 L	E		L
126	Kalena Agrahara Lake BBMP - South - 1.7 ha (4.2 acres)	Watch / verify steady; keep watching	C	41 ±15 n6 L	14 ±12 n6 M	algae-rich water 0.11 ±0.04 n6 L	D		L
127	Chikka Kammanahalli BBMP - South - 1.4 ha (3.6 acres)	Watch / verify 100% covered by vegetation; one warning sign, to be checked	C	0 ±5 n7 L	100 ±5 n7 L	no open water to read			L
128	B. Narayanapura Lake BBMP - East - 1.2 ha (3.1 acres)	Watch / verify 47% covered by vegetation; one warning sign, to be checked	C	40 ±17 n8 l	47 ±17 n8 L	algae-rich water 0.20 ±0.09 n8 l	D		I
129	Manganahalli Lake BBMP - outside the 2025 ward layer - 1.1 ha (2.8 acres)	Watch / verify 54% covered by vegetation; one warning sign, to be checked	C	18 ±15 n5 l	54 ±17 n5 L	no open water to read			I
130	Pattandur agrahara -54 Lake BBMP - East - 3.6 ha (8.9 acres)	Watch / verify 93% covered by vegetation; one warning sign, to be checked	C	0 ±6 n10 L	93 ±8 n10 M	no open water to read	D		L
131	Sheelavathana Kere BBMP - East - 4.6 ha (11.3 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	59 ±10 n10 L	21 ±9 n10 M	heavy algae 0.21 ±0.15 n10 L	E		L
132	Devasandra lake BBMP - East - 4.3 ha (10.5 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	C	51 ±11 n8 L	16 ±9 n8 M	algae-rich water 0.17 ±0.07 n7 L	E		L
133	Deverabisanahalli Lake BBMP - East - 4.1 ha (10.1 acres)	Watch / verify 31% covered by vegetation; one warning sign, to be checked	C	50 ±11 n6 L	31 ±10 n6 M	algae-rich water 0.14 ±0.05 n6 L	E		L
134	Subramanyapura Lake BBMP - South - 3.8 ha (9.3 acres)	Watch / verify steady; keep watching	C	53 ±11 n4 L	32 ±11 n4 M	heavy algae 0.27 ±0.12 n4 L	D		L
135	Hoodi Giddanakere Lake (Hoodi Lake) BBMP - East - 3.4 ha (8.5 acres)	Watch / verify works under way	C	29 ±11 n11 L	20 ±10 n11 M	algae-rich water 0.15 ±0.08 n11 L		works underway	L
136	Bhattarahalli Lake BBMP - East - 3.4 ha (8.3 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	C	52 ±11 n11 L	10 ±9 n11 M	algae-rich water 0.12 ±0.09 n10 L	E		L
137	Bagalagunte Lake BBMP - North - 3.0 ha (7.4 acres)	Watch / verify 52% covered by vegetation; one warning sign, to be checked	C	23 ±11 n8 L	52 ±12 n8 M	algae-rich water 0.12 ±0.04 n6 L			L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
138	Haralakunte Lake (Somasandra Palya Kere) (Somasundarapalya Lake) BBMP - South - 2.8 ha (7.0 acres)	Watch / verify steady; keep watching	C	69 ±11 n6 L	2 ±7 n6 M	algae-rich water 0.10 ±0.06 n6 L	D		L
139	Byrasandra BBMP - Central - 2.7 ha (6.6 acres)	Watch / verify steady; keep watching	C	65 ±12 n10 L	29 ±11 n10 M	heavy algae 0.24 ±0.12 n10 L	D		L
140	Varanasi Lake (Jimkenahalli Kere) BBMP - East - 2.1 ha (5.3 acres)	Watch / verify holds 32% of its usual open water; one warning sign, to be checked	C	26 ±13 n11 L	0 ±5 n11 M	some algae 0.08 ±0.02 n7 L	E		L
141	Nyanappanahalli Lake / Akshayanagara Lake (Akshaynagar Lake) BBMP - South - 1.3 ha (3.3 acres)	Watch / verify steady; keep watching	C	40 ±16 n6 L	40 ±16 n6 L	some algae 0.10 ±0.15 n5 L	D		L
142	Vishwaneedam Lake Bangalore North (Herohalli Thotadakere) BBMP - West - 0.9 ha (2.3 acres)	Watch / verify 76% covered by vegetation; one warning sign, to be checked	C	0 ±5 n5 l	76 ±18 n5 L	no open water to read			I
143	Srigandakaval Lake BBMP - West - 0.6 ha (1.5 acres)	Watch / verify 96% covered by vegetation; one warning sign, to be checked	C	0 ±5 n6 l	96 ±12 n6 L	no open water to read			I
144	Jogi kere BBMP - South - 0.6 ha (1.4 acres)	Watch / verify 62% covered by vegetation; one warning sign, to be checked	C	4 ±13 n4 l	62 ±23 n4 L	no open water to read			I
145	Halasuru lake BBMP - Central - 40.0 ha (99 acres)	Watch / verify works under way	B	77 ±6 n7 M	18 ±6 n7 M	heavy algae 0.28 ±0.09 n7 L		works underway	L
146	Ramapura Kere BBMP - outside the 2025 ward layer - 45.3 ha (112 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	B	75 ±6 n4 M	16 ±6 n4 M	heavy algae 0.32 ±0.18 n4 L	E		L
147	Saul Kere BBMP - East - 18.2 ha (45 acres)	Watch / verify 73% covered by vegetation; one warning sign, to be checked	B	13 ±7 n7 M	73 ±7 n7 M	algae-rich water 0.20 ±0.16 n7 L			L
148	Seegehalli Lake BBMP - East - 8.5 ha (21.0 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	B	71 ±9 n9 M	14 ±8 n9 M	algae-rich water 0.14 ±0.15 n9 L	E	proposed	L
149	Palanahalli Lake BBMP - North - 7.3 ha (18.1 acres)	Watch / verify algal bloom on the open water; one warning sign, to be checked	B	73 ±9 n20 M	26 ±9 n20 M	algal bloom 0.47 ±0.12 n20 L			L
150	Kenchanapura Govt. Lake BBMP - outside the 2025 ward layer - 5.0 ha (12.5 acres)	Watch / verify 41% covered by vegetation; one warning sign, to be checked	B	29 ±10 n6 L	41 ±10 n6 M	algae-rich water 0.19 ±0.09 n4 L		proposed	L
151	Gunjur Palya kere BBMP - East - 12.8 ha (32 acres)	Watch / verify 89% covered by vegetation; one warning sign, to be checked	B	0 ±5 n6 M	89 ±7 n6 M	no open water to read		proposed	M
152	Basavanapura Kere BBMP - East - 3.9 ha (9.7 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	B	71 ±10 n9 L	20 ±10 n9 M	heavy algae 0.32 ±0.12 n9 L	E		L
153	Subedharana Lake BBMP - South - 3.6 ha (9.0 acres)	Watch / verify 47% covered by vegetation; one warning sign, to be checked	B	40 ±11 n6 L	47 ±11 n6 M	algae-rich water 0.16 ±0.15 n6 L			L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
154	Medi agraphara BBMP - outside the 2025 ward layer - 1.7 ha (4.3 acres)	Watch / verify holds 46% of its usual open water; one warning sign, to be checked	B	29 ±14 n6 L	0 ±6 n6 M	some algae 0.03 ±0.01 n5 L			L
155	Deepanjali Nagara lake BBMP - West - 1.4 ha (3.5 acres)	Watch / verify built over; one warning sign, to be checked	B	51 ±15 n5 L	22 ±14 n5 L	some algae 0.07 ±0.04 n5 L		proposed	L
156	Jakkur Lake BBMP - North - 50.9 ha (126 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	A	81 ±6 n5 M	14 ±6 n5 M	heavy algae 0.38 ±0.11 n5 L	E	proposed	L
157	Vengayyana Lake BBMP - East - 14.3 ha (35 acres)	Watch / verify works under way	A	74 ±8 n8 M	9 ±7 n8 M	heavy algae 0.25 ±0.14 n8 L	E	works underway	L
158	Doddabommasandra Lake BBMP - North - 36.2 ha (90 acres)	Maintain in fair shape; upkeep and monitoring	B	64 ±7 n7 M	12 ±6 n7 M	heavy algae 0.26 ±0.14 n7 L			L
159	Venkojirao Kere / Agara Kere (Agara Lake) BBMP - South - 29.6 ha (73 acres)	Maintain in fair shape; upkeep and monitoring	B	68 ±7 n7 M	13 ±6 n7 M	algae-rich water 0.19 ±0.07 n7 L	D		L
160	Sarakki Lake BBMP - South - 23.7 ha (59 acres)	Maintain in fair shape; upkeep and monitoring	B	77 ±7 n4 M	10 ±6 n4 M	some algae 0.05 ±0.02 n4 L	D		L
161	Attur lake BBMP - North - 23.7 ha (59 acres)	Maintain in fair shape; upkeep and monitoring	B	76 ±7 n5 M	16 ±7 n5 M	heavy algae 0.32 ±0.06 n5 L			L
162	Gantiganahalli Lake BBMP - North - 20.0 ha (49 acres)	Maintain in fair shape; upkeep and monitoring	B	63 ±7 n17 M	31 ±7 n17 M	heavy algae 0.37 ±0.11 n17 L			L
163	Horamavu Agara Lake BBMP - East - 14.9 ha (37 acres)	Maintain in fair shape; upkeep and monitoring	B	86 ±7 n8 M	11 ±7 n8 M	heavy algae 0.38 ±0.11 n8 L			L
164	Kasavanahalli lake BBMP - South - 13.9 ha (34 acres)	Maintain in fair shape; upkeep and monitoring	B	37 ±8 n7 M	12 ±7 n7 M	some algae 0.06 ±0.02 n6 L	D		L
165	Kaggadasapura BBMP - Central - 12.2 ha (30 acres)	Maintain in fair shape; upkeep and monitoring	B	69 ±8 n8 M	16 ±7 n8 M	heavy algae 0.22 ±0.11 n8 L			L
166	Gottigere BBMP - South - 12.0 ha (30 acres)	Maintain in fair shape; upkeep and monitoring	B	63 ±8 n4 M	10 ±7 n4 M	algae-rich water 0.13 ±0.16 n4 L	D	proposed	L
167	Thirumenahalli Lake BBMP - North - 5.7 ha (14.1 acres)	Maintain in fair shape; upkeep and monitoring	B	54 ±10 n6 M	20 ±9 n6 M	heavy algae 0.24 ±0.13 n5 L			L
168	Doddanekundi lake BBMP - East - 38.1 ha (94 acres)	Maintain in fair shape; upkeep and monitoring	A	84 ±6 n8 M	12 ±6 n8 M	heavy algae 0.35 ±0.12 n8 M	D	proposed	M
169	Sulikere/ Herekere Lake BBMP - outside the 2025 ward layer - 42.2 ha (104 acres)	Maintain in fair shape; upkeep and monitoring	A	65 ±7 n5 M	10 ±6 n5 M	algae-rich water 0.10 ±0.08 n4 L			L
170	Veerasagara lake BBMP - outside the 2025 ward layer - 6.7 ha (16.7 acres)	Maintain in fair shape; upkeep and monitoring	A	37 ±9 n5 M	6 ±7 n5 M	some algae 0.08 ±0.04 n4 L			L
171	Kattigenahalli Lake BBMP - North - 5.7 ha (14.0 acres)	Steward in good shape; protect and monitor	B	43 ±10 n4 M	11 ±8 n4 M	no open water to read			M
172	Konasandra Lake BBMP - West - 10.5 ha (26 acres)	Steward in good shape; protect and monitor	B	64 ±8 n5 M	24 ±8 n5 M	algae-rich water 0.13 ±0.12 n5 L			L

#	Lake (satellite footprint)	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
173	Arekere lake BBMP - South - 7.5 ha (18.6 acres)	Steward in good shape; protect and monitor	B	42 ±9 n7 M	16 ±8 n7 M	some algae 0.08 ±0.03 n7 L		proposed	L
174	Anjanapura Lake / nagara Churchaghatta Kere Alahalli (Avalahalli Lake) BBMP - South - 5.6 ha (13.8 acres)	Steward in good shape; protect and monitor	B	62 ±10 n7 L	12 ±8 n7 M	heavy algae 0.21 ±0.05 n7 L	D		L
175	Agrahara Lake BBMP - North - 4.4 ha (11.0 acres)	Steward in good shape; protect and monitor	B	48 ±10 n6 L	14 ±9 n6 M	heavy algae 0.25 ±0.11 n5 L			L
176	Yelenahalli Lake BBMP - South - 1.2 ha (3.0 acres)	Steward in good shape; protect and monitor	B	52 ±17 n7 I	10 ±12 n7 L	some algae 0.06 ±0.02 n7 I	D		I
177	Doddkammanahalli Lake BBMP - South - 4.9 ha (12.2 acres)	Steward in good shape; protect and monitor	B	57 ±10 n5 L	4 ±7 n5 M	algae-rich water 0.18 ±0.08 n5 L	D		L
178	Gowdana Kere BBMP - South - 2.5 ha (6.1 acres)	Steward in good shape; protect and monitor	B	49 ±12 n6 L	10 ±9 n6 M	heavy algae 0.27 ±0.12 n6 L			L
179	Thalaghattapura Lake BBMP - South - 4.1 ha (10.1 acres)	Steward in good shape; protect and monitor	A	57 ±11 n6 L	38 ±11 n6 M	algae-rich water 0.19 ±0.10 n5 L			L
180	Nagarabhavi Lake BBMP - West - 0.9 ha (2.2 acres)	Steward in good shape; protect and monitor	A	56 ±19 n6 I	7 ±12 n6 L	some algae 0.03 ±0.05 n6 I			I

1. Yelahanka Amani kere


Listed as Yelahanka Amani kere (BBMP); North corporation, Aerocity ward; satellite footprint 98.6 ha (244 acres) (the mapped boundary and observed water, not the survey area); reading window pre-monsoon (Mar-May) 2026, 18 clear passes.

Fund now. Algal bloom on the open water; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Open water over 95% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.

What the money buys: nutrient control at the inlets and in-lake aeration.

Open water (share of footprint)	95% ± 5 (n 18, M)
Vegetation cover (mats, reeds, scum)	4% ± 5 (n 18, M)
Exposed bed	1% ± 5 (n 18, M)
Algae in the water (chlorophyll proxy)	algal bloom: 0.42 ± 0.07 (n 18, M)
Algae against its own history	98th percentile of its 2017-2025 pre-monsoon record (n 107)
Vegetation against its own history	25th percentile of its 2017-2025 pre-monsoon record (n 107)
Share of its usual open water held	97% ± 6 (n 18, M)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 2.8 mg/l, BOD 12 mg/l, turbidity 24 NTU
Programme on record	none
Lake series	position 5 in its chain; upstream on the custody list: Puttenahalli Lake (E), Kogilu Lake (D); 2 other water bodies upstream; 0 custody lakes downstream; 7,186 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2017	2	93%	4%	algal bloom
2018	3	95%	1%	heavy algae
2019	18	88%	2%	heavy algae
2020	15	85%	10%	heavy algae
2021	13	86%	9%	clear water
2022	11	86%	10%	clear water
2023	13	84%	11%	algae-rich water
2024	14	89%	6%	algae-rich water
2025	18	89%	6%	heavy algae
2026	18	95%	4%	algal bloom

Medians of the clear passes in the pre-monsoon (March to May) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

2. Puttenahalli Lake


Listed as Puttenahalli Lake (Forest Department); North corporation, Doddabettahalli ward; satellite footprint 8.7 ha (21.6 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 100% covered by vegetation; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Vegetation covers 100% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	100% ± 5 (n 5, M)
Exposed bed	0% ± 5 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	96th percentile of its 2019-2025 monsoon record (n 38)
Share of its usual open water held	0% ± 9 (n 5, M) (water under vegetation cover is not visible to the satellite)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (-38 points since 2019)
Froth passes per year (lower bound)	2023: 1
KSPCB, June 2026	Class E; DO 2.4 mg/l, BOD 8 mg/l, turbidity 12 NTU
Programme on record	none
Lake series	position 4 in its chain; upstream on the custody list: Attur lake (B), Veerasagara lake (A), Ramagondanahalli Lake (A); 1 custody lakes downstream; 5,562 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	3	15%	70%	algae-rich water
2020	5	6%	88%	algae-rich water
2021	7	22%	61%	algae-rich water
2022	8	32%	56%	heavy algae
2023	5	26%	44%	algae-rich water
2024	5	37%	57%	heavy algae
2025	5	0%	100%	
2026	5	0%	100%	some algae

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

3. Kannalli kere


Listed as Kanna halli lake (BBMP); outside the 2025 ward layer corporation; satellite footprint 22.5 ha (56 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 93% covered by vegetation; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Vegetation covers 93% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	93% ± 6 (n 5, M)
Exposed bed	5% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	78th percentile of its 2019-2025 monsoon record (n 27)
Share of its usual open water held	0% ± 9 (n 5, M) (water under vegetation cover is not visible to the satellite)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 0.5 mg/l, BOD 35 mg/l, turbidity 24.6 NTU
Programme on record	none
Lake series	position 3 in its chain; upstream on the custody list: Kodigehalli lake (D); 1 other water bodies upstream; 2 custody lakes downstream; 7,158 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	2	4%	84%	algae-rich water
2020	5	40%	49%	some algae
2021	6	9%	71%	heavy algae
2022	5	15%	78%	algae-rich water
2023	2	0%	94%	
2024	3	1%	94%	some algae
2025	4	0%	94%	clear water
2026	5	0%	93%	some algae

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

4. Hosakerahalli Lake


Listed as Hoskerehalli Lake (BBMP); West corporation, Bangarappa Nagara ward; satellite footprint 15.0 ha (37 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 91% covered by vegetation; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Vegetation covers 91% of the lake in the reading window, with open water at 2%; KSPCB's June 2026 class is E.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	2% ± 6 (n 5, M)
Vegetation cover (mats, reeds, scum)	91% ± 7 (n 5, M)
Exposed bed	4% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	20th percentile of its 2019-2025 monsoon record (n 25)
Share of its usual open water held	20% ± 62 (n 5, M) (water under vegetation cover is not visible to the satellite)
Built share inside the satellite footprint, not against the survey boundary (2026)	3% (-6 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 1 mg/l, BOD 27 mg/l, turbidity 18.6 NTU
Programme on record	none
Lake series	position 2 in its chain; upstream on the custody list: Chikkalasandra lake (E); 0 custody lakes downstream; 30,273 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	2	27%	56%	some algae
2020	2	4%	92%	some algae
2021	6	0%	98%	
2022	8	0%	99%	some algae
2023	3	0%	78%	algae-rich water
2024	3	0%	98%	heavy algae
2025	1	0%	98%	
2026	5	2%	91%	some algae

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

5. Rachenahalli Lake

Listed as Rachenahalli Lake (BBMP); North corporation, Jakkur ward; satellite footprint 37.1 ha (92 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 6 clear passes.

Fund now. Algal bloom on the open water; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Open water over 85% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.

What the money buys: nutrient control at the inlets and in-lake aeration.

Open water (share of footprint)	85% ± 6 (n 6, M)
Vegetation cover (mats, reeds, scum)	14% ± 6 (n 6, M)
Exposed bed	1% ± 5 (n 6, M)
Algae in the water (chlorophyll proxy)	algal bloom: 0.44 ± 0.11 (n 6, L)
Algae against its own history	75th percentile of its 2020-2025 monsoon record (n 32)
Vegetation against its own history	69th percentile of its 2020-2025 monsoon record (n 32)
Share of its usual open water held	89% ± 6 (n 6, M)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 2 mg/l, BOD 8 mg/l, turbidity 10 NTU
Programme on record	none
Lake series	position 5 in its chain; upstream on the custody list: Jakkur Lake (A), Amruthalli Lake (C); 1 other water bodies upstream; 0 custody lakes downstream; 11,338 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2020	4	86%	9%	heavy algae
2021	3	85%	12%	heavy algae
2022	10	78%	16%	heavy algae
2023	3	82%	14%	heavy algae
2024	4	87%	13%	algal bloom
2025	8	75%	13%	heavy algae
2026	6	85%	14%	algal bloom

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

6. Gangondanahalli Lake


Listed as Gangondanahalli Lake (BBMP); outside the 2025 ward layer corporation; satellite footprint 15.6 ha (39 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 99% covered by vegetation; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Vegetation covers 99% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	99% ± 6 (n 5, M)
Exposed bed	1% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	66th percentile of its 2019-2025 monsoon record (n 29)
Share of its usual open water held	0% ± 18 (n 5, M) (water under vegetation cover is not visible to the satellite)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 0.7 mg/l, BOD 90 mg/l, turbidity 5.7 NTU
Programme on record	none
Lake series	position 3 in its chain; upstream on the custody list: Narasappanahalli kere (D), Andrahalli Lake (C); 1 other water bodies upstream; 0 custody lakes downstream; 4,392 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	2	11%	68%	some algae
2020	2	16%	75%	some algae
2021	6	2%	94%	some algae
2022	7	1%	98%	some algae
2023	5	0%	100%	
2024	4	0%	96%	algae-rich water
2025	3	0%	99%	
2026	5	0%	99%	some algae

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

7. Dasarahalli (Chokkasandra) Lake


Listed as Dasarahalli (Chokkasandra) Lake (BBMP); West corporation, Chokkasandra ward; satellite footprint 6.0 ha (14.8 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 6 clear passes.

Fund now. Holds 17% of its usual open water; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Holding 17% of its usual open water this season; KSPCB's June 2026 class is E.

What the money buys: inflow and storage restoration.

Open water (share of footprint)	15% ± 8 (n 6, M)
Vegetation cover (mats, reeds, scum)	28% ± 9 (n 6, M)
Exposed bed	36% ± 9 (n 6, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	66th percentile of its 2019-2025 monsoon record (n 29)
Share of its usual open water held	17% ± 10 (n 6, M)
Built share inside the satellite footprint, not against the survey boundary (2026)	8% (+3 points since 2019)
Froth passes per year (lower bound)	2023: 2, 2024: 1, 2026: 1
KSPCB, June 2026	Class E; DO 2.5 mg/l, BOD 25 mg/l, turbidity 17.1 NTU
Programme on record	none
Lake series	position 1 in its chain; 1 custody lakes downstream; 4,138 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	2	47%	30%	heavy algae
2020	2	73%	12%	some algae
2021	7	42%	40%	heavy algae
2022	8	34%	24%	heavy algae
2023	3	65%	3%	some algae
2024	4	30%	22%	algae-rich water
2025	3	48%	27%	algae-rich water
2026	6	15%	28%	algae-rich water

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

8. Byrasandra Melina Kere


Listed as Melina Byrasandra (DRDO) (BBMP); Central corporation, New Thippasandra ward; satellite footprint 6.6 ha (16.4 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 8 clear passes.

Fund now. 38% covered by vegetation; holds 27% of its usual open water; froth seen about 34 times a year; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Holding 27% of its usual open water this season; froth on 103 clear passes since 2024.

What the money buys: inflow and storage restoration; surfactant and sewage control upstream of the weir.

Open water (share of footprint)	19% ± 9 (n 8, M)
Vegetation cover (mats, reeds, scum)	38% ± 10 (n 8, M)
Exposed bed	20% ± 9 (n 8, M)
Algae in the water (chlorophyll proxy)	algae-rich water: 0.13 ± 0.13 (n 7, L)
Algae against its own history	65th percentile of its 2019-2025 monsoon record (n 20)
Vegetation against its own history	3th percentile of its 2019-2025 monsoon record (n 29)
Share of its usual open water held	27% ± 13 (n 8, M)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (-2 points since 2019)
Froth passes per year (lower bound)	2022: 38, 2023: 37, 2024: 32, 2025: 33, 2026: 38
KSPCB, June 2026	no station joined
Programme on record	none
Lake series	position 1 in its chain; 1 custody lakes downstream; 1,130 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




0.5 km across
Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	2	18%	45%	heavy algae
2020	3	8%	43%	algae-rich water
2021	4	2%	58%	algae-rich water
2022	9	2%	62%	some algae
2023	4	6%	57%	some algae
2024	5	4%	49%	some algae
2025	2	6%	63%	algal bloom
2026	8	19%	38%	algae-rich water

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

9. Bhoganahalli Lake


Listed as Bhoganahalli Lake (BBMP); East corporation, Panathur ward; satellite footprint 3.7 ha (9.2 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 8 clear passes.

Fund now. Almost no open water this season; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Exposed bed over 71% of the footprint; KSPCB's June 2026 class is E.

What the money buys: inflow and storage restoration after a boundary survey.

Open water (share of footprint)	4% ± 7 (n 8, L)
Vegetation cover (mats, reeds, scum)	8% ± 8 (n 8, M)
Exposed bed	71% ± 10 (n 8, M)
Algae in the water (chlorophyll proxy)	algae-rich water: 0.19 ± 0.08 (n 5, L)
Algae against its own history	71th percentile of its 2019-2025 monsoon record (n 17)
Vegetation against its own history	36th percentile of its 2019-2025 monsoon record (n 28)
Share of its usual open water held	5% ± 10 (n 8, L)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	2022: 1, 2023: 3, 2026: 2
KSPCB, June 2026	Class E; DO 2 mg/l, BOD 19 mg/l, turbidity 8.6 NTU
Programme on record	none
Lake series	position 1 in its chain; 2 custody lakes downstream; 415 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2019	1	0%	3%	
2020	2	22%	27%	some algae
2021	5	2%	68%	some algae
2022	8	49%	22%	heavy algae
2023	4	6%	0%	some algae
2024	4	4%	13%	heavy algae
2025	4	8%	6%	algae-rich water
2026	8	4%	8%	algae-rich water

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

10. Chinnappanahalli


Listed as Chinnappanahalli (BBMP); East corporation, Priyadarshini Ward ward; satellite footprint 3.6 ha (8.9 acres) (the mapped boundary and observed water, not the survey area); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 31% covered by vegetation; algal bloom on the open water; froth seen about 27 times a year; KSPCB class E; no works on record. The class rests on the lake's present condition as the satellite reads it and the works on record; it does not say why the lake is in this state, what was done before the record, or that a lake-level work alone is the answer. Read it with the lake series and the catchment.

What the satellite shows. Algal bloom on the open water; froth on 103 clear passes since 2024; KSPCB's June 2026 class is E.

What the money buys: nutrient control at the inlets and in-lake aeration; surfactant and sewage control upstream of the weir.

Open water (share of footprint)	49% ± 12 (n 5, L)
Vegetation cover (mats, reeds, scum)	31% ± 11 (n 5, M)
Exposed bed	6% ± 8 (n 5, M)
Algae in the water (chlorophyll proxy)	algal bloom: 0.48 ± 0.13 (n 5, L)
Algae against its own history	83th percentile of its 2020-2025 monsoon record (n 24)
Vegetation against its own history	53th percentile of its 2020-2025 monsoon record (n 30)
Share of its usual open water held	50% ± 12 (n 5, L)
Built share inside the satellite footprint, not against the survey boundary (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	2022: 30, 2023: 31, 2024: 27, 2025: 43, 2026: 33
KSPCB, June 2026	Class E; DO 3 mg/l, BOD 13 mg/l, turbidity 7.3 NTU
Programme on record	none
Lake series	position 1 in its chain; 2 custody lakes downstream; 918 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium




Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

The same season, year by year

Year	Clear passes	Open water	Vegetation	Algae
2020	3	44%	32%	heavy algae
2021	4	39%	33%	algal bloom
2022	10	20%	41%	algae-rich water
2023	5	42%	16%	some algae
2024	5	7%	27%	algae-rich water
2025	3	15%	13%	algae-rich water
2026	5	49%	31%	algal bloom

Medians of the clear passes in the monsoon (June to September) of each year since 2017; a year with fewer than two clear passes shows its passes but its values should be read with care. The shaded row is this edition's reading window.

Surface composition, monthly medians 2019 to date




Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.


What continuous monitoring looks like

Three lakes, monthly medians of the surface composition from 2019 (a month with fewer than two clear passes is a gap, not a value). The monsoon months are thin on every lake, which is what an honest optical record looks like.


Bellandur (BDA)



Varthur (BDA)




Jakkur (BBMP)




Surface classes per pass: open water, vegetation cover (floating mats, reeds along the margins, surface scum; a reed fringe is healthy, a hyacinth mat is not, and the split is a coming refinement), froth, and exposed bed. Sentinel-2, 10 m.

Ulsoor, November 2025 to August 2026




Open-water share of the footprint per clear pass. The lake was drained from February 2026 for its NDMF desilting works; the series will show the refill.

Coverage, 2019 to date



Median clear passes per lake per month. The monsoon gap is reported, never filled; the archive over Bengaluru is dense from 2019.



Assessed lakes with an algae reading: vegetation cover against algae in the water, reading window medians. Two groups: mat-covered lakes and bloom-prone open lakes; both are eutrophication, with different measures.

Confidence

Assessed lakes by the weakest of their open-water, vegetation and chlorophyll readings: insufficient 19, low 142, medium 19.

A confidence class is the weakest of six components: pixels inside the lake after the shoreline ring, the share of the lake close to shore, clear passes in the window, the length of the lake's own record, validation of the surface classes on the lake's type, and the boundary's provenance. High needs every component High, which a 10 m sensor cannot give a lake under about 20 ha and a mapped boundary cannot give any lake; Medium is the ceiling for the large lakes until a surveyed boundary and field calibration exist. The monsoon window also thins the clear passes; the post-monsoon edition will lift the pass component for most lakes.

The monsoon window. Storage is read in the wettest months, so the share-of-extent band flatters no lake, and the vegetation and algae readings are at their seasonal high; the November edition reads the same lakes after the rains.

Method, in brief

Universe. The Karnataka Tank Conservation and Development Authority custody lists for Bengaluru (BBMP, BDA, Forest Department, BMRCL): 210 lakes, each joined to a mapped boundary, the BBMP Lake Management System point, the 2025 ward and corporation, Neer Vazhvu's drainage-network layer, the regulator's June 2026 station, and the programme rows on record.

Sensor. Copernicus Sentinel-2 (10 m, a pass every two to three days over Bengaluru), every scene from March 2017 to the reading date, cloud-masked pixel by pixel; observed passes only, nothing interpolated.

Per lake, per pass. A fixed footprint (the mapped boundary united with the observed water extent); the share of the footprint reading as open water, vegetation (mats and emergent growth), froth and exposed bed; and on the open water, relative indices for chlorophyll, turbidity, coloured organic matter and apparent colour. These are relative readings: comparable across lakes and years, not concentrations.

Per lake, per window. Seasonal medians with their spread, percentile against the lake's own same-season history, water area and share of the observed maximum, froth events per year, built share inside the footprint, and the confidence class. Health Card bands are assigned only where the band is wider than the error.

Need class and order. Neer Vazhvu's published rules over four axes (Condition, Stakes, Tractability, Urgency) with the programme on record; lakes are ordered within the city as the funding unit. The full method, error model and rule set are in the Neer Vazhvu methodology note, available on request.

Unassessed at 10 m (30)

Listed with the reason. A traced boundary or a sub-metre image moves a lake into the assessed set.

Lake	Reason
Siddapura Lake BBMP -	no usable boundary at 10 m; location known
Gangashetty Lake BBMP -	no usable boundary at 10 m; location known; KSPCB samples at its station 'Gangashetty Lake' at 13.00502, 77.693716 (Class E, June 2026)
Puttenahalli / Byraweshwara BBMP -	no usable boundary at 10 m; location known
Lingadeeranahalli (handrahalli) North Lake Bangalore North BBMP -	no usable boundary at 10 m; location known
Chikkabasthi lake BBMP -	no usable boundary at 10 m; location known
Gandhinagar Hosakerehalli BBMP -	no usable boundary at 10 m; location known
Varahasandra Lake BBMP -	no usable boundary at 10 m; location known
Gattigerepalya (Sompura) lake BBMP -	no usable boundary at 10 m; location known
Chikkagowdanapalya lake BBMP -	no usable boundary at 10 m; location known
Busegowdana lake BBMP -	no usable boundary at 10 m; location known
Bayyapanapalya Kunte BBMP -	no usable boundary at 10 m; location known
Narasipura Lake 26 BBMP -	no usable boundary at 10 m; location known
(Nagasandra) BBMP -	no usable boundary at 10 m; no location known
19 Malagala BBMP -	no usable boundary at 10 m; no location known
Byatagunte Playa BBMP -	no usable boundary at 10 m; no location known
Lingarajapura Lake BBMP -	no usable boundary at 10 m; no location known
Geddalahalli BBMP -	no usable boundary at 10 m; no location known
Konena Agrahara BBMP -	no usable boundary at 10 m; location known
(Lingannana Bilaekahalli Kere) (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Dorasanni Palya (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Ittmadu BBMP -	no usable boundary at 10 m; no location known
Thavarekare BBMP -	no usable boundary at 10 m; no location known
Karisandra lake BBMP -	no usable boundary at 10 m; no location known
Nandi shettappa lake BBMP -	no usable boundary at 10 m; no location known
Arehalli 2 & 3 (Small tanks) (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Bovimaranahalli BBMP -	no usable boundary at 10 m; no location known
Gundopanth lake BBMP -	no usable boundary at 10 m; no location known
Kamakshipalya Lake BBMP -	no usable boundary at 10 m; no location known
Sanegoravanahalli Lake BBMP -	no usable boundary at 10 m; no location known
Agraharadasarahalli Lake BBMP -	no usable boundary at 10 m; no location known

Appendix: condition inputs per lake

C1 share of observed extent held, C3 built share, C4 vegetation cover, C5 chlorophyll proxy, C8 froth events per year, G2 the regulator's class; a band followed by candidates in brackets, such as D(C/D), means the error band straddles a boundary and the value's band is shown with both candidates.

#	Lake	Condition	Inputs	Notes
1	Yelahanka Amani kere	E	C1=A C3=A(A/B) C4=A C5=E(D/E) C8=A G2=E	C3 candidates A/B; C5 candidates D/E
2	Puttenahalli Lake	E	C3=A(A/B) C4=E C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B
3	Kannalli kere	E	C3=A(A/B) C4=E C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B
4	Hosakerahalli Lake	E	C3=B(B/C) C4=E C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C
5	Rachenahalli Lake	E	C1=A(A/B) C3=A(A/B) C4=B(A/B/C) C5=E(D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates D/E
6	Gangondanahalli Lake	E	C3=A(A/B) C4=E C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B
7	Dasarahalli (Chokkasandra) Lake	E	C1=E C3=C(C/D) C4=C(B/C/D) C8=B G2=E	C3 candidates C/D; C4 candidates B/C/D
8	Byrasandra Melina Kere	E	C1=E(D/E) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=E	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
9	Bhoganahalli Lake	E	C1=E C3=A(A/B) C4=A(A/B) C5=C(C/D) C8=B G2=E	C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
10	Chinnappanahalli	E	C1=C(C/D) C3=A(A/B) C4=D(C/D/E) C5=E(D/E) C8=E G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E
11	Chelekere	E	C3=A(A/B) C4=E C5=B(B/C) C8=B G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C
12	Veerasandra Lake	E	C3=A(A/B) C4=E C8=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B
13	Devarakere (ISRO Layout Lake)	E	C3=A(A/B) C4=E(D/E) C5=D(C/D) C8=B G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates C/D
14	Kogilu Lake	D	C1=D(D/E) C3=A(A/B) C4=D(D/E) C8=A G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates D/E
15	Begur Lake	D	C3=A(A/B) C4=E(D/E) C5=D(C/D) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates C/D
16	Kaikondrahalli Lake	D	C1=D(C/D) C3=B(A/B) C4=B(B/C) C5=D(B/D/E) C8=E G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C; C5 candidates B/D/E
17	J.P Park (Mathikere Lake)	D	C3=A(A/B) C4=E C8=D G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B
18	Kammagondanahalli Lake	D	C3=A(A/B) C4=E C5=D(D/E) C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates D/E
19	Byrasandra Lake	D	C1=D(D/E) C3=A(A/B) C4=B(A/B/C) C5=D(C/D) C8=E	C1 candidates D/E; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D
20	Nayandahalli Lake	D	C1=E(D/E) C3=A(A/B) C4=B(A/B/C) C8=D G2=D	C1 candidates D/E; C3 candidates A/B; C4 candidates A/B/C
21	Konappana Agrahara Lake (Karabu Kere/Konappana agrahara lake)	D	C1=D(C/D/E) C3=A(A/B) C4=D(B/D/E) C5=D(B/D) C8=B G2=D	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/D/E; C5 candidates B/D
22	Yediyur Lake	D	C1=D(C/D) C3=A(A/B) C4=D(C/D/E) C5=D(C/D/E) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D/E
23	Avalahalli	D	C3=B(B/C) C4=E C8=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C
24	Hulimavu Lake	E	C3=D(C/D) C4=E C5=C(B/C) C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates C/D; C5 candidates B/C
25	Kalkere Lake	E	C3=A(A/B) C4=E C5=D(B/D) C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/D

#	Lake	Condition	Inputs	Notes
26	Kacharakannahalli	E	C1=E(C/E) C3=E C4=A C5=C(B/C) C8=B	C1 candidates C/E; C5 candidates B/C
27	Bellanduru Lake	E	C3=A(A/B) C4=E C5=C(B/C) C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C
28	Shivapura Old Lake	E	C3=E C4=E(D/E) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E
29	Kengeri Lake	E	C3=A(A/B) C4=E(D/E) C5=C(B/C) C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C
30	Ullal Lake	E	C3=D(C/D) C4=E C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates C/D
31	Munekolala Lake	E	C1=D(D/E) C3=B(A/B) C4=D(C/D/E) C5=E(D/E) C8=E G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E
32	Ambalipura Upper Lake	E	C3=C(B/C) C4=E C8=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C
33	Singapura Lake	E	C1=E C3=A(A/B) C4=C(B/C/D) C8=B G2=E	C3 candidates A/B; C4 candidates B/C/D
34	Ambalipura Lower Lake	E	C3=A(A/B) C4=E C5=D(C/D) C8=A G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates C/D
35	Panathur lake	E	C3=A(A/B) C4=E(D/E) C5=D(D/E) C8=B G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates D/E
36	Mangamma Palya Kere (ITI Layout Lake)	E	C1=E C3=B(B/C) C4=A(A/B) C5=B(B/C) C8=E G2=D	C3 candidates B/C; C4 candidates A/B; C5 candidates B/C
37	Dore Kere	D	C3=C(B/C) C4=E(D/E) C5=D(B/D/E) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C; C4 candidates D/E; C5 candidates B/D/E
38	Sompura Govt.lake	D	C3=D C4=E C5=B C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite
39	Sankey Lake	C	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
40	Nagaraesh Nagenahalli Lake	C	C1=C(C/D) C3=A(A/B) C4=A(A/B) C5=D(C/D) C8=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
41	Mahadevapura Lake-1	E	C1=E C3=C(C/D) C4=C(B/C) C5=D(C/D/E) C8=E G2=E	C3 candidates C/D; C4 candidates B/C; C5 candidates C/D/E
42	Vibhuthipura kere (Lal Bahadur Shastri Nagar Lake)	E	C3=D(C/D) C4=E C5=D(C/D) C8=C G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates C/D; C5 candidates C/D
43	Iblur Lake	E	C1=E C3=A(A/B) C4=C(B/C/D) C5=C(C/D) C8=E G2=D	C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
44	Konanakunte Lake	E	C3=E C4=E C8=B	C1 not read: water under vegetation cover is not visible to the satellite
45	Vasanthapura Kere / Janardhana Kere	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
46	B Channasandra Lake	E	C3=E C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite
47	Garudacharpalya Lake	E	C1=D(D/E) C4=B(A/B/D) C5=B(A/B/D) C8=E G2=E	C1 candidates D/E; C4 candidates A/B/D; C5 candidates A/B/D
48	Uttarahalli Lake	E	C3=D(D/E) C4=E C5=D(B/D) C8=B G2=E	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates D/E; C5 candidates B/D
49	Beraterna Agrahara Lake	E	C3=E C4=E(D/E) C8=C	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E
50	Gubbalala Kere	E	C3=D C4=E C8=B G2=E	C1 not read: water under vegetation cover is not visible to the satellite
51	Lingadeeranahalli	E	C3=E C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite
52	Kembathahali kere	E	C3=E C4=E(D/E) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E
53	Pattangere / Kenchenahalli lake (Kenchanahalli Lake)	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
54	Chokkanahalli Lake	E	C1=E C4=D(A/D/E) C8=E	C4 candidates A/D/E
55	Mestripalya Lake	E	C3=E C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite
56	Chikkalasandra lake	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
57	Bheemanakatte Lake	E	C4=E C8=E	C1 not read: water under vegetation cover is not visible to the satellite
58	Panathur Chikka Kere	E	C1=E(D/E) C4=B(A/B/D) C5=C(B/C/D) C8=B G2=E	C1 candidates D/E; C4 candidates A/B/D; C5 candidates B/C/D
59	Junnasandra lake	E	C1=E C4=A C8=E	

#	Lake	Condition	Inputs	Notes
60	Kalyanikunte (Near Saibaba Temple) (Vasantapura Temple Kalyani)	E	C1=E(D/E) C4=C(A/C/E) C8=E	C1 candidates D/E; C4 candidates A/C/E
61	Shivanahalli Lake	E	C1=E C4=A C8=E	
62	Narasappanahalli kere	D	C3=D(D/E) C4=E C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates D/E
63	Chikka Begur Lake	D	C3=D C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
64	Hoodi kere	D	C3=D(D/E) C4=E C5=C(B/C) C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates D/E; C5 candidates B/C
65	Pattandur agrahara lake-124	D	C3=D(C/D) C4=E C8=A	C3 candidates C/D; no open water observed 2017-2026: boundary and hydrology to scope
66	Kodigehalli lake	D	C1=D(C/D/E) C3=D(D/E) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates C/D/E; C3 candidates D/E; C4 candidates C/D/E; C5 candidates B/C/D
67	Garvebhavipalya lake	D	C3=D(C/D) C4=E C8=B	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates C/D
68	Garudachar Palya (Goshala) Lake (Goshala Lake)	D	C1=D(D/E) C4=B(A/B/C) C5=D(C/D/E) C8=E G2=D	C1 candidates D/E; C4 candidates A/B/C; C5 candidates C/D/E
69	Mallasandra Lake	D	C3=D(D/E) C4=E C8=A	C3 candidates D/E; no open water observed 2017-2026: boundary and hydrology to scope
70	Venkateshapura Lake	D	C4=E C8=C	C1 not read: water under vegetation cover is not visible to the satellite
71	Gunjuru Lake	C	C1=E(B/E) C3=C(B/C) C4=D(C/D/E) C5=B(B/C) C8=B	C1 candidates B/E; C3 candidates B/C; C4 candidates C/D/E; C5 candidates B/C; single severe input C1: little or no open water in the reading window; storage and inflow to scope
72	Nelagadiranahalli Hosakere	C	C1=E C3=C(B/C) C4=C(B/C/D) C8=B	C3 candidates B/C; C4 candidates B/C/D; single severe input C1: little or no open water in the reading window; storage and inflow to scope
73	Chikkabettahalli Lake	C	C1=E C3=B(A/B) C4=C(B/C/E) C8=C	C3 candidates A/B; C4 candidates B/C/E; single severe input C1: little or no open water in the reading window; storage and inflow to scope
74	Vaderahalli	C	C1=E(D/E) C3=D(C/D) C4=C(B/C/D) C5=C(C/D) C8=C	C1 candidates D/E; C3 candidates C/D; C4 candidates B/C/D; C5 candidates C/D; single severe input C1: little or no open water in the reading window; storage and inflow to scope
75	Swarnakunte Gudda Kere (Chandrasekhar Layout Lake)	C	C1=E C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=B	C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D; single severe input C1: little or no open water in the reading window; storage and inflow to scope
76	Bande Mahadevapura kere	C	C1=E(D/E) C4=B(A/B/C) C5=C(B/C) C8=D	C1 candidates D/E; C4 candidates A/B/C; C5 candidates B/C; single severe input C1: little or no open water in the reading window; storage and inflow to scope
77	Sadaramangala Lake	C	C8=A G2=E	no open water observed 2017-2026: boundary and hydrology to scope
78	Mylasandra (Sunnakallu palya) lake	C	C4=E(A/E) C8=A	C4 candidates A/E; no open water observed 2017-2026: boundary and hydrology to scope
79	Srinivasapura Lake	C	C4=A(A/B) C8=E	C4 candidates A/B; no open water observed 2017-2026: boundary and hydrology to scope
80	Hebbal Lake	B	C1=E C3=A(A/B) C4=B(B/C) C5=C(B/C) C8=A	C3 candidates A/B; C4 candidates B/C; C5 candidates B/C; single severe input C1: little or no open water in the reading window; storage and inflow to scope
81	Chikka Bellanduru Lake	B	C1=E C3=B(A/B) C4=B(A/B) C8=A	C3 candidates A/B; C4 candidates A/B; single severe input C1: little or no open water in the reading window; storage and inflow to scope
82	Nagawara Lake	B	C1=E C3=A(A/B) C4=B(A/B/C) C5=B C8=A	C3 candidates A/B; C4 candidates A/B/C; single severe input C1: little or no open water in the reading window; storage and inflow to scope
83	B. Channasandra	B	C3=B(A/B) C4=E C8=A	C3 candidates A/B; no open water observed 2017-2026: boundary and hydrology to scope
84	Ramagondanahalli Lake	A	C1=E(D/E) C3=A(A/B) C4=A C5=B C8=A	C1 candidates D/E; C3 candidates A/B; single severe input C1: little or no open water in the reading window; storage and inflow to scope
85	Doddakalasandra Lake	C	C3=B(A/B) C4=E C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
86	Kundalahalli Lake	C	C1=C(C/D) C3=A(A/B) C4=B(B/C) C5=D(D/E) C8=E G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C; C5 candidates D/E; single severe input C8: flagged for a closer read, not a verdict
87	Nallurahalli Lake	C	C3=B(A/B) C4=E C5=C(B/C/D) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
88	Varthur Lake	C	C3=A(A/B) C4=E C5=C C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
89	Madiwala Lake	C	C3=A(A/B) C4=E C5=C(B/C) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
90	Bheemanakuppa Lake	C	C1=C C3=A(A/B) C4=C(B/C) C5=C(B/C) C8=A	C3 candidates A/B; C4 candidates B/C; C5 candidates B/C
91	Chikkabanavara lake	C	C1=C(C/D) C3=A(A/B) C4=D(D/E) C5=C C8=A G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates D/E
92	Allalasandra lake	C	C1=C C3=A(A/B) C4=B(A/B/C) C5=D(B/D) C8=B G2=E	C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/D; single severe input G2: flagged for a closer read, not a verdict
93	Mallathahalli lake	C	C3=B(A/B) C4=E C5=C(B/C) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
94	Kudlu Anekal & Doddakere (Hosakere)	C	C1=B(A/B) C3=A(A/B) C4=C(B/C) C5=C(B/C/D) C8=A G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C; C5 candidates B/C/D
95	Herohalli Lake Bangalore North	C	C1=B(B/C) C3=B(A/B) C4=C(C/D) C5=D(D/E) C8=A G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D; C5 candidates D/E
96	Haraluru kere	C	C1=B(B/C) C3=A(A/B) C4=C(C/D) C5=C(C/D) C8=A G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D; C5 candidates C/D
97	Doddakannelli Lake	C	C1=C C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=C G2=D	C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
98	Amruthalli Lake	C	C1=C(C/D) C3=B(B/C) C4=D(D/E) C5=C(B/C/D) C8=B G2=E	C1 candidates C/D; C3 candidates B/C; C4 candidates D/E; C5 candidates B/C/D; single severe input G2: flagged for a closer read, not a verdict
99	Kempambudhi Lake	C	C1=B(A/B/C) C3=B(A/B) C4=C(B/C/D) C5=D(D/E) C8=A G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates D/E
100	Kowdenahalli lake	C	C1=C(B/C) C3=A(A/B) C4=D(C/D/E) C5=D(C/D) C8=A G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
101	Horamavu Lake	C	C1=D(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=C	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
102	Parappana Agrahara	C	C3=A(A/B) C4=E C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
103	Subrayana Lake	C	C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite; single severe input C4: flagged for a closer read, not a verdict
104	Kommagatta Lake	C	C1=D(C/D) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
105	Abbigere Lake	C	C3=A(A/B) C4=E C5=C(C/D) C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates C/D; single severe input C4: flagged for a closer read, not a verdict
106	K R Puram (BEML) / Benniganahalli Lake (Benniganahalli Lake)	C	C1=D(C/D) C3=B(A/B) C4=B(A/B/C) C5=D(C/D) C8=C G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
107	H Gollahalli kere (Hemmigepura Kere)	C	C1=C(B/C/D) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=B	C1 candidates B/C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
108	Narsipura Lake	C	C1=C(B/C/D) C3=A(A/B) C4=A(A/B) C5=C(B/C) C8=D G2=D	C1 candidates B/C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
109	Kothanuru Lake (Krishna Nagara Lake)	C	C1=D(C/D) C3=A(A/B) C4=B(A/B) C5=C(B/C) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
110	Dubasi Palya Kere	C	C3=B(B/C) C4=E C5=C(B/C) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
111	Seetharampalya Lake	C	C1=C(B/C/D) C3=A(A/B) C4=D(C/D/E) C5=D(D/E) C8=A G2=E	C1 candidates B/C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict
112	Andrahalli Lake	C	C1=D(C/D) C3=B(A/B) C4=C(B/C/D) C5=B(B/C) C8=A G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict
113	Puttenhalli Lake	C	C1=D(D/E) C3=A(A/B) C4=D(C/D/E) C5=C(B/C) C8=A G2=D	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C
114	Kudlu Chikka Kere (Haraluru Lake)	C	C1=B(A/B) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
115	Kodige Singasandra Lake (Begur Kere)	C	C3=B(B/C) C4=E C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
116	Halagevader Halli Lake	C	C3=D C4=E C5=B C8=B	C1 not read: water under vegetation cover is not visible to the satellite; single severe input C4: flagged for a closer read, not a verdict
117	Basapura Lake-2	C	C1=C(B/C/D) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=B G2=D	C1 candidates B/C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
118	Singasandra Lake South Bangalore South	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/E) C5=C(B/C/D) C8=E G2=D	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/E; C5 candidates B/C/D; single severe input C8: flagged for a closer read, not a verdict
119	Basapura Lake-1	C	C1=B(A/B/C) C3=A(A/B) C4=C(B/C/E) C5=E(D/E) C8=A G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/E; C5 candidates D/E; single severe input C5: flagged for a closer read, not a verdict
120	Carmelaram Lake	C	C3=A(A/B) C4=E C8=C	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
121	Annappanakere / Yelchenahalli Lake (Yelachenahalli Kere)	C	C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
122	Ramasandra Lake	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/E) C5=D(B/D) C8=A	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/E; C5 candidates B/D
123	Lakshmipura Lake	C	C1=C(B/C/D) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=A	C1 candidates B/C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
124	Basavanapura Pond	C	C3=A(A/B) C4=E C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
125	Vijinapura Lake	C	C1=C(A/C) C3=A(A/B) C4=D(C/D/E) C5=D(B/D/E) C8=A G2=E	C1 candidates A/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/D/E; single severe input G2: flagged for a closer read, not a verdict
126	Kalena Agrahara Lake	C	C1=D(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=C G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
127	Chikka Kammanahalli	C	C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite; single severe input C4: flagged for a closer read, not a verdict
128	B. Narayanapura Lake	C	C4=E(D/E) C5=C(C/D) C8=B G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E; C5 candidates C/D; single severe input C4: flagged for a closer read, not a verdict
129	Manganahalli Lake	C	C4=E(D/E) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E; single severe input C4: flagged for a closer read, not a verdict
130	Pattandur agrahara -54 Lake	C	C3=B(A/B) C4=E C8=A G2=D	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
131	Sheelavathana Kere	C	C1=C(B/C) C3=A(A/B) C4=C(B/C/D) C5=D(B/D) C8=A G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/D; single severe input G2: flagged for a closer read, not a verdict
132	Devasandra lake	C	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(C/D) C8=B G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
133	Deverabisanahalli Lake	C	C1=C(C/D) C3=B(B/C) C4=D(C/D/E) C5=C(B/C) C8=C G2=E	C1 candidates C/D; C3 candidates B/C; C4 candidates C/D/E; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
134	Subramanyapura Lake	C	C1=C(B/C) C3=A(A/B) C4=D(C/D/E) C5=D(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D
135	Hoodi Giddanakere Lake (Hoodi Lake)	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=B	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
136	Bhattarahalli Lake	C	C1=C(B/C) C3=A(A/B) C4=A(A/B) C5=C(B/C/D) C8=B G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C/D; single severe input G2: flagged for a closer read, not a verdict
137	Bagalagunte Lake	C	C3=D(D/E) C4=E C5=C(B/C) C8=B	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates D/E; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
138	Haralakunte Lake (Somasandra Palya Kere) (Somasundarapalya Lake)	C	C1=B(A/B/C) C3=A(A/B) C4=A C5=C(B/C) C8=C G2=D	C1 candidates A/B/C; C3 candidates A/B; C5 candidates B/C
139	Byrasandra	C	C1=B(A/B/C) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=C G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
140	Varanasi Lake (Jimkenahalli Kere)	C	C1=D(D/E) C3=A(A/B) C4=A C5=B(B/C) C8=D G2=E	C1 candidates D/E; C3 candidates A/B; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict
141	Nyanappanahalli Lake / Akshayanagara Lake (Akshaynagar Lake)	C	C1=C(B/C/D) C4=D(C/D/E) C5=B(A/B/D) C8=B G2=D	C1 candidates B/C/D; C4 candidates C/D/E; C5 candidates A/B/D
142	Vishwaneedam Lake Bangalore North (Herohalli Thotadakere)	C	C4=E C8=A	C1 not read: water under vegetation cover is not visible to the satellite; single severe input C4: flagged for a closer read, not a verdict
143	Srigandakaval Lake	C	C4=E C8=B	C1 not read: water under vegetation cover is not visible to the satellite; single severe input C4: flagged for a closer read, not a verdict
144	Jogi kere	C	C4=E(D/E) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C4 candidates D/E; single severe input C4: flagged for a closer read, not a verdict
145	Halasuru lake	B	C1=B(A/B) C3=C(B/C) C4=B(B/C) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates B/C; C4 candidates B/C; C5 candidates C/D
146	Ramapura Kere	B	C1=B(A/B) C3=A(A/B) C4=B(A/B/C) C5=D(C/D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D/E; single severe input G2: flagged for a closer read, not a verdict
147	Saul Kere	B	C3=A(A/B) C4=E C5=C(B/C/D) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
148	Seegehalli Lake	B	C1=B(B/C) C3=A(A/B) C4=B(A/B/C) C5=C(A/C/D) C8=B G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B/C; C5 candidates A/C/D; single severe input G2: flagged for a closer read, not a verdict
149	Palanahalli Lake	B	C1=A(A/B) C3=B(A/B) C4=C(B/C/D) C5=E(D/E) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates D/E; single severe input C5: flagged for a closer read, not a verdict
150	Kenchanapura Govt. Lake	B	C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
151	Gunjur Palya kere	B	C3=A(A/B) C4=E C8=B	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; single severe input C4: flagged for a closer read, not a verdict
152	Basavanapura Kere	B	C1=B(A/B) C3=A(A/B) C4=B(B/C) C5=D(D/E) C8=B G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict
153	Subedharana Lake	B	C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=A	C1 not read: water under vegetation cover is not visible to the satellite; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
154	Medi aghara	B	C1=D(C/D/E) C3=E C4=A C5=B C8=B	C1 candidates C/D/E; single severe input C3: flagged for a closer read, not a verdict
155	Deepanjali Nagara lake	B	C1=B(A/B/C) C3=E C4=C(A/C/D) C5=B(B/C) C8=B	C1 candidates A/B/C; C4 candidates A/C/D; C5 candidates B/C; single severe input C3: flagged for a closer read, not a verdict
156	Jakkur Lake	A	C1=A(A/B) C3=A(A/B) C4=B(A/B/C) C5=D(D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
157	Vengayyana Lake	A	C1=A(A/B) C3=A(A/B) C4=A(A/B) C5=D(C/D) C8=B G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
158	Doddabommasandra Lake	B	C1=C(B/C) C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=A	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
159	Venkojirao Kere / Agara Kere (Agara Lake)	B	C1=B(B/C) C3=A(A/B) C4=B(A/B) C5=C(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
160	Sarakki Lake	B	C1=B(A/B) C3=B(A/B) C4=A(A/B) C5=B C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B
161	Attur lake	B	C1=B(A/B) C3=A(A/B) C4=B(A/B/C) C5=D C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C
162	Gantiganahalli Lake	B	C1=B(A/B) C3=A(A/B) C4=D(C/D) C5=D(D/E) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates C/D; C5 candidates D/E
163	Horamavu Agara Lake	B	C1=A(A/B) C3=A(A/B) C4=B(A/B) C5=D(D/E) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates D/E
164	Kasavanahalli lake	B	C1=D C3=A(A/B) C4=B(A/B) C5=B C8=B G2=D	C3 candidates A/B; C4 candidates A/B
165	Kaggadasapura	B	C1=A(A/B) C3=B(A/B) C4=B(A/B/C) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D
166	Gottigere	B	C1=A(A/B) C3=A(A/B) C4=B(A/B) C5=C(A/C/D) C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates A/C/D
167	Thirumenahalli Lake	B	C1=C(B/C) C3=A(A/B) C4=B(B/C) C5=D(C/D) C8=B	C1 candidates B/C; C3 candidates A/B; C4 candidates B/C; C5 candidates C/D
168	Doddanekundi lake	A	C1=A C3=A(A/B) C4=B(A/B) C5=D(D/E) C8=A G2=D	C3 candidates A/B; C4 candidates A/B; C5 candidates D/E
169	Sulikere/ Herekere Lake	A	C1=B(B/C) C3=A(A/B) C4=A(A/B) C5=C(B/C) C8=A	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
170	Veerasagara lake	A	C1=D(C/D) C3=A(A/B) C4=A(A/B) C5=B(B/C) C8=A	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
171	Kattigenahalli Lake	B	C1=D(C/D) C3=A(A/B) C4=B(A/B) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B
172	Konasandra Lake	B	C1=B(A/B) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
173	Arekere lake	B	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=B(B/C) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
174	Anjanapura Lake / nagara Chunchaghatta Kere Alahalli (Avalahalli Lake)	B	C1=B(B/C) C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
175	Agrahara Lake	B	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=D(C/D) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D
176	Yelenahalli Lake	B	C1=B(A/B/D) C4=B(A/B/C) C5=B C8=B G2=D	C1 candidates A/B/D; C4 candidates A/B/C
177	Doddkammanahalli Lake	B	C1=B(B/C) C3=A(A/B) C4=A(A/B) C5=C(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
178	Gowdana Kere	B	C1=A(A/B) C3=C(C/D) C4=B(A/B) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates C/D; C4 candidates A/B; C5 candidates C/D
179	Thalaghattapura Lake	A	C1=A(A/B) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
180	Nagarabhavi Lake	A	C1=A(A/C) C4=A(A/B) C5=B(A/B) C8=B	C1 candidates A/C; C4 candidates A/B; C5 candidates A/B

Sources

- KTCDA, List of Lakes in Bengaluru (BBMP, BDA, Forest Department, BMRCL custody lists), ktcda.karnataka.gov.in/28/list-of-lakes-in-bengaluru/en, downloaded 3 September 2026.
- BBMP Lake Management System, lake locations (lms.bbmpgov.in), 3 September 2026.

- KSPCB, Water Quality Data of Bengaluru Lakes for the Month of June 2026 (130 stations); Classification of Water Quality under NWMP, April 2025 to February 2026.
- Copernicus Sentinel-2 Level-2A imagery, March 2017 to August 2026; Dynamic World land cover (Google and WRI).
- OpenStreetMap water polygons; Greater Bengaluru 2025 ward and corporation layers; Neer Vazhvu's drainage-network layer.
- Programme rows: Deccan Herald, 17 July 2025, "BBMP allocates Rs 50 crore to develop 24 lakes"; 21 June 2025, "Karnataka Govt approves Rs 80 crore to resume desilting work" (Bellandur); 17 November 2025, "Bellandur Lake rejuvenation pushed to March 2026"; 27 February 2026, "Authority plans revival of drained city lakes"; Citizen Matters, 3 March 2020, "BDA concretises restoration of Bellandur Lake"; Newsfirst, 18 February 2026, "Ulsoor Lake drained for Rs 4-crore mega desilting"; SANDRP, 10 February 2026, "Bengaluru Lakes 2025"; NGT OA 125/2017, orders of 6 December 2018 and 12 March 2021.
- Method: Neer Vazhvu, satellite monitoring of Bengaluru lakes, methodology note (September 2026), available on request.