



Neer Vazhvu

India's Water Intelligence

contact@neervazhvu.org - neervazhvu.org

Bengaluru Lakes Snapshot, monsoon 2026

Every lake on the Greater Bengaluru custody lists, read from Sentinel-2 as relative, uncalibrated readings, with an order of priority for restoration funding. Reading window: **monsoon (Jun-Sep) 2026** for 173 of 180 assessed lakes (each lake's own window is named in the list). Archive 28 March 2017 to 30 August 2026; observed passes only, nothing interpolated. A post-monsoon edition follows in November 2026 on the same method.

What this snapshot is for. Greater Bengaluru lists 210 lakes in the care of four agencies. Each is monitored in its own way, and no single reading covers all of them on the same footing, so a funder, a custodian or a lake group has no common basis on which to decide where the next rupee of restoration money does the most good.

This snapshot reads every listed lake the same way, from free satellite imagery going back to 2017: how much of each lake is open water, vegetation or exposed bed, how green the water is, how much of its usual extent it holds, whether it is built over, and how it compares with its own past. It sets these beside the regulator's June 2026 classification and the works already on record, and orders the lakes by a published rule into classes a funder can act on: Fund now, Co-fund, Design first, and the rest.

It is a starting point, not a verdict. Every reading carries its uncertainty and a confidence class, nothing is estimated where there is no observation, and the order improves with each edition, with ground sampling, and with surveyed boundaries.

Custody lakes on the KTCDAs lists

210

BBMP, BDA, Forest Department,
BMRCCL

Assessed from satellite

180

30 unassessed: no usable boundary
at 10 m, or too few clear readings

Condition D or E

85

1,151 of 2,259 ha of assessed
footprint

Fundable now

46

Fund now 28 and Co-fund 18; Design
first 53

How to read a number in this report

Each value is a seasonal median of clear satellite passes, shown as **value ± band** with **n** passes and a confidence class **H / M / L**. The band is the reading's own uncertainty (sampling and classification for shares, spread across passes for indices). A Health Card band is assigned only where the band is wider than the error; otherwise both candidate bands are listed. Where the evidence is too thin, the value reads "insufficient".

Why nothing reads High. A class is the weakest of six components, and two cannot reach High from a 10 m satellite and a mapped boundary: closeness to shore (only lakes over about 100 ha escape it) and boundary provenance (High needs a surveyed boundary). Medium is the ceiling for now; a surveyed boundary and a field calibration unlock High.

The monsoon window. Storage is read in the wettest months, so the share-of-extent band flatters no lake and the vegetation and chlorophyll readings are at their seasonal high; the November edition reads the same lakes after the rains.

What this snapshot cannot say

Dissolved oxygen, BOD, COD, nutrients, coliform, metals and toxins have no optical signature; the regulator's Use Based Class (KSPCB, June 2026) is shown beside the satellite reading for 101 lakes and is never recomputed. Chlorophyll and turbidity are relative indices until a field calibration exists; no calibrated concentration appears here. The vegetation share includes floating mats and emergent reeds inside the footprint. Encroachment is read at 10 m from Dynamic World and needs a survey sketch or a sub-metre scene before any claim. Boundaries are OpenStreetMap polygons united with the observed water extent, not survey boundaries.

The first ten in the order


1. **Yelahanka Amani kere** (BBMP, 98.6 ha (244 acres)): Fund now. Open water over 95% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.
2. **Puttenahalli Lake** (Forest Department, 8.7 ha (21.6 acres)): Fund now. Vegetation covers 100% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.
3. **Doddakalasandra Lake** (BBMP, 5.8 ha (14.4 acres)): Fund now. Vegetation covers 99% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is D.
4. **Kannalli kere** (BBMP, 22.5 ha (56 acres)): Fund now. Vegetation covers 93% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.
5. **Hosakerahalli Lake** (BBMP, 15.0 ha (37 acres)): Fund now. Vegetation covers 91% of the lake in the reading window, with open water at 2%; KSPCB's June 2026 class is E.
6. **Rachenahalli Lake** (BBMP, 37.1 ha (92 acres)): Fund now. Open water over 85% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.
7. **Saul Kere** (BBMP, 18.2 ha (45 acres)): Fund now. Vegetation covers 73% of the lake in the reading window, with open water at 13%.
8. **J.P Park (Mathikere Lake)** (BBMP, 4.6 ha (11.5 acres)): Fund now. Vegetation covers 84% of the lake in the reading window, with open water at 2%; froth on 25 clear passes since 2024; KSPCB's June 2026 class is D.
9. **Parappana Agrahara** (BBMP, 4.6 ha (11.4 acres)): Fund now. Vegetation covers 100% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is D.
10. **Gangondanahalli Lake** (BBMP, 15.6 ha (39 acres)): Fund now. Vegetation covers 99% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.

Order: Need class (Fund now, Co-fund, Intervene early, Design first, then the rest), Condition band, the published Need index, confidence, footprint area. Lakes are ordered within the city as the funding unit; custodians are not compared.


The city in one view

■ Fund now
 ■ Co-fund
 ■ Design first
 ■ Other classes


Numbers mark the first ten in the ordered list; lakes under 20 ha are drawn as dots.



Beyond the frame: Bheemanakuppa Lake (Watch / verify). Fixed footprints of the 180 assessed lakes on the five 2025 corporation outlines, coloured by Need class. Footprint = mapped boundary united with the observed water extent since 2017.



Condition A (best) to E (worst) is the worse of the median and the worst repeated input over six readings: share of its usual water held, built share, vegetation cover, algae in the water, froth events and the regulator's class.



Need class by Neer Vazhvu's published rules: Condition D or E with a tractable boundary and no works on record reads Fund now (a budget line alone does not change it); with works on record, Co-fund; with a boundary or built-up question, or no water held in the window, Design first; a single severe input against an otherwise sound reading is a flag for a closer read (Watch / verify), not a verdict.

The regulator's view, June 2026: KSPCB classed 68 monitored lakes D (wildlife and fisheries) and 62 E (irrigation and industrial cooling), none A to C; 101 of those stations join a custody lake here.

Lakes with no open water observed in nine years: B. Channasandra, Chikka Begur Lake, Chikkakalasandra Lake, Mallasandra gudde Lake, Mylasandra (Sunnakallu palya) lake, Pattandur agrahara lake-124, Pattangere/Kenchenahalli lake, Sadaramangala Lake, Srinivasapura Lake, Vasanthapura Kere / Janardhana Kere. These read as dry, vegetated or built over at 10 m and are listed with Low boundary confidence.

The ordered list, fundable now first

Open water and vegetation cover (mats, reeds, scum) are shares of the lake's footprint in its reading window (percent $\pm$ points). Algae in the water is read from the greenness of the open water on five levels: clear water, some algae, algae-rich water, heavy algae, algal bloom (the satellite index behind it is shown small). n = clear passes with a value. H / M / L = confidence class. Rows shaded orange are Fund now and Co-fund. Condition A (best) to E (worst) is the worse of the median and the worst repeated input over storage, built share, vegetation, chlorophyll, froth and the regulator's class. The reason under each Need class names the inputs that drive it; every input per lake, with its band, is in the appendix at the end.

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
1	Yelahanka Amani kere BBMP - North - 98.6 ha (244 acres)	Fund now Algal bloom on the open water; KSPCB class E; no works on record	E	95 $\pm$ 5 n18 M	4 $\pm$ 5 n18 M	algal bloom 0.42 $\pm$ 0.07 n18 M	E		M
2	Puttenahalli Lake Forest Department - North - 8.7 ha (21.6 acres)	Fund now 100% covered by vegetation; almost no water this season; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	100 $\pm$ 5 n5 M	no open water to read	E		M
3	Doddakalasandra Lake BBMP - South - 5.8 ha (14.4 acres)	Fund now 99% covered by vegetation; almost no water this season; KSPCB class D; no works on record	E	0 $\pm$ 5 n18 M	99 $\pm$ 6 n18 M	no open water to read	D		M
4	Kannalli kere BBMP - outside the 2025 ward layer - 22.5 ha (56 acres)	Fund now 93% covered by vegetation; almost no water this season; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	93 $\pm$ 6 n5 M	no open water to read	E		M
5	Hosakerahalli Lake BBMP - West - 15.0 ha (37 acres)	Fund now 91% covered by vegetation; holds 20% of its usual water; KSPCB class E; no works on record	E	2 $\pm$ 6 n5 M	91 $\pm$ 7 n5 M	no open water to read	E		M
6	Rachenahalli Lake BBMP - North - 37.1 ha (92 acres)	Fund now Algal bloom on the open water; KSPCB class E; no works on record	E	85 $\pm$ 6 n6 M	14 $\pm$ 6 n6 M	algal bloom 0.44 $\pm$ 0.11 n6 L	E		L
7	Saul Kere BBMP - East - 18.2 ha (45 acres)	Fund now 73% covered by vegetation; holds 17% of its usual water; no works on record	E	13 $\pm$ 7 n7 M	73 $\pm$ 7 n7 M	algae-rich water 0.20 $\pm$ 0.16 n7 L			L
8	J.P Park (Mathikere Lake) BBMP - North - 4.6 ha (11.5 acres)	Fund now 84% covered by vegetation; almost no water this season; froth seen about 8 times a year; KSPCB class D; no works on record	E	2 $\pm$ 7 n6 L	84 $\pm$ 10 n6 M	no open water to read	D		L
9	Parappana Agrahara BBMP - South - 4.6 ha (11.4 acres)	Fund now 100% covered by vegetation; almost no water this season; KSPCB class D; no works on record	E	0 $\pm$ 5 n4 L	100 $\pm$ 5 n4 M	no open water to read	D		L
10	Gangondanahalli Lake BBMP - outside the 2025 ward layer - 15.6 ha (39 acres)	Fund now 99% covered by vegetation; almost no water this season; KSPCB class E; no works on record	E	0 $\pm$ 5 n5 M	99 $\pm$ 6 n5 M	no open water to read	E		M
11	Dasarahalli (Chokkasandra) Lake BBMP - West - 6.0 ha (14.8 acres)	Fund now Holds 17% of its usual water; KSPCB class E; no works on record	E	15 $\pm$ 8 n6 M	28 $\pm$ 9 n6 M	no open water to read	E		M
12	Kammagondanahalli Lake BBMP - North - 7.5 ha (18.5 acres)	Fund now 78% covered by vegetation; holds 16% of its usual water; heavy algae on the open water; KSPCB class D; no works on record	E	10 $\pm$ 7 n6 M	78 $\pm$ 8 n6 M	heavy algae 0.32 $\pm$ 0.12 n4 L	D		L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
13	Byrasandra Melina Kere BBMP - Central - 6.6 ha (16.4 acres)	Fund now 38% covered by vegetation; holds 27% of its usual water; froth seen about 34 times a year; no works on record	E	19 ±9 n8 M	38 ±10 n8 M	algae-rich water 0.13 ±0.13 n7 L			L
14	Bhoganahalli Lake BBMP - East - 3.7 ha (9.2 acres)	Fund now Almost no water this season; KSPCB class E; no works on record	E	4 ±7 n8 L	8 ±8 n8 M	algae-rich water 0.19 ±0.08 n5 L	E		L
15	Chinnappanahalli BBMP - East - 3.6 ha (8.9 acres)	Fund now 31% covered by vegetation; algal bloom on the open water; froth seen about 27 times a year; KSPCB class E; no works on record	E	49 ±12 n5 L	31 ±11 n5 M	algal bloom 0.48 ±0.13 n5 L	E		L
16	Chelekere BBMP - East - 3.0 ha (7.5 acres)	Fund now 58% covered by vegetation; holds 37% of its usual water; KSPCB class E; no works on record	E	22 ±12 n7 L	58 ±13 n7 M	some algae 0.09 ±0.04 n4 L	E		L
17	Annappanakere / Yelchenahalli Lake (Yelachenahalli Kere) BBMP - South - 2.1 ha (5.2 acres)	Fund now 50% covered by vegetation; holds 9% of its usual water; KSPCB class D; no works on record	E	9 ±10 n7 L	50 ±13 n7 M	algae-rich water 0.16 ±0.11 n5 L	D		L
18	Basavanapura Pond BBMP - South - 1.7 ha (4.3 acres)	Fund now 68% covered by vegetation; holds 9% of its usual water; KSPCB class D; no works on record	E	7 ±10 n6 L	68 ±14 n6 M	no open water to read	D		L
19	Veerasandra Lake BMRCL - outside the 2025 ward layer - 4.1 ha (10.0 acres)	Fund now 58% covered by vegetation; almost no water this season; froth seen about 19 times a year; no works on record	E	0 ±6 n9 L	58 ±12 n9 M	no open water to read			L
20	Avalahalli BBMP - outside the 2025 ward layer - 3.9 ha (9.7 acres)	Fund now 92% covered by vegetation; almost no water this season; froth seen about 6 times a year; no works on record	E	0 ±5 n5 L	92 ±8 n5 M	no open water to read			L
21	Pattandur aghahara -54 Lake BBMP - East - 3.6 ha (8.9 acres)	Fund now 93% covered by vegetation; almost no water this season; KSPCB class D; no works on record	E	0 ±6 n10 L	93 ±8 n10 M	no open water to read	D		L
22	Devarakere (ISRO Layout Lake) BBMP - South - 1.8 ha (4.3 acres)	Fund now 47% covered by vegetation; holds 20% of its usual water; heavy algae on the open water; KSPCB class E; no works on record	E	15 ±12 n6 L	47 ±14 n6 M	heavy algae 0.27 ±0.09 n5 L	E		L
23	Kogilu Lake BBMP - North - 24.3 ha (60 acres)	Fund now 40% covered by vegetation; holds 30% of its usual water; KSPCB class E; no works on record	D	20 ±7 n4 M	40 ±7 n4 M	no open water to read	E		M
24	Kaikondrahalli Lake BBMP - South - 31.8 ha (78 acres)	Fund now Holds 44% of its usual water; heavy algae on the open water; froth seen about 26 times a year; KSPCB class D; no works on record	D	41 ±7 n8 M	17 ±7 n8 M	heavy algae 0.23 ±0.18 n8 L	D		L
25	Byrasandra Lake BBMP - Central - 4.4 ha (10.8 acres)	Fund now Holds 32% of its usual water; heavy algae on the open water; froth seen about 32 times a year; no works on record	D	28 ±11 n7 L	18 ±10 n7 M	heavy algae 0.20 ±0.07 n7 L			L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
26	Nayandahalli Lake BBMP - West - 4.2 ha (10.3 acres)	Fund now Holds 28% of its usual water; froth seen about 7 times a year; KSPCB class D; no works on record	D	25 ±10 n4 L	12 ±9 n4 M	no open water to read	D		L
27	Konappana Agrahara Lake (Karabu Kere/Konappana agrahara lake) BBMP - South - 1.4 ha (3.4 acres)	Fund now 31% covered by vegetation; holds 39% of its usual water; heavy algae on the open water; KSPCB class D; no works on record	D	29 ±15 n9 L	31 ±15 n9 L	heavy algae 0.25 ±0.15 n6 L	D		L
28	Yediyr Lake BBMP - West - 4.2 ha (10.5 acres)	Fund now 36% covered by vegetation; holds 43% of its usual water; heavy algae on the open water; KSPCB class D; no works on record	D	41 ±10 n6 L	36 ±10 n6 M	heavy algae 0.31 ±0.11 n6 L	D		L
29	Hulimavu Lake BBMP - South - 41.2 ha (102 acres)	Co-fund 76% covered by vegetation; holds 12% of its usual water; 11% built over; KSPCB class E; works under way	E	9 ±6 n6 M	76 ±6 n6 M	algae-rich water 0.11 ±0.05 n6 M	E	works underway	M
30	Kalkere Lake BBMP - East - 49.2 ha (122 acres)	Co-fund 89% covered by vegetation; holds 6% of its usual water; heavy algae on the open water; KSPCB class E; budget line on record	E	6 ±6 n7 M	89 ±6 n7 M	heavy algae 0.23 ±0.14 n7 L	E	proposed	L
31	Kacharakanahalli BBMP - North - 6.0 ha (14.9 acres)	Co-fund Holds 15% of its usual water; built over; works under way	E	2 ±6 n6 M	2 ±6 n6 M	algae-rich water 0.10 ±0.08 n4 L		works underway	L
32	Bellanduru Lake BDA - East - 316.8 ha (783 acres)	Co-fund 64% covered by vegetation; holds 9% of its usual water; KSPCB class E; works under way	E	6 ±2 n4 M	64 ±3 n4 M	algae-rich water 0.12 ±0.02 n4 M	E	works underway	M
33	Varthur Lake BDA - East - 155.0 ha (383 acres)	Co-fund 61% covered by vegetation; holds 26% of its usual water; KSPCB class D; works under way	E	21 ±6 n5 M	61 ±6 n5 M	algae-rich water 0.14 ±0.02 n5 M	D	works underway	M
34	Sompura Govt.lake BBMP - South - 7.3 ha (18.1 acres)	Co-fund 49% covered by vegetation; holds 17% of its usual water; 17% built over; KSPCB class D; budget line on record	E	8 ±7 n4 M	49 ±9 n4 M	some algae 0.08 ±0.01 n4 L	D	proposed	L
35	Shivapura Old Lake BBMP - West - 1.7 ha (4.1 acres)	Co-fund 50% covered by vegetation; almost no water this season; built over; KSPCB class D; budget line on record	E	1 ±7 n6 L	50 ±15 n6 M	no open water to read	D	proposed	L
36	Kengeri Lake BBMP - West - 9.8 ha (24.2 acres)	Co-fund 44% covered by vegetation; KSPCB class E; budget line on record	E	25 ±8 n7 M	44 ±8 n7 M	algae-rich water 0.12 ±0.03 n6 L	E	proposed	L
37	Gunjur Palya kere BBMP - East - 12.8 ha (32 acres)	Co-fund 89% covered by vegetation; almost no water this season; budget line on record	E	0 ±5 n6 M	89 ±7 n6 M	no open water to read		proposed	M
38	Ullal Lake BBMP - West - 9.9 ha (24.4 acres)	Co-fund 96% covered by vegetation; almost no water this season; 12% built over; KSPCB class E; budget line on record	E	0 ±5 n6 M	96 ±6 n6 M	no open water to read	E	proposed	M
39	Abbigere Lake BBMP - North - 9.5 ha (23.4 acres)	Co-fund 76% covered by vegetation; holds 15% of its usual water; KSPCB class D; budget line on record	E	11 ±7 n6 M	76 ±8 n6 M	algae-rich water 0.19 ±0.05 n5 L	D	proposed	L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
40	Munekolala Lake BBMP - East - 7.5 ha (18.6 acres)	Co-fund 32% covered by vegetation; holds 39% of its usual water; algal bloom on the open water; froth seen about 26 times a year; KSPCB class E; budget line on record	E	39 ±9 n5 M	32 ±9 n5 M	algal bloom 0.46 ±0.13 n5 L	E	proposed	L
41	Ambalipura Upper Lake BBMP - South - 4.9 ha (12.1 acres)	Co-fund 72% covered by vegetation; holds 6% of its usual water; froth seen about 24 times a year; budget line on record	E	4 ±7 n8 L	72 ±10 n8 M	no open water to read		proposed	L
42	Singapura Lake BBMP - North - 3.1 ha (7.6 acres)	Co-fund Holds 6% of its usual water; KSPCB class E; budget line on record	E	6 ±8 n5 L	27 ±11 n5 M	no open water to read	E	proposed	L
43	Ambalipura Lower Lake BBMP - South - 2.2 ha (5.4 acres)	Co-fund 64% covered by vegetation; holds 17% of its usual water; heavy algae on the open water; KSPCB class E; budget line on record	E	10 ±10 n8 L	64 ±13 n8 M	heavy algae 0.29 ±0.10 n5 L	E	proposed	L
44	Carmelaram Lake BBMP - East - 2.1 ha (5.2 acres)	Co-fund 69% covered by vegetation; almost no water this season; works under way	E	0 ±5 n7 L	69 ±13 n7 M	no open water to read		works underway	L
45	Panathur lake BBMP - East - 4.5 ha (11.1 acres)	Co-fund 41% covered by vegetation; holds 33% of its usual water; heavy algae on the open water; KSPCB class E; budget line on record	E	32 ±10 n6 L	41 ±10 n6 M	heavy algae 0.33 ±0.09 n6 L	E	proposed	L
46	Mangammana Palya Kere (ITI Layout Lake) BBMP - South - 4.9 ha (12.2 acres)	Co-fund Holds 11% of its usual water; froth seen about 26 times a year; KSPCB class D; budget line on record	E	11 ±9 n6 L	6 ±8 n6 M	some algae 0.07 ±0.06 n6 L	D	proposed	L
47	Sankey Lake BBMP - West - 14.3 ha (35 acres)	Intervene early getting worse against its own past; no works on record	C	52 ±8 n4 M	15 ±7 n4 M	algae-rich water 0.10 ±0.03 n4 L	D		L
48	Nagaraesh Nagenahalli Lake BBMP - East - 2.2 ha (5.4 acres)	Intervene early getting worse against its own past; no works on record	C	49 ±13 n7 L	3 ±8 n7 M	heavy algae 0.22 ±0.08 n6 L			L
49	Mahadevapura Lake-1 BBMP - East - 29.8 ha (74 acres)	Design first Holds 19% of its usual water; heavy algae on the open water; froth seen about 35 times a year; KSPCB class E; no works on record	E	19 ±7 n7 L	21 ±7 n7 M	heavy algae 0.30 ±0.16 n7 L	E		L
50	Narasappanahalli kere BBMP - West - 17.6 ha (43 acres)	Design first 92% covered by vegetation; almost no water this season; 20% built over; KSPCB class D; no works on record	E	1 ±5 n4 M	92 ±6 n4 M	no open water to read	D		M
51	Hoodi kere BBMP - East - 9.2 ha (22.8 acres)	Design first 84% covered by vegetation; almost no water this season; 18% built over; KSPCB class D; no works on record	E	1 ±6 n12 M	84 ±8 n12 M	algae-rich water 0.11 ±0.04 n5 L	D		L
52	Subrayana Lake BBMP - South - 1.1 ha (2.6 acres)	Design first 100% covered by vegetation; almost no water this season; no works on record; boundary or built-up question	E	0 ±5 n20 I	100 ±5 n20 L	no open water to read			I
53	Garvebhavipalya lake BBMP - South - 7.4 ha (18.3 acres)	Design first 84% covered by vegetation; almost no water this season; 11% built over; no works on record	E	0 ±5 n6 M	84 ±8 n6 M	no open water to read			M

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
54	Vibhuthipura kere (Lal Bahadur Shastri Nagar Lake) BBMP - East - 13.2 ha (33 acres)	Design first 56% covered by vegetation; holds 21% of its usual water; heavy algae on the open water; 11% built over; KSPCB class E; no works on record	E	16 ±7 n9 L	56 ±8 n9 M	heavy algae 0.27 ±0.13 n9 L	E		L
55	Iblur Lake BBMP - South - 6.7 ha (16.6 acres)	Design first Holds 7% of its usual water; froth seen about 32 times a year; KSPCB class D; no works on record	E	6 ±8 n6 L	21 ±10 n6 M	algae-rich water 0.18 ±0.07 n5 L	D		L
56	Kodige Singasandra Lake (Begur Kere) BBMP - South - 3.1 ha (7.7 acres)	Design first 85% covered by vegetation; almost no water this season; KSPCB class D; no works on record	E	0 ±5 n7 L	85 ±10 n7 M	no open water to read	D		L
57	Halagevader Halli Lake BBMP - West - 2.9 ha (7.1 acres)	Design first 61% covered by vegetation; holds 26% of its usual water; 14% built over; no works on record	E	16 ±10 n7 L	61 ±12 n7 M	some algae 0.05 ±0.03 n6 L			L
58	Konanakunte Lake BBMP - South - 2.0 ha (5.0 acres)	Design first 96% covered by vegetation; holds 6% of its usual water; 30% built over; no works on record; boundary or built-up question	E	2 ±7 n6 L	96 ±8 n6 M	no open water to read			L
59	Vasanthapura Kere / Janardhana Kere BBMP - South - 1.8 ha (4.5 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n4 L	98 ±8 n4 M	no open water to read			L
60	B Channasandra Lake BBMP - Central - 1.7 ha (4.2 acres)	Design first 96% covered by vegetation; almost no water this season; built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	96 ±9 n6 M	no open water to read			L
61	Garudacharpalya Lake BBMP - East - 1.7 ha (4.2 acres)	Design first Holds 32% of its usual water; froth seen about 12 times a year; KSPCB class E; no works on record; boundary or built-up question	E	27 ±15 n9 L	20 ±14 n9 L	some algae 0.09 ±0.11 n7 L	E		L
62	Chikka Kammanahalli BBMP - South - 1.4 ha (3.6 acres)	Design first 100% covered by vegetation; almost no water this season; no works on record; boundary or built-up question	E	0 ±5 n7 L	100 ±5 n7 L	no open water to read			L
63	Uttarahalli Lake BBMP - South - 4.4 ha (10.9 acres)	Design first 57% covered by vegetation; holds 26% of its usual water; heavy algae on the open water; 19% built over; KSPCB class E; no works on record	E	23 ±10 n7 L	57 ±10 n7 M	heavy algae 0.20 ±0.10 n7 L	E		L
64	Beratena Agrahara Lake BBMP - South - 2.7 ha (6.7 acres)	Design first 52% covered by vegetation; almost no water this season; built over; no works on record; boundary or built-up question	E	0 ±6 n10 L	52 ±12 n10 M	no open water to read			L
65	Gubbalala Kere BBMP - South - 2.0 ha (4.9 acres)	Design first 93% covered by vegetation; almost no water this season; 17% built over; KSPCB class E; no works on record	E	0 ±5 n5 L	93 ±9 n5 M	no open water to read	E		L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
66	Lingadeeranahalli BBMP - South - 1.8 ha (4.3 acres)	Design first 98% covered by vegetation; almost no water this season; 32% built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	98 ±7 n6 M	no open water to read			L
67	Kembathahali kere BBMP - South - 1.7 ha (4.3 acres)	Design first 51% covered by vegetation; almost no water this season; 49% built over; KSPCB class D; no works on record; boundary or built-up question	E	3 ±8 n5 L	51 ±15 n5 M	no open water to read		D	L
68	Pattangere / Kenchenahalli lake (Kenchanahalli Lake) BBMP - West - 1.6 ha (3.8 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n7 L	99 ±7 n7 L	no open water to read			L
69	Chokkanahalli Lake BBMP - North - 0.9 ha (2.2 acres)	Design first 35% covered by vegetation; almost no water this season; froth seen about 37 times a year; budget line on record; boundary or built-up question	E	4 ±13 n8 l	35 ±26 n8 L	no open water to read		proposed	I
70	Mestripalya Lake BBMP - South - 2.3 ha (5.7 acres)	Design first 99% covered by vegetation; almost no water this season; 69% built over; no works on record; boundary or built-up question	E	0 ±5 n6 L	99 ±7 n6 M	no open water to read			L
71	Chikkalasandra lake BBMP - South - 2.2 ha (5.4 acres)	Design first No open water seen since 2017; no works on record	E	0 ±5 n9 L	62 ±13 n9 M	no open water to read			L
72	Bheemanakatte Lake BBMP - West - 1.0 ha (2.5 acres)	Design first 64% covered by vegetation; holds 28% of its usual water; froth seen about 14 times a year; no works on record; boundary or built-up question	E	8 ±13 n6 l	64 ±19 n6 L	no open water to read			I
73	Vishwaneedam Lake Bangalore North (Herohalli Thotadakere) BBMP - West - 0.9 ha (2.3 acres)	Design first 76% covered by vegetation; almost no water this season; no works on record; boundary or built-up question	E	0 ±5 n5 l	76 ±18 n5 L	no open water to read			I
74	Panathur Chikka Kere BBMP - East - 0.9 ha (2.3 acres)	Design first Holds 17% of its usual water; KSPCB class E; no works on record; boundary or built-up question	E	14 ±14 n6 l	19 ±15 n6 L	algae-rich water 0.14 ±0.06 n4 l		E	I
75	Junnasandra lake BBMP - South - 0.8 ha (2.0 acres)	Design first Almost no water this season; froth seen about 35 times a year; no works on record; boundary or built-up question	E	2 ±12 n9 l	0 ±5 n9 l	no open water to read			I
76	Srigandakaval Lake BBMP - West - 0.6 ha (1.5 acres)	Design first 96% covered by vegetation; almost no water this season; no works on record; boundary or built-up question	E	0 ±5 n6 l	96 ±12 n6 L	no open water to read			I
77	Jogi kere BBMP - South - 0.6 ha (1.4 acres)	Design first 62% covered by vegetation; holds 10% of its usual water; no works on record; boundary or built-up question	E	4 ±13 n4 l	62 ±23 n4 L	no open water to read			I

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
78	Venkateshapura Lake BBMP - North - 0.5 ha (1.1 acres)	Design first 74% covered by vegetation; almost no water this season; no works on record; boundary or built-up question	E	0 ±5 n7 l	74 ±25 n7 L	no open water to read			I
79	Kalyanikunte (Near Saibaba Temple) (Vasantapura Temple Kalyani) BBMP - South - 0.4 ha (1.1 acres)	Design first Holds 12% of its usual water; froth seen about 14 times a year; no works on record; boundary or built-up question	E	9 ±18 n6 l	24 ±24 n6 L	no open water to read			I
80	Shivanahalli Lake BBMP - North - 0.4 ha (1.1 acres)	Design first Almost no water this season; froth seen about 36 times a year; no works on record; boundary or built-up question	E	2 ±12 n7 l	0 ±5 n7 l	no open water to read			I
81	Chikka Begur Lake BBMP - South - 9.8 ha (24.3 acres)	Design first No open water seen since 2017; budget line on record	D	0 ±5 n7 L	81 ±8 n7 M	no open water to read		proposed	L
82	Pattandur aghara lake-124 BBMP - East - 4.5 ha (11.2 acres)	Design first No open water seen since 2017; no works on record	D	0 ±5 n8 L	92 ±8 n8 M	no open water to read			L
83	Kodigehalli lake BBMP - outside the 2025 ward layer - 3.3 ha (8.1 acres)	Design first 38% covered by vegetation; holds 49% of its usual water; 18% built over; no works on record	D	25 ±11 n7 L	38 ±11 n7 M	algae-rich water 0.18 ±0.12 n5 L			L
84	Garudachar Palya (Goshala) Lake (Goshala Lake) BBMP - East - 2.7 ha (6.6 acres)	Design first Holds 34% of its usual water; heavy algae on the open water; froth seen about 23 times a year; KSPCB class D; no works on record; boundary or built-up question	D	31 ±14 n8 L	12 ±11 n8 M	heavy algae 0.29 ±0.14 n7 L	D		L
85	Manganahalli Lake BBMP - outside the 2025 ward layer - 1.1 ha (2.8 acres)	Design first 54% covered by vegetation; holds 31% of its usual water; no works on record; boundary or built-up question	D	18 ±15 n5 l	54 ±17 n5 L	no open water to read			I
86	Mallasandra Lake BBMP - North - 4.4 ha (10.9 acres)	Design first No open water seen since 2017; no works on record	D	0 ±5 n6 L	100 ±5 n6 M	no open water to read			L
87	Bagalagunte Lake BBMP - North - 3.0 ha (7.4 acres)	Design first 52% covered by vegetation; holds 42% of its usual water; 18% built over; no works on record	D	23 ±11 n8 L	52 ±12 n8 M	algae-rich water 0.12 ±0.04 n6 L			L
88	Gunjuru Lake BBMP - East - 20.6 ha (51 acres)	Design first 35% covered by vegetation; almost no water this season; works under way	C	0 ±5 n10 M	35 ±7 n10 M	some algae 0.09 ±0.03 n4 L		works underway	L
89	Nelagadiranahalli Hosakere BBMP - West - 5.9 ha (14.5 acres)	Design first Holds 5% of its usual water; budget line on record	C	4 ±7 n6 M	23 ±9 n6 M	no open water to read		proposed	M
90	Chikkabettahalli Lake BBMP - North - 2.0 ha (5.0 acres)	Design first Almost no water this season; no works on record	C	0 ±6 n6 L	29 ±13 n6 M	no open water to read			L
91	Vaderahalli BBMP - outside the 2025 ward layer - 2.4 ha (6.0 acres)	Design first Holds 28% of its usual water; 11% built over; no works on record	C	16 ±11 n6 L	23 ±11 n6 M	algae-rich water 0.19 ±0.05 n6 L			L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
92	Swarnakunte Gudda Kere (Chandrasekhar Layout Lake) BBMP - South - 1.6 ha (3.8 acres)	Design first 38% covered by vegetation; almost no water this season; no works on record	C	1 ±7 n19 L	38 ±15 n19 M	algae-rich water 0.14 ±0.07 n7 L			L
93	Bande Mahadevapura kere BBMP - East - 1.6 ha (4.0 acres)	Design first Holds 27% of its usual water; froth seen about 7 times a year; no works on record; boundary or built-up question	C	26 ±16 n8 L	12 ±14 n8 L	algae-rich water 0.13 ±0.04 n7 L			I
94	Sadaramangala Lake BBMP - East - 0.1 ha (0.2 acres)	Design first No open water seen since 2017; no works on record	C	insufficient	insufficient	no open water to read	E		I
95	Mylasandra (Sunnakallu palya) lake BBMP - West - 0.7 ha (1.8 acres)	Design first No open water seen since 2017; no works on record	C	0 ±5 n5 L	62 ±54 n5 L	no open water to read			I
96	Srinivasapura Lake BBMP - North - 0.3 ha (0.8 acres)	Design first No open water seen since 2017; no works on record	C	2 ±14 n5 L	1 ±13 n5 L	no open water to read			I
97	Hebbal Lake Forest Department - North - 46.6 ha (115 acres)	Design first Almost no water this season; budget line on record	B	2 ±5 n5 M	18 ±6 n5 M	algae-rich water 0.13 ±0.07 n4 L		proposed	L
98	Chikka Bellanduru Lake BBMP - East - 20.1 ha (50 acres)	Design first Almost no water this season; budget line on record	B	0 ±5 n8 M	12 ±7 n8 M	no open water to read		proposed	M
99	Nagawara Lake Forest Department - North - 30.3 ha (75 acres)	Design first Holds 18% of its usual water; budget line on record	B	13 ±6 n7 M	16 ±6 n7 M	some algae 0.07 ±0.01 n7 L		proposed	L
100	B. Channasandra BBMP - East - 2.9 ha (7.2 acres)	Design first No open water seen since 2017; no works on record	B	0 ±5 n8 L	95 ±8 n8 M	no open water to read			L
101	Ramagondanahalli Lake BBMP - outside the 2025 ward layer - 11.3 ha (28 acres)	Design first Holds 23% of its usual water; no works on record	A	19 ±7 n6 M	2 ±6 n6 M	some algae 0.05 ±0.02 n6 L			L
102	Kundalahalli Lake BBMP - East - 11.4 ha (28 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	48 ±9 n8 M	19 ±8 n8 M	heavy algae 0.36 ±0.07 n8 L	D		L
103	Nallurahalli Lake BBMP - East - 9.4 ha (23.3 acres)	Watch / verify 52% covered by vegetation; one warning sign, to be checked	C	37 ±8 n9 M	52 ±9 n9 M	algae-rich water 0.14 ±0.08 n9 L	D		L
104	Dore Kere BBMP - South - 9.1 ha (22.5 acres)	Watch / verify 48% covered by vegetation; one warning sign, to be checked	C	45 ±9 n6 M	48 ±9 n6 M	heavy algae 0.23 ±0.18 n6 L	D	proposed	L
105	Madiwala Lake Forest Department - South - 91.0 ha (225 acres)	Watch / verify 55% covered by vegetation; one warning sign, to be checked	C	29 ±6 n4 M	55 ±6 n4 M	algae-rich water 0.10 ±0.07 n4 L	D		L
106	Begur Lake BBMP - South - 43.3 ha (107 acres)	Watch / verify 42% covered by vegetation; one warning sign, to be checked	C	53 ±7 n17 M	42 ±7 n17 M	heavy algae 0.26 ±0.09 n17 L	D		L
107	Bheemanakuppa Lake BBMP - outside the 2025 ward layer - 39.8 ha (98 acres)	Watch / verify steady; keep watching	C	58 ±7 n7 M	22 ±6 n7 M	algae-rich water 0.10 ±0.04 n7 L			L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
108	Chikkabanavara lake BDA - outside the 2025 ward layer - 33.9 ha (84 acres)	Watch / verify steady; keep watching	C	54 ±7 n6 M	37 ±7 n6 M	algae-rich water 0.16 ±0.04 n6 L	D		L
109	Allalasandra lake BBMP - North - 16.0 ha (39 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	59 ±8 n6 M	17 ±7 n6 M	heavy algae 0.21 ±0.11 n6 L	E		L
110	Mallathahalli lake BBMP - West - 13.9 ha (34 acres)	Watch / verify 66% covered by vegetation; one warning sign, to be checked	C	26 ±8 n4 M	66 ±8 n4 M	algae-rich water 0.10 ±0.04 n4 L	D		L
111	Kudlu Anekal & Doddakere (Hosakere) BBMP - South - 13.2 ha (33 acres)	Watch / verify steady; keep watching	C	70 ±8 n9 L	21 ±7 n9 M	algae-rich water 0.20 ±0.13 n9 L	D		L
112	Herohalli Lake Bangalore North BBMP - West - 10.3 ha (25 acres)	Watch / verify steady; keep watching	C	66 ±8 n4 M	30 ±8 n4 M	heavy algae 0.35 ±0.06 n4 L	D		L
113	Haraluru kere BBMP - South - 8.6 ha (21.2 acres)	Watch / verify steady; keep watching	C	68 ±9 n7 M	29 ±8 n7 M	algae-rich water 0.17 ±0.06 n6 L	D		L
114	Doddakannelli Lake BBMP - East - 8.0 ha (19.9 acres)	Watch / verify steady; keep watching	C	58 ±9 n7 M	10 ±7 n7 M	heavy algae 0.28 ±0.10 n7 L	D		L
115	Amruthalli Lake BBMP - North - 7.7 ha (19.1 acres)	Watch / verify 40% covered by vegetation; one warning sign, to be checked	C	30 ±9 n7 M	40 ±9 n7 M	algae-rich water 0.18 ±0.09 n5 L	E		L
116	Kempambudhi Lake BBMP - West - 7.7 ha (19.0 acres)	Watch / verify steady; keep watching	C	71 ±9 n6 M	27 ±9 n6 M	heavy algae 0.36 ±0.16 n6 L	D		L
117	Kowdenahalli lake BBMP - East - 5.9 ha (14.6 acres)	Watch / verify 32% covered by vegetation; one warning sign, to be checked	C	59 ±10 n7 M	32 ±9 n7 M	heavy algae 0.24 ±0.12 n7 L	E		L
118	Kenchanapura Govt. Lake BBMP - outside the 2025 ward layer - 5.0 ha (12.5 acres)	Watch / verify 41% covered by vegetation; one warning sign, to be checked	C	29 ±10 n6 L	41 ±10 n6 M	algae-rich water 0.19 ±0.09 n4 L		proposed	L
119	Horamavu Lake BBMP - East - 5.0 ha (12.5 acres)	Watch / verify steady; keep watching	C	34 ±10 n11 L	19 ±9 n11 M	algae-rich water 0.11 ±0.08 n10 L			L
120	Kommagatta Lake BDA - outside the 2025 ward layer - 11.6 ha (29 acres)	Watch / verify steady; keep watching	C	43 ±8 n8 M	38 ±8 n8 M	algae-rich water 0.13 ±0.10 n6 L			L
121	K R Puram (BEML) / Benniganahalli Lake (Benniganahalli Lake) BBMP - East - 8.0 ha (19.8 acres)	Watch / verify holds 46% of its usual water; one warning sign, to be checked	C	43 ±9 n8 M	17 ±8 n8 M	heavy algae 0.24 ±0.11 n8 L	E		L
122	H Gollahalli kere (Hemmigepura Kere) BBMP - outside the 2025 ward layer - 5.7 ha (14.2 acres)	Watch / verify steady; keep watching	C	49 ±10 n6 M	33 ±10 n6 M	algae-rich water 0.16 ±0.06 n6 L			L
123	Narsipura Lake BBMP - North - 5.5 ha (13.5 acres)	Watch / verify steady; keep watching	C	57 ±11 n9 L	4 ±7 n9 M	algae-rich water 0.11 ±0.03 n9 L	D		L
124	Kothanuru Lake (Krishna Nagara Lake) BBMP - South - 4.6 ha (11.3 acres)	Watch / verify steady; keep watching	C	35 ±10 n6 L	11 ±8 n6 M	algae-rich water 0.13 ±0.06 n6 L	D		L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
125	Dubasi Palya Kere BBMP - West - 4.2 ha (10.4 acres)	Watch / verify 54% covered by vegetation; one warning sign, to be checked	C	31 ±10 n7 L	54 ±11 n7 M	algae-rich water 0.13 ±0.04 n7 L		proposed	L
126	Seetharampalya Lake BBMP - East - 4.1 ha (10.0 acres)	Watch / verify 38% covered by vegetation; one warning sign, to be checked	C	49 ±11 n9 L	38 ±10 n9 M	heavy algae 0.39 ±0.18 n9 L	E		L
127	Andrahalli Lake BBMP - West - 3.7 ha (9.1 acres)	Watch / verify holds 50% of its usual water; one warning sign, to be checked	C	46 ±11 n5 L	24 ±10 n5 M	some algae 0.08 ±0.04 n5 L	E		L
128	Subedharana Lake BBMP - South - 3.6 ha (9.0 acres)	Watch / verify 47% covered by vegetation; one warning sign, to be checked	C	40 ±11 n6 L	47 ±11 n6 M	algae-rich water 0.16 ±0.15 n6 L			L
129	Puttenhalli Lake BBMP - South - 3.5 ha (8.6 acres)	Watch / verify steady; keep watching	C	27 ±10 n10 L	36 ±11 n10 M	algae-rich water 0.11 ±0.08 n10 L	D		L
130	Kudlu Chikka Kere (Haraluru Lake) BBMP - South - 3.3 ha (8.2 acres)	Watch / verify steady; keep watching	C	73 ±11 n7 L	23 ±10 n7 M	algae-rich water 0.17 ±0.08 n7 L	D		L
131	Basapura Lake-2 BBMP - South - 2.7 ha (6.7 acres)	Watch / verify steady; keep watching	C	49 ±12 n6 L	25 ±11 n6 M	heavy algae 0.22 ±0.08 n6 L	D		L
132	Singasandra Lake South Bangalore BBMP - South - 2.6 ha (6.4 acres)	Watch / verify holds 42% of its usual water; one warning sign, to be checked	C	38 ±13 n9 L	29 ±12 n9 M	algae-rich water 0.14 ±0.09 n9 L	D		L
133	Basapura Lake-1 BBMP - South - 2.3 ha (5.7 acres)	Watch / verify algal bloom on the open water; one warning sign, to be checked	C	70 ±12 n6 L	30 ±12 n6 M	algal bloom 0.45 ±0.14 n6 L	D		L
134	Ramasandra Lake BDA - outside the 2025 ward layer - 2.0 ha (5.0 acres)	Watch / verify steady; keep watching	C	21 ±12 n6 L	28 ±12 n6 M	heavy algae 0.21 ±0.16 n4 L			L
135	Lakshmipura Lake BBMP - North - 1.9 ha (4.7 acres)	Watch / verify steady; keep watching	C	32 ±14 n5 L	27 ±13 n5 M	heavy algae 0.28 ±0.11 n4 L			L
136	Vijinapura Lake BBMP - East - 1.7 ha (4.3 acres)	Watch / verify 36% covered by vegetation; one warning sign, to be checked	C	56 ±14 n8 L	36 ±14 n8 M	heavy algae 0.25 ±0.17 n8 L	E		L
137	Kalena Agrahara Lake BBMP - South - 1.7 ha (4.2 acres)	Watch / verify steady; keep watching	C	41 ±15 n6 L	14 ±12 n6 M	algae-rich water 0.11 ±0.04 n6 L	D		L
138	B. Narayanapura Lake BBMP - East - 1.2 ha (3.1 acres)	Watch / verify 47% covered by vegetation; one warning sign, to be checked	C	40 ±17 n8 L	47 ±17 n8 L	algae-rich water 0.20 ±0.09 n8 L	D		I
139	Sheelavathana Kere BBMP - East - 4.6 ha (11.3 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	C	59 ±10 n10 L	21 ±9 n10 M	heavy algae 0.21 ±0.15 n10 L	E		L
140	Devasandra lake BBMP - East - 4.3 ha (10.5 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	C	51 ±11 n8 L	16 ±9 n8 M	algae-rich water 0.17 ±0.07 n7 L	E		L
141	Deverabisanahalli Lake BBMP - East - 4.1 ha (10.1 acres)	Watch / verify 31% covered by vegetation; one warning sign, to be checked	C	50 ±11 n6 L	31 ±10 n6 M	algae-rich water 0.14 ±0.05 n6 L	E		L
142	Subramanyapura Lake BBMP - South - 3.8 ha (9.3 acres)	Watch / verify steady; keep watching	C	53 ±11 n4 L	32 ±11 n4 M	heavy algae 0.27 ±0.12 n4 L	D		L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
143	Hoodi Giddanakere Lake (Hoodi Lake) BBMP - East - 3.4 ha (8.5 acres)	Watch / verify works under way	C	29 ±11 n11 L	20 ±10 n11 M	algae-rich water 0.15 ±0.08 n11 L		works underway	L
144	Bhattarahalli Lake BBMP - East - 3.4 ha (8.3 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	C	52 ±11 n11 L	10 ±9 n11 M	algae-rich water 0.12 ±0.09 n10 L	E		L
145	Haralakunte Lake (Somasandra Palya Kere) (Somasundrapalya Lake) BBMP - South - 2.8 ha (7.0 acres)	Watch / verify steady; keep watching	C	69 ±11 n6 L	2 ±7 n6 M	algae-rich water 0.10 ±0.06 n6 L	D		L
146	Byrasandra BBMP - Central - 2.7 ha (6.6 acres)	Watch / verify steady; keep watching	C	65 ±12 n10 L	29 ±11 n10 M	heavy algae 0.24 ±0.12 n10 L	D		L
147	Varanasi Lake (Jimkenahalli Kere) BBMP - East - 2.1 ha (5.3 acres)	Watch / verify holds 32% of its usual water; one warning sign, to be checked	C	26 ±13 n11 L	0 ±5 n11 M	some algae 0.08 ±0.02 n7 L	E		L
148	Nyanappanahalli Lake / Akshayanagara Lake (Akshaynagar Lake) BBMP - South - 1.3 ha (3.3 acres)	Watch / verify steady; keep watching	C	40 ±16 n6 L	40 ±16 n6 L	some algae 0.10 ±0.15 n5 L	D		L
149	Halasuru lake BBMP - Central - 40.0 ha (99 acres)	Watch / verify works under way	B	77 ±6 n7 M	18 ±6 n7 M	heavy algae 0.28 ±0.09 n7 L		works underway	L
150	Ramapura Kere BBMP - outside the 2025 ward layer - 45.3 ha (112 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	B	75 ±6 n4 M	16 ±6 n4 M	heavy algae 0.32 ±0.18 n4 L	E		L
151	Seegehalli Lake BBMP - East - 8.5 ha (21.0 acres)	Watch / verify KSPCB class E; one warning sign, to be checked	B	71 ±9 n9 M	14 ±8 n9 M	algae-rich water 0.14 ±0.15 n9 L	E	proposed	L
152	Palanahalli Lake BBMP - North - 7.3 ha (18.1 acres)	Watch / verify algal bloom on the open water; one warning sign, to be checked	B	73 ±9 n20 M	26 ±9 n20 M	algal bloom 0.47 ±0.12 n20 L			L
153	Basavanapura Kere BBMP - East - 3.9 ha (9.7 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	B	71 ±10 n9 L	20 ±10 n9 M	heavy algae 0.32 ±0.12 n9 L	E		L
154	Medi agraphara BBMP - outside the 2025 ward layer - 1.7 ha (4.3 acres)	Watch / verify holds 46% of its usual water; one warning sign, to be checked	B	29 ±14 n6 L	0 ±6 n6 M	some algae 0.03 ±0.01 n5 L			L
155	Deepanjali Nagara lake BBMP - West - 1.4 ha (3.5 acres)	Watch / verify built over; one warning sign, to be checked	B	51 ±15 n5 L	22 ±14 n5 L	some algae 0.07 ±0.04 n5 L		proposed	L
156	Jakkur Lake BBMP - North - 50.9 ha (126 acres)	Watch / verify heavy algae on the open water; one warning sign, to be checked	A	81 ±6 n5 M	14 ±6 n5 M	heavy algae 0.38 ±0.11 n5 L	E	proposed	L
157	Vengayyana Lake BBMP - East - 14.3 ha (35 acres)	Watch / verify works under way	A	74 ±8 n8 M	9 ±7 n8 M	heavy algae 0.25 ±0.14 n8 L	E	works underway	L
158	Doddabommasandra Lake BBMP - North - 36.2 ha (90 acres)	Maintain in fair shape; upkeep and monitoring	B	64 ±7 n7 M	12 ±6 n7 M	heavy algae 0.26 ±0.14 n7 L			L

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
159	Venkojirao Kere / Agara Kere (Agara Lake) BBMP - South - 29.6 ha (73 acres)	Maintain in fair shape; upkeep and monitoring	B	68 ±7 n7 M	13 ±6 n7 M	algae-rich water 0.19 ±0.07 n7 L	D		L
160	Sarakki Lake BBMP - South - 23.7 ha (59 acres)	Maintain in fair shape; upkeep and monitoring	B	77 ±7 n4 M	10 ±6 n4 M	some algae 0.05 ±0.02 n4 L	D		L
161	Attur lake BBMP - North - 23.7 ha (59 acres)	Maintain in fair shape; upkeep and monitoring	B	76 ±7 n5 M	16 ±7 n5 M	heavy algae 0.32 ±0.06 n5 L			L
162	Gantiganahalli Lake BBMP - North - 20.0 ha (49 acres)	Maintain in fair shape; upkeep and monitoring	B	63 ±7 n17 M	31 ±7 n17 M	heavy algae 0.37 ±0.11 n17 L			L
163	Horamavu Agara Lake BBMP - East - 14.9 ha (37 acres)	Maintain in fair shape; upkeep and monitoring	B	86 ±7 n8 M	11 ±7 n8 M	heavy algae 0.38 ±0.11 n8 L			L
164	Kasavanahalli lake BBMP - South - 13.9 ha (34 acres)	Maintain in fair shape; upkeep and monitoring	B	37 ±8 n7 M	12 ±7 n7 M	some algae 0.06 ±0.02 n6 L	D		L
165	Kaggadasapura BBMP - Central - 12.2 ha (30 acres)	Maintain in fair shape; upkeep and monitoring	B	69 ±8 n8 M	16 ±7 n8 M	heavy algae 0.22 ±0.11 n8 L			L
166	Gottigere BBMP - South - 12.0 ha (30 acres)	Maintain in fair shape; upkeep and monitoring	B	63 ±8 n4 M	10 ±7 n4 M	algae-rich water 0.13 ±0.16 n4 L	D	proposed	L
167	Thirumenahalli Lake BBMP - North - 5.7 ha (14.1 acres)	Maintain in fair shape; upkeep and monitoring	B	54 ±10 n6 M	20 ±9 n6 M	heavy algae 0.24 ±0.13 n5 L			L
168	Doddanekundi lake BBMP - East - 38.1 ha (94 acres)	Maintain in fair shape; upkeep and monitoring	A	84 ±6 n8 M	12 ±6 n8 M	heavy algae 0.35 ±0.12 n8 M	D	proposed	M
169	Sulikere/ Herekere Lake BBMP - outside the 2025 ward layer - 42.2 ha (104 acres)	Maintain in fair shape; upkeep and monitoring	A	65 ±7 n5 M	10 ±6 n5 M	algae-rich water 0.10 ±0.08 n4 L			L
170	Veerasagara lake BBMP - outside the 2025 ward layer - 6.7 ha (16.7 acres)	Maintain in fair shape; upkeep and monitoring	A	37 ±9 n5 M	6 ±7 n5 M	some algae 0.08 ±0.04 n4 L			L
171	Kattigenahalli Lake BBMP - North - 5.7 ha (14.0 acres)	Steward in good shape; protect and monitor	B	43 ±10 n4 M	11 ±8 n4 M	no open water to read			M
172	Konasandra Lake BBMP - West - 10.5 ha (26 acres)	Steward in good shape; protect and monitor	B	64 ±8 n5 M	24 ±8 n5 M	algae-rich water 0.13 ±0.12 n5 L			L
173	Arekere lake BBMP - South - 7.5 ha (18.6 acres)	Steward in good shape; protect and monitor	B	42 ±9 n7 M	16 ±8 n7 M	some algae 0.08 ±0.03 n7 L		proposed	L
174	Anjanapura Lake / nagara Chunchaghatta Kere Alahalli (Avalahalli Lake) BBMP - South - 5.6 ha (13.8 acres)	Steward in good shape; protect and monitor	B	62 ±10 n7 L	12 ±8 n7 M	heavy algae 0.21 ±0.05 n7 L	D		L
175	Agrahara Lake BBMP - North - 4.4 ha (11.0 acres)	Steward in good shape; protect and monitor	B	48 ±10 n6 L	14 ±9 n6 M	heavy algae 0.25 ±0.11 n5 L			L
176	Yelenahalli Lake BBMP - South - 1.2 ha (3.0 acres)	Steward in good shape; protect and monitor	B	52 ±17 n7 I	10 ±12 n7 L	some algae 0.06 ±0.02 n7 I	D		I

#	Lake	Need class and why	Condition	Open water	Vegetation cover	Algae in the water	KSPCB class	Programme on record	Conf.
177	Doddkammanahalli Lake BBMP - South - 4.9 ha (12.2 acres)	Steward in good shape; protect and monitor	B	57 ±10 n5 L	4 ±7 n5 M	algae-rich water 0.18 ±0.08 n5 L	D		L
178	Gowdana Kere BBMP - South - 2.5 ha (6.1 acres)	Steward in good shape; protect and monitor	B	49 ±12 n6 L	10 ±9 n6 M	heavy algae 0.27 ±0.12 n6 L			L
179	Thalaghattapura Lake BBMP - South - 4.1 ha (10.1 acres)	Steward in good shape; protect and monitor	A	57 ±11 n6 L	38 ±11 n6 M	algae-rich water 0.19 ±0.10 n5 L			L
180	Nagarabhavi Lake BBMP - West - 0.9 ha (2.2 acres)	Steward in good shape; protect and monitor	A	56 ±19 n6 I	7 ±12 n6 L	some algae 0.03 ±0.05 n6 I			I

1. Yelahanka Amani kere


Listed as Yelahanka Amani kere (BBMP); North corporation, Aerocity ward; footprint 98.6 ha (244 acres); reading window pre-monsoon (Mar-May) 2026, 18 clear passes.

Fund now. Algal bloom on the open water; KSPCB class E; no works on record.

What the satellite shows. Open water over 95% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.


What the money buys: nutrient control at the inlets and in-lake aeration.

Open water (share of footprint)	95% ± 5 (n 18, M)
Vegetation cover (mats, reeds, scum)	4% ± 5 (n 18, M)
Exposed bed	1% ± 5 (n 18, M)
Algae in the water (chlorophyll proxy)	algal bloom: 0.42 ± 0.07 (n 18, M)
Algae against its own history	98th percentile of its 2017-2025 pre-monsoon record (n 107)
Vegetation against its own history	25th percentile of its 2017-2025 pre-monsoon record (n 107)
Share of its usual water held	97% ± 6 (n 18, M)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 2.8 mg/l, BOD 12 mg/l, turbidity 24 NTU
Programme on record	none
Drainage chain	position 5 in its chain, 0 listed lakes downstream; 7,186 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



1.9 km across
Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

2. Puttenahalli Lake


Listed as Puttenahalli Lake (Forest Department); North corporation, Doddabettahalli ward; footprint 8.7 ha (21.6 acres); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 100% covered by vegetation; almost no water this season; KSPCB class E; no works on record.

What the satellite shows. Vegetation covers 100% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.


What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	100% ± 5 (n 5, M)
Exposed bed	0% ± 5 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	96th percentile of its 2019-2025 monsoon record (n 38)
Share of its usual water held	0% ± 9 (n 5, M)
Built share inside the footprint (2026)	0% (-38 points since 2019)
Froth passes per year (lower bound)	2023: 1
KSPCB, June 2026	Class E; DO 2.4 mg/l, BOD 8 mg/l, turbidity 12 NTU
Programme on record	none
Drainage chain	position 4 in its chain, 1 listed lakes downstream; 5,562 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

3. Doddakalasandra Lake


Listed as Doddakallasandra Lake (BBMP); South corporation, Anjanapura ward; footprint 5.8 ha (14.4 acres); reading window pre-monsoon (Mar-May) 2026, 18 clear passes.

Fund now. 99% covered by vegetation; almost no water this season; KSPCB class D; no works on record.


What the satellite shows. Vegetation covers 99% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is D.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 18, M)
Vegetation cover (mats, reeds, scum)	99% ± 6 (n 18, M)
Exposed bed	1% ± 6 (n 18, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	95th percentile of its 2017-2025 pre-monsoon record (n 104)
Share of its usual water held	0% ± 7 (n 18, M)
Built share inside the footprint (2026)	3% (+0 points since 2019)
Froth passes per year (lower bound)	2022: 1, 2023: 1, 2024: 1
KSPCB, June 2026	Class D; DO 4.8 mg/l, BOD 8 mg/l, turbidity 27.5 NTU
Programme on record	none
Drainage chain	position 2 in its chain, 2 listed lakes downstream; 2,105 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

4. Kannalli kere


Listed as Kanna halli lake (BBMP); outside the 2025 ward layer corporation; footprint 22.5 ha (56 acres); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 93% covered by vegetation; almost no water this season; KSPCB class E; no works on record.

What the satellite shows. Vegetation covers 93% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.


What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	93% ± 6 (n 5, M)
Exposed bed	5% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	78th percentile of its 2019-2025 monsoon record (n 27)
Share of its usual water held	0% ± 9 (n 5, M)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 0.5 mg/l, BOD 35 mg/l, turbidity 24.6 NTU
Programme on record	none
Drainage chain	position 3 in its chain, 2 listed lakes downstream; 7,158 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

5. Hosakerahalli Lake


Listed as Hoskerehalli Lake (BBMP); West corporation, Bangarappa Nagara ward; footprint 15.0 ha (37 acres); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 91% covered by vegetation; holds 20% of its usual water; KSPCB class E; no works on record.

What the satellite shows. Vegetation covers 91% of the lake in the reading window, with open water at 2%; KSPCB's June 2026 class is E.


What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	2% ± 6 (n 5, M)
Vegetation cover (mats, reeds, scum)	91% ± 7 (n 5, M)
Exposed bed	4% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	20th percentile of its 2019-2025 monsoon record (n 25)
Share of its usual water held	20% ± 62 (n 5, M)
Built share inside the footprint (2026)	3% (-6 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 1 mg/l, BOD 27 mg/l, turbidity 18.6 NTU
Programme on record	none
Drainage chain	position 2 in its chain, 0 listed lakes downstream; 30,273 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

6. Rachenahalli Lake


Listed as Rachenahalli Lake (BBMP); North corporation, Jakkur ward; footprint 37.1 ha (92 acres); reading window monsoon (Jun-Sep) 2026, 6 clear passes.

Fund now. Algal bloom on the open water; KSPCB class E; no works on record.

What the satellite shows. Open water over 85% of the footprint; algal bloom on the open water; KSPCB's June 2026 class is E.


What the money buys: nutrient control at the inlets and in-lake aeration.

Open water (share of footprint)	85% ± 6 (n 6, M)
Vegetation cover (mats, reeds, scum)	14% ± 6 (n 6, M)
Exposed bed	1% ± 5 (n 6, M)
Algae in the water (chlorophyll proxy)	algal bloom: 0.44 ± 0.11 (n 6, L)
Algae against its own history	75th percentile of its 2020-2025 monsoon record (n 32)
Vegetation against its own history	69th percentile of its 2020-2025 monsoon record (n 32)
Share of its usual water held	89% ± 6 (n 6, M)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 2 mg/l, BOD 8 mg/l, turbidity 10 NTU
Programme on record	none
Drainage chain	position 5 in its chain, 0 listed lakes downstream; 11,338 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

7. Saul Kere


Listed as Sowl kere (BBMP); East corporation, Shivanasamudra Ward ward; footprint 18.2 ha (45 acres); reading window monsoon (Jun-Sep) 2026, 7 clear passes.

Fund now. 73% covered by vegetation; holds 17% of its usual water; no works on record.


What the satellite shows. Vegetation covers 73% of the lake in the reading window, with open water at 13%.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	13% ± 7 (n 7, M)
Vegetation cover (mats, reeds, scum)	73% ± 7 (n 7, M)
Exposed bed	14% ± 7 (n 7, M)
Algae in the water (chlorophyll proxy)	algae-rich water: 0.20 ± 0.16 (n 7, L)
Algae against its own history	71th percentile of its 2019-2025 monsoon record (n 24)
Vegetation against its own history	48th percentile of its 2019-2025 monsoon record (n 27)
Share of its usual water held	17% ± 9 (n 7, M)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	2026: 1
KSPCB, June 2026	no station joined
Programme on record	none
Drainage chain	position 6 in its chain, 1 listed lakes downstream; 5,863 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

8. J.P Park (Mathikere Lake)


Listed as ,ward no 154 J.P Park / Bangalore North (BBMP); North corporation, J.P PARK ward; footprint 4.6 ha (11.5 acres); reading window monsoon (Jun-Sep) 2026, 6 clear passes.

Fund now. 84% covered by vegetation; almost no water this season; froth seen about 8 times a year; KSPCB class D; no works on record.

What the satellite shows. Vegetation covers 84% of the lake in the reading window, with open water at 2%; froth on 25 clear passes since 2024; KSPCB's June 2026 class is D.


What the money buys: weed and mat removal with inflow control so it does not regrow; surfactant and sewage control upstream of the weir.

Open water (share of footprint)	2% ± 7 (n 6, L)
Vegetation cover (mats, reeds, scum)	84% ± 10 (n 6, M)
Exposed bed	14% ± 9 (n 6, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	100th percentile of its 2019-2025 monsoon record (n 33)
Share of its usual water held	2% ± 10 (n 6, L)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	2022: 21, 2023: 11, 2024: 11, 2025: 14
KSPCB, June 2026	Class D; DO 4.2 mg/l, BOD 5 mg/l, turbidity 10 NTU
Programme on record	none
Drainage chain	position 2 in its chain, 0 listed lakes downstream; 9,374 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

9. Parappana Agrahara


Listed as Parappana Agrahara / Bangalore (BBMP); South corporation, Naganathapura ward; footprint 4.6 ha (11.4 acres); reading window monsoon (Jun-Sep) 2026, 4 clear passes.

Fund now. 100% covered by vegetation; almost no water this season; KSPCB class D; no works on record.


What the satellite shows. Vegetation covers 100% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is D.

What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 4, L)
Vegetation cover (mats, reeds, scum)	100% ± 5 (n 4, M)
Exposed bed	0% ± 5 (n 4, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	100th percentile of its 2020-2025 monsoon record (n 29)
Share of its usual water held	0% ± 6 (n 4, L)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	2023: 1, 2024: 1
KSPCB, June 2026	Class D; DO 5.2 mg/l, BOD 6 mg/l, turbidity 34.9 NTU
Programme on record	none
Drainage chain	position 1 in its chain, 7 listed lakes downstream; 2,174 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Surface composition, monthly medians 2019 to date



Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.

10. Gangondanahalli Lake


Listed as Gangondanahalli Lake (BBMP); outside the 2025 ward layer corporation; footprint 15.6 ha (39 acres); reading window monsoon (Jun-Sep) 2026, 5 clear passes.

Fund now. 99% covered by vegetation; almost no water this season; KSPCB class E; no works on record.

What the satellite shows. Vegetation covers 99% of the lake in the reading window, with open water at 0%; KSPCB's June 2026 class is E.


What the money buys: weed and mat removal with inflow control so it does not regrow.

Open water (share of footprint)	0% ± 5 (n 5, M)
Vegetation cover (mats, reeds, scum)	99% ± 6 (n 5, M)
Exposed bed	1% ± 6 (n 5, M)
Algae in the water (chlorophyll proxy)	no open water to read
Algae against its own history	no baseline yet
Vegetation against its own history	66th percentile of its 2019-2025 monsoon record (n 29)
Share of its usual water held	0% ± 18 (n 5, M)
Built share inside the footprint (2026)	0% (+0 points since 2019)
Froth passes per year (lower bound)	none recorded
KSPCB, June 2026	Class E; DO 0.7 mg/l, BOD 90 mg/l, turbidity 5.7 NTU
Programme on record	none
Drainage chain	position 3 in its chain, 0 listed lakes downstream; 4,392 buildings in the catchment
Boundary	mapped boundary and observed water, confidence medium



Fixed footprint: the mapped boundary united with the observed water extent since 2017. All condition inputs for this lake are in the appendix.

Surface composition, monthly medians 2019 to date




Open water, vegetation cover and the rest, per month; a month with fewer than two clear passes is a gap.


What continuous monitoring looks like

Three lakes, monthly medians of the surface composition from 2019 (a month with fewer than two clear passes is a gap, not a value). The monsoon months are thin on every lake, which is what an honest optical record looks like.


Bellandur (BDA)



Varthur (BDA)




Jakkur (BBMP)




Surface classes per pass: open water, vegetation cover (floating mats, reeds along the margins, surface scum; a reed fringe is healthy, a hyacinth mat is not, and the split is a coming refinement), froth, and exposed bed. Sentinel-2, 10 m.

Ulsoor, November 2025 to August 2026




Open-water share of the footprint per clear pass. The lake was drained from February 2026 for its NDMF desilting works; the series will show the refill.

Coverage, 2019 to date



Median clear passes per lake per month. The monsoon gap is reported, never filled; the archive over Bengaluru is dense from 2019.



Assessed lakes with an algae reading: vegetation cover against algae in the water, reading window medians. Two groups: mat-covered lakes and bloom-prone open lakes; both are eutrophication, with different measures.

Confidence

Assessed lakes by the weakest of their open-water, vegetation and chlorophyll readings: insufficient 19, low 142, medium 19.

A confidence class is the weakest of six components: pixels inside the lake after the shoreline ring, the share of the lake close to shore, clear passes in the window, the length of the lake's own record, validation of the surface classes on the lake's type, and the boundary's provenance. High needs every component High, which a 10 m sensor cannot give a lake under about 20 ha and a mapped boundary cannot give any lake; Medium is the ceiling for the large lakes until a surveyed boundary and field calibration exist. The monsoon window also thins the clear passes; the post-monsoon edition will lift the pass component for most lakes.

Method, in brief

Universe. The Karnataka Tank Conservation and Development Authority custody lists for Bengaluru (BBMP, BDA, Forest Department, BMRCL): 210 lakes, each joined to a mapped boundary, the BBMP Lake Management System point, the 2025 ward and corporation, Neer Vazhvu's drainage-network layer, the regulator's June 2026 station, and the programme rows on record.

Sensor. Copernicus Sentinel-2 (10 m, a pass every two to three days over Bengaluru), every scene from March 2017 to the reading date, cloud-masked pixel by pixel; observed passes only, nothing interpolated.

Per lake, per pass. A fixed footprint (the mapped boundary united with the observed water extent); the share of the footprint reading as open water, vegetation (mats and emergent growth), froth and exposed bed; and on the open water, relative indices for chlorophyll, turbidity, coloured organic matter and apparent colour. These are relative readings: comparable across lakes and years, not concentrations.

Per lake, per window. Seasonal medians with their spread, percentile against the lake's own same-season history, water area and share of the observed maximum, froth events per year, built share inside the footprint, and the confidence class. Health Card bands are assigned only where the band is wider than the error.

Need class and order. Neer Vazhvu's published rules over four axes (Condition, Stakes, Tractability, Urgency) with the programme on record; lakes are ordered within the city as the funding unit. The full method, error model and rule set are in the Neer Vazhvu methodology note, available on request.

Unassessed at 10 m (30)

Listed with the reason. A traced boundary or a sub-metre image moves a lake into the assessed set.

Lake	Reason
Siddapura Lake BBMP -	no usable boundary at 10 m; location known
Gangashetty Lake BBMP -	no usable boundary at 10 m; location known; KSPCB samples at its station 'Gangashetty Lake' at 13.00502, 77.693716 (Class E, June 2026)
Puttenahalli / Byraweshwara BBMP -	no usable boundary at 10 m; location known
Lingadeeranahalli (handrahalli) North Lake Bangalore North BBMP -	no usable boundary at 10 m; location known
Chikkabasthi lake BBMP -	no usable boundary at 10 m; location known
Gandhinagar Hosakerehalli BBMP -	no usable boundary at 10 m; location known
Varahasandra Lake BBMP -	no usable boundary at 10 m; location known
Gattigerepalya (Sompura) lake BBMP -	no usable boundary at 10 m; location known
Chikkagowdanapalya lake BBMP -	no usable boundary at 10 m; location known
Busegowdana lake BBMP -	no usable boundary at 10 m; location known
Bayyapanapalya Kunte BBMP -	no usable boundary at 10 m; location known
Narasipura Lake 26 BBMP -	no usable boundary at 10 m; location known
(Nagasandra) BBMP -	no usable boundary at 10 m; no location known
19 Malagala BBMP -	no usable boundary at 10 m; no location known
Byatagunte Playa BBMP -	no usable boundary at 10 m; no location known
Lingarajapura Lake BBMP -	no usable boundary at 10 m; no location known
Geddalahalli BBMP -	no usable boundary at 10 m; no location known
Konena Agrahara BBMP -	no usable boundary at 10 m; location known
(Lingannana Bilaekahalli Kere) (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Dorasanni Palya (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Ittmadu BBMP -	no usable boundary at 10 m; no location known
Thavarekare BBMP -	no usable boundary at 10 m; no location known
Karisandra lake BBMP -	no usable boundary at 10 m; no location known
Nandi shettappa lake BBMP -	no usable boundary at 10 m; no location known
Arehalli 2 & 3 (Small tanks) (Disused lake) BBMP -	no usable boundary at 10 m; no location known
Bovimaranahalli BBMP -	no usable boundary at 10 m; no location known
Gundopanth lake BBMP -	no usable boundary at 10 m; no location known
Kamakshipalya Lake BBMP -	no usable boundary at 10 m; no location known
Sanegoravanahalli Lake BBMP -	no usable boundary at 10 m; no location known
Agraharadasarahalli Lake BBMP -	no usable boundary at 10 m; no location known

Appendix: condition inputs per lake

C1 share of observed extent held, C3 built share, C4 vegetation cover, C5 chlorophyll proxy, C8 froth events per year, G2 the regulator's class; a band followed by candidates in brackets, such as D(C/D), means the error band straddles a boundary and the value's band is shown with both candidates.

#	Lake	Condition	Inputs	Notes
1	Yelahanka Amani kere	E	C1=A C3=A(A/B) C4=A C5=E(D/E) C8=A G2=E	C3 candidates A/B; C5 candidates D/E
2	Puttenahalli Lake	E	C1=E C3=A(A/B) C4=E C8=A G2=E	C3 candidates A/B
3	Doddakalasandra Lake	E	C1=E C3=B(A/B) C4=E C8=B G2=D	C3 candidates A/B
4	Kannalli kere	E	C1=E C3=A(A/B) C4=E C8=A G2=E	C3 candidates A/B
5	Hosakerahalli Lake	E	C1=E(B/E) C3=B(B/C) C4=E C8=A G2=E	C1 candidates B/E; C3 candidates B/C
6	Rachenahalli Lake	E	C1=A(A/B) C3=A(A/B) C4=B(A/B/C) C5=E(D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates D/E
7	Saul Kere	E	C1=E C3=A(A/B) C4=E C5=C(B/C/D) C8=A	C3 candidates A/B; C5 candidates B/C/D
8	J.P Park (Mathikere Lake)	E	C1=E C3=A(A/B) C4=E C8=D G2=D	C3 candidates A/B
9	Parappana Agrahara	E	C1=E C3=A(A/B) C4=E C8=A G2=D	C3 candidates A/B
10	Gangondanahalli Lake	E	C1=E C3=A(A/B) C4=E C8=A G2=E	C3 candidates A/B
11	Dasarahalli (Chokkasandra) Lake	E	C1=E C3=C(C/D) C4=C(B/C/D) C8=B G2=E	C3 candidates C/D; C4 candidates B/C/D
12	Kammagondanahalli Lake	E	C1=E C3=A(A/B) C4=E C5=D(D/E) C8=A G2=D	C3 candidates A/B; C5 candidates D/E
13	Byrasandra Melina Kere	E	C1=E(D/E) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=E	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
14	Bhoganahalli Lake	E	C1=E C3=A(A/B) C4=A(A/B) C5=C(C/D) C8=B G2=E	C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
15	Chinnappanahalli	E	C1=C(C/D) C3=A(A/B) C4=D(C/D/E) C5=E(D/E) C8=E G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E
16	Chelekere	E	C1=D(C/D/E) C3=A(A/B) C4=E C5=B(B/C) C8=B G2=E	C1 candidates C/D/E; C3 candidates A/B; C5 candidates B/C
17	Annappanakere / Yelchenahalli Lake (Yelachenahalli Kere)	E	C1=E C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=B G2=D	C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D
18	Basavanapura Pond	E	C1=E C3=A(A/B) C4=E C8=B G2=D	C3 candidates A/B
19	Veerasandra Lake	E	C1=E C3=A(A/B) C4=E C8=E	C3 candidates A/B
20	Avalahalli	E	C1=E C3=B(B/C) C4=E C8=D	C3 candidates B/C
21	Pattandur agrahara -54 Lake	E	C1=E C3=B(A/B) C4=E C8=A G2=D	C3 candidates A/B
22	Devarakere (ISRO Layout Lake)	E	C1=E(D/E) C3=A(A/B) C4=E(D/E) C5=D(C/D) C8=B G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates D/E; C5 candidates C/D
23	Kogilu Lake	D	C1=D(D/E) C3=A(A/B) C4=D(D/E) C8=A G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates D/E
24	Kaikondrahalli Lake	D	C1=D(C/D) C3=B(A/B) C4=B(B/C) C5=D(B/D/E) C8=E G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C; C5 candidates B/D/E
25	Byrasandra Lake	D	C1=D(D/E) C3=A(A/B) C4=B(A/B/C) C5=D(C/D) C8=E	C1 candidates D/E; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D
26	Nayandahalli Lake	D	C1=E(D/E) C3=A(A/B) C4=B(A/B/C) C8=D G2=D	C1 candidates D/E; C3 candidates A/B; C4 candidates A/B/C

#	Lake	Condition	Inputs	Notes
27	Konappana Agrahara Lake (Karabu Kere/Konappana agrahara lake)	D	C1=D(C/D/E) C3=A(A/B) C4=D(B/D/E) C5=D(B/D) C8=B G2=D	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/D/E; C5 candidates B/D
28	Yediyur Lake	D	C1=D(C/D) C3=A(A/B) C4=D(C/D/E) C5=D(C/D/E) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D/E
29	Hulimavu Lake	E	C1=E C3=D(C/D) C4=E C5=C(B/C) C8=A G2=E	C3 candidates C/D; C5 candidates B/C
30	Kalkere Lake	E	C1=E C3=A(A/B) C4=E C5=D(B/D) C8=A G2=E	C3 candidates A/B; C5 candidates B/D
31	Kacharakanahalli	E	C1=E(C/E) C3=E C4=A C5=C(B/C) C8=B	C1 candidates C/E; C5 candidates B/C
32	Bellanduru Lake	E	C1=E C3=A(A/B) C4=E C5=C(B/C) C8=A G2=E	C3 candidates A/B; C5 candidates B/C
33	Varthur Lake	E	C1=E(D/E) C3=A(A/B) C4=E C5=C C8=A G2=D	C1 candidates D/E; C3 candidates A/B
34	Sompura Govt.lake	E	C1=E(D/E) C3=D C4=E C5=B C8=A G2=D	C1 candidates D/E
35	Shivapura Old Lake	E	C1=E C3=E C4=E(D/E) C8=B G2=D	C4 candidates D/E
36	Kengeri Lake	E	C1=A(A/C) C3=A(A/B) C4=E(D/E) C5=C(B/C) C8=A G2=E	C1 candidates A/C; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C
37	Gunjur Palya kere	E	C1=E C3=A(A/B) C4=E C8=B	C3 candidates A/B
38	Ullal Lake	E	C1=E C3=D(C/D) C4=E C8=A G2=E	C3 candidates C/D
39	Abbigere Lake	E	C1=E C3=A(A/B) C4=E C5=C(C/D) C8=A G2=D	C3 candidates A/B; C5 candidates C/D
40	Munekolala Lake	E	C1=D(D/E) C3=B(A/B) C4=D(C/D/E) C5=E(D/E) C8=E G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E
41	Ambalipura Upper Lake	E	C1=E C3=C(B/C) C4=E C8=E	C3 candidates B/C
42	Singapura Lake	E	C1=E C3=A(A/B) C4=C(B/C/D) C8=B G2=E	C3 candidates A/B; C4 candidates B/C/D
43	Ambalipura Lower Lake	E	C1=E(D/E) C3=A(A/B) C4=E C5=D(C/D) C8=A G2=E	C1 candidates D/E; C3 candidates A/B; C5 candidates C/D
44	Carmelaram Lake	E	C1=E C3=A(A/B) C4=E C8=C	C3 candidates A/B
45	Panathur lake	E	C1=D(D/E) C3=A(A/B) C4=E(D/E) C5=D(D/E) C8=B G2=E	C1 candidates D/E; C3 candidates A/B; C4 candidates D/E; C5 candidates D/E
46	Mangamma Palya Kere (ITI Layout Lake)	E	C1=E C3=B(B/C) C4=A(A/B) C5=B(B/C) C8=E G2=D	C3 candidates B/C; C4 candidates A/B; C5 candidates B/C
47	Sankey Lake	C	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
48	Nagaraesh Nagenahalli Lake	C	C1=C(C/D) C3=A(A/B) C4=A(A/B) C5=D(C/D) C8=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
49	Mahadevapura Lake-1	E	C1=E C3=C(C/D) C4=C(B/C) C5=D(C/D/E) C8=E G2=E	C3 candidates C/D; C4 candidates B/C; C5 candidates C/D/E
50	Narasappanahalli kere	E	C1=E C3=D(D/E) C4=E C8=A G2=D	C3 candidates D/E
51	Hoodi kere	E	C1=E C3=D(D/E) C4=E C5=C(B/C) C8=A G2=D	C3 candidates D/E; C5 candidates B/C
52	Subrayana Lake	E	C1=E C4=E C8=A	
53	Garvebhavipalya lake	E	C1=E(D/E) C3=D(C/D) C4=E C8=B	C1 candidates D/E; C3 candidates C/D
54	Vibhuthipura kere (Lal Bahadur Shastri Nagar Lake)	E	C1=E(D/E) C3=D(C/D) C4=E C5=D(C/D) C8=C G2=E	C1 candidates D/E; C3 candidates C/D; C5 candidates C/D
55	Iblur Lake	E	C1=E C3=A(A/B) C4=C(B/C/D) C5=C(C/D) C8=E G2=D	C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D

#	Lake	Condition	Inputs	Notes
56	Kodige Singasandra Lake (Begur Kere)	E	C1=E C3=B(B/C) C4=E C8=B G2=D	C3 candidates B/C
57	Halagevader Halli Lake	E	C1=E(D/E) C3=D C4=E C5=B C8=B	C1 candidates D/E
58	Konanakunte Lake	E	C1=E(D/E) C3=E C4=E C8=B	C1 candidates D/E
59	Vasanthapura Kere / Janardhana Kere	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
60	B Channasandra Lake	E	C1=E(B/E) C3=E C4=E C8=A	C1 candidates B/E
61	Garudacharpalya Lake	E	C1=D(D/E) C4=B(A/B/D) C5=B(A/B/D) C8=E G2=E	C1 candidates D/E; C4 candidates A/B/D; C5 candidates A/B/D
62	Chikka Kammanahalli	E	C1=E C4=E C8=A	
63	Uttarahalli Lake	E	C1=E(D/E) C3=D(D/E) C4=E C5=D(B/D) C8=B G2=E	C1 candidates D/E; C3 candidates D/E; C5 candidates B/D
64	Beratena Agrahara Lake	E	C1=E C3=E C4=E(D/E) C8=C	C4 candidates D/E
65	Gubbalala Kere	E	C1=E C3=D C4=E C8=B G2=E	
66	Lingadeeranahalli	E	C1=E(A/E) C3=E C4=E C8=A	C1 candidates A/E
67	Kembathahali kere	E	C1=E C3=E C4=E(D/E) C8=B G2=D	C4 candidates D/E
68	Pattangere / Kenchenahalli lake (Kenchanahalli Lake)	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
69	Chokkanahalli Lake	E	C1=E C4=D(A/D/E) C8=E	C4 candidates A/D/E
70	Mestripalya Lake	E	C1=E C3=E C4=E C8=A	
71	Chikkalasandra lake	E	C3=E C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
72	Bheemanakatte Lake	E	C1=E(B/E) C4=E C8=E	C1 candidates B/E
73	Vishwaneedam Lake Bangalore North (Herohalli Thotadakere)	E	C1=E C4=E C8=A	
74	Panathur Chikka Kere	E	C1=E(D/E) C4=B(A/B/D) C5=C(B/C/D) C8=B G2=E	C1 candidates D/E; C4 candidates A/B/D; C5 candidates B/C/D
75	Junnasandra lake	E	C1=E C4=A C8=E	
76	Srigandakaval Lake	E	C1=E C4=E C8=B	
77	Jogi kere	E	C1=E(D/E) C4=E(D/E) C8=A	C1 candidates D/E; C4 candidates D/E
78	Venkateshapura Lake	E	C1=E C4=E C8=C	
79	Kalyanikunte (Near Saibaba Temple) (Vasantapura Temple Kalyani)	E	C1=E(D/E) C4=C(A/C/E) C8=E	C1 candidates D/E; C4 candidates A/C/E
80	Shivanahalli Lake	E	C1=E C4=A C8=E	
81	Chikka Begur Lake	D	C3=D C4=E C8=A	no open water observed 2017-2026: boundary and hydrology to scope
82	Pattandur agrahara lake-124	D	C3=D(C/D) C4=E C8=A	C3 candidates C/D; no open water observed 2017-2026: boundary and hydrology to scope
83	Kodigehalli lake	D	C1=D(C/D/E) C3=D(D/E) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates C/D/E; C3 candidates D/E; C4 candidates C/D/E; C5 candidates B/C/D
84	Garudachar Palya (Goshala) Lake (Goshala Lake)	D	C1=D(D/E) C4=B(A/B/C) C5=D(C/D/E) C8=E G2=D	C1 candidates D/E; C4 candidates A/B/C; C5 candidates C/D/E
85	Manganahalli Lake	D	C1=D(C/D/E) C4=E(D/E) C8=A	C1 candidates C/D/E; C4 candidates D/E
86	Mallasandra Lake	D	C3=D(D/E) C4=E C8=A	C3 candidates D/E; no open water observed 2017-2026: boundary and hydrology to scope
87	Bagalagunte Lake	D	C1=D(C/D/E) C3=D(D/E) C4=E C5=C(B/C) C8=B	C1 candidates C/D/E; C3 candidates D/E; C5 candidates B/C
88	Gunjuru Lake	C	C1=E(B/E) C3=C(B/C) C4=D(C/D/E) C5=B(B/C) C8=B	C1 candidates B/E; C3 candidates B/C; C4 candidates C/D/E; C5 candidates B/C; single severe input C1: little or no water in the reading window; storage and inflow to scope
89	Nelagadirahalli Hosakere	C	C1=E C3=C(B/C) C4=C(B/C/D) C8=B	C3 candidates B/C; C4 candidates B/C/D; single severe input C1: little or no water in the reading window; storage and inflow to scope
90	Chikkabettahalli Lake	C	C1=E C3=B(A/B) C4=C(B/C/E) C8=C	C3 candidates A/B; C4 candidates B/C/E; single severe input C1: little or no water in the reading window; storage and inflow to scope
91	Vaderahalli	C	C1=E(D/E) C3=D(C/D) C4=C(B/C/D) C5=C(C/D) C8=C	C1 candidates D/E; C3 candidates C/D; C4 candidates B/C/D; C5 candidates C/D; single severe input C1: little or no water in the reading window; storage and inflow to scope

#	Lake	Condition	Inputs	Notes
92	Swarnakunte Gudda Kere (Chandrasekhar Layout Lake)	C	C1=E C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=B	C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D; single severe input C1: little or no water in the reading window; storage and inflow to scope
93	Bande Mahadevapura kere	C	C1=E(D/E) C4=B(A/B/C) C5=C(B/C) C8=D	C1 candidates D/E; C4 candidates A/B/C; C5 candidates B/C; single severe input C1: little or no water in the reading window; storage and inflow to scope
94	Sadaramangala Lake	C	C8=A G2=E	no open water observed 2017-2026: boundary and hydrology to scope
95	Mylasandra (Sunnakallu palya) lake	C	C4=E(A/E) C8=A	C4 candidates A/E; no open water observed 2017-2026: boundary and hydrology to scope
96	Srinivasapura Lake	C	C4=A(A/B) C8=E	C4 candidates A/B; no open water observed 2017-2026: boundary and hydrology to scope
97	Hebbal Lake	B	C1=E C3=A(A/B) C4=B(B/C) C5=C(B/C) C8=A	C3 candidates A/B; C4 candidates B/C; C5 candidates B/C; single severe input C1: little or no water in the reading window; storage and inflow to scope
98	Chikka Bellanduru Lake	B	C1=E C3=B(A/B) C4=B(A/B) C8=A	C3 candidates A/B; C4 candidates A/B; single severe input C1: little or no water in the reading window; storage and inflow to scope
99	Nagawara Lake	B	C1=E C3=A(A/B) C4=B(A/B/C) C5=B C8=A	C3 candidates A/B; C4 candidates A/B/C; single severe input C1: little or no water in the reading window; storage and inflow to scope
100	B. Channasandra	B	C3=B(A/B) C4=E C8=A	C3 candidates A/B; no open water observed 2017-2026: boundary and hydrology to scope
101	Ramagondanahalli Lake	A	C1=E(D/E) C3=A(A/B) C4=A C5=B C8=A	C1 candidates D/E; C3 candidates A/B; single severe input C1: little or no water in the reading window; storage and inflow to scope
102	Kundalahalli Lake	C	C1=C(C/D) C3=A(A/B) C4=B(B/C) C5=D(D/E) C8=E G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C; C5 candidates D/E; single severe input C8: flagged for a closer read, not a verdict
103	Nallurahalli Lake	C	C1=D(C/D) C3=B(A/B) C4=E C5=C(B/C/D) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
104	Dore Kere	C	C1=C(C/D) C3=C(B/C) C4=E(D/E) C5=D(B/D/E) C8=B G2=D	C1 candidates C/D; C3 candidates B/C; C4 candidates D/E; C5 candidates B/D/E; single severe input C4: flagged for a closer read, not a verdict
105	Madiwala Lake	C	C1=D(D/E) C3=A(A/B) C4=E C5=C(B/C) C8=B G2=D	C1 candidates D/E; C3 candidates A/B; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
106	Begur Lake	C	C1=C(B/C) C3=A(A/B) C4=E(D/E) C5=D(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates D/E; C5 candidates C/D; single severe input C4: flagged for a closer read, not a verdict
107	Bheemanakuppa Lake	C	C1=C C3=A(A/B) C4=C(B/C) C5=C(B/C) C8=A	C3 candidates A/B; C4 candidates B/C; C5 candidates B/C
108	Chikkabanavara lake	C	C1=C(C/D) C3=A(A/B) C4=D(D/E) C5=C C8=A G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates D/E
109	Allalasandra lake	C	C1=C C3=A(A/B) C4=B(A/B/C) C5=D(B/D) C8=B G2=E	C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/D; single severe input G2: flagged for a closer read, not a verdict
110	Mallathahalli lake	C	C1=D(D/E) C3=B(A/B) C4=E C5=C(B/C) C8=B G2=D	C1 candidates D/E; C3 candidates A/B; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
111	Kudlu Anekal & Doddakere (Hosakere)	C	C1=B(A/B) C3=A(A/B) C4=C(B/C) C5=C(B/C/D) C8=A G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C; C5 candidates B/C/D
112	Herohalli Lake Bangalore North	C	C1=B(B/C) C3=B(A/B) C4=C(C/D) C5=D(D/E) C8=A G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D; C5 candidates D/E
113	Haraluru kere	C	C1=B(B/C) C3=A(A/B) C4=C(C/D) C5=C(C/D) C8=A G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D; C5 candidates C/D
114	Doddakannelli Lake	C	C1=C C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=C G2=D	C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
115	Amruthalli Lake	C	C1=C(C/D) C3=B(B/C) C4=D(D/E) C5=C(B/C/D) C8=B G2=E	C1 candidates C/D; C3 candidates B/C; C4 candidates D/E; C5 candidates B/C/D; single severe input G2: flagged for a closer read, not a verdict
116	Kempambudhi Lake	C	C1=B(A/B/C) C3=B(A/B) C4=C(B/C/D) C5=D(D/E) C8=A G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates D/E
117	Kowdenahalli lake	C	C1=C(B/C) C3=A(A/B) C4=D(C/D/E) C5=D(C/D) C8=A G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
118	Kenchanapura Govt. Lake	C	C1=D(C/D/E) C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=A	C1 candidates C/D/E; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
119	Horamavu Lake	C	C1=D(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=C	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
120	Kommagatta Lake	C	C1=D(C/D) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
121	K R Puram (BEML) / Benniganahalli Lake (Benniganahalli Lake)	C	C1=D(C/D) C3=B(A/B) C4=B(A/B/C) C5=D(C/D) C8=C G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
122	H Gollahalli kere (Hemmigepura Kere)	C	C1=C(B/C/D) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=B	C1 candidates B/C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
123	Narsipura Lake	C	C1=C(B/C/D) C3=A(A/B) C4=A(A/B) C5=C(B/C) C8=D G2=D	C1 candidates B/C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
124	Kothanuru Lake (Krishna Nagara Lake)	C	C1=D(C/D) C3=A(A/B) C4=B(A/B) C5=C(B/C) C8=B G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
125	Dubasi Palya Kere	C	C1=D(C/D/E) C3=B(B/C) C4=E C5=C(B/C) C8=A	C1 candidates C/D/E; C3 candidates B/C; C5 candidates B/C; single severe input C4: flagged for a closer read, not a verdict
126	Seetharampalya Lake	C	C1=C(B/C/D) C3=A(A/B) C4=D(C/D/E) C5=D(D/E) C8=A G2=E	C1 candidates B/C/D; C3 candidates A/B; C4 candidates C/D/E; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict
127	Andrahalli Lake	C	C1=D(C/D) C3=B(A/B) C4=C(B/C/D) C5=B(B/C) C8=A G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict
128	Subedharana Lake	C	C1=D(C/D) C3=A(A/B) C4=E(D/E) C5=C(B/C/D) C8=A	C1 candidates C/D; C3 candidates A/B; C4 candidates D/E; C5 candidates B/C/D; single severe input C4: flagged for a closer read, not a verdict
129	Puttenhalli Lake	C	C1=D(D/E) C3=A(A/B) C4=D(C/D/E) C5=C(B/C) C8=A G2=D	C1 candidates D/E; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C
130	Kudlu Chikka Kere (Haraluru Lake)	C	C1=B(A/B) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
131	Basapura Lake-2	C	C1=C(B/C/D) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=B G2=D	C1 candidates B/C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
132	Singasandra Lake South Bangalore South	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/E) C5=C(B/C/D) C8=E G2=D	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/E; C5 candidates B/C/D; single severe input C8: flagged for a closer read, not a verdict
133	Basapura Lake-1	C	C1=B(A/B/C) C3=A(A/B) C4=C(B/C/E) C5=E(D/E) C8=A G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/E; C5 candidates D/E; single severe input C5: flagged for a closer read, not a verdict
134	Ramasandra Lake	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/E) C5=D(B/D) C8=A	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/E; C5 candidates B/D
135	Lakshmipura Lake	C	C1=C(B/C/D) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=A	C1 candidates B/C/D; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
136	Vijinapura Lake	C	C1=C(A/C) C3=A(A/B) C4=D(C/D/E) C5=D(B/D/E) C8=A G2=E	C1 candidates A/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/D/E; single severe input G2: flagged for a closer read, not a verdict
137	Kalena Agrahara Lake	C	C1=D(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(B/C) C8=C G2=D	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
138	B. Narayanapura Lake	C	C1=C(A/C/D) C4=E(D/E) C5=C(C/D) C8=B G2=D	C1 candidates A/C/D; C4 candidates D/E; C5 candidates C/D; single severe input C4: flagged for a closer read, not a verdict
139	Sheelavathana Kere	C	C1=C(B/C) C3=A(A/B) C4=C(B/C/D) C5=D(B/D) C8=A G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/D; single severe input G2: flagged for a closer read, not a verdict
140	Devasandra lake	C	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=C(C/D) C8=B G2=E	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict

#	Lake	Condition	Inputs	Notes
141	Deverabisanahalli Lake	C	C1=C(C/D) C3=B(B/C) C4=D(C/D/E) C5=C(B/C) C8=C G2=E	C1 candidates C/D; C3 candidates B/C; C4 candidates C/D/E; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict
142	Subramanyapura Lake	C	C1=C(B/C) C3=A(A/B) C4=D(C/D/E) C5=D(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates C/D/E; C5 candidates C/D
143	Hoodi Giddanakere Lake (Hoodi Lake)	C	C1=D(C/D/E) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=B	C1 candidates C/D/E; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
144	Bhattarahalli Lake	C	C1=C(B/C) C3=A(A/B) C4=A(A/B) C5=C(B/C/D) C8=B G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C/D; single severe input G2: flagged for a closer read, not a verdict
145	Haralakunte Lake (Somasandra Palya Kere) (Somasundarapalya Lake)	C	C1=B(A/B/C) C3=A(A/B) C4=A C5=C(B/C) C8=C G2=D	C1 candidates A/B/C; C3 candidates A/B; C5 candidates B/C
146	Byrasandra	C	C1=B(A/B/C) C3=A(A/B) C4=C(B/C/D) C5=D(C/D) C8=C G2=D	C1 candidates A/B/C; C3 candidates A/B; C4 candidates B/C/D; C5 candidates C/D
147	Varanasi Lake (Jimkenahalli Kere)	C	C1=D(D/E) C3=A(A/B) C4=A C5=B(B/C) C8=D G2=E	C1 candidates D/E; C3 candidates A/B; C5 candidates B/C; single severe input G2: flagged for a closer read, not a verdict
148	Nyanappanahalli Lake / Akshayanagara Lake (Akshayanagara Lake)	C	C1=C(B/C/D) C4=D(C/D/E) C5=B(A/B/D) C8=B G2=D	C1 candidates B/C/D; C4 candidates C/D/E; C5 candidates A/B/D
149	Halasuru lake	B	C1=B(A/B) C3=C(B/C) C4=B(B/C) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates B/C; C4 candidates B/C; C5 candidates C/D
150	Ramapura Kere	B	C1=B(A/B) C3=A(A/B) C4=B(A/B/C) C5=D(C/D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D/E; single severe input G2: flagged for a closer read, not a verdict
151	Seegehalli Lake	B	C1=B(B/C) C3=A(A/B) C4=B(A/B/C) C5=C(A/C/D) C8=B G2=E	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B/C; C5 candidates A/C/D; single severe input G2: flagged for a closer read, not a verdict
152	Palanahalli Lake	B	C1=A(A/B) C3=B(A/B) C4=C(B/C/D) C5=E(D/E) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates D/E; single severe input C5: flagged for a closer read, not a verdict
153	Basavanapura Kere	B	C1=B(A/B) C3=A(A/B) C4=B(B/C) C5=D(D/E) C8=B G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict
154	Medi agrahara	B	C1=D(C/D/E) C3=E C4=A C5=B C8=B	C1 candidates C/D/E; single severe input C3: flagged for a closer read, not a verdict
155	Deepanjali Nagara lake	B	C1=B(A/B/C) C3=E C4=C(A/C/D) C5=B(B/C) C8=B	C1 candidates A/B/C; C4 candidates A/C/D; C5 candidates B/C; single severe input C3: flagged for a closer read, not a verdict
156	Jakkur Lake	A	C1=A(A/B) C3=A(A/B) C4=B(A/B/C) C5=D(D/E) C8=A G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates D/E; single severe input G2: flagged for a closer read, not a verdict
157	Vengayyana Lake	A	C1=A(A/B) C3=A(A/B) C4=A(A/B) C5=D(C/D) C8=B G2=E	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D; single severe input G2: flagged for a closer read, not a verdict
158	Doddabommasandra Lake	B	C1=C(B/C) C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=A	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
159	Venkojirao Kere / Agara Kere (Agara Lake)	B	C1=B(B/C) C3=A(A/B) C4=B(A/B) C5=C(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
160	Sarakki Lake	B	C1=B(A/B) C3=B(A/B) C4=A(A/B) C5=B C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B
161	Attur lake	B	C1=B(A/B) C3=A(A/B) C4=B(A/B/C) C5=D C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C
162	Gantiganahalli Lake	B	C1=B(A/B) C3=A(A/B) C4=D(C/D) C5=D(D/E) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates C/D; C5 candidates D/E
163	Horamavu Agara Lake	B	C1=A(A/B) C3=A(A/B) C4=B(A/B) C5=D(D/E) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates D/E
164	Kasavanahalli lake	B	C1=D C3=A(A/B) C4=B(A/B) C5=B C8=B G2=D	C3 candidates A/B; C4 candidates A/B
165	Kaggadasapura	B	C1=A(A/B) C3=B(A/B) C4=B(A/B/C) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D

#	Lake	Condition	Inputs	Notes
166	Gottigere	B	C1=A(A/B) C3=A(A/B) C4=B(A/B) C5=C(A/C/D) C8=B G2=D	C1 candidates A/B; C3 candidates A/B; C4 candidates A/B; C5 candidates A/C/D
167	Thirumenahalli Lake	B	C1=C(B/C) C3=A(A/B) C4=B(B/C) C5=D(C/D) C8=B	C1 candidates B/C; C3 candidates A/B; C4 candidates B/C; C5 candidates C/D
168	Doddanekundi lake	A	C1=A C3=A(A/B) C4=B(A/B) C5=D(D/E) C8=A G2=D	C3 candidates A/B; C4 candidates A/B; C5 candidates D/E
169	Sulikere/ Herekere Lake	A	C1=B(B/C) C3=A(A/B) C4=A(A/B) C5=C(B/C) C8=A	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
170	Veerasagara lake	A	C1=D(C/D) C3=A(A/B) C4=A(A/B) C5=B(B/C) C8=A	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B; C5 candidates B/C
171	Kattigenahalli Lake	B	C1=D(C/D) C3=A(A/B) C4=B(A/B) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B
172	Konasandra Lake	B	C1=B(A/B) C3=A(A/B) C4=C(B/C/D) C5=C(B/C/D) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates B/C/D; C5 candidates B/C/D
173	Arekere lake	B	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=B(B/C) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates B/C
174	Anjanapura Lake / nagara Churchaghatta Kere Alahalli (Avalahalli Lake)	B	C1=B(B/C) C3=A(A/B) C4=B(A/B) C5=D(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
175	Agrahara Lake	B	C1=C(C/D) C3=A(A/B) C4=B(A/B/C) C5=D(C/D) C8=B	C1 candidates C/D; C3 candidates A/B; C4 candidates A/B/C; C5 candidates C/D
176	Yelenahalli Lake	B	C1=B(A/B/D) C4=B(A/B/C) C5=B C8=B G2=D	C1 candidates A/B/D; C4 candidates A/B/C
177	Doddkammanahalli Lake	B	C1=B(B/C) C3=A(A/B) C4=A(A/B) C5=C(C/D) C8=B G2=D	C1 candidates B/C; C3 candidates A/B; C4 candidates A/B; C5 candidates C/D
178	Gowdana Kere	B	C1=A(A/B) C3=C(C/D) C4=B(A/B) C5=D(C/D) C8=B	C1 candidates A/B; C3 candidates C/D; C4 candidates A/B; C5 candidates C/D
179	Thalaghattapura Lake	A	C1=A(A/B) C3=A(A/B) C4=D(C/D/E) C5=C(B/C/D) C8=A	C1 candidates A/B; C3 candidates A/B; C4 candidates C/D/E; C5 candidates B/C/D
180	Nagarabhavi Lake	A	C1=A(A/C) C4=A(A/B) C5=B(A/B) C8=B	C1 candidates A/C; C4 candidates A/B; C5 candidates A/B

Sources

- KTCDA, List of Lakes in Bengaluru (BBMP, BDA, Forest Department, BMRCL custody lists), ktcda.karnataka.gov.in/28/list-of-lakes-in-bengaluru/en, downloaded 3 September 2026.
- BBMP Lake Management System, lake locations (lms.bbmpgov.in), 3 September 2026.
- KSPCB, Water Quality Data of Bengaluru Lakes for the Month of June 2026 (130 stations); Classification of Water Quality under NWMP, April 2025 to February 2026.
- Copernicus Sentinel-2 Level-2A imagery, March 2017 to August 2026; Dynamic World land cover (Google and WRI).
- OpenStreetMap water polygons; Greater Bengaluru 2025 ward and corporation layers; Neer Vazhvu's drainage-network layer.
- Programme rows: Deccan Herald, 17 July 2025, "BBMP allocates Rs 50 crore to develop 24 lakes"; 21 June 2025, "Karnataka Govt approves Rs 80 crore to resume desilting work" (Bellandur); 17 November 2025, "Bellandur Lake rejuvenation pushed to March 2026"; 27 February 2026, "Authority plans revival of drained city lakes"; Citizen Matters, 3 March 2020, "BDA concretises restoration of Bellandur Lake"; Newsfirst, 18 February 2026, "Ulsoor Lake drained for Rs 4-crore mega desilting"; SANDRP, 10 February 2026, "Bengaluru Lakes 2025"; NGT OA 125/2017, orders of 6 December 2018 and 12 March 2021.
- Method: Neer Vazhvu, satellite monitoring of Bengaluru lakes, methodology note (September 2026), available on request.