

CASE REPORT

Esophageal Perforation in a Cervical Fracture Patient With Progressed Ankylosing Spondylitis

Case Report and Review of the Literature

Jianxi Wang, MD, Liangyu Shi, MD, Huaijiang Chen, MD, and Wen Yuan, MD

Study Design. Case report and review of relevant literature.

Objective. To report a rare complication of esophageal perforation in cervical fracture patient with progressive ankylosing spondylitis (AS) and review of relevant literature.

Summary of Background Data. Esophageal perforation in cervical fracture is extremely rare. This complication has never been reported in AS patients. Key points in the early diagnosis and management of this severe complication along with the cervical fracture were presented in detail in this case report.

Methods. A 61-year-old male with AS, who sustained C6 fracture and dislocation after a vehicle accident. Initial treatment strategy was combined anterior-posterior fixation and fusion. Although esophageal perforation in the dorsal wall of esophagus was detected in anterior surgery. After thorough debridement, the esophageal lesion was closed by resorbable interrupted sutures. Surgical incision was washed by saline and hydrogen peroxide without primary closure. Cervical fracture was treated by long level posterior fixation alone. After surgery, the anterior surgical incision was irrigated with normal saline twice a day and closed 3 weeks later.

Results. Esophageal perforation was healed completely and neurologic results were improved significantly after surgery. Union of the fracture and segmental stability of cervical spine was confirmed radiologically at 1-year follow up.

Conclusion. Esophageal perforation in cervical fracture patient with progressed AS is an extremely rare and potentially life-threatening complication. Surgical debridement and drainage with intensive care are essential for good outcome.

Key words: ankylosing spondylitis, cervical fracture, complication, esophageal perforation.

From the Department of Orthopedic Surgery, Changzheng Hospital, Second Military Medical University, Shanghai, China.

Acknowledgment date: December 11, 2015. First revision date: February 28, 2016. Acceptance date: March 25, 2016.

The manuscript submitted does not contain information about medical device(s)/drug(s).

No funds were received in support of this work.

No relevant financial activities outside the submitted work.

Address correspondence and reprint requests to Huaijiang Chen, MD, Department of Orthopedic Surgery, Changzheng Hospital, Second Military Medical University, Shanghai, China; E-mail: spine.chen@163.com

DOI: 10.1097/BRS.0000000000001885

Level of Evidence: 5
Spine 2016;41:E1364–E1367

CASE REPORT

A 61-year-old man suffering from AS for about 25 years was admitted to our emergency room 12 hours after a traffic accident. His chief complaints were neck pain, left upper limb pain, and numbness. Muscle strength of the upper extremities was 3/5 (left) and 4/5 (right). Hypertonia and hyperreflexia were observed in the left upper extremities. The Japanese Orthopedic Association (JOA) score for evaluating the spinal cord function was 11 points. Preoperative radiographic examination revealed typical “bamboo spine” with C6 fracture and dislocation. CT scan demonstrated transverse fracture through C6 vertebral body with laminar and spinous process fracture. MR imaging showed prevertebral edema, rupture of anterior longitudinal ligament, and compression of spinal cord (Figure 1A–F).

Treatment was commenced with skull traction immediately after admission. Three days later, the patient developed continuous fever (about 39°C) and throat pain that intensified when swallowing. Laboratory tests revealed a leucocyte count of $20.8 \times 10^9/L$, with 93.6% neutrophils. After treatment with moxifloxacin, the body temperature quickly returned to normal.

Radiography revealed no reduction of the fracture after traction. The initial treatment strategy was combined anterior-posterior fixation and fusion. During the anterior approach, yellowish viscous pus was observed in the prevertebral space. An esophageal perforation measuring about 0.5 cm in length, caused by the sharp fracture fragment, was detected on the dorsal wall of the esophagus. A nasogastric tube was inserted, and after thorough debridement, the esophageal lesion was closed by resorbable interrupted sutures. The surgical incision was washed using saline and hydrogen peroxide without primary closure. Subsequently, posterior surgery was performed and fracture reduction was accomplished by fixation from C4 to T2 (Figure 2A, B).




Figure 1. Preoperative imaging assessment. **A** and **B**, Preoperative x-ray examination suggested a typical “bamboo spine” with C6 fracture and dislocation. **C** and **D**, CT sagittal reconstruction confirmed the transverse fracture through C6 vertebral body with laminar and spinous process fracture. **E** and **F**, MRI demonstrated prevertebral edema, rupture of anterior longitudinal ligament, and compression of spinal cord.

The patient was treated with total parenteral nutrition (TPN) and broad-spectrum antibiotics after surgery. The surgical incision was irrigated with normal saline twice a day. The incision was closed 3 weeks later, after which it healed completely. Flexible endoscopy was performed 4 weeks after surgery, with no evidence of abnormality. The patient was immobilized with a hard cervical collar for 2 months. His neurological symptoms improved significantly after surgery, and his JOA score increased from 11 points preoperatively to 15 points at the final follow-up. Postoperative radiographs revealed satisfactory reduction and fixation of the fracture. Union of the fracture and segmental stability of the cervical spine was radiologically confirmed at the one-year follow-up (Figure 3A–D).

DISCUSSION

Esophageal perforation is an extremely rare complication in patients with cervical fracture. We performed a review of the literature and the results were summarized as follows. Only 10 cases with detailed clinical information reported in 9 case reports from 1960 to 2013 are available (Table 1).^{3–11} The mean age of the patients in the 10 cases was 51.2 ± 20.7 years (range, 19–79 years). Vehicle accidents and falls were the most common causes for injury. The cervical injury level was mostly in C4 to C6. However, none of these reported cases were complicated with AS.

In this report, we presented a case of esophageal perforation in the cervical fracture of a patient with progressed AS, and described the diagnosis and management of this unique and severe complication in detail. Owing to the atypical signs and symptoms accompanied by the injury, prompt diagnosis of this complication can be difficult. Clinical signs that could lead to the diagnosis include increasing anterior cervical pain and tenderness, swelling and edema of the cervical area, dyspnea, and dysphagia.⁷ Patients with prevertebral edema or emphysema in CT or MR imaging should be highly suspected. Barium esophagogram and esophageal endoscopy can help confirm the diagnosis.

To treat this complication, most published studies emphasized the importance of surgical debridement and drainage with intensive care. Continuous irrigation is an alternative



Figure 2. **A**, The surgical incision without primary closure was irrigated with normal saline twice a day after surgery. **B**, The surgical incision was closed 3 weeks later and healed.




Figure 3. **A** and **B**, Postoperative anteroposterior and lateral radiographs revealed satisfactory reduction and fixation of the fracture. **C** and **D**, Union of the fracture and segmental stability of cervical spine was confirmed radiologically at 1-year follow up.

TABLE 1. Summary of Cases of Esophageal Injury in Cervical Fracture Reported in Literature

Author	Year	Journal	Age/Sex	Cause of Injury	Injury Level of Cervical Spine	Description of the Esophageal Injury	Management of the Esophageal Injury	Results
Dabija <i>et al</i> ³	2014	Rev Med Chir Soc Med Nat Iasi	65/F	Fall	C6–7	A small bone fragment inserted in the esophagus on his left side, with a small defect at the adventitia level	Drainage, esophageal suture and gastrostomy	Recovery with a permanent gastrostoma
Delos <i>et al</i> ⁴	2013	Int J Surg Case Rep.	51/F	Fall	C4–C6	Contained esophageal perforation at the C3–C4 level	Broad-spectrum empiric antibiotics, total parenteral nutrition, oral hygiene	Complete recovery
Makoyo PZ ⁵	1979	J Natl Med Assoc	22/M	Vehicle accident	C4–5	Esophageal perforation in the posterior wall of esophagus	Debridement, irrigation and gastrostomy	Complete recovery
Morrison A ⁶	1960	J Bone Joint Surg Br	73/M	Fall	C4–7	A two centimeters long tear in the back of the oesophagus to the left of the mid-line	Drainage and chemotherapy	Dead
Nerot <i>et al</i> ⁷	2002	J Spinal Disord Tech	55/M	Vehicle accident	C2,C5–6	A tear of the esophagus on the right side with copious outflow of pus	Debridement and drainage	Complete recovery
Reddin <i>et al</i> ⁸	1987	J Trauma	79/F	Fall	C4–6	1.5-cm vertical laceration of the posterior midline of the cervical esophagus	Repaired in two layers with interrupted 3–0 Vicryl sutures, irrigation	Dead
Stringeret <i>et al</i> ⁹	1980	J Neurosurg	53/F	Fall	C5–6	Anterior and posterior tears of the esophagus 1 to 2 cm above the sternal notch	Separate suture closure and drainage	Complete recovery
Tomaszek <i>et al</i> ¹⁰	1984	Neurosurgery	19/F	Dive	C5–6	A small cervical esophageal perforation and mediastinitis	Gastrostomy, jejunostomy and drainage	Complete recovery

TABLE 1 (Continued)

Author	Year	Journal	Age/Sex	Cause of Injury	Injury Level of Cervical Spine	Description of the Esophageal Injury	Management of the Esophageal Injury	Results
			32/F	Vehicle accident	C6–7	A left paratracheal abscess at the level of the cricoid cartilage extended posteriorly toward to esophagus and cervical spine	Drainage and chemotherapy	Complete recovery
Agha FP ¹¹	1982	Br J Radiol	63/F	Vehicle accident	C7	A wide posterolateral perforation of the upper oesophagus	No details	Dead

management method for wounds with discharging pus. In early diagnosis, repair of the esophageal laceration is possible. Treatment with antibiotics after surgery is essential for the prevention of incision and mediastinal infection. As shown in Table 1, three of the patients in the 10 reviewed cases died, suggesting the high mortality rate of this complication. Diagnosis of esophageal perforation was not made before surgery in the current case and the treatment strategy was modified accordingly during operation. The outcome was satisfactory, which was attributed to the reasonable treatment and postoperative intensive care.

Key Points

- Esophageal perforation complicating in cervical fracture patient with progressed ankylosing spondylitis is extremely rare and potentially life threatening.
- To avoid delayed diagnosis, great importance should be attached to clinical signs that could lead to esophageal perforation in cervical fracture patients.
- Surgical debridement and drainage with intensive care are essential for good outcome of this severe complication.

References

1. Lazennec JY, d'Astorg H, Rousseau MA. Cervical spine surgery in ankylosing spondylitis: review and current concept. *Orthop Traumatol Surg Res* 2015;101:507–13.
2. Dakhil-Jerew F, Derry F. Management of cervical spine fracture in patient with advanced ankylosing spondylitis using SOMI brace. *Injury Extra* 2008;39:347–51.
3. Dabija MG, Iliescu BF, Andronic D, et al. Rare complication of the cervical spine trauma—traumatic esophageal fistula: case report and review of the literature. *Rev Med Chir Soc Med Nat Iasi* 2014;118:683–7.
4. Delos Reyes AP, Clancy C, Lach J, et al. Conservative management of esophageal perforation after a fall. *Int J Surg Case Rep* 2013;4:550–3.
5. Makoyo PZ. Rupture of cervical esophagus from blunt trauma with concomitant fracture dislocation of C4–C5 vertebrae. *J Natl Med Assoc* 1979;71:473–4.
6. Morrison A. Hyperextension injury of the cervical spine with rupture of the oesophagus. *J Bone Joint Surg Br* 1960;42-b:356–7.
7. Nerot C, Jeanneret B, Lardenois T, et al. Esophageal perforation after fracture of the cervical spine: case report and review of the literature. *J Spinal Disord Tech* 2002;15:513–8.
8. Reddin A, Mirvis SE, Diaconis JN. Rupture of the cervical esophagus and trachea associated with cervical spine fracture. *J Trauma* 1987;27:564–6.
9. Stringer WL, Kelly DL Jr, Johnston FR, et al. Hyperextension injury of the cervical spine with esophageal perforation. Case report. *J Neurosurg* 1980;53:541–3.
10. Tomaszek DE, Rosner MJ. Occult esophageal perforation associated with cervical spine fracture. *Neurosurgery* 1984;14:492–4.
11. Agha FP, Raji MR. Oesophageal perforation with fracture dislocation of cervical spine due to hyperextension injury. *Br J Radiol* 1982;55:369–72.