# EAGLE EYE

Cabinet QC report · drawing-first verification

**EE-DEMO-01**

Run 20261024-202527-de86
2026-10-24 20:25:29


## HOLD · 2 faults to fix before shipping

Every FAIL is boxed on the photo with expected-vs-found proof.

| 39 | 2 | 0 | 0 |
|---|---|---|---|
| PASS | FAIL · FIX BEFORE SHIPPING | REVIEW · EVIDENCE UNRESOLVED | SKIP · ROOT CAUSE ELSEWHERE |

### Inspection details

| | |
|---|---|
| Cabinet | EE-DEMO-01 |
| Photo | forge_295.jpg |
| GA drawing | GA_EE-DEMO-01.pdf |
| Wire list | WireList_EE-DEMO-01.xlsx |
| QC checklist | QC_Checklist_EE-DEMO-01.xlsx |
| Checks | GA · ORDER · LABEL · FERRULE · COLOUR |
| Items checked | 41 expected items from the drawing and wire list |
| Registration | backplate outline + 17 label/ferrule anchors, 15 RANSAC inliers; off-pattern: CB42, CB41 |
| Processing | 0.8 s on CPU |
| Engine | EAGLE EYE 3.3.0 · Tesseract OCR · OpenCV · PyMuPDF |




### How to read this report

Every item is checked one at a time at the spot the GA drawing gives it. An item is FAIL only when independent evidence agrees; anything unclear is REVIEW (re-photo that zone) instead of a guess. SKIP means the root cause is already reported by another item (a missing part is one FAIL, not five). Numbers match the boxes on the photo.


# Findings (2)

## 1 ORD-RAIL-1 Rail order — FAIL

EXPECTED · GA drawing




FOUND · photo




| | |
|---|---|
| Expected (drawing) | CB41-CB42-CB43-CB44 |
| Found (photo) | CB41 <-> CB42 swapped |
| Evidence | read along rail: CB42-CB41-CB43-CB44 |

## 2 LBL-PS11 Device label — FAIL

EXPECTED · GA drawing




FOUND · photo




| | |
|---|---|
| Expected (drawing) | PS11 |
| Found (photo) | Wrong label: reads 'PS17' |
| Evidence | label sticker+print found: True; OCR votes ['PS17', 'PS17', 'PS17', 'PS17'] |

# QC checklist (41 items)

| Item | Check | Expected (drawing) | Found (photo) | Result |
|---|---|---|---|---|
| GA-PS11 | Part present | Installed | Present | PASS |
| GA-PS12 | Part present | Installed | Present | PASS |
| GA-D12 | Part present | Installed | Present | PASS |
| GA-CB41 | Part present | Installed | Present | PASS |
| GA-CB42 | Part present | Installed | Present | PASS |
| GA-CB43 | Part present | Installed | Present | PASS |
| GA-CB44 | Part present | Installed | Present | PASS |
| GA-1CBP01 | Part present | Installed | Present | PASS |
| GA-1CBP02 | Part present | Installed | Present | PASS |
| GA-1CBP03 | Part present | Installed | Present | PASS |
| GA-1CBP04 | Part present | Installed | Present | PASS |
| GA-PE | Part present | Installed | Present | PASS |
| ORD-RAIL-1 | Rail order | CB41-CB42-CB43-CB44 | CB41 <-> CB42 swapped | FAIL #1 |
| LBL-PS11 | Device label | PS11 | Wrong label: reads 'PS17' | FAIL #2 |
| LBL-PS12 | Device label | PS12 | PS12 | PASS |
| LBL-D12 | Device label | D12 | D12 | PASS |
| LBL-CB41 | Device label | CB41 | CB41 | PASS |
| LBL-CB42 | Device label | CB42 | CB42 | PASS |
| LBL-CB43 | Device label | CB43 | CB43 | PASS |
| LBL-CB44 | Device label | CB44 | CB44 | PASS |
| LBL-1CBP01 | Device label | 1CBP01 | 1CBP01 | PASS |
| LBL-1CBP02 | Device label | 1CBP02 | 1CBP02 | PASS |
| LBL-1CBP03 | Device label | 1CBP03 | 1CBP03 | PASS |
| LBL-1CBP04 | Device label | 1CBP04 | 1CBP04 | PASS |
| LBL-PE | Device label | PE | PE | PASS |
| FER-X3:1 | Ferrule text | X3-1/CB41-2 | X3-1/CB41-2 | PASS |
| FER-X3:2 | Ferrule text | X3-2/CB42-2 | X3-2/CB42-2 | PASS |
| FER-X3:3 | Ferrule text | X3-3/CB43-2 | X3-3/CB43-2 | PASS |
| FER-X3:4 | Ferrule text | X3-4/CB44-2 | X3-4/CB44-2 | PASS |
| FER-X3:5 | Ferrule text | X3-5/PS11+ | X3-5/PS11+ | PASS |
| FER-X3:6 | Ferrule text | X3-6/PS11- | X3-6/PS11- | PASS |
| FER-X3:7 | Ferrule text | X3-7/D12-L | X3-7/D12-L | PASS |
| FER-X3:8 | Ferrule text | X3-8/PE-1 | X3-8/PE-1 | PASS |
| COL-X3:1 | Wire colour | BN | BN | PASS |
| COL-X3:2 | Wire colour | BN | BN | PASS |
| COL-X3:3 | Wire colour | BN | BN | PASS |
| COL-X3:4 | Wire colour | BN | BN | PASS |
| COL-X3:5 | Wire colour | RD | RD | PASS |
| COL-X3:6 | Wire colour | BK | BK | PASS |
| COL-X3:7 | Wire colour | BU | BU | PASS |
| COL-X3:8 | Wire colour | GNYE | GNYE | PASS |

Generated 2026-10-24 20:25:29 by EAGLE EYE. Every result is traceable to the drawing item it checks and to the evidence listed above.