# EAGLE EYE

Cabinet QC report · drawing-first verification

**EE-DEMO-01**

Run 20261024-063829-d828

2026-10-24 06:38:31


## PASS · ready to ship

All 41 items the drawing expects were verified on the photo.

| 41 | 0 | 0 | 0 |
|---|---|---|---|
| PASS | FAIL · FIX BEFORE SHIPPING | REVIEW · RE-PHOTO ZONE | SKIP · ROOT CAUSE ELSEWHERE |

### Inspection details

| | |
|---|---|
| Cabinet | EE-DEMO-01 |
| Photo | 02_clean_cabinet_no_faults.jpg |
| Re-check of | 20261024-063813-d433 |
| GA drawing | GA_EE-DEMO-01.pdf |
| Wire list | WireList_EE-DEMO-01.xlsx |
| QC checklist | QC_Checklist_EE-DEMO-01.xlsx |
| Checks | GA · ORDER · LABEL · FERRULE · COLOUR |
| Items checked | 41 expected items from the drawing and wire list |
| Registration | backplate outline + 20 label/ferrule anchors, 20 RANSAC inliers |
| Processing | 1.7 s on CPU |
| Engine | EAGLE EYE 3.0.0 · Tesseract OCR · OpenCV · PyMuPDF |




### How to read this report


Every item is checked one at a time at the spot the GA drawing gives it. An item is FAIL only when independent evidence agrees; anything unclear is REVIEW (re-photo that zone) instead of a guess. SKIP means the root cause is already reported by another item (a missing part is one FAIL, not five). Numbers match the boxes on the photo.

# Re-check findings (4)

## 1 GA-PS12 Part present

CLOSED

EXPECTED · GA drawing




FOUND · photo





| | |
|---|---|
| Expected (drawing) | Installed |
| Found (photo) | Present |
| Evidence | slot occupancy 92%; label seen: True |
| Before re-check | FAIL: Missing |

## 2 ORD-RAIL-1 Rail order

CLOSED

EXPECTED · GA drawing




FOUND · photo




| | |
|---|---|
| Expected (drawing) | CB41-CB42-CB43-CB44 |
| Found (photo) | CB41-CB42-CB43-CB44 |
| Evidence | read along rail: CB41-CB42-CB43-CB44 |
| Before re-check | FAIL: CB43 <-> CB44 swapped |

## 3 LBL-1CBP03 Device label

CLOSED

EXPECTED · GA drawing




FOUND · photo





| | |
|---|---|
| Expected (drawing) | 1CBP03 |
| Found (photo) | 1CBP03 |
| Evidence | label sticker+print found: True; OCR votes ['1CBP03', '1CBP03', '1CBPO3', '1CBP03'] |
| Before re-check | FAIL: No label |


## 4 FER-X3:3 Ferrule text

CLOSED

EXPECTED · GA drawing



FOUND · photo




| | |
|---|---|
| Expected (drawing) | X3-3/CB43-2 |
| Found (photo) | X3-3/CB43-2 |
| Evidence | OCR votes ['X3-3/CB43-2', 'X3-3/CB43-2', 'X3-3/CB43-2', 'X3-3/CB43-2'] |
| Before re-check | FAIL: No ferrule |

# Re-check against the previous inspection

CLOSED 4 · OPEN 0 · REGRESSION 0 · NEW 0

| # | Item | Before | Now | Status |
|---|---|---|---|---|
| 1 | GA-PS12 | FAIL: Missing | PASS: Present | CLOSED |
| 2 | ORD-RAIL-1 | FAIL: CB43 <-> CB44 swapped | PASS: CB41-CB42-CB43-CB44 | CLOSED |
| 3 | LBL-1CBP03 | FAIL: No label | PASS: 1CBP03 | CLOSED |
| 4 | FER-X3:3 | FAIL: No ferrule | PASS: X3-3/CB43-2 | CLOSED |

# QC checklist (41 items)

| Item | Check | Expected (drawing) | Found (photo) | Result |
|---|---|---|---|---|
| GA-PS11 | Part present | Installed | Present | PASS |
| GA-PS12 | Part present | Installed | Present | PASS · CLOSED #1 |
| GA-D12 | Part present | Installed | Present | PASS |
| GA-CB41 | Part present | Installed | Present | PASS |
| GA-CB42 | Part present | Installed | Present | PASS |
| GA-CB43 | Part present | Installed | Present | PASS |
| GA-CB44 | Part present | Installed | Present | PASS |
| GA-1CBP01 | Part present | Installed | Present | PASS |
| GA-1CBP02 | Part present | Installed | Present | PASS |
| GA-1CBP03 | Part present | Installed | Present | PASS |
| GA-1CBP04 | Part present | Installed | Present | PASS |
| GA-PE | Part present | Installed | Present | PASS |
| ORD-RAIL-1 | Rail order | CB41-CB42-CB43-CB44 | CB41-CB42-CB43-CB44 | PASS · CLOSED #2 |
| LBL-PS11 | Device label | PS11 | PS11 | PASS |
| LBL-PS12 | Device label | PS12 | PS12 | PASS |
| LBL-D12 | Device label | D12 | D12 | PASS |
| LBL-CB41 | Device label | CB41 | CB41 | PASS |
| LBL-CB42 | Device label | CB42 | CB42 | PASS |
| LBL-CB43 | Device label | CB43 | CB43 | PASS |
| LBL-CB44 | Device label | CB44 | CB44 | PASS |
| LBL-1CBP01 | Device label | 1CBP01 | 1CBP01 | PASS |
| LBL-1CBP02 | Device label | 1CBP02 | 1CBP02 | PASS |
| LBL-1CBP03 | Device label | 1CBP03 | 1CBP03 | PASS · CLOSED #3 |
| LBL-1CBP04 | Device label | 1CBP04 | 1CBP04 | PASS |
| LBL-PE | Device label | PE | PE | PASS |
| FER-X3:1 | Ferrule text | X3-1/CB41-2 | X3-1/CB41-2 | PASS |
| FER-X3:2 | Ferrule text | X3-2/CB42-2 | X3-2/CB42-2 | PASS |
| FER-X3:3 | Ferrule text | X3-3/CB43-2 | X3-3/CB43-2 | PASS · CLOSED #4 |
| FER-X3:4 | Ferrule text | X3-4/CB44-2 | X3-4/CB44-2 | PASS |
| FER-X3:5 | Ferrule text | X3-5/PS11+ | X3-5/PS11+ | PASS |
| FER-X3:6 | Ferrule text | X3-6/PS11- | X3-6/PS11- | PASS |
| FER-X3:7 | Ferrule text | X3-7/D12-L | X3-7/D12-L | PASS |
| FER-X3:8 | Ferrule text | X3-8/PE-1 | X3-8/PE-1 | PASS |
| COL-X3:1 | Wire colour | BN | BN | PASS |
| COL-X3:2 | Wire colour | BN | BN | PASS |
| COL-X3:3 | Wire colour | BN | BN | PASS |
| COL-X3:4 | Wire colour | BN | BN | PASS |
| COL-X3:5 | Wire colour | RD | RD | PASS |
| COL-X3:6 | Wire colour | BK | BK | PASS |
| COL-X3:7 | Wire colour | BU | BU | PASS |
| COL-X3:8 | Wire colour | GNYE | GNYE | PASS |

Generated 2026-10-24 06:38:31 by EAGLE EYE. Every result is traceable to the drawing item it checks and to the evidence listed above.