

V/Line – Completion Report



Project: 2589 - V/Line 55.500 - 58.630 DBKWDG Access Track Maintenance Equipment

Customer: V/Line

PO / LOE: 194664

Location: Wandong, Victoria (KP 55.500 – 58.630)

Status: Completed

Date Completed: 2025-07-01

- **Work Description:** The mulching and vegetation removal around the pole lines have been completed, effectively mitigating fire hazards behind the Wandong Shopping Centre, between the rail line and the Easman boundary. Furthermore, we have cleared all blackberry and gorse, including areas under the pole lines and within the easement, extending from the rail street crossing to Wandong Station.
- **Scope of Works:** Clear under powerlines all areas. Create access for ARTC to poles.
- **Address:** 64 Rail Street, Wandong, Victoria, 3758, Australia
- **Date of Works:** 2025-06-07

Summary

Vegetation mulching and access track reinstatement were successfully completed between Epping-Kilmore Road and Wandong Station. All blackberry and gorse were effectively cleared, particularly under and around powerlines, which has improved access for ARTC and reduced fire hazards behind the Wandong Shopping Centre.

Key Findings


- All blackberry and gorse vegetation cleared from under and around powerlines.
- Access track reinstated from Epping-Kilmore Road crossing to Wandong Station.
- Fire hazards behind Wandong Shopping Centre have been mitigated.
- Access for ARTC to power poles has been created.

- Works included areas within the easement and between the rail line and Easman boundary.

Media

Before

During



After



Generated by **Systems @ TMC enviro**

www.tmcenviro.com.au

Email: systems@tmcenviro.com.au | Phone: +61 458 922 033