Pre-Existing Damage Report

Condition of the property before the tenancy began: 4 items of existing damage, recorded on video.

Property address **12 Example Street, Sampletown**

Tenant(s) **Sample Tenant**

Landlord / agent **Sample Property Co.**

Inspection date **2026-11-01**

Report prepared **2026-11-12**

File	TEST_walkthrough.mp4
Recorded (video metadata)	1 Nov 2026, 7:22 PM
Length	0:49
Size / format	20.5 MB, 1280x720 @ 30 fps
SHA-256 fingerprint	`3f72b5c5231e243f2285eb51545e538c40b06f467f00d23901da2acdc1a75627`

Each photo below is an unedited still frame taken from the video file identified above, at the time shown under it. Each description is transcribed from the narration recorded in that same video while the damage was being shown. The SHA-256 fingerprint lets anyone confirm they are looking at the same, unaltered video file.


SUMMARY

#	Location	Damage	Video time
1	Kitchen - on the countertop, to the left of the sink	There's a chip on the front edge, about half an inch wide.	0:00 - 0:10
2	Kitchen, the cabinet door under the sink	There's water damage at the bottom, the wood is swollen and the paint is peeling.	0:14 - 0:22
3	Living room, the wall behind the front door	There is a hole in the drywall from the door handle, about two inches across.	0:26 - 0:35
4	Main bedroom carpet, near the closet	There's a dark stain roughly the size of a dinner plate.	0:39 - 0:45

ITEMS

1 Kitchen - on the countertop, to the left of the sink

Video 0:00 - 0:10




Video frame at 0:11.8

DESCRIPTION

There's a chip on the front edge, about half an inch wide.

2 Kitchen, the cabinet door under the sink

Video 0:14 - 0:22




Video frame at 0:19.1

DESCRIPTION

There's water damage at the bottom, the wood is swollen and the paint is peeling.

3 Living room, the wall behind the front door

Video 0:26 - 0:35




Video frame at 0:31.5

DESCRIPTION

There is a hole in the drywall from the door handle, about two inches across.

4 Main bedroom carpet, near the closet

Video 0:39 - 0:45



Video frame at 0:43.1

DESCRIPTION

There's a dark stain roughly the size of a dinner plate.

ACKNOWLEDGEMENT

The parties below agree that this report records damage that existed at the start of the tenancy.

Tenant signature

Date

Landlord / agent signature

Date

APPENDIX: FULL NARRATION TRANSCRIPT

Machine transcription of the whole video's audio, with times, for cross-checking.

0:00 Okay, starting in the kitchen.

0:04 On the countertop, to the left of the sink, there's a chip on the front edge, about half an inch wide.

0:14 Kitchen, the cabinet door under the sink.

0:18 There's water damage at the bottom, the wood is swollen and the paint is peeling.

0:26 Living room, the wall behind the front door.

0:30 There is a hole in the drywall from the door handle, about two inches across.

0:39 Main bedroom carpet, near the closet.

0:42 There's a dark stain roughly the size of a dinner plate.