






D01 - OVERALL ROTOR GENERAL ARRANGEMENT

Source: openfan_rotor_assembly_v02_final.SLDASM (LOCKED CAD BASELINE)

Blade count B = 16 Station pitch = 22.5 deg (exact) Rotor axis: global Z

Assembly: 34 components, 99 native mates, 34/34 fully constrained

Blade-to-blade min surface clearance: 205.5 mm (measured)

Blade<->root interface gap: 0.000000 mm (measured)

Root-to-tip axial rake: 6.121 mm (measured; historical v02 defect was 757 mm)

Evidence: FINAL_CAD_LOCK_REPORT.md, FULL_ROTOR_ASSEMBLY_BUILD_REPORT.md

STATUS: Geometrically complete and assembly-verified. NOT structurally, aerodynamically, or manufacturing validated. No FEA or CFD has been performed on this geometry.