Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



1-Risk Identifier

Date Taken: 11/13/2024

Taken By: Jacob Richards

•

Risk address



2-Risk Overview

Date Taken: 11/13/2024

Taken By: Jacob Richards

The Dwelling risk is a 1 story residential building with 25 year 3 tab shingles on the roof and brick veneer on the elevations. The members mortgage company was verified as . The member had power outage on the DOL resulting in of food loss of \$500.

Photo Sheet -1 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001


Policy #: 123456789-95A



3-Dwelling Roof

Date Taken: 11/13/2024
Taken By: Jacob Richards

The dwelling roof is a 6/14 one story gable roof with 25 year 3-tab shingles installed as a single layer. Felt and drip edge is present. The roof is approximately 20 years old.



4-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Single layer, drip edge


Photo Sheet - 2 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



5-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

6/14 pitch



6-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

25 year 3 tab shingles

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



7-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

1 ft overhang



8-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards


Roof overview

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




9-Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

PVC ridge vent



10- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards


5 pipe jacks

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




11- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Front slope overview



12- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Front slope is North facing

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




13- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Front slope has 13 wind damaged

shingles



14- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind


Photo Sheet -7 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




15- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



16- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind


Photo Sheet - 8 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




17- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



18- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind


Photo Sheet - 9 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




19- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Rear slope overview



20- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards
Rear slope has 150 wind damaged

shingles

Photo Sheet - 10 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



21- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



22- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind


Photo Sheet - 11 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




23- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



24- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind


Photo Sheet - 12 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



25- Dwelling Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



26- Front Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Front elevation overview

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



27- Front Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Fascia displaced



28- Right Elevation

Date Taken: 11/13/2024 Taken By: Jacob Richards

Right elevation is free from wind damage

Photo Sheet - 14 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



29- Rear Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Rear elevation overview



30- Rear Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Fascia damaged

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




31- Rear Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Fascia damaged/displaced



32- Rear Elevation

Date Taken: 11/13/2024
Taken By: Jacob Richards

A.C unit free from damage

Photo Sheet - 16 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



33- Rear Elevation

Date Taken: 11/13/2024
Taken By: Jacob Richards

A.C unit free from damage



34- Rear Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged fascia

Photo Sheet - 17 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




35-Left Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Left elevation overview



36-Left Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Fascia displaced

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




37- Left Elevation

Date Taken: 11/13/2024

Taken By: Jacob Richards

Fascia displaced



38- Detached Garage

Date Taken: 11/13/2024

Taken By: Jacob Richards

Detached garage overview

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




39- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Detached garage roof is comprised of

3-tab shingles



40- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Single layer, drip edge

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




41- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

25 year 3-tab shingles



42- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

6/12 pitch


Photo Sheet - 21 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



43- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Roof overview



44- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards


PVC ridge vent

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



45- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Right slope overview



46- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Right slope is free from wind damage


Photo Sheet - 23 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



47- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Left slope overview



48- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Left slope has 26 wind damaged shingles

Photo Sheet - 24 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




49- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



50- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind

Photo Sheet - 25 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



51- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



52- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards


Missing/damaged shingles from wind

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



53- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Missing/damaged shingles from wind



54- Detached Garage Roof

Date Taken: 11/13/2024

Taken By: Jacob Richards

Rear slope free from storm damage

Photo Sheet - 27 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



55- Detached Garage Elevations

Date Taken: 11/13/2024
Taken By: Jacob Richards

Front elevation is free from wind damage



56- Detached Garage Elevations

Date Taken: 11/13/2024 Taken By: Jacob Richards

Right elevation is free from wind damage

Photo Sheet - 28 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



57- Detached Garage Elevations

Date Taken: 11/13/2024
Taken By: Jacob Richards

Rear elevation is free from wind damage



58- Detached Garage Elevations

Date Taken: 11/13/2024 Taken By: Jacob Richards

Left elevation is free from wind damage

Photo Sheet - 29 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



59- Fence

Date Taken: 11/13/2024
Taken By: Jacob Richards

The members privacy fence is comprised of 6 foot high PVC panels. All runs of the PVC privacy fence are owned by the member. The runs of the PVC fence are front right and left facing.



60- Fence/Front

Date Taken: 11/13/2024
Taken By: Jacob Richards

5 panels missing from front run of fence

Photo Sheet - 30 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



61- Fence/Front

Date Taken: 11/13/2024

Taken By: Jacob Richards



62- Fence/Front

Date Taken: 11/13/2024

Taken By: Jacob Richards

One gate is missing from storm

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



63- Fence/Right

Date Taken: 11/13/2024

Taken By: Jacob Richards

Right run overview



64- Fence/Right

Date Taken: 11/13/2024

Taken By: Jacob Richards
10 panels missing and damaged from


storm

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



65- Fence/Right

Date Taken: 11/13/2024
Taken By: Jacob Richards

10 panels missing and damaged from

storm



66- Fence/Left

Date Taken: 11/13/2024

Taken By: Jacob Richards


Left run overview

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




67- Fence/Left

Date Taken: 11/13/2024

Taken By: Jacob Richards

5 panels missing from left run



68- Fence/Left

Date Taken: 11/13/2024

Taken By: Jacob Richards

One small gate missing from left run

Photo Sheet - 34 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A




69- Pool

Date Taken: 11/13/2024

Taken By: Jacob Richards

Pool overview



70-Pool

Date Taken: 11/13/2024
Taken By: Jacob Richards

During the storm the fence panels were seen by the member flying into pool causing rips and damages


Photo Sheet - 35 - 11/13/2024

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley

Claim #: 123456789-001

Policy #: 123456789-95A



71- Pool

Date Taken: 11/13/2024
Taken By: Jacob Richards



72-Pool

Date Taken: 11/13/2024

Taken By: Jacob Richards

Pool filtration system

Alacrity Solutions

A Geico Service Provider PO BOX 33490 San Antonio, TX 70265 800-521-8722 Insured: David Riley


Claim #: 123456789-001

Policy #: 123456789-95A



73- Pool

Date Taken: 11/13/2024
Taken By: Jacob Richards



74- Pool

Date Taken: 11/13/2024
Taken By: Jacob Richards

Photo Sheet - 37 - 11/13/2024