

CARAT planner, sensor reading +0.03 m³/m³ too wet, test season 2020, seed 1, budget 10 readings. A twin that is too wet under-irrigates and causes stress; (b) avoids this but runs slightly dry, the healthy-sensor cost discussed in METHODOLOGY §5.1. Simulated farm.