HTML Injection

Description:

This server is vulnerable to HTML injection which occurs when an attacker is able to control an input point and is able to inject arbitrary HTML code into a vulnerable web page using metacharacters. This may lead to consequences like disclosure of a user's session cookies or it can allow the attacker to modify the page content seen by the victims.

Solution

Properly validate meta-characters from user's inputs.

Occurrence:


Occurrence: 1


URL: http://testphp.vulnweb.com/userinfo.php

Parameter: urname

Payload: <marquee><h2>html injection test</h2></marquee>

Images:





Occurrence: 2

URL: http://testphp.vulnweb.com/search.php?test=query

Parameter: searchFor

Payload: <marquee><h2>html injection test</h2></marquee>

Images:

