STM TripModifications

Detours whose cancelled range is shorter than the detour itself

In a detour at the end of a line, the cancelled range collapses to a single stop while the detour shape published in the same entity skips a longer run of stops. The stops in between stay in the trip although the vehicle never reaches them, and a stop the vehicle no longer serves is sometimes re-added as a replacement stop. Detours in the middle of a line are correct. Each page below shows one affected modification: the same detour shape in both panels, the stops as the feed claims them on the left, and as the shape implies them on the right.

Feed timestamp 1794435064 (2026-11-11 17:11 America/Montreal) · 175 entities examined · 2 repaired

A stop is taken to be unserved when it lies more than 100 m from the detour shape. Stops the vehicle does serve measure 0–26 m from it; the errors below measure 94–471 m, so the reading does not depend on where in that gap the line is drawn.

Entity	Route	Declared	Repaired	What changed
`detour_197_E_23_75502`	197	`[42..42]`	`[41..42]`	+1 stop cancelled

Replacement stop not on the detour

`detour_57_N_9_71636`	57	`[2..2]`	`[2..2]`	dropped 52829 (196 m)

Source data: Société de transport de Montréal, licensed CC-BY 4.0. This analysis is unofficial and is not endorsed by the STM.


Route 197: cancelled range [42..42] should be [41..42]

197 — Rosemont → Est via de la Pépinière


`detour_197_E_23_75502` · `modification 0` · `trip 302037109`

1 stop kept in the trip sits up to 166 m from the detour shape.

STM's feed as published



After repair



Scheduled route · Detour shape from the feed · Stop still served · Stop cancelled · Replacement stop · Changed by the repair

Basemap: Esri, HERE, Garmin, © OpenStreetMap contributors. Transit data: Société de transport de Montréal, CC-BY 4.0.


Route 57: a replacement stop is not on the detour

57 — Charlevoix → Nord


`detour_57_N_9_71636` · `modification 0` · `trip 305633175`

replacement stop 52829 is 196 m from it.

STM's feed as published



After repair



Scheduled route · Detour shape from the feed · Stop still served · Stop cancelled · Replacement stop · Changed by the repair

Basemap: Esri, HERE, Garmin, © OpenStreetMap contributors. Transit data: Société de transport de Montréal, CC-BY 4.0.