


## PUMP TEST REPORT

| Invoice Number: | 1        |
|-----------------|----------|
| Customer:       | Madorido |
| Job Number:     | 1        |

| FABRICATION        |               | HYDRAULIC TEST    |            |
|--------------------|---------------|-------------------|------------|
| Pump Model:        | PT 0.55KW     | Date of Test:     | 2025-03-17 |
| Serial Number:     | 1101 002 - 25 | Duration of Test: | 1          |
| Impeller Diameter: | 1             | Test Medium:      | 1          |
| Assembled By:      | tester1       | Tested By:        | tester1    |

| DETAILS          |   |                    |    |  |
|------------------|---|--------------------|----|--|
| Motor Size:      | 1 | Frequency:         | 11 |  |
| Motor Speed:     | 1 | Pump Housing:      | 1  |  |
| Motor Volts:     | 1 | Pump Connection:   | 1  |  |
| Motor Enclosure: | 1 | Suction:           | 1  |  |
| Mechanical Seal: | 1 | Discharge:         | 11 |  |
|                  |   | Flush Arrangement: | No |  |

| TEST RESULTS |                |                |              |  |  |
|--------------|----------------|----------------|--------------|--|--|
| Test         | Flowrate (L/h) | Pressure (bar) | Amperage (A) |  |  |
| Test 1       | 17912          | 2.85           | 6.19         |  |  |
| Test 2       | 12050          | 3.05           | 5.52         |  |  |
| Test 3       | 8078           | 3.05           | 5.2          |  |  |
| Test 4       | 4089           | 3.05           | 4.87         |  |  |
| Test 5       | 0              | 3.05           | 4.74         |  |  |



| APPROVAL APPROVAL |            |  |  |  |
|-------------------|------------|--|--|--|
| Approved By:      | 1          |  |  |  |
| Date:             | 2025-03-17 |  |  |  |