


PUMP TEST REPORT

| Invoice Number: | |
|-----------------|----------------|
| Customer: | Mageu Number 1 |
| Job Number: | |

| Fabrication | | | |
|------------------------------|------------|------------------|--------|
| Pump Model: | PS 1.1KW | | |
| Serial Number: 3101 001 - 25 | | | |
| Impeller Diameter: | 140 | | |
| Assembled By: | tester1 | | |
| Details | | | |
| Motor Size: | 3 KW | Frequency: | 380 |
| Motor Speed: | 2882 | Pump Housing: | SS 316 |
| Motor Volts: | 380 | Pump Connection: | DIN |
| Motor Enclosure: | IP 55 | Suction: | 50 |
| Mechanical Seal: | TC/TC EPDM | Discharge: | 40 |
| | | Flush Arrangemen | t: No |

| Hydraulic Test | |
|-------------------|------------|
| Date of Test: | 2025-03-17 |
| Duration of Test: | 1 HOUR |
| Test Medium: | WATER |
| Tested By: | tester1 |

| Test Data | Flowrate (L/h) | Pressure (bar) | Amperage (A) |
|-----------|----------------|----------------|--------------|
| Test 1 | 17912 | 2.85 | 6.19 |
| Test 2 | 12050 | 3.05 | 5.52 |
| Test 3 | 8078 | 3.05 | 5.2 |
| Test 4 | 4089 | 3.05 | 4.87 |
| Test 5 | 0 | 3.05 | 4.74 |



| Approval | |
|--------------|-------------|
| Approved By: | TRAVIS MAIN |

Date: 2025-03-17