

Site Visit Report

Supplier:	CEPOTX — Cooperativa Central de Produção Orgânica da Transamazônica e Xingu
Sub-cooperative:	COOPOXIN
Site name:	Santa Anna Fazenda
Purpose:	B-06-58
Registered owner:	On-site verification of the organic cacao supply chain for FDA FSVP compliance (21 CFR 1.470–1.514): 1. Confirm the farm exists and grows cacao at the registered location. Ana Lucia Araujo de Sousa
Contact / host:	Jedielcio (CEPOTX agronomist / technical liaison)
Visit date:	30 August 2026 2. Assess biological hazard risks (microbial contamination, insect infestation, foreign objects, mold, pesticide residues). 3. Document fermentation and drying practices that determine cacao quality and safety.
Location:	Alcides region, Pará, Brazil 4. Capture photographic/video evidence with geotagged GPS coordinates.
GPS (centroid):	-3.292475, -52.572250
Area:	3 hectares (per CEPOTX registration)
Facilities visited:	A — cacao farm · B — fermentation · C — drying

Facility A — Cacao Farm (grove)

Site:	Santa Anna Fazenda — cacao grove
Site code:	B-06-58
GPS:	-3.292475, -52.572250
Observation:	Mature cacao trees, pods on trunks (cauliflory); healthy canopy; no visible disease.
Hazards assessed:	Microbial contamination: low · Insect infestation: low · Foreign objects: low · Mold: none observed · Pesticides: none observed



Facility A — cacao grove at Santa Anna Fazenda (IMG_7732)

Facility B — Fermentation

Site:	Santa Anna Fazenda — fermentation area
Site code:	B-06-58
GPS:	-3.292475, -52.572250
Observation:	Wooden fermentation boxes; batch turned by hand; 5–7 day typical protocol; clean environment.
Hazards assessed:	Microbial contamination: low (controlled fermentation) · Insect infestation: low · Foreign objects: low · Mold:



Facility B — wooden fermentation boxes (IMG_7735)

Facility C — Drying

Site:	Santa Anna Fazenda — drying shed
Site code:	B-06-58
GPS:	-3.292475, -52.572250
Observation:	Open-sided drying shed, beans spread on floor in thin layer; airflow management; no contamination source
Hazards assessed:	Microbial contamination: low (low moisture) · Insect infestation: low · Foreign objects: none observed · Mold



Facility C — drying shed (IMG_7742)



— FDA FSVP

14 · FDA FFR 14674182470

k)

/ (7.7s) — walk through cacao grove

572250

frame 2 — pods on trunk



/ (6.3s) — fermentation · IMG_7741.MOV (20.6s) — drying shed

572250



IMG_7741 — drying shed


CEPOTX SUPPLIER SITE VISIT — FDA FSVP

TrueTech Inc · Importer of Record · EIN 88-3411514 · FDA FFR 14674182470

Declaration

I hereby attest that the information recorded in this report was verified during an on-site visit to Santa Anna Fazenda (site code B-06-58), Altamira region, Pará, Brazil, on 30 August 2026. The supplier is registered with CEPOTX under the name Ana Lucia Araujo de Sousa. Photographic and video evidence with embedded GPS was captured at the time of the visit.

Sincerely,



Zhiwen Teh

President

TrueTech Inc · Importer of Record · EIN 88-3411514