
(a)
The gap across GIS 5/6 (where the model groin sits now)
Gap across GIS 5/6 (m)
GIS 6 minus GIS 5
175
150
125
100
75
50
25
0
built
repaired
Gordon
last repair
Isabel
Buxton fill
142
123
63
(b)
The gap across GIS 6/7
Gap across GIS 6/7 (m)
GIS 7 minus GIS 6
31
15
13
1970
1980
1990
2000
2010
2020
Year
CoastSat, annual, moved onto the photos
aerial photos
calibration 1996-2009
test 2009-2025
structural losses reported, 2015-2021