
The groin's life in one continuous run, 1967-2025
(a)
built
last repair
2017 fill; groin off
2022 fill
storms replayed from 1984-1999
Gap across the groins since 1967 (m)
175
150
125
100
75
50
25
0
−25
(b)
Strength
0.3
0.2
0.1
0.0
1970
1980
1990
2000
2010
2020
Year
model, no groin
model, window fits run continuously (0.25, then 0.16, 0.10, off)
model, fitted history (ramp to 0.25 by 1978, 0.25 to 2009, 0.2 to 2016, off)
observed, annual CoastSat (placed on the photos)
observed, wet/dry photo dates