IMS BEARING PREDICTIVE MAINTENANCE TECHNICAL REPORT

Report Date: 2026-10-09 11:04:14 Asset: Rexnord ZA-2115 Bearing #1

Vibration RMS Degradation Curve over Time



Bearing Health Index (HI) Prognosis Profile



Parameter	Engineered Value	Operational Status
Initial Vibration RMS	0.0863 g	Normal (Baseline)
Final Vibration RMS	0.8725 g	Severe Degradation
Peak Kurtosis	0.21	Spike Damage
BPFO Fault Energy	837210.03117	Outer Race Fault
Estimated RUL	0.0 Hours	Replace Immediately