


100-YEAR FLOODPLAIN DELINEATION — EXISTING AND PROPOSED CONDITIONS

North Branch Broad Creek at Fort Foote Road



0 100 FEET 1 in = 43 ft

KEALEE

Design, build, deliver

PROJECT

Indian Queen East — Lots 53, 54, 55 and 56

ADDRESS

9588 · 9584 · 9580 · 9576 Fort Foote Road

JURISDICTION

Prince George's County, Maryland

SHEET

FP-103 — FLOODPLAIN DELINEATION

DISCIPLINE

Maryland Professional Engineer

HORIZONTAL DATUM

NAD 83, Maryland State Plane, US survey feet (EPSG:2248)

VERTICAL DATUM

NAVD 88

WATERCOURSE

North Branch Broad Creek

CONTROLLING STRUCTURE

Fort Foote Road crossing, sag EL 54.00

DATE

2026-09-11

STATUS

PRELIMINARY. This delineation is derived from published county LIDAR terrain, not from a field survey, and is not a sealed floodplain study.

PROFESSIONAL CERTIFICATION

Maryland P.E. No. _____ Date _____

WATER-SURFACE ELEVATIONS

EVENT	EXISTING	PROPOSED	AREA
10-year	EL 54.61	EL 54.62	3.95 ac
25-year	EL 54.93	EL 54.94	4.05 ac
50-year	EL 55.20	EL 55.22	4.16 ac
100-year	EL 55.51	EL 55.52	4.27 ac

AREA BELOW THE 100-YEAR SURFACE

LOT	LOT AREA	EXISTING	PROPOSED
LOT 53	12,500 sf	11,100 sf (89%)	5,900 sf (47%)
LOT 54	23,500 sf	23,500 sf (100%)	22,100 sf (94%)
LOT 55	25,600 sf	24,500 sf (96%)	23,000 sf (90%)
LOT 56	13,900 sf	2,800 sf (20%)	700 sf (5%)

LEGEND

- 100-year floodplain limit — EXISTING condition
- 100-year floodplain limit — PROPOSED condition
- Lot boundary of record, Plat Book WWW 65 L 60
- Existing contour, 2 ft, county LIDAR (2023)
- Area below the 100-year water surface

BASIS OF DELINEATION

The limits shown are the intersection of the modelled water surface with the terrain, flood-filled from the watercourse so that depressions not connected to it are excluded. Water surface elevations are from a one-dimensional steady standard-step model of North Branch Broad Creek through the Fort Foote Road crossing, with the crossing analysed by FPAWA HCS-5 and the roadway treated as a broad-crested weir. Discharges are by NRCS TR-55 on a 307-acre contributing area. Terrain is PGADAS Contour 2 Ft (2023), NAVD 88, NOT A FIELD SURVEY. The existing culvert has not been measured. FPS 200546, the controlling county study of record, has not been obtained. See the floodplain study for the full basis, assumptions and limitations.