


1) KP

1.1 - Main Gate Camera



Weighment



Comment - Gate include weighment also , camera is far away from main gate ,
- Number of vehicle is running on the highway , large vehicle bounding bbox can collide with entry line , may be create false positive case with this angle.

2) UNIT – 2 - Main Gate



- Weighment is there but the camera is not working

Comment – For main Gate it is good , we can detect the entry , but what about the security guard ?? There is no office or cabin seen nearby for security guard if any activity will happen , security guard should be seen properly .

Eir camera an

There is weightment but person is going out from vehicle or not while weighing can't be accurat edrawn in this angle .

3) UNIT-4 : IP Camera 01_unit-4




Unit 4: workshop road view_unit-4



- Weighments are there but the cameras are not working(*weighment front view, weighment back view*)
- Main gate cameras are not working(Main gate overall outside, Main gate outside)

4) KARLAM: Main Gate KARLAM



KARLAM: New Main Gate_Karlam



KARLAM: Weighment front view KARLAM



- Weighment overall *Karlam* and *weighment Room cam Karlam* cameras are not working


KARLAM: Main Gate Outside view karlam



Comment -


Entry of person and vehicle we can detect , weightment camera should be from top but it is downward , we need to check

5) UNIT-6: MAIN GATE_UNIT-6



- *No weighments*

6) UNIT-11: MAIN GATE_UNIT-11




UNIT-11: MAIN GATE ENTRANCE_UNIT-11



Unit 11: Weight Front view unit-11



Unit 11: Weight overall view unit-11




Comment – Weightment View is Good and ok , but main gate entrance need to check

7) BBP-3: Main Gate




BBP-3: Main Gate Outside view



- No weighments

Camera is too far away

8) SHABAD: Main Gate



- No weighments

9) PEDDAPURAM: Main Gate




- PEDDAPURAM: Main Gate Outside cam1 and cam2 are not Working
- No weighments

10) HOSPET: Main Gate Hospet



- No weighments

11) BHUVANAGIRI: Main Gate




- No weighments

12) UNIT-3: Main Gate not working

- Main gate overall outside and main gate outside cameras are not working
- Main gate and weighments area camera is not working
- Weighments front view and weighments back view camera is not working

13) CWD: Main Gate view2



CWD: Weighment front view



Note - Other 4 facility Camera is Offline