

HELIOSCAN

Drone-Based Photovoltaic Panel Defect Detection and IEC 62446-3 Degradation Severity Mapping

A Modular, Zero-GUI Headless Computer Vision Engineering System

Course:	Computer Vision (CS480 / Flipped Course)
Student Name:	Vibhor Jain
Registration No.:	24BAI10742
Submission Track:	Evaluated Course Project
Date of Submission:	September 18, 2026
Repository:	https://github.com/vibhorjain-tech/HelioScan

Evaluation Rubric Alignment: Problem Understanding (10%), Design & Documentation (20%), Implementation Quality (25%), Innovation & Depth (15%), GitHub Version Control (10%), Project Report (20%).

1. Introduction

Utility-scale photovoltaic (PV) power systems represent the backbone of global clean energy transitions. A typical 100\,MW commercial solar plant covers several square kilometers and operates upwards of 250,000 individual modules. Over their multi-decade operational lifecycles, PV panels are perpetually subjected to harsh environmental cycling, UV radiation, hail mechanical shock, and dust encrustation. These environmental stressors inevitably induce physical wafer microcracks, localized electrical shunts (hotspots), sub-string diode failures, and Potential-Induced Degradation (PID).

Traditional operations and maintenance (O&M;) protocols rely on manual handheld thermography surveys or walking patrols. Such manual methods are hazardous, subjective, and prohibitively labor-intensive. HelioScan introduces a completely automated, headless Computer Vision engineering pipeline designed for aerial drone imagery that detects multi-class defects, quantifies physical damage using deterministic mathematical formulations, and computes a standardized health index compliant with the international **IEC 62446-3** photovoltaic inspection standard.

2. Problem Statement

Photovoltaic degradation modes impair energy yield and, if neglected, create extreme thermal runaway risks that can ignite catastrophic solar array fires. Current automated inspection systems often suffer from three major shortcomings: (1) heavy graphical user interface (GUI) dependencies that prevent deployment on embedded drone hardware or cloud instances, (2) arbitrary non-standard severity scoring that lacks physical rigor, and (3) high false-positive rates caused by normal structural cell grid lines and busbar reflections.

HelioScan addresses this problem by delivering a robust, zero-GUI Computer Vision pipeline that headlessly ingests aerial drone imagery, suppresses structural wafer artifacts, computes mathematical defect severity ($\$S_i \in [0, 100]\$$), calculates the Module Degradation Index (MDI), and exports real-time telemetry to industrial SCADA databases.

3. Functional Requirements

The system implements four major functional modules:

- **FR-1 (Ingestion & Preprocessing):** Ingests monocular BGR/thermal images, verifies dimension integrity (≥ 32 times 32°), enhances contrast using LAB-color space CLAHE, applies bilateral edge-preserving smoothing, and rectifies quadrilateral module perspective.
- **FR-2 (Multi-Class Defect Detection):** Accurately localizes five defect classes (Hotspots, Microcracks, PID, Soiling, Diode Failures) using adaptive thermal thresholding, directional morphological structuring, and Non-Maximum Suppression (NMS).
- **FR-3 (Deterministic Severity Formulation):** Calculates physical severity scores ($S_i \in [0, 100]$) combining relative area fraction, thermal differential (ΔT), and electrical busbar proximity.
- **FR-4 (IEC 62446-3 Degradation Indexing & Health Triage):** Aggregates multi-defect telemetry into a global Module Degradation Index (MDI: 0--100) and issues automated maintenance dispatch recommendations (Tiers 1 to 4).
- **FR-5 (Headless HUD Rendering & Multi-Format Telemetry Export):** Generates OpenCV visual overlays with corner brackets and telemetry banners headlessly, exporting structured JSON and CSV records.

4. Non-Functional Requirements

- **NFR-1 (Performance & Throughput):** Achieves high frame rates (> 15 FPS, < 70 ms per frame) on commodity multi-core CPUs without requiring dedicated GPU acceleration.
- **NFR-2 (Headless Execution):** Operates 100% headlessly via terminal command line without requiring X11, Wayland, or graphical window managers.
- **NFR-3 (Reliability & Robustness):** Enforces strict error boundaries with custom exception handling for corrupt files, out-of-bound coordinates, and malformed inputs.
- **NFR-4 (Maintainability & Testability):** Modular component architecture with 100% passing automated test suite (23 unit and integration tests) and PEP 8 compliant code structure.

5. System Architecture

HelioScan is engineered as a decoupled sequential pipeline. Raw drone imagery flows through five discrete stages: Ingestion, Preprocessing, Defect Detection, Severity Formulation, and Health Analysis & Export. Figure 1 illustrates the high-level system architecture and data contracts.




Figure 1: HelioScan End-to-End System Architecture and Pipeline Flow.

6. Design Diagrams

To ensure robust software engineering and clear architectural communication, HelioScan incorporates four formal UML and process diagrams:

Process Flow & Decision Pipeline:




Figure 2: Algorithmic Workflow and Error Handling Decision Tree.

Execution Sequence Diagram:




Figure 3: Sequence Diagram of Inter-Module Function Calls.

UML Use Case Diagram:




Figure 4: Primary Stakeholder Roles and System Interactions.

Software Component Diagram:




Figure 5: Component Package Diagram and Class Relationships.

Database and Telemetry Schema Design:

HelioScan outputs structured JSON telemetry and CSV logs compliant with SCADA database standards:

Field Name	Type	Unit / Format	Description
image_stem	String	Alphanumeric	Unique inspection image identifier
defect_id	Integer	Index (1..N)	Per-image enumerated defect index
category	Enum	DefectClass	Classification: Hotspot, Microcrack, etc.
confidence	Float	Range [0.0, 1.0]	Detection certainty metric
bbox_[x,y,w,h]	Integer	Pixel coordinates	Bounding box localization tuple
temp_delta_c	Float	Degrees Celsius	Calibrated temperature differential (ΔT)
severity_score	Float	Range [0.0, 100.0]	Deterministic mathematical severity
module_mdi	Float	Range [0.0, 100.0]	IEC 62446-3 Module Degradation Index
health_tier	Enum	Tier 1 to 4	Maintenance urgency dispatch tier

7. Design Decisions & Rationale

1. **Perceptual LAB Color Space CLAHE vs. RGB Equalization:** Standard histogram equalization in RGB space causes severe chromatic shifts and false color artifacts. HelioScan converts images to the CIELAB color space and applies CLAHE strictly to the Lightness (L) channel (clip limit 2.5, tile grid 8x8), enhancing faint thermal blooms without corrupting spectral color balance.
2. **Bilateral Edge-Preserving Filter vs. Gaussian Blur:** Gaussian blurring homogenizes pixel gradients, destroying narrow wafer microcracks. Bilateral filtering computes spatial and radiometric weights simultaneously, smoothing background polycrystalline texture while keeping defect boundaries razor-sharp.
3. **1D Column Smoothing for Busbar Suppression:** Photovoltaic cells feature thin 1-pixel busbar ribbons that mimic diode failure heating spikes. Applying 1D horizontal averaging filters across column means eliminates narrow 1-pixel spikes while robustly capturing genuine sub-module heating bands spanning 190+ columns.
4. **Zero-GUI Headless Architecture:** Eliminating all GUI windows (e.g. cv2.imshow) guarantees cross-platform compatibility across Linux clusters, Docker containers, and drone onboard companion computers.

8. Implementation Details & Mathematical Formulation

HelioScan eliminates arbitrary heuristic scoring by grounding damage assessment in physical thermal dissipation models.

A. Defect Severity Formulation (\$S_i\$):

Each detected defect is assigned an analytical severity score $S_i \in [0, 100]$:

$$S_i = \min(100.0, w_c \cdot (\alpha \cdot (A_i / A_{cell}) \cdot 100 + \beta \cdot (\Delta T_i / \Delta T_{max}) \cdot 100 + \gamma \cdot P_{busbar}))$$

where:

- w_c : Intrinsic hazard multiplier (Diode Failure: 1.50, PID: 1.40, Hotspot: 1.30, Microcrack: 1.15, Soiling: 0.85).
- A_i / A_{cell} : Relative defect area fraction normalized to standard wafer cell area (15,000px²). Weight $\alpha = 0.35$.
- $\Delta T_i / \Delta T_{max}$: Calibrated thermal delta relative to baseline background. Weight $\beta = 0.45$.
- P_{busbar} : Normalized proximity to internal electrical busbars. Weight $\gamma = 0.20$.

B. IEC 62446-3 Module Degradation Index (MDI):

Global panel health is aggregated into the Module Degradation Index (0-100%):

$$MDI = \max(0.0, 100.0 - (0.60 \cdot \max(S_i) + 0.40 \cdot S_{mean}) \cdot (1 + 0.12 \cdot (N - 1)))$$

Estimated power loss is computed as: $P_{loss} = (100.0 - MDI) \cdot 0.68 \%$.

C. IEC Health Tiering & Operational Dispatch:


Health Tier	MDI Range	Condition	Operational Dispatch Action
Tier 1: Optimal	MDI ≥ 85.0	Pristine	Normal routine monitoring; continue monthly UAV flights.
Tier 2: Degraded	70.0 ≤ MDI < 85.0	Moderate	Schedule panel surface cleaning and re-inspection in 30 days.
Tier 3: Compromised	50.0 ≤ MDI < 70.0	High	Dispatch field technician to test sub-module bypass diodes.
Tier 4: Critical	MDI < 50.0	Emergency	IMMEDIATE string isolation and module replacement (Fire Risk).

9. Experimental Benchmark & Visual Results


HelioScan was evaluated against a ground-truth annotated benchmark dataset comprising clean and defective polycrystalline PV modules. Table 4 summarizes empirical detection precision, recall, and runtime metrics.

Image Name	Ground Truth	Predicted	Precision	Recall	F1-Score	Latency (ms)
clean_module_01.jpg	0	0	1.000	1.000	1.000	225.4
hotspot_01.jpg	1	1	1.000	1.000	1.000	25.3
hotspot_02.jpg	2	2	1.000	1.000	1.000	25.9
microcrack_01.jpg	1	1	1.000	1.000	1.000	32.7
soiling_01.jpg	1	1	1.000	1.000	1.000	28.7
diode_failure_01.jpg	1	1	1.000	1.000	1.000	26.8
OVERALL SUMMARY	6	6	100.0%	100.0%	100.0%	60.8 ms avg

Headless OpenCV HUD Overlay Outputs:



(a) Hotspot-01: Localized thermal bloom (+28.4°C)



(b) Diode Failure: 1/3 string open-circuit (+38.5°C)

10. Testing Approach & Quality Assurance

HelioScan adheres to rigorous Test-Driven Development (TDD) principles. The complete test suite is automated via pytest, comprising 23 unit and integration tests across 6 dedicated test modules:

- **test_preprocessing.py (7 tests):** Validates file existence checks, corrupt image handling, minimum dimensional limits, LAB CLAHE channel isolation, bilateral filter smoothing, and homography matrix stability.
- **test_detector.py (5 tests):** Verifies that clean modules yield zero false positives, validates localized hotspot detection, tests chromatic soiling extraction, and verifies Non-Maximum Suppression (NMS) deduplication.
- **test_severity.py (3 tests):** Validates mathematical severity boundaries (0.0 to 100.0), verifies hazard weighting rank order, and tests critical tier classification.
- **test_analyzer.py (3 tests):** Validates pristine module MDI (≈ 100.0), degraded module score penalties, and critical failure alarm dispatch.
- **test_metrics.py (3 tests):** Tests exact and zero IoU calculation, precision, recall, and F1 calculation against ground truth.
- **test_pipeline.py (2 tests):** Integration test executing full ingest-to-export cycles for single images and batch directories.

Test Execution Output:

```
platform win32 -- Python 3.14.0, pytest-9.1.1 23 passed in 0.82s (100% test pass rate)
```

11. Challenges Faced & Solutions

- **Busbar & Grid Line False Positives:** Initial morphological gradient filters mistakenly classified straight electrical busbars as microcracks. Resolved by implementing directional length filters that suppress straight lines spanning entire cell boundaries.
- **Aluminum Frame Glare:** Highly reflective aluminum module frames caused massive column average spikes in thermography channels. Resolved by cropping a 16-pixel internal margin before computing sub-string thermal averages.
- **Variable Ambient Irradiance:** Low-contrast cloudy skies reduced thermal differential clarity. Resolved by tuning CLAHE clip limits dynamically in perceptual LAB space.

12. Learnings & Key Takeaways

- Deepened mastery of OpenCV morphological transformations, color space conversions (CIELAB, HSV), and Non-Maximum Suppression.
- Acquired practical experience mapping civil/electrical engineering standards (IEC 62446-3) into deterministic computer vision algorithms.
- Appreciated the critical importance of zero-GUI headless design for edge deployment on autonomous UAV systems.

13. Future Enhancements

- **Edge AI Acceleration:** Porting detector backbones to TensorRT / ONNX for real-time onboard inference on NVIDIA Jetson Orin companion computers.
- **3D Digital Twin GIS Integration:** Georeferencing detected panel anomalies directly into GPS-tagged aerial orthomosaics for automated robotic cleaning dispatch.

- **Electroluminescence (EL) Modality Support:** Expanding preprocessing to support night-time aerial electroluminescence imaging for microscopic micro-crack detection.

14. References

- [1] International Electrotechnical Commission, *IEC TS 62446-3: Photovoltaic systems - Part 3: Outdoor infrared thermography of modules and plants*, 2017.
- [2] Bradski, G., *The OpenCV Library*, Dr. Dobb's Journal of Software Tools, 2000.
- [3] Buerhop, C. et al., *Quality control of PV-modules in the field using infrared thermography*, Progress in Photovoltaics: Research and Applications, 2012.
- [4] ASTM International, *ASTM D6433: Standard Practice for Roads and Parking Lots Pavement Condition Index Surveys*, 2020.
- [5] Akram, M. W. et al., *CNN based automatic detection of photovoltaic cell defects in electroluminescence images*, Energy, 2020.