

	<b>PROOFLOAD (Services) Limited</b> RC.433639 Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt. Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a>	
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>		

CERTIFICATE NO. PSL/SI/ENL/HAW/MW/DEC.22/001

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH (STARBOARD SIDE).  
**SERIAL NUMBER** : MEP-063-1/1  
**TYPE** : MEP-AWMH-26-DG-SD4-10  
**MANUFACTURER/YEAR** : MARINELEAD MACHINE (TAIXING) Pte. Ltd (China)/JAN. 2010  
**RATED LOAD/CHAIN DIA.** : 28.2KN/26MM  
**SPEED** : 9M/MIN  
**DATE OF CURRENT INSPECTION** : 17.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- **VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** and found to be in satisfactory condition.

- **FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** in accordance to industry standards and statutory regulations as per **BS3701** and found to be in satisfactory condition.

- **MAINTENANCE RECORDS**

**HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided no major mechanical repairs are carried out on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**INSPECTOR** : OSAYAMWEN, SOLOMON  
**NEXT DUE DATE** : 16.06.2023

**SIGNATURE/DATE** : *PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*



**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT****CERTIFICATE NO. PSL/SI/ENL/HAW/MW/DEC.22/002**

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH (PORT SIDE).  
**SERIAL NUMBER** : MEP-063-1/2  
**TYPE** : MEP-AWMH-26-DG-SD4-10  
**MANUFACTURER/YEAR** : MARINELEAD MACHINE (TAIXING) Pte. Ltd (China)/JAN. 2010  
**RATED LOAD/CHAIN DIA.** : 28.2KN/26MM  
**SPEED** : 9M/MIN  
**DATE OF CURRENT INSPECTION** : 17.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

**• VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** and found to be in satisfactory condition.

**• FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** in accordance to industry standards and statutory regulations as per **BS3701** and found to be in satisfactory condition.

**• MAINTENANCE RECORDS**

**HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided no major mechanical repairs are carried out on the **HYDRAULIC ANCHOR WINDGLASS/MOORING WINCH** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**INSPECTOR** : OSAYAMWEN, SOLOMON

**NEXT DUE DATE** : 16.05.2023

**SIGNATURE/DATE** :

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt





## **PROOFLOAD (Services) Limited RC. 433639**

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### **REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/CH/DEC.22/001**

<b>Client</b>	<b>: ELSHCON NIGERIA LIMITED.</b>		
<b>Address Of Client/Location</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.</b>		
<b>DESCRIPTION</b>	<b>: CHAIN HOIST</b>		
<b>ID NO</b>	<b>: 166615</b>		
<b>SWL</b>	<b>: 5 TONS</b>		
<b>MAKE</b>	<b>: TOYO</b>		
<b>NO OF FALLS</b>	<b>: 2 FALLS</b>		
<b>DIAMETER</b>	<b>: 10 MM</b>		
<b>LENGTH</b>	<b>: 3 METERS</b>		

**INSPECTION DATE: 17.12.2022**

**NEXT DUE DATE: 16.06.2023**

<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARK / RECOMMENDATIONS</b>
STRUCTURAL	YES		Thorough Visual and function test were carried out and equipment certified fit for service
TROLLEY	YES		
MARKINGS	YES		
CHAIN	YES		
BOLT/NUT	YES		
HOOK	YES		
CONTROL	YES		
HOUSING	YES		
STOPPER	YES		
BEAM	YES		
WHEEL / TYRES	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13001**, and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt*

Date of Issue: 17.12.2022





## **PROOFLOAD (Services) Limited RC. 433639**

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### **REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/CH/DEC.22/002**

<b>Client</b>	<b>: ELSHCON NIGERIA LIMITED.</b>		
<b>Address Of Client/Location</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.</b>		
<b>DESCRIPTION</b>	<b>: CHAIN HOIST</b>		
<b>ID NO</b>	<b>: 166609</b>		
<b>SWL</b>	<b>: 5 TONS</b>		
<b>MAKE</b>	<b>: TOYO</b>		
<b>NO OF FALLS</b>	<b>: 2 FALLS</b>		
<b>DIAMETER</b>	<b>: 10 MM</b>		
<b>LENGTH</b>	<b>: 3 METERS</b>		

**INSPECTION DATE: 17.06.2022**

**NEXT DUE DATE: 16.06.2023**

<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARK / RECOMMENDATIONS</b>
STRUCTURAL	YES		Thorough Visual and function test were carried out and equipment certified fit for service
TROLLEY	YES		
MARKINGS	YES		
CHAIN	YES		
BOLT/NUT	YES		
HOOK	YES		
CONTROL	YES		
HOUSING	YES		
STOPPER	YES		
BEAM	YES		
WHEEL / TYRES	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13001**, and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

Date of Issue: 17.12.2022

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu Rumuigbo  
 Port Harcourt





## **PROOFLOAD (Services) Limited RC. 433639**

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### **REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/CH/DEC.22/003**

<b>Client</b>	<b>: ELSHCON NIGERIA LIMITED.</b>		
<b>Address Of Client/Location</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.</b>		
<b>DESCRIPTION</b>	<b>: CHAIN HOIST</b>		
<b>ID NO</b>	<b>: 166623</b>		
<b>SWL</b>	<b>: 5 TONS</b>		
<b>MAKE</b>	<b>: TOYO</b>		
<b>NO OF FALLS</b>	<b>: 2 FALLS</b>		
<b>DIAMETER</b>	<b>: 10 MM</b>		
<b>LENGTH</b>	<b>: 3 METERS</b>		

**INSPECTION DATE: 17.12.2022**

**NEXT DUE DATE: 16.06.2023**

<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARK / RECOMMENDATIONS</b>
STRUCTURAL	YES		Thorough Visual and function test were carried out and equipment certified fit for service
TROLLEY	YES		
MARKINGS	YES		
CHAIN	YES		
BOLT/NUT	YES		
HOOK	YES		
CONTROL	YES		
HOUSING	YES		
STOPPER	YES		
BEAM	YES		
WHEEL / TYRES	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13001**, and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu Rumuigbo  
 Port Harcourt

Date of Issue: 17.12.2022





## **PROOFLOAD (Services) Limited RC. 433639**

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### **REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/CH/DEC.22/004**

<b>Client</b>	<b>: ELSHCON NIGERIA LIMITED.</b>		
<b>Address Of Client/Location</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.</b>		
<b>DESCRIPTION</b>	<b>: CHAIN HOIST</b>		
<b>ID NO</b>	<b>: 166619</b>		
<b>SWL</b>	<b>: 5 TONS</b>		
<b>MAKE</b>	<b>: TOYO</b>		
<b>NO OF FALLS</b>	<b>: 2 FALLS</b>		
<b>DIAMETER</b>	<b>: 10 MM</b>		
<b>LENGTH</b>	<b>: 3 METERS</b>		

**INSPECTION DATE: 17.12.2022**

**NEXT DUE DATE: 16.06.2023**

<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARK / RECOMMENDATIONS</b>
STRUCTURAL	YES		Thorough Visual and function test were carried out and equipment certified fit for service
TROLLEY	YES		
MARKINGS	YES		
CHAIN	YES		
BOLT/NUT	YES		
HOOK	YES		
CONTROL	YES		
HOUSING	YES		
STOPPER	YES		
BEAM	YES		
WHEEL / TYRES	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13001**, and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

  
 PROOFLOAD SERVICES LTD.  
 Plot 23C Gbei Road,  
 Nkpolu Rumuigbo  
 Port Harcourt

Date of Issue: 17.12.2022





## PROOFLOAD (Services) Limited RC. 433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

**CERTIFICATE No: PSL/SI/ENL/WRS/DEC.22/001**

<b>Client</b>	: ELSHCON NIGERIA LIMITED.
<b>Address Of Client/Location</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.
<b>DESCRIPTION</b>	: ONE PART WIRE ROPE SLING FITTED WITH SOFT EYE BOTH ENDS.
<b>ID/TAG NO</b>	: TIGS/ENL/04/22/001
<b>Nominal Rope Diameter</b>	: 48 MM
<b>Length</b>	: 20 MTRS
<b>SWL</b>	: 29.6 TONS

<b>INSPECTION DATE: 17.12.2022</b>		<b>NEXT DUE DATE: 16.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Core	YES		
Entire length	YES		
Markings	YES		
Wire Termination (Ferrule)	YES		
Soft Eye	YES		
Thimble Eye	YES		
Diameter	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13414/1-4:2003** and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

Date of Issue: 17.12.2022

  
**PROOFLOAD SERVICES LTD**  
 Plot 23C Gbei Road,  
 Nkpolu Rumuigbo  
 Port Harcourt





## PROOFLOAD (Services) Limited RC. 433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.

Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

**CERTIFICATE No: PSL/SI/ENL/WRS/DEC.22/002**

<b>Client</b>	: ELSHCON NIGERIA LIMITED.
<b>Address Of Client/Location</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR.
<b>DESCRIPTION</b>	: ONE PART WIRE ROPE SLING FITTED WITH SOFT EYE BOTH ENDS.
<b>ID/TAG NO</b>	: TIGS/ENL/04/22/002
<b>Nominal Rope Diameter</b>	: 48 MM
<b>Length</b>	: 20 MTRS
<b>SWL</b>	: 29.6 TONS

<b>INSPECTION DATE: 17.12.2022</b>		<b>NEXT DUE DATE: 16.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Core	YES		
Entire length	YES		
Markings	YES		
Wire Termination (Ferrule)	YES		
Soft Eye	YES		
Thimble Eye	YES		
Diameter	YES		

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 13414/1-4:2003** and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp:

Date of Issue: 17.12.2022

**PROOFLOAD SERVICES LTD**  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo  
 Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/001**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED.
<b>ADDRESS OF CLIENT/LOCATION</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR
<b>NAME/ADDRESS OF MANUFACTURER</b>	: MORDEC
<b>ID NO.</b>	: E17
<b>DESCRIPTION</b>	: SAFETY PIN BOW SHACKLE
<b>SWL</b>	: 55 TONS

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: N/A</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin			
Body			
Split Pin			
Safe Working Load			
Nut			
Safety Pin			

**BAD, DUE TO WEARY GOUGE**

- VISUAL INSPECTION**  
Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in unsatisfactory condition.
- FUNCTION TEST**  
Function test was conducted on the shackle and was found to be in unsatisfactory condition.
- MAINTENANCE RECORDS**  
Shackle rejected is to be withdrawn from operations.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified unfit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/002**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED.
<b>ADDRESS OF CLIENT/LOCATION</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR
<b>NAME/ADDRESS OF MANUFACTURER</b>	:
<b>ID NO.</b>	: E20
<b>DESCRIPTION</b>	: SAFETY PIN BOW SHACKLE
<b>SWL</b>	: 13.5 TONS

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: N/A</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin			
Body			
Split Pin			
Safe Working Load			
Nut			
Safety Pin			

- **VISUAL INSPECTION**  
Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in unsatisfactory condition.
- **FUNCTION TEST**  
Function test was conducted on the shackle and was found to be in unsatisfactory condition.
- **MAINTENANCE RECORDS**  
Shackle rejected is to be withdrawn from operations.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified unfit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/003**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED.
<b>ADDRESS OF CLIENT/LOCATION</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR
<b>NAME/ADDRESS OF MANUFACTURER</b>	: MORDEC
<b>ID NO.</b>	: E12
<b>DESCRIPTION</b>	: SAFETY PIN BOW SHACKLE
<b>SWL</b>	: 35 TONS

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: N/A</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin			
Body			
Split Pin			
Safe Working Load			
Nut			
Safety Pin			

**BAD, DUE TO WEARY GOUGE**

- VISUAL INSPECTION**  
Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in unsatisfactory condition.
- FUNCTION TEST**  
Function test was conducted on the shackle and was found to be in unsatisfactory condition.
- MAINTENANCE RECORDS**  
Shackle rejected is to be withdrawn from operations.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified unfit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/004**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: GREEN PIN</b>
<b>ID NO.</b>	<b>: E05</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 12 TONS</b>

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: 15.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*





## PROOFLOAD (Services) Limited RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/005**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: GREEN PIN</b>	
<b>ID NO.</b>	<b>: 1NT</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 17 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**


Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo  
 Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/006**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: GREEN PIN</b>
<b>ID NO.</b>	<b>: E06</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 17 TONS</b>

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: 15.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/007**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: MORDEC</b>	
<b>ID NO.</b>	<b>: E001</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 25 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

• **VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

• **FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

• **MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/008**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: MORDEC</b>
<b>ID NO.</b>	<b>: E003</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 25 TONS</b>

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: 15.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/009**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: MORDEC</b>	
<b>ID NO.</b>	<b>: E005</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 25 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

• **VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

• **FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

• **MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt*





## PROOFLOAD (Services) Limited RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/010**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: MORDEC</b>	
<b>ID NO.</b>	<b>: E002</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 25 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo  
 Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/011**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED.
<b>ADDRESS OF CLIENT/LOCATION</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR
<b>NAME/ADDRESS OF MANUFACTURER</b>	: MORDEC
<b>ID NO.</b>	: E006
<b>DESCRIPTION</b>	: SAFETY PIN BOW SHACKLE
<b>SWL</b>	: 25 TONS

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: N/A</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin			
Body			
Split Pin			
Safe Working Load			
Nut			
Safety Pin			

**BAD, DUE TO DEFORMED BODY**

- VISUAL INSPECTION**  
Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in unsatisfactory condition.
- FUNCTION TEST**  
Function test was conducted on the shackle and was found to be in unsatisfactory condition.
- MAINTENANCE RECORDS**  
Shackle rejected is to be withdrawn from operations.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified unfit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt





## PROOFLOAD (Services) Limited RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/012**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: MORDEC</b>	
<b>ID NO.</b>	<b>: E017</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 17 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**


Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo  
 Port Harcourt





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloadng.com](mailto:info@proofloadng.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/013**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>	
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>	
<b>ID NO.</b>	<b>: E013/A</b>	
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>	
<b>SWL</b>	<b>: 55 TONS</b>	

<b>INSPECTION DATE: 16.12.2022</b>		<b>NEXT DUE DATE: 15.06.2023</b>	
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

• **VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

• **FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

• **MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/014**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>
<b>ID NO.</b>	<b>: E018</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 13.5 TONS</b>

<b>INSPECTION DATE: 16.12.2022</b>			<b>NEXT DUE DATE: 15.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 16.12.2022

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/015**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>
<b>ID NO.</b>	<b>: E55A</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 55 TONS</b>

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 17.12.2022

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/016**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>
<b>ID NO.</b>	<b>: E55B</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 55 TONS</b>

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 17.12.2022

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu-Rumuigbo  
Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/017**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>
<b>ID NO.</b>	<b>: E55C</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 55 TONS</b>

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 17.12.2022

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/ENL/SH/DEC.22/018**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>ADDRESS OF CLIENT/LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>NAME/ADDRESS OF MANUFACTURER</b>	<b>: CROSBY</b>
<b>ID NO.</b>	<b>: E01A</b>
<b>DESCRIPTION</b>	<b>: SAFETY PIN BOW SHACKLE</b>
<b>SWL</b>	<b>: 8.5 TONS</b>

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Screw Pin	N/A		
Body	YES		
Split Pin			<b>N/A</b>
Safe Working Load	YES		
Nut	YES		
Safety Pin	YES		

- VISUAL INSPECTION**

Thorough Visual inspection was conducted to check for break, wear, nicks, cracks, gouges, corrosion, deformation and was found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the shackle and was found to be in satisfactory condition.

- MAINTENANCE RECORDS**

Shackle accepted is to be maintained regularly.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been thoroughly Examined in accordance with **BS 3551:1998**, and is therefore **certified fit for service** as at the time of inspection.

Name of Govt. Licensed Inspector: OSAYAMWEN, SOLOMON

Signature and Company Official Stamp

Date of Issue: 17.12.2022

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*



	<b>PROOFLOAD (Services) Limited</b> RC.433639 Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt. Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a>	
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>		

CERTIFICATE NO. PSL/SI/ENL/SJ/DEC.22/001

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED
<b>LOCATION</b>	: ONBOARD ENL SUPERIOR
<b>ITEM</b>	: SHARK JAW/TOW PIN COMBINATION (PORT SIDE)
<b>SERIAL NUMBER</b>	: MEP-063-1/6
<b>SWL</b>	: 100 TONS
<b>MANUFACTURER</b>	: MARINELEAD MACHINERY (TAIXING) PTE LTD.
<b>SHARK JAW ROPE SIZE</b>	: 40 ~ 80 MM
<b>SHARK JAW CHAIN SIZE</b>	: 32 ~ 80 MM
<b>TOW PIN HEIGHT</b>	: 450 MM
<b>DATE OF CURRENT INSPECTION</b>	: 16.12.2022
<b>VALIDITY</b>	: SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- VISUAL INSPECTION**

A visual Inspection was conducted on the **SHARK JAW/TOW PIN COMBINATION** and found to be in satisfactory condition.

- FUNCTION TEST**

Function Test was conducted on the **SHARK JAW/TOW PIN COMBINATION** in accordance to industry standards and statutory regulations as per **LOLER/PUWER** and found to be in satisfactory condition.

- MAINTENANCE RECORDS**

**SHARK JAW** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR (PORT SIDE)** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided no major mechanical repairs are carried out on the **SHARK JAW/TOW PIN COMBINATION** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**INSPECTOR** : OSAYAMWEN, SOLOMON

**NEXT DUE DATE** : 15.06.2023

**SIGNATURE/DATE**

  
**PROOFLOAD SERVICES LTD.**  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo  
 Port Harcourt



**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT****CERTIFICATE NO. PSL/SI/ENL/SJ/DEC.22/002**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED
<b>LOCATION</b>	: ONBOARD ENL SUPERIOR
<b>ITEM</b>	: SHARK JAW/TOW PIN COMBINATION (STARBOARD SIDE)
<b>SERIAL NUMBER</b>	: MEP-063-1/6
<b>SWL</b>	: 100 TONS
<b>MANUFACTURER</b>	: MARINELEAD MACHINERY (TAIXING) PTE LTD.
<b>SHARK JAW ROPE SIZE</b>	: 40 ~ 80 MM
<b>SHARK JAW CHAIN SIZE</b>	: 32 ~ 80 MM
<b>TOW PIN HEIGHT</b>	: 450 MM
<b>DATE OF CURRENT INSPECTION</b>	: 16.12.2022
<b>VALIDITY</b>	: SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

**• VISUAL INSPECTION**

A visual Inspection was conducted on the **SHARK JAW/TOW PIN COMBINATION** and found to be in satisfactory condition.

**• FUNCTION TEST**

Function Test was conducted on the **SHARK JAW/TOW PIN COMBINATION** in accordance to industry standards and statutory regulations as per **LOLER/PUWER** and found to be in satisfactory condition.

**• MAINTENANCE RECORDS**

**SHARK JAW** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR (STARBOARD SIDE)** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided no major mechanical repairs are carried out on the **SHARK JAW/TOW PIN COMBINATION** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**INSPECTOR** : OSAYAMWEN, SOLOMON

**NEXT DUE DATE** : 15.06.2023

**SIGNATURE/DATE**

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt*





## PROOFLOAD (Services) Limited RC. 433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

### REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

CERTIFICATE NO. PSL/SI/ENL/STR/DEC.22/001

<b>OWNER</b>	<b>: ELSHCON NIGERIA LIMITED.</b>	
<b>LOCATION</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH Rivers State, Nigeria/ONBOARD ENL SUPERIOR.</b>	
<b>DESCRIPTION</b>	<b>: 1 PC OF NYLON 8 STRANDS DOUBLE LINE ROPE STRETCHER FITTED WITH SOLID THIMBLE WITH MASTER LINK AT BOTH ENDS.</b>	
<b>ID. NO</b>	<b>: BLS/ENL/08/15/005</b>	
<b>DIAMETER</b>	<b>: 102 MM</b>	
<b>LENGTH</b>	<b>: 20 MTRS</b>	
<b>MBL</b>	<b>: 163 TONS</b>	

	<b>INSPECTION DATE: 17.12.2022</b>		<b>NEXT DUE DATE: 16.06.2023</b>
	<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>
Entire length	Yes		
marking	Yes		
Termination	Yes		
Eye	Yes		
Diameter	Yes		

- VISUAL INSPECTION**

A visual inspection was conducted on the **STRETCHER** and found to be in satisfactory condition.

- FUNCTION TEST**

Function test was conducted on the **STRETCHER** in line with Industry and Statutory Standards as per **BS EN 1942-2004** and found to be satisfactory.

- MAINTENANCE RECORDS**

**STRETCHER ROPE** should be replaced on or before next due date while maintaining stretcher as per maker's recommendation.

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment have been inspected, and is therefore **certified fit for service** within its normal operational parameters; provided no major mechanical repairs are carried out on the **STRETCHER** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**NAME OF INSPECTOR: OSAYAMWEN, SOLOMON**

**SIGNATURE AND COMPANY OFFICIAL STAMP**

**DATE: 17.12.2022**

*PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt*





**PROOFLOAD (Services) Limited** RC.433639

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT**

**CERTIFICATE No: PSL/SI/CM TON/WS/CTB/DEC.22/001**

<b>CLIENT</b>	: ELSHCON NIGERIA LIMITED.
<b>Address OF Client/Location</b>	: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR
<b>DESCRIPTION</b>	: DOUBLE PLY FLAT WEBBING SLING
<b>TAG NUMBER</b>	: 0235
<b>MAKE</b>	: MAXTECH
<b>LENGTH</b>	: 1 MTR
<b>SAFE WORKING LOAD</b>	: 2 TONNES

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Eyes	YES		VISUALLY INSPECTED AND FOUND OK
Web	YES		VISUALLY INSPECTED AND FOUND OK

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 1492-1:2000** and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYEMWEN, SOLOMON

Signature and Company Official Stamp:

Date: 17.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt



**PROOFLOAD (Services) Limited RC.433639**

Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.  
Tel: +2348033100923, +2348033090238, [info@proofloading.com](mailto:info@proofloading.com)

**REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT****CERTIFICATE No: PSL/SI/CM TON/WS/CTB/DEC.22/002**

<b>CLIENT</b>	<b>: ELSHCON NIGERIA LIMITED.</b>
<b>Address OF Client/Location</b>	<b>: Deborah Lawson House, F6 Abacha Road, GRA Phase 3, PH. Rivers State, Nigeria/ONBOARD ENL SUPERIOR</b>
<b>DESCRIPTION</b>	<b>: DOUBLE PLY FLAT WEBBING SLING</b>
<b>TAG NUMBER</b>	<b>: 1882/49</b>
<b>MAKE</b>	<b>: CAM</b>
<b>LENGTH</b>	<b>: 1 MTR</b>
<b>SAFE WORKING LOAD</b>	<b>: 2 TONNES</b>

<b>INSPECTION DATE: 17.12.2022</b>			<b>NEXT DUE DATE: 16.06.2023</b>
<b>GENERAL CONDITION OF</b>	<b>GOOD</b>	<b>BAD</b>	<b>REMARKS / RECOMMENDATIONS</b>
Eyes	YES		VISUALLY INSPECTED AND FOUND OK
Web	YES		VISUALLY INSPECTED AND FOUND OK

I hereby declare on behalf of PROOFLOAD (Services) Limited that the above equipment has been inspected in accordance with **BS EN 1492-1:2000** and is therefore **certified fit for service** as at the time of inspection.

Name of Inspector: OSAYEMWEN, SOLOMON

Signature and Company Official Stamp

Date: 17.12.2022

PROOFLOAD SERVICES LTD.  
Plot 23C Gbei Road,  
Nkpolu Rumuigbo  
Port Harcourt



	<b>PROOFLOAD (Services) Limited</b> RC.433639 Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt. Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a>	
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>		

CERTIFICATE NO. PSL/SI/ENL/TW/DEC.22/001

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC TUGGER WINCH  
**SERIAL NUMBER** : MEP-063-1/3  
**MANUFACTURER/YEAR** : PTE LIMITED/JAN. 2010  
**DRUM CAPACITY** : 200 MTRS X 20 MM  
**RATED CAPACITY** : 5 TONS @ 10M  
**DATE OF CURRENT INSPECTION** : 16.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- **VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC TUGGER WINCH** and found to be in satisfactory condition.

- **FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC TUGGER WINCH** in accordance to industry standards and statutory regulations as per **BS 3701** and found to be in satisfactory condition. (**Tugger wire: No hook. Wire should be installed with socket and hook.**)

- **MAINTENANCE RECORDS**

**HYDRAULIC TUGGER WINCH** should be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided the above recommendations are carried out, in line with industry standards and statutory regulations as per **BS3701**.

**INSPECTOR** : OSAYAMWEN, SOLOMON

**NEXT DUE DATE** : 15.06.2023

**SIGNATURE/DATE** :

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*



	<p><b>PROOFLOAD (Services) Limited</b> RC.433639            Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt.            Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a></p>	
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>		

CERTIFICATE NO. PSL/SI/ENL/TW/DEC.22/002

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC TOWING WINCH (UPPER DRUM)  
**WINCH SERIAL NUMBER** : MEP-063-1/1  
**MAKE** : MEP SYSTEMS PTE LTD  
**MODEL** : MEP-AHTW-WF55-110  
**YEAR OF MANUFACTURE** : 2010  
**WIRE MANUFACTURER/YEAR** : DSR WIRE CORP/JAN. 2010  
**BRAKE HOLDING** : 110T  
**RATED PULL** : 55t @ 10M/MIN  
**DRUM CAPACITY** : 750 MTRS X 48 MM  
**DATE OF CURRENT INSPECTION** : 16.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC TOWIN WINCH (Upper Drum)** and found to be in satisfactory condition.

- FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC TOWIN WINCH (Upper drum)** in accordance to industry standards and statutory regulations as per **BS3701** and found to be in satisfactory condition.

- MAINTENANCE RECORDS**

**HYDRAULIC TOWIN WINCH** should be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided the crushed tow wire area are removed and resocketed, in line with industry standards and statutory regulations as per **BS3701**.

**INSPECTOR** : OSAYAMWEN, SOLOMON  
**NEXT DUE DATE** : 15.06.2023  
**SIGNATURE/DATE** :

*PROOFLOAD SERVICES LTD.  
 Plot 23C Gbei Road,  
 Nkpolu-Rumuigbo,  
 Port Harcourt*



	<b>PROOFLOAD (Services) Limited</b> RC.433639 Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt. Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a>
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>	

CERTIFICATE NO. PSL/SI/ENL/TW/DEC.22/003

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC TOWING WINCH (LOWER DRUM)  
**WINCH SERIAL NUMBER** : MEP-063-1/2  
**MAKE** : MEP SYSTEMS PTE LTD  
**MODEL** : MEP-AHTW-WF55-110  
**YEAR OF MANUFACTURE** : 2010  
**WIRE MANUFACTURER/YEAR** : DSR WIRE CORP/JAN. 2010  
  
**BRAKE HOLDING** : 110T  
**RATED PULL** : 55t @ 10M/MIN  
**DRUM CAPACITY** : 750 MTRS X 48 MM  
**DATE OF CURRENT INSPECTION** : 16.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC TOWIN WINCH (Lower Drum)** and found to be in satisfactory condition.

- FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC TOWIN WINCH (Lower drum)** in accordance to industry standards and statutory regulations as per **BS3701** and found to be in satisfactory condition.

- MAINTENANCE RECORDS**

**HYDRAULIC TOWIN WINCH** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided the leakage on the hoses connection point is stopped, in line with industry standards and statutory regulations as per **BS3701**.

**INSPECTOR** : OSAYAMWEN, SOLOMON  
**NEXT DUE DATE** : 15.06.2023  
**SIGNATURE/DATE** :

*PROOFLOAD SERVICES LTD.*  
*Plot 23C Gbei Road,*  
*Nkpolu-Rumuigbo*  
*Port Harcourt*



	<b>PROOFLOAD (Services) Limited</b> RC.433639 Office: Plot 23c Gbei Road, Nkpolu-Rumuigbo, Port Harcourt. Tel: +2348033100923, +2348033090238, <a href="mailto:info@proofloading.com">info@proofloading.com</a>	
<b>REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT</b>		

CERTIFICATE NO. PSL/SI/ENL/HSRW/DEC.22/004

**CLIENT** : ELSHCON NIGERIA LIMITED  
**LOCATION** : ONBOARD ENL SUPERIOR  
**ITEM** : HYDRAULIC STORAGE REEL WINCH (EMERGENCY)  
**SERIAL NUMBER** : MEP-063-1/4  
**MANUFACTURER/YEAR** : MEP SYSTEMS PTE LIMITED/JAN. 2010  
**DRUM CAPACITY** : 800 MTRS X 48 MM  
**SPEED** : 10M/MIN  
**DATE OF CURRENT INSPECTION** : 16.12.2022  
**VALIDITY** : SIX MONTHS INTERVAL AND AS REQUIRED DUE TO CONDITION

- **VISUAL INSPECTION**

A visual Inspection was conducted on the **HYDRAULIC STORAGE REEL WINCH** and found to be in satisfactory condition.

- **FUNCTION TEST**

Functional Tests was conducted on the **HYDRAULIC STORAGE REEL WINCH** in accordance to industry standards and statutory regulations as per **BS3701** and found to be in satisfactory condition.

- **MAINTENANCE RECORDS**

**HYDRAULIC STORAGE REEL WINCH** is to be maintained on a regular basis.

The above item located **ONBOARD ENL SUPERIOR** was tested by **PROOFLOAD SERVICES LIMITED** and is hereby certified fit for use within its normal operational parameters; provided no major mechanical repairs are carried out on the **HYDRAULIC STORAGE REEL WINCH** without the prior knowledge of the undersigned as such will nullify the validity of this certificate.

**INSPECTOR** : OSAYAMWEN, SOLOMON

**NEXT DUE DATE** : 15.06.2023

**SIGNATURE/DATE** :

PROOFLOAD SERVICES LTD.  
 Plot 23C Gbei Road,  
 Nkpolu Rumuigbo  
 Port Harcourt

