

property / Ground

floor 3D ULPIN: 3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:F001

Building 3D ULPIN: 3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:B001 · revision 1

Application identifiers, not official national issuance. Selected scope: floor. Findings and shared source files retain building context.

Property register


Parcel details

2D ULPIN: DEMO-LV-P01 (Demo - not officially issued)

FICTIONAL TRAINING DATA. All properties, plans and parcel IDs in this dataset are authored examples.


Parcel	Recorded area	Association
Parcel A	624 m²	confirmed

Building footprint: 360 m². Height: 12.8 m.



Plan in EPSG:32643 local metres. Blue: parcel; green: property; orange: computed discrepancy. Geometry is tied to the cited revisions.

Section



East–west cut at local northing 9.00 m. Levels in metres relative to BM-LAKEVIEW-DEMO. Both axes use the same scale; separate references are never aligned by assumption.

Building, floor and unit register

3D ULPIN	Record	Levels m	Area m ²	Volume m ³
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:F001	property / Ground Revision 1	Not supplied	Not supplied	Not supplied
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:S001	Living / dining Revision 1	0–3.2	70.52	225.664
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:S002	Bedroom Revision 1	0–3.2	70.52	225.664
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:S003	Studio Revision 1	0–3.2	70.52	225.664
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:S004	Bedroom / study Revision 1	0–3.2	70.52	225.664
3DU-0DXM2X7DCP8TM9J65B3F0A8CXY:S005	Common hall & stairs Revision 1	0–3.2	52.2	167.04

Building discrepancies and conditions

BUILDING_ROAD_OVERLAP Positive horizontal footprint overlap of 40.000 m² requires source/geometry review; this is not a legal determination. 558734c5-4f0a-4fb3-8859-53228d27fbb5: synthetic; fdb6f855-f533-487c-9ac7-525944640b2b: synthetic. 40 m²

Evidence

[fictional-building.json](#) · revision 1 · 2026-09-15T07:20:11.696Z

SHA-256 15dcdca98a301018a6ed6443f972a6b3bd538edf5c927fa781af402ddc81ad4b

[fictional-parcel.json](#) · revision 1 · 2026-09-15T07:20:11.856Z

SHA-256 950373c97ae02c5e045d2295284d40e88a34216bc1f180e976abde5c8ab636f2

[A-authored-spaces.csv](#) · revision 1 · 2026-09-15T07:20:12.316Z

SHA-256 3eadf2bb69660075e66f48decd31afebe37251cf76e8d9d07b4220d893f6fdd8

[A-floor-plans.pdf](#) · revision 1 · 2026-09-15T07:20:12.350Z

SHA-256 7c078e71c1cab8ebd3b97fff78b312af79cf1991ff63f24f2b7919dc5de78113

[A-floor-0.png](#) · revision 1 · 2026-09-15T07:20:12.369Z

SHA-256 d5c5f5a44d1e57ca44b184d5e0a39f74a60d01ca935fdb4c92aea3d1de68dcda

[A-floor-1.png](#) · revision 1 · 2026-09-15T07:20:12.388Z

SHA-256 32f23cf0fb2a71baddd76b5322f88c864aee1dfeaf99f69ea6c07b6af55af7c2

[A-floor-2.png](#) · revision 1 · 2026-09-15T07:20:12.404Z

SHA-256 f4421f9810e5207a22df26fce2c053d5a14fe6e4ac0f1dc362034f858ed9c0ac

[A-floor-3.png](#) · revision 1 · 2026-09-15T07:20:12.422Z

SHA-256 d0dddec9f6f616dc303936ad963c8273ad6ad6f086ab44ea94fff54e50d2ee476

[12 Lake View Road · reviewed detail derivative](#) · revision 1 · 2026-09-15T07:20:13.700Z

SHA-256 37ce6da0cc4c55142c6ac33cb36a4dbaf450b55f08760c631dc93e30e7d605a3

[R3.arcgis.json](#) · revision 1 · 2026-09-15T12:21:53.510Z

SHA-256 a0dd316d558942971bf5ed0f5ab9f4f040d069b21c6fd18b03580434d4c3bf74

[site-and-identity-schedule.pdf](#) · revision 1 · 2026-09-15T12:24:21.629Z

SHA-256 8ee4714f096ed30764a8816454ed9fb2d86db6f162c23868ea924898e14bb48c

Decision record

Local technical investigation; no official title, certificate or legal order. Sources remain immutable; unresolved conditions are retained.