


Hilbert curve absorber by Matthew Petroff











Coments:

Original file made by Petroff was bigger than the maximal printing size of our Form 3 printer, therefore design vas cut to fit printer building table with size 145×145 mm. » deformations were observed on print, one on the top of aborber edges a defect in edge was observed (marked with red). Another defect was observed on the bootom, and it was concluded, that it's source is defect on formlabs printer screen, which was most likely produced by a small support part, which was squezzed betwen laser head and screen and make irreverible deformation on the screen.