



**CONSULTANCY SERVICES TO VERIFY AND RECORD ASSETS
UNDER THE UGIFT PROGRAMME
REF: MOFPED/UGIFT/CONS/25/26/00015
ASSET VERIFICATION REPORT**

SUBMITTED BY:

SK&CO **Sejjaaka, Kaawaase & Co.**
AUDIT • ADVISORY • FORENSICS **Certified Public Accountants**

Plot 31, Bukoto Street
P.O Box 7657, Kampala, Uganda
+256 (0) 39 2000216/0772525235
email: cpa@cpa.ug
www.cpa.com

6 October 2026
Financial reporting date 30 September 2026

Executive summary.....	5
Priority actions.....	6
1 Introduction and background	7
1.1 Introduction.....	7
1.2 Background to the verification.....	7
1.3 Justification	8
1.4 Objectives of the assignment	8
1.5 Scope of Work	9
1.6 Expected deliverables	9
2 Approach and methodology	10
2.1 Preparation	10
2.2 Pilot Test.....	10
2.3 Data collection	10
2.4 Quality assurance	11
2.5 Asset categories, condition, use and identification	11
2.6 Financial analysis and Valuation	11
2.7 Analysis and reporting	11
2.8 Challenges and Limitations to the assignment.....	11
3 Findings	13
3.1 Overall results	13
3.2 National level Ministries and Agencies results.....	22
3.3 MDA specific results	23
3.3.1 Ministry of Finance, Planning and Economic Development	23
3.3.2 Ministry of Works and Transport.....	24
3.3.3 Ministry of Education and Sports	25
3.3.4 Ministry of Agriculture, Animal Industry and Fisheries.....	27
3.3.5 Ministry of Health.....	28
3.3.6 Office of the Prime Minister	29
3.3.7 Ministry of Water and Environment	30
3.3.8 Ministry of Gender, Labour and Social Development	31
3.3.9 National Environment Management Authority.....	31
3.3.10 Public Procurement and Disposal of Public Assets Authority.....	32
3.3.11 Office of the Auditor General (OAG).....	33
3.3.12 Ministry of Local Government	34
3.3.13 Ministry of Lands, Housing and Urban Development	35
3.4 Results from blood banks.....	37

3.4.1 Arua Regional Blood Bank	37
3.4.2 Hoima Regional Blood Bank	38
3.4.3 Soroti Regional Blood Bank	39
3.5 Local Government level results	41
3.6 Health Centres.....	41
3.6.1 Availability of the assets	41
3.6.2 Asset condition and functionality	42
3.6.3 Asset marking and Identification	44
3.7 Seed Secondary Schools	47
3.7.1 Availability of the assets	47
3.7.2 Asset condition and functionality	48
3.7.3 Asset marking and Identification	48
3.8 Financial Value of school assets	49
3.9 Completion Status of Facilities	50
3.10 Field Observations,	52
3.11 Location and Name changes	52
3.12 UgIFT support to service delivery	53
3.12.1 Gaps and Challenges.....	53
4 Asset management	55
4.1 Maintenance and repairs	55
4.2 Obsolete and Unserviceable Assets	56
4.3 Missing and Unrecorded Assets.....	56
5 Recommendations.....	58
5.1 Actions to address the reported service gaps	59
Annexures Appendices	60
Appendix A Financial reconciliation and valuation limitations	60
Extent of existing cost estimates	60
Appendix B Service date exceptions and supporting evidence	61
Rules for an approved register correction	62
Appendix C Definitions used in the analysis	63
Principal references.....	64
Appendix D Programme list exception roster.....	64
Appendix E Documented outstanding works and handover	66
Appendix F Facility interview scope and denominators.....	70
Appendix G Asset reconciliation examples	71
Appendix H Photographic schedule.....	72

Appendix I Land records and ownership evidence	74
Appendix J Additional assets and classification checks	76
Appendix K Financial analysis by asset type.....	76
MoFPED	77
MoWT	78
MoES	79
MAAIF.....	79
MoH	80
OPM.....	80
MoWE.....	81
MoGLSD.....	81
NEMA.....	82
PPDA	82
OAG.....	82
MoLG.....	82
MoLHUD.....	83
Arua Regional Blood Bank.....	83
Hoima Regional Blood Bank	85
Soroti Regional Blood Bank	86
Health centres.....	86
Schools.....	88
Appendix L Responses to reviewer comments	90

List of acronyms

GOU	Government of Uganda
HC	Health centre
ICT	Information and communications technology
IFMIS	Integrated Financial Management Information System
KCCA	Kampala Capital City Authority
LGFC	Local Government Finance Commission
MAAIF	Ministry of Agriculture, Animal Industry and Fisheries
MDA	Ministry, department or agency
MoDVA	Ministry of Defence and Veteran Affairs
MoES	Ministry of Education and Sports
MOES	Ministry of Education and Sports (as engraved)
MoFPED	Ministry of Finance, Planning and Economic Development
MoGLSD	Ministry of Gender, Labour and Social Development
MoH	Ministry of Health
MOH	Ministry of Health (as engraved)
MoLG	Ministry of Local Government
MoLHUD	Ministry of Lands, Housing and Urban Development
MoPS	Ministry of Public Service
MoWE	Ministry of Water and Environment
MoWT	Ministry of Works and Transport
NEMA	National Environment Management Authority
OAG	Office of the Auditor General
OPM	Office of the Prime Minister
PforR	Program-for-Results
PPDA	Public Procurement and Disposal of Public Assets Authority
RCU	Reform Coordination Unit
TELA	Teacher Effectiveness and Learner Assessment
UBTS	Uganda Blood Transfusion Services
UgIFT	Uganda Intergovernmental Fiscal Transfer
UGX	Uganda shillings
UPS	Uninterruptible power supply

Executive summary

The findings show a substantial stock of UgIFT assets supporting health care and secondary education, alongside equipment and buildings requiring attention. Facilities reported improvements in their services, but unfinished works, equipment out of use and weaknesses in asset identification limit the benefits. The report sets out the action needed to maintain the assets, complete outstanding works and resolve errors in the financial and custody records.

A total of 229,024 asset records were identified. Schools account for 145,256 and Health Centres for 63,432. A further 16,663 relate to ministries and agencies, 602 to regional blood banks, 3,067 to hospitals under local governments and four to other local-government locations. The total includes items whose receipt, classification or programme assignment still requires confirmation. These cases must be resolved before the full population can be certified as physically verified UgIFT assets.

Overall, 215,504 items (94.1%) are classified Functional and 13,520 (5.9%) Faulty, with the same numbers recorded as in use and out of use, respectively. Reasons for non-use include lack of power, unfinished buildings, missing parts and insufficient training. These require different responses. Usable tag details are unavailable for 178,695 items, making identification and custody checks a substantial task.

Facilities reported improvements in services following UgIFT support. Of 284 health-centre respondents, 238 (83.8%) reported at least one benefit, including improved maternity services, access to care and use of equipment. Of 193 school respondents, 144 (74.6%) reported benefits such as better learning conditions and access to secondary education. These are the facilities' accounts of changes in their services; the exercise did not measure how much of each change was caused by the programme.

The programme list contains 629 distinct facility entries. Supporting returns account for 590, while 39 have discrepancies requiring reconciliation. The reviewed evidence identifies at least 70 facilities with incomplete works and 13 others awaiting handover or commissioning. Some facilities were operating while particular buildings or supporting structures remained unfinished. Completion, handover and readiness for use therefore need to be confirmed separately.

Priority actions

MoFPED and the responsible institutions should first confirm when assets were placed in service. Of 201,066 full service dates, 3,345 precede programme approval on 27 June 2017. A further 27,958 entries contain partial dates or text, which cannot be accepted as exact service dates. The review also found 787 purchase dates later than the recorded service date. These findings overlap. Each affected date should be checked against receipt, acceptance or commissioning records, together with the asset's ownership and programme assignment.

Where a full service date cannot be supported, retain the reported period or status in the supporting records and leave the exact-date field blank until it is confirmed. A purchase date or the programme start date should not be used to fill the gap. Approve supported corrections before migration to IFMIS and recalculate depreciation and net book value where the corrected dates affect them.

Available recorded costs total UGX 996.813 billion, with costs missing for 1,086 records. Net book value remains unresolved for 23,016 records. For the 180,730 recognized records with complete accounting figures, cost of UGX 760.987 billion less accumulated depreciation of UGX 165.185 billion gives a net book value of UGX 595.802 billion at 30 September 2026. Net book value is the recorded cost remaining after depreciation; it does not measure the asset's market value or physical condition.

Cost evidence also needs review. Costs for 166,593 items were estimated by comparison with similar assets. These account for 82.44% of available recorded cost. Of 298 construction-in-progress entries, 275 have zero cost and four have no cost recorded. The recorded amounts therefore cannot establish the full value of unfinished works. Obtain the supporting expenditure or valuation records, resolve missing amounts and approve changes before treating the balances as a verified programme valuation.

Facility managers, local governments and the responsible ministries should give priority to essential equipment, reliable power and water, user training and outstanding buildings. Keep an action list naming the item or facility, the responsible officer and the agreed completion date. Assess faulty items for repair, replacement or disposal, and review the 22,161 fully depreciated records still marked in use. Reconcile delivery, transfer and custody records before concluding that an asset is missing. The recommendations and appendices provide the specific cases and follow-up required.

1 Introduction and background

1.1 Introduction

This report presents the findings of the UgIFT asset verification undertaken by the Ministry of Finance, Planning and Economic Development as part of programme closure activities. It sets out the status of the assets provided by the programme to the targeted national institutions responsible for supporting the implementation of the programme, Blood Banks and local governments specifically targeting Seed Secondary Schools and health facilities upgraded from Health Centre II to Health Centre III.

1.2 Background to the verification

The Uganda Intergovernmental Fiscal Transfers (UgIFT) Programme is a government programme implemented through a Programme-for-Results (PforR) launched and aligned with the broader IGFT Reform Programme (2015). UgIFT 1.0 began with US\$200 million in FY2017/18, supporting Education and Health. This was later expanded through additional financing of US\$300 million, including US\$240 million in credit and US\$60 million in grants, with US\$50 million from the IDA Refugee Support Window, expanding beyond Education and Health to water and Environment and Agriculture (micro-scale irrigation) making the overall funding total of US\$500 million.

The Intergovernmental Fiscal Transfer Reform Programme (IGFT RP) was revised in 2020 to align with the Third National Development Plan (NDP III 2020/21 - 2024/25), and to directly contribute to Four (04) Programmes i.e. Human Capital Development; Public Sector Transformation; Natural Resources, Environment, Climate change, Land and Water Management; and Development Plan Implementation.

Overall, the development objective of the UgIFT Programme was to: “Improve the adequacy, equity, and effectiveness of financing and the oversight, management, and delivery of Local Government services in Education, Health, Water and Environment, and Agriculture (micro-scale irrigation), including refugees and their host communities”.

Specifically, the Programme sought to:

1. Increase the adequacy and predictability of fiscal transfers to Local Governments for service delivery;
2. Improve the equity and transparency of allocation mechanisms through the introduction of formula-based transfers;
3. Strengthen performance incentives and accountability systems for Local Governments; and
4. Expand access to quality education and health infrastructure, particularly in under-served areas.

The UgIFT Programme had four components aimed at strengthening the intergovernmental fiscal transfer system while supporting investments in service delivery infrastructure. These included;

Component 1: Reform of the Intergovernmental Fiscal Transfer System

This supported the design and implementation of a reformed fiscal transfer framework based on objective and transparent allocation criteria. This resulted into introduction of formula-based grants - Revised allocation formulas reflecting population, infrastructure gaps, and service delivery needs.

Component 2: Education Infrastructure Development

This component financed the construction and upgrading of education facilities, particularly government secondary schools in under-served sub-counties. This involved construction and equipping of new secondary schools - classrooms, laboratories, administration blocks, sanitation facilities, teachers' houses, furniture and ICT equipment in the different local governments.

Component 3: Health Infrastructure Development

This supported investments in health facilities to improve access to primary health care services at the local level. The major outputs under the component were construction and upgrading of health centers - Staff accommodation, sanitation facilities and provision of medical equipment.

Component 4: Local Government Performance and Institutional Strengthening

This aimed at strengthening LG capacity in planning, budgeting, procurement, and infrastructure management. Under this component, annual Local Government Performance Assessments have been undertaken across the 176 LGs, capacity building and technical support strengthened monitoring and reporting systems.

The Programme was implemented through a clearly defined results framework that connected actions and incentives across three levels of government to strengthen service delivery outcomes. The programme came to an end on 31 December 2025. The following areas of support describe the following outputs under the different components; current asset and facility findings are presented later in this report.

1. Budget Support

- a) Education: 196 of 259 Seed Secondary Schools are complete of which 189 are operational.
- b) Health: 354 of 373 health facilities, upgrades/new constructions (HC II to HC III) are complete.
- c) Water and Environment: 758 - piped water systems, 5,398- point water sources, 7,082 water supply systems rehabilitated, 325 designs completed, and 256 sanitation facilities in the targeted service units.
- d) Agriculture (Micro-scale Irrigation): Over 6,235 irrigation systems were installed (4,843 hectares under irrigation), 632 irrigation demonstration sites in 135 LGs set up.
- e) Refugee intervention: 51 primary schools and 35 health facilities in refugee hosting districts (RHD) were transitioned and integrated into the LG service.
- f) Blood Banks: Regional Blood Banks in Arua and Hoima were completed and commissioned while Soroti Regional Blood Bank was rehabilitated.

2. Grant management

Assets for institutional strengthening and retooling including ICT equipment and vehicles were provided. The Ministry of Finance, Planning and Economic Development (MoFPED) through PFM Coordination Unit (RCU) manages the Government of Uganda counterpart funding of the programme to support the grant management component of the UgIFT programme. The grant management supports in financing of Central Government actions intended to achieve programme objectives and Disbursement Linked Indicators (DLIs). To this end, MoFPED through RCU supported MDAs to acquire different assets meant to support programme implementation.

1.3 Justification

The UgIFT programme came to an end on 31st December 2025. As part of the programme's closure activities, MoFPED, through RCU, commissioned an end-of-programme asset verification exercise to take stock of the assets procured under the programme and to establish where those assets were, how they were being used as part of the processes to hand them over to government for sustainability purposes.

1.4 Objectives of the assignment

The objective of the assignment was to undertake verification and recording of all assets acquired under the UgIFT Programme. Specifically, the assignment intended to;

- a) Identify and verify the existence of the assets
- b) Verify the assets condition and status: specifically, the condition on functionality, usage/performance and location among others
- c) Assess financial management aspects: residual value of the investments/hardware/tools for purposes of financial reporting for project closure
- d) List the assets that are obsolete, unserviceable and require disposal
- e) Develop a computerized database of the investment/hardware/tools to facilitate recording of new deployed assets/investments.
- f) Undertake PFM Assessment on Asset Management practices (including sustainability, Operations and Maintenance) of the UgIFT implementing LGs

1.5 Scope of Work

The assignment covered institutions at national and local government level that directly implemented the UgIFT programme through coordination, support and implementation. At local government level, the study focused on upgraded health facilities and Seed Secondary Schools that received assets under the programme. Health Centers and other local-government assets are also reported separately.

Specifically, the assignment involved the following tasks;

- a) Verification of the Asset's Records of targeted ministries departments and agencies and local governments
- b) Physical and Functional Verification of assets
- c) Data Consolidation for generation of a single data base of assets provided by the program
- d) Generation of an IFMIS ready Asset Register for Integration, and Migration into IFMIS
- e) Review of the UgIFT Asset Management Practices

1.6 Expected deliverables

Key expected outputs of the consultant include:

- a) Report with the list and current status of assets acquired under the programmes;
- b) An automated up-to-date assets data base of UgIFT Investments across MDALGs;
- c) Report on the estimated value of assets under the programme as well as operations and maintenance arrangements;
- d) IFMIS-Ready Asset Register and Data Migration Report
- e) Report on functionality of assets relating to systems investments;
- f) Report on Assessment of Asset Management Practices, Risks and recommendations.

2 Approach and methodology

The verification exercise was conducted using a participatory and consultative process and implemented in three interlinked phases: Preparatory and inception phase, Data collection phase and the report writing phase.

2.1 Preparation

After signing of the contract, the assignment commenced with an entry meeting on 28th May 2026. During this meeting, the Client specified target MDAs to be visited, the LG stakeholders to be reached as well as the documents to be reviewed. The Inception phase was completed and the inception report submitted on 18th June, 2026 which provided an agreed scope, approach and work plan for the exercise.

2.2 Pilot Test

The team also undertook a pilot test in Wakiso District Local Government, with verification carried out at Buloba Health Centre III and Sumbwe Seed Secondary School. During the pilot test, it was found out that, among others, there are cases of mismatches of facility names, that UgIFT assets can be integrated into the general LG asset register. This facilitated improving the design of the data collection process including; design of data collection tools, determining the timeline for data collection and estimated costs.

2.3 Data collection

This exercise was undertaken in two phases first at National level and later at the Local government level.

National level: Physical visits to verify assets provided by the programme at the national-level was completed on the 19th of August 2026. This covered 15 MDAs including; Ministry of Works and Transport (MoWT); Ministry of Education and Sports (MoES); Ministry of Agriculture, Animal Industries and Fisheries (MAAIF); Ministry of Health (MoH); Office of the Prime Minister (OPM); Ministry of Water and Environment (MoWE); Ministry of Gender, Labour and Social Development (MoGLSD); Local Government Finance Commission; National Environment Management Authority (NEMA); Public Procurement and Disposal of Assets Authority (PPDA); Office of the Auditor General (OAG); Ministry of Public Service (MoPs); Ministry of Lands, Housing and Urban Development (MoLHUD); Ministry of Local Government (MoLG) and Ministry of Finance, Planning and Economic Development (MoFPED). Additionally, three Blood Banks of Hoima, Arua and Soroti were covered.

Local government level: The local government verification targeted UgIFT upgraded or constructed Health Centres and Seed Secondary Schools. The programme reconciliation list contains 629 distinct entries: 371 Health Centres and 258 schools under 160 recorded local government names. The process began with training of field teams prior to the actual field verification.

Training of field teams: A total of 85 Research Assistants (RAs) and 7 Regional Supervisors were trained. The training took place from 21st to 23rd August 2026 while physical verification started on the 24th of August 2026. During the asset verification, the RAs visited Seed Secondary Schools, Health Centres and Blood Banks.

Physical verification: This exercise commenced on the 24th of August 2026 and was completed on 17th September 2026. The local government physical verification involved entry meetings with the LG leadership at the LG headquarters for authorization and review of reports relating to UgIFT assets, key informant interviews with the technical teams especially the Chief Administrative Officers, Finance Officers, District Health Officers and District Education Officers. Thereafter, the RAs proceeded to the facilities for physical verification of the assets.

At local government level, the programme list had 629 facilities: 371 Health Centres and 258 Seed Secondary Schools. The list recorded 547 facilities (87.0%) as complete and 82 (13.0%) as ongoing. The ongoing works were more common among Seed Secondary Schools (63, or 24.4%) than among Health Centres (19, or 5.1%).

2.4 Quality assurance

Regional supervisors checked daily field activity and reviewed the completed tools. The central technical team carried out spot checks and helped resolve operational questions. Teams compared institutional asset information with the items and explanations provided during visits, while supervisors referred matters requiring clarification to the team leader and field coordinator.

2.5 Asset categories, condition, use and identification

Asset categories: Each entry in the Asset Register represents one recorded unit. The analysis covers buildings, ICT equipment, transport equipment, furniture and fittings, medical, laboratory and research equipment, other classified assets, items outside fixed-asset classification and unclassified entries. Assets are grouped by the institution or beneficiary to which they are attributed.

Condition and use: Condition and use were reported for each asset during the verification. A working asset is one recorded as functional and in use. An asset recorded as faulty was reported as not working and not in use. This included assets that were broken down or damaged. An asset that was new and in store was recorded as functional but not in use. Additionally, an asset that was held elsewhere, not yet delivered or awaiting power installation, completion of buildings or trained users, was also recorded as functional but not in use.

Identification: An asset is properly identified when carried a UgIFT programme marking. However, there were other assets that had no UgIFT marking but the officers on ground identified them as UgIFT assets.

2.6 Financial analysis and Valuation

The Government of Uganda Asset Accounting Policies and Guidelines 2023 was used to determine as the policy basis for determining recorded values, depreciation and net book values. Financial values are reported as at 30th September 2026. Straight-line depreciation was applied where the required information was available.

2.7 Analysis and reporting

Analysis and reporting was done through triangulation of the literature from different policy, Planning and Financial documents including: Government of Uganda Asset Accounting Policies and Guidelines 2023; asset registers; asset records at national and local government levels; physical inspections; discussions with facility managers; photographs and asset counts for each institution.

2.8 Challenges and Limitations to the assignment

- a) Difficult terrain and poor physical accessibility of facilities: Physical accessibility presented a significant operational challenge especially for facilities located in areas characterised by difficult terrain and limited transport accessibility such as Bwesumbu HC III, Bwesumbu Seed School, Buhuhira and Kabingo in Kasese District. In addition, accessing facilities within the Island was difficult, time consuming and expensive. This led the teams to overshoot the anticipated time for data collection.
- b) High transportation cost: Given the national wide coverage, the rising fuel prices led to high field costs. The field teams spent more money than was anticipated. The costs were extra ordinarily higher for island facilities like Kalangala, Buvuma, Mayuge among others. For instance, Kalangala had 3 facilities with long distance on water that required hiring a private boat since it was not a

common route to the transporters and outside the ferry schedules. A similar situation was encountered in Buvuma and Namayingo districts.

- c) Poor record keeping: In many LGs and facilities, there were no clear records about the assets delivered under UgIFT. The LGs and the facilities had incomplete or missing UgIFT asset registers which delayed data collection. Subsequently, the teams took longer in such facilities identifying the assets as most of these were not engraved with the UgIFT identifiers while others were not engraved at all. In addition, the field teams encountered situations where some Assets could not be physically accessed especially for schools since it was holiday time.

3 Findings

This section presents results of the verification exercise based on the specific objectives. The results are presented in different results levels indicating availability of assets, asset condition and functionality, asset marking and identification and the financial analysis in each subsection.

3.1 Overall results

This section provides an overall view of the UgFT asset status combining both National level agencies and schools and health centres.

1. Overall asset availability

A total of 229,024 assets are recorded across the targeted MDAs, beneficiary Blood Banks, Upgraded Health Centres and Seed Secondary School. These include vehicles, laptops, printers, desktop computers, projectors, cameras, furniture (desks, chairs, tables and stools), UPS systems, digital phones, paper shredders, tablets and clinical equipment, among others.

Overall, the Seed Secondary Schools hold the majority of assets 63.4% (145,256), followed by Health Centres with 27.7% (63,432). MDAs hold 7.3% (16,663) and regional Blood Banks with 0.3% (602). In addition, some assets were found to have been reallocated by LGs from Health Center to hospitals such as Rukoki general hospital in Kasese Municipality. Hospitals hold 3,067 assets (1.3%) and other local-government locations hold four (less than 0.1%).




Figure 1: Distribution of assets

Source: Primary data analysis

2. Overall asset Condition and functionality

Overall, 215,504 assets constituting 94.1%, were classified as functional and in use, while 13,520 (5.9%) were classified as faulty and out of use. The detailed analysis of asset condition is indicated in table 1.

Table 1: Overall condition of UgIFT assets and functionality

Institution	Assets	Functional and in use	Faulty and not in use	Functional share
MoFPED	458	458	0	100.0%
MoWT	87	71	16	81.6%

Institution	Assets	Functional and in use	Faulty and not in use	Functional share
MoES	10,783	10,783	0	100.0%
MAAIF	2,045	2,045	0	100.0%
MoH	260	259	1	99.6%
OPM	10	7	3	70.0%
MoWE	2,939	2,939	0	100.0%
MoGLSD	10	10	0	100.0%
NEMA	6	6	0	100.0%
PPDA	5	5	0	100.0%
OAG	20	20	0	100.0%
MoLG	13	13	0	100.0%
MoLHUD	27	27	0	100.0%
Health centres	63,432	57,759	5,673	91.1%
Seed Secondary Schools	145,256	137,465	7,791	94.6%
Blood Banks	602	578	24	96.0%
Hospitals on LG books	3,067	3,055	12	99.6%
Other LG locations	4	4	0	100.0%
Total	229,024	215,504	13,520	94.1%

Source: Primary data analysis

As indicated in table 1 above, most of the deployed assets were already in service while some were in store and still in good condition but not in use. This was attributed mainly to some localized challenges such as power, incomplete structures, untrained staff, among others. Some assets were broken mainly furniture in Seed Secondary Schools and require repair.

Verification also noted that 13,520 assets, mainly in seed secondary schools and Health Centres, were classified as faulty and out of use. Some were awaiting installation or the facility itself was not yet ready. Notable among the facilities include Lungulu Seed Secondary School in Nwoya District where desktop computers, a printer and UPS units were still boxed because the school was waiting for power connection. At Nansanga Seed Secondary School in Budaka, 27 of 28 desktop computers remained packed for lack of reliable power.

Figure 2 shows the reasons for non-deployment of some of the assets even when they were found to be in good condition.




Figure 2: Reasons for equipment not in use reported by facilities (156 respondents; multiple responses)

Source: Primary data analysis

In addition, broken desks and stools were in classrooms and stores at Seed schools in Namisindwa and Napak. At Arua Regional Blood Bank, six blood pressure machines were recorded as damaged or not functional. The information above is depicted in some of the photos presented below.

	
Delivery bed with a torn mattress cover at a health centre, Busia District (Bukedi)	Pedal suction unit marked MAJANJI H/C III still in its packing, recorded as not in use for lack of technical knowledge, Majanji Health Centre III, Busia District (Bukedi)



Stacked desks, chairs and stools, some recorded as broken and none engraved, at Napak Seed Secondary School, Napak District (Karamoja)



Cracked health centre block above collapsed ground, Bulambuli District (Bugisu)



Broken desk frame at a seed secondary school, Namisindwa District (Bugisu)



Empty ICT and library block with a few chairs and items kept in one corner at Iriiri Seed Secondary School, Napak District (Karamoja), not yet in use while the school remained with the contractor




Stained and peeling ceiling at a health centre, Sironko District (Bugisu)



Flood-affected older health facility at Butiaba, Buliisa District (Bunyoro)



Desktop computers, a printer and UPS units still boxed in the store at Lungulu Seed Secondary School, Nwoya District (Acholi), awaiting a power connection for installation



Laboratory stools and desks stored and not yet in use at Butungama Seed Secondary School, Ntoroko District (Tooro), where the school buildings were still under construction



HP computer sets stacked in store with cables still bundled and not installed at Bumufuni Seed Secondary School, Bulambuli District (Bugisu)



beds and screens stacked in storage at a health centre, Kagadi District (Bunyoro)



Boxed projector, air conditioner and other equipment in store at King Solomon Seed Secondary School, Kagadi District (Bunyoro), kept boxed because the school was still under construction



Boxed handheld pulse oximeters at Kibiri Health Centre III, Makindye-Ssabagabo Municipal Council (Buganda), where equipment was still being arranged after the facility opened on 31 August 2026

3. Asset Marking and Identification

The verification revealed that 50,329 (22.0%) of the assets had usable identifiers and 178,695 (78.0%) had no usable identifier recorded. Of all assets, 22,253 (9.7%) had identifiers containing UgIFT or UGFT as a form of identification.

Identification varied at the different asset locations. Identifiers are recorded for 30.3% of MDA records, 24.5% of school records and 15.0% of health-centre records. Among the MDAs, the Ministry of Education and Sports accounts for most of the ministry assets without usable identifiers, and these were mainly the TELA handsets and tablets. The details of asset identification are provided in figure 3.





Figure 3: Asset marking and Identification

Below are some of the photos depicting the different markings and identification engravements of assets across the institutions

Engraving reading GOU/MOH-UGIFT PROJECT FY/2023/2024 on a desk at Namwaya Health Centre III, Tororo District	Engraving reading APSSS MOES/UGIFT/KABE/SPLRS/2023-24/001 on a desk at Aperikira Seed Secondary School, Kaberamaido District
Chair engraved UgiFT/ BUDDE SEED S.S M-PHALL CHAIR 102 with a serial number at Budde Seed Secondary School, Butambala District	Wheelchair backrest marked GOU/MOH UGIFT-PROJECT. FY2023/2024 at Kalemungole Health Centre III, Moroto District

	
Engraving reading GOU/MOH-UGIFT PROJECT FY2023-2024/01 on a weighing scale at Kalemungole Health Centre III, Moroto District	Microscope marked KAMORU HC III by hand at Kamoru Health Centre III, Kotido District
	
Engraving reading KING SOLOMON SEED SECONDARY SCHOOL, without a UgIFT marking, on furniture at King Solomon Seed Secondary School, Kagadi District	Engraving reading KWN/MED-EQ/MOYOK HCIII on a steel cupboard at Moyok Health Centre III, Kween District

4. Financial analysis/ valuation

Overall, the 229,024 assets across the different institutions had an available recorded value of UGX 996,812,628,890. Based on the straight-line depreciation method, available accumulated depreciation was UGX 165,185,197,307 and available net book value was UGX 595,801,587,531 as at 30th September 2026. Recorded values vary by institution, with MDAs at UGX 32,054,743,836, Blood Banks at UGX 1,503,720,926, Seed Secondary Schools at UGX 700,242,561,371 and Health Centres at UGX 260,692,452,291, as indicated in table 2. Hospital and other local-government assets account for the remaining UGX 2,319,150,466. These available totals cover different populations; Appendix A reconciles cost less depreciation to net book value for assets with complete accounting information.

Table 2: Overall Recorded asset value and net book value

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Schools 145,256 records; NBV 130,449/145,256	700,242.561*	104,574.530*	394,241.709*	79.0%
Health centres 63,432 records; NBV 55,604/63,432	260,692.452*	39,211.095*	189,403.577*	82.8%
Ministries and agencies 16,663 records; NBV 16,567/16,663	32,054.744*	19,787.511*	10,265.925*	34.2%
Hospitals on LG books 3,067 records; NBV 2,795/3,067	1,888.015*	778.948*	912.033*	53.9%
Regional blood banks 602 records; NBV 589/602	1,503.721*	553.689*	826.632*	59.9%

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Other LG locations 4 records; NBV 4/4	431.136	279.424	151.712	35.2%
Total 229,024 assets; NBV 206,008/229,024	996,812.629*	165,185.197*	595,801.588*	78.3%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.2 National level Ministries and Agencies results

1. Overall Asset availability at Ministries and Agencies

The exercise recorded 16,663 assets of the different categories across all the thirteen asset-holding Ministries and agencies. In terms of categorization, the exercise recorded 15,192 ICT equipment items including desktop computers, laptops, tablets and Uninterruptible Power Supply (UPS) units, 77 transport items, 99 furniture and fittings, 48 other classified assets, 1,235 items outside fixed-asset classification and 12 unclassified entries.

By location, most MDA assets (94.6%) were at MoES, MoWE and MAAIF while PPDA was found with only five assets including three Lenovo ThinkPad laptops, one HP LaserJet printer and one Samsung Galaxy tablet as indicated in figure 4 below.




Figure 4: UgFT Assets available at each of the verified MDAs

2. MDA asset Condition and functionality

At MDA level, apart from sixteen faulty assets at Ministry of Works and Transport, one faulty double-cabin pickup at Ministry of Health and three faulty laptops at the Office of the Prime Minister, the rest of the assets, 16,643 (99.9%), were recorded as functional and in use. The Ministry of Education and Sports holds 10,783 of these assets, mainly TELA handsets and tablets, all recorded as in use at the different schools across the country. LGFC and MoPS indicated that they never received UgIFT assets.

3. Asset marking and Identification

At MDA level, there were 16,663 asset records, of which 5,045 (30.3%) had usable identifiers, with 4,925 assets (29.6%) bearing UgIFT or UGFT in the tag field and 120 (0.7%) carrying another identifier. The majority of assets, 11,618 (69.7%), had no usable tag recorded. Figure 5 below shows the identification status of the assets at the different MDAs. These tag-field counts do not confirm physical engraving.




Figure 5: Asset marking and Identification at MDAs

4. Financial analysis/ valuation

Financial value of assets: recorded costs total UGX 32,054,743,836 across 16,651 of 16,663 records. Accumulated depreciation totals UGX 19,787,511,232 and net book value totals UGX 10,265,924,979 at 30 September 2026. Net book value remains unavailable for 96 records. The table below gives the category breakdown and identifies any unavailable amounts.

3.3 MDA specific results

3.3.1 Ministry of Finance, Planning and Economic Development

Asset availability: The ministry keeps a UgIFT asset register and the consolidated register for all MDAs that received UgIFT assets. A total of 458 assets were recorded at the ministry including 230 ICT items, 99 furniture and fittings, 21 transport items, 37 other classified assets, 65 items outside fixed-asset classification and six unclassified entries. The main items were office chairs and desks, desktop computers, tablets and 20 Toyota Hilux double-cabin pickups.

Condition and functionality: All 458 assets (100.0%) were recorded as functional and in use, and none was classified as faulty.

Reports described spoilt keyboards and UPS units, computers that freeze and laptop losses. The affected quantities and individual assets were not specified, so the number of broken or lost items could not be established. The asset manager should identify the affected items and reconcile the damage and loss reports.

Marking and identification: A total of 282 assets (61.6%) had usable identifiers and 176 (38.4%) had no usable tag recorded. Of all 458 assets, 247 (53.9%) had UgIFT or UGFT in the tag field and 35 (7.6%) carried another identifier. The 20 double-cabin pickups were identified by their registration numbers rather than UgIFT tag text. These tag-field counts do not confirm physical engraving.

Financial Value of assets: The recorded value of the ministry's UgIFT assets is UGX 6,204,318,000. Accumulated depreciation is UGX 4,312,193,629 and net book value is UGX 1,785,677,771 at 30 September 2026. Net book value remains unavailable for 20 records; the figures sum only available amounts.

Table 3: Recorded costs and available accounting values at MoFPED

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 230 records; NBV 216/230	1,350.105	1,011.732*	238.731*	19.1%
Furniture and fittings 99 records; NBV 99/99	137.037	96.069	40.968	29.9%
Outside fixed-asset classification 65 records; NBV 65/65	6.564	0.000	0.000	n/a
Other classified assets 37 records; NBV 36/37	159.987*	158.377*	1.610*	1.0%
Transport equipment 21 records; NBV 20/21	4,550.385*	3,046.016*	1,504.369*	33.1%
Unclassified 6 records; NBV 2/6	0.240	0.000*	0.000*	n/a
Total 458 assets; NBV 438/458	6,204.318*	4,312.194*	1,785.678*	29.3%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.2 Ministry of Works and Transport

Asset availability: The Ministry did not provide a UgIFT Asset Register. The MoWT register contained 87 assets, of which 69 ICT items were mainly desktop computers, monitors, uninterruptible power supply (UPS) units, video-conferencing equipment, printers and photocopiers; one Toyota Hilux pickup; sixteen items outside fixed-asset classification; and one unclassified entry. The sixteen items outside fixed-asset classification were keyboards. The unclassified entry was entered as Ministry of Local Government, as presented in Figure 6. Computer components are recorded separately and are included in these totals.




Figure 6: Assets verified at MoWT

Condition and functionality: Of the 87 assets, 71 (81.6%) were recorded as functional and in use; sixteen (18.4%) were recorded as faulty and not in use.

Marking and Identification: Of the 87 assets, 79 (90.8%) had usable identifiers, with 77 (88.5%) having UgIFT or UGFT in the tag field and two (2.3%) carrying another identifier; eight (9.2%) had no usable tag recorded.

Financial Value of assets: The recorded value was established as UGX 455,932,376 as presented in Table 4. Accumulated depreciation is UGX 326,484,882 and net book value is UGX 115,311,494 at 30 September 2026. Net book value remains unavailable for 19 records; the figures sum only available amounts.

Table 4: MoWT asset values by category

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 69 records; NBV 51/69	259.914	137.001*	108.778*	44.3%
Outside fixed-asset classification 16 records; NBV 16/16	0.000	0.000	0.000	n/a
Transport equipment 1 records; NBV 1/1	196.018	189.484	6.534	3.3%
Unclassified 1 records; NBV 0/1	Unavailable	Unavailable	Unavailable	n/a
Total 87 assets; NBV 68/87	455.932*	326.485*	115.311*	26.1%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.3.3 Ministry of Education and Sports

Asset availability: The verification at the Ministry of Education and Sports (MoES) established that the ministry had 10,783 assets. All the assets are ICT equipment and these include 9,324 TELA handsets, 1,001 tablets (976 of them inspection tablets), 456 laptops, a photocopier and a printer. The breakdown of these assets is shown below in figure 7. Teacher, Effectiveness and Learner Achievement (TELA) is the system, financed by UgIFT, that the ministry uses to monitor attendance and performance in schools; the handsets and inspection tablets are deployed in local governments and remain MoES assets.




Figure 7: Assets verified at MoES

All the 10,783 assets (100.0%) are recorded as functional and in use. All the 456 laptops are recorded as functional and in use. Their identification status is shown in table 6.

Table 5: Condition and use of assets at MoES

Condition	Records	Share
Functional	10,783	100.0%
Faulty	0	0.0%
Total	10,783	100.0%

Marking and Identification: Of the 10,783 assets, 458 (4.2%) had UgIFT or UgFT in the tag field, while 10,325 (95.8%) had no usable tag recorded. None of the handset or tablet records has a usable tag recorded; the tag fields do not confirm physical engraving.

Table 6: Recorded tag content of assets at MoES

Identification	Records	Share of all records
Tag contains UgIFT or UgFT	458	4.2%
Other identifier	0	0.0%
No usable tag recorded	10,325	95.8%

Financial Value of assets: The recorded value is UGX 14,925,128,359, the highest among the MDAs. Accumulated depreciation is UGX 10,607,476,704 and net book value is UGX 4,317,651,655 at 30 September 2026.

Table 7: Recorded costs and available accounting values at MoES

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 10,783 records; NBV 10,783/10,783	14,925.128	10,607.477	4,317.652	28.9%
Total 10,783 assets; NBV 10,783/10,783	14,925.128	10,607.477	4,317.652	28.9%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.4 Ministry of Agriculture, Animal Industry and Fisheries

Asset availability: The team recorded UgIFT assets at the Ministry of Agriculture, Animal Industry and Fisheries (MAAIF) and established that it held 2,045 assets. These included 1,236 ICT equipment items, two transport items and 807 others, comprising 797 outside fixed-asset classification, five other classified assets and five unclassified entries. The ICT items were mainly 819 tablets, 211 computers (162 desktop CPU entries and 49 laptops), 149 monitors and 21 printers. The breakdown of the assets mentioned above is shown in figure 8.




Figure 8: Assets verified: MAAIF

All 2,045 assets (100.0%) are recorded as functional and in use. All 211 computers and 819 tablets are recorded as functional and in use. Identification is reported separately in table 9.

Table 8: Condition and use of assets at MAAIF

Condition	Records	Share
Functional	2,045	100.0%
Faulty	0	0.0%
Total	2,045	100.0%

Marking and Identification: Of the 2,045 assets, 1,232 (60.2%) had usable identifiers, 1,228 (60.0%) with UgIFT or UGFT in the tag field and four (0.2%) with another identifier; 813 (39.8%) had no usable tag recorded. The denominator includes all ministry records, including items outside fixed-asset classification, and the tag fields do not confirm physical engraving.

Table 9: Recorded tag content of assets at MAAIF

Identification	Records	Share of all records
Tag contains UgIFT or UGFT	1,228	60.0%
Other identifier	4	0.2%
No usable tag recorded	813	39.8%

Financial Value of assets: The recorded value was UGX 2,856,556,593. Accumulated depreciation is UGX 1,380,059,505 and net book value is UGX 1,403,429,899 at 30 September 2026. Net book value remains unavailable for 7 records; the figures sum only available amounts.

Table 10: Recorded costs and available accounting values at MAAIF

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 1,236 records; NBV 1,234/1,236	2,278.449*	952.109*	1,326.341*	58.2%
Outside fixed-asset classification 797 records; NBV 797/797	72.467	0.000	0.000	n/a
Other classified assets 5 records; NBV 5/5	8.000	5.467	2.533	31.7%
Unclassified 5 records; NBV 0/5	0.600	Unavailable	Unavailable	n/a
Transport equipment 2 records; NBV 2/2	497.040	422.484	74.556	15.0%
Total 2,045 assets; NBV 2,038/2,045	2,856.557*	1,380.060*	1,403.430*	50.4%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.5 Ministry of Health

The verification at the MoH did not find the Ugift Asset Register but relied on the listing provided by the Ministry of Finance, Planning and Economic Development.

Asset availability: A total of 260 assets were recorded. Of the 260 assets, 31 were classified as ICT equipment, 25 as transport equipment (motor vehicles and motorcycles), six as other classified assets and 198 as items outside fixed-asset classification, as indicated in Figure 9.

The Ministry of Health's other items include two heavy-duty binding machines, two CC20240 paper shredders and 12 entries described as Accessories (12-Helmets). All 12 helmet entries share asset number UGIFT-217204, so the identity and quantity of the helmets require confirmation. The reported total of six power items remains unreconciled. Three have been traced to Kyamwinula Health Centre III under Tororo Municipal Council: one power bank and two regulators (UGIFT-118553–UGIFT-118555). These are already included in the health-centre total. These items are also associated with TASO or RHITES E, so their attribution to UgIFT requires confirmation. The other three power items have not been identified.




Figure 9: Assets verified at MoH

Condition and functionality: The assets recorded as functional and in use were 259 (99.6%). Only one asset, a double-cabin pickup, was recorded as faulty and not in use.

Marking and Identification: Out of the 260 assets, 32 (12.3%) had usable identifiers while 228 (87.7%) had no usable tag recorded. There were fourteen (5.4%) assets with UgIFT or UGFT in the tag field and eighteen (6.9%) with other identifiers. These tag fields do not confirm physical engraving.

Financial Value of assets: The MoH assets had a recorded value of UGX 1,186,689,609. Accumulated depreciation is UGX 441,202,460 and net book value is UGX 384,551,313 at 30 September 2026. Net book value remains unavailable for 1 record; the figures sum only available amounts.

Table 11: Recorded costs and available accounting values at MoH

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Outside fixed-asset classification 198 records; NBV 198/198	175.368	0.000	0.000	n/a
ICT equipment 31 records; NBV 31/31	211.927	109.806	102.122	48.2%
Transport equipment 25 records; NBV 24/25	789.136	326.267*	277.300*	45.9%
Other classified assets 6 records; NBV 6/6	10.259	5.129	5.129	50.0%
Total 260 assets; NBV 259/260	1,186.690	441.202*	384.551*	46.6%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.6 Office of the Prime Minister

The Assets Register for the Office of the Prime Minister was not obtained and no list of assets was provided. The verification relied on the listing obtained from the Ministry of Finance, Planning and Economic Development.

Asset availability: Office of the Prime Minister received 10 assets which were all HP laptop computers as shown in Figure 10.




Figure 10: Assets verified: OPM

Condition and functionality: Seven assets (70.0%) were recorded as functional and in use. Three (30.0%) were recorded as faulty and out of use.

Marking and identification: All the ten laptops (100.0%) had UgIFT or UGFT in the tag field.

Financial Value of assets: The recorded value of these computers in OPM was UGX 53,535,300. Accumulated depreciation is UGX 48,181,770 and net book value is UGX 5,353,530 at 30 September 2026.

Table 12: Recorded costs and available accounting values at OPM

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 10 records; NBV 10/10	53.535	48.182	5.354	10.0%
Total 10 assets; NBV 10/10	53.535	48.182	5.354	10.0%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.7 Ministry of Water and Environment

Asset availability: The Asset Verification at the Ministry of Water and Environment found out that the ministry keeps a general register which does not conform to IFMIS Standards. The register recorded 2,939 assets, of which 2,782 were classified as ICT equipment and 157 outside fixed-asset classification. The assets received by the Ministry included 2,368 tablets, of which 2,344 were Euron tablets; computers and related monitors, keyboards and UPS units; and 31 laptops. The Ministry also received sixteen real-time kinematic GPS machines. Computer components are recorded separately and are included in these totals.

However, other assets were identified which included 157 keyboards recorded with Dell OptiPlex computers, seven survey units described as ground-penetrating radar equipment, 3 Samsung Galaxy Tab S9 tablets, 2 Lenovo ThinkBook notebooks, 1 Kyocera heavy-duty copier, 1 Huawei 65-inch infrared screen and 1 UPS unit. These items are already included in the ministry total.

Asset condition and functionality: The findings further indicated that all 2,939 assets (100.0%) were recorded as functional and in use, and none was classified as faulty.

Marking and Identification: The ministry received a total of 2,939 assets, of which 2,897 (98.6%) had usable identifiers, 2,864 (97.4%) with UgIFT or UGFT in the tag field and 33 (1.1%) with another identifier; 42 (1.4%) had no usable tag recorded. These tag fields do not confirm physical engraving.

Financial Value of the assets: The recorded value was UGX 5,029,981,561. Accumulated depreciation is UGX 2,092,642,121 and net book value is UGX 1,535,627,440 at 30 September 2026. Net book value remains unavailable for 43 records; the figures sum only available amounts.

Table 13: Recorded costs and available accounting values at MoWE

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 2,782 records; NBV 2,739/2,782	3,773.982*	2,092.642*	1,535.627*	42.3%
Outside fixed-asset classification 157 records; NBV 157/157	1,256.000	0.000	0.000	n/a
Total 2,939 assets; NBV 2,896/2,939	5,029.982*	2,092.642*	1,535.627*	42.3%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.8 Ministry of Gender, Labour and Social Development

Asset availability: The Asset Verification at the Ministry of Gender, Labour and Social Development found out that the ministry keeps a UgIFT asset register which had ten UgIFT assets. These comprised eight Lenovo computers, including four ThinkBook laptops, and two Samsung tablets. Figure 11 presents the UgIFT assets recorded for MoGLSD.

Asset condition and functionality: The findings further indicate that all ten UgIFT assets (100.0%) were recorded as functional and in use.

Marking and Identification: Eight Lenovo computers (80.0%) had UgIFT or UGFT in the tag field and the two Samsung tablets (20.0%) had no usable tag recorded.

Financial Value of the assets: The findings pointed out that the recorded value to be UGX 46,180,000. Accumulated depreciation is UGX 13,260,000 and net book value is UGX 14,860,000 at 30 September 2026. Net book value remains unavailable for 4 records; the figures sum only available amounts.

Table 14: Recorded costs and available accounting values at MoGLSD

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 10 records; NBV 6/10	46.180	13.260*	14.860*	52.8%
Total 10 assets; NBV 6/10	46.180	13.260*	14.860*	52.8%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.




Figure 11: Assets verified: MoGLSD

3.3.9 National Environment Management Authority

Asset availability:

National Environment Management Authority (NEMA) had six ICT items: four computers, a printer and a heavy-duty photocopier.

Condition and functionality: All six assets (100.0%) were recorded as functional and in use.



Figure 12: Assets verified: NEMA

Asset marking and identification:

One asset (16.7%), the heavy-duty photocopier, had UgIFT or UGFT in the tag field while the other five (83.3%) had no usable tag recorded.

Financial value of Assets: The recorded value is UGX 46,824,409. Accumulated depreciation is UGX 32,841,273 and net book value is UGX 13,983,136 at 30 September 2026.

Table 15: Recorded costs and available accounting values at NEMA

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 6 records; NBV 6/6	46.824	32.841	13.983	29.9%
Total 6 assets; NBV 6/6	46.824	32.841	13.983	29.9%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.3.10 Public Procurement and Disposal of Public Assets Authority

Public Procurement and Disposal of Public Assets Authority (PPDA) did not provide a Ugift Asset Register. The verification relied on the information obtained from the Ministry of Finance, Planning and Economic Development.

Asset availability: A total of 5 assets were verified in PPDA; these were 3 Lenovo ThinkPad laptops, a Samsung Galaxy tablet and an HP printer as indicated in Figure 13.



Figure 13: Assets verified at PPDA

Asset condition and functionality: All the five assets (100.0%) were recorded as functional and in use.

Asset marking and identification: All five assets (laptops, a tablet and a printer) had UgIFT or UGFT in the tag field.

Financial Value of assets: The MF register states a recorded cost of UGX 30,153,500 for these assets. Accumulated depreciation is UGX 13,066,516 and net book value is UGX 17,086,984 at 30 September 2026.

Table 16: Recorded costs and available accounting values at PPDA

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 5 records; NBV 5/5	30.154	13.067	17.087	56.7%
Total 5 assets; NBV 5/5	30.154	13.067	17.087	56.7%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.3.11 Office of the Auditor General (OAG)

Asset availability: Evidence gathered during the verification confirmed that OAG had no UgIFT asset register rather a list which indicated 20 assets; 18 of which were ICT items (16 laptops and 2 printers) and 2 pickup vehicles. The above information is depicted in figure 14.

Asset condition and functionality: All twenty assets (100.0%) were recorded as functional and in use.

Asset marking and Identification: Six assets (30.0%) had UgIFT or UGFT in the tag field and fourteen (70.0%) carried other identifiers. The other identifiers were the office's own asset codes or vehicle registration numbers for the two pickups. These tag-field counts do not confirm physical engraving.




Figure 14: Assets verified at OAG

Financial value of Assets: The assets were worth UGX 388,773,680. Accumulated depreciation is UGX 111,591,545 and net book value is UGX 277,182,135 at 30 September 2026.

Table 17: Recorded costs and available accounting values at OAG

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 18 records; NBV 18/18	228.774	71.592	157.182	68.7%
Transport equipment 2 records; NBV 2/2	160.000	40.000	120.000	75.0%
Total 20 assets; NBV 20/20	388.774	111.592	277.182	71.3%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.3.12 Ministry of Local Government

Asset availability: The asset verification at the Ministry of Local Government (MoLG) found that the ministry kept a UgIFT asset register and had thirteen UgIFT assets: one double-cabin pickup and twelve ICT items. The ICT assets comprised six computer entries, four laptops and two photocopier entries, one described as heavy duty. Figure 15 presents the UgIFT assets recorded for MoLG.

The two photocopier entries share the identifier UGIFT-MOLG/PHC/23-01. Their identity requires reconciliation to establish whether they are two separate items. Computer components are counted separately in the figure.




Figure 15: Assets verified at MoLG

Asset condition and functionality: The findings further indicate that all thirteen assets (100.0%) were recorded as functional and in use.

Asset marking and identification: Out of the thirteen assets, eight (61.5%) had usable identifiers while five (38.5%) had no usable tag recorded. Of the eight identified assets, seven (53.8% of all assets) had UgIFT or UGFT in the tag field while one (7.7%) carried another identifier. These tag-field counts do not confirm physical engraving.

Financial Value of assets: The findings pointed out the recorded value to be UGX 343,320,450. Accumulated depreciation is UGX 284,670,827 and net book value is UGX 54,649,623 at 30 September 2026. Net book value remains unavailable for 1 record; the figures sum only available amounts.

Table 18: Recorded costs and available accounting values at MoLG

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
ICT equipment 12 records; NBV 11/12	94.800	36.151*	54.650*	60.2%
Transport equipment 1 records; NBV 1/1	248.520	248.520	0.000	0.0%
Total 13 assets; NBV 12/13	343.320	284.671*	54.650*	16.1%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.3.13 Ministry of Lands, Housing and Urban Development

Asset availability: The findings from the verification exercise indicate that MoLH &UD had 27 UgIFT assets. These include 25 Honda motorcycles and two other entries described as Accessories (12-Helmets). The description has not been multiplied by twelve to derive a helmet count.




Figure 16: Assets verified at MoLHUD

Additionally, the ministry received survey equipment and other motorcycles that it gave out to local governments.

Asset condition and functionality: All the 27 assets (100.0%) were recorded as functional and in use, and none was classified as faulty.

Asset marking and Identification: None of the 27 assets had UgIFT or UGFT in the tag field. Thirteen (48.1%) had other identifiers and fourteen (51.9%) had no usable tag recorded. The motorcycles' registration numbers are distinguished from UgIFT tag text.

Financial Value of assets: The findings further indicate the recorded value to be UGX 487,349,999. Accumulated depreciation is UGX 123,840,000 and net book value is UGX 340,559,999 at 30 September 2026. Net book value remains unavailable for 1 record; the figures sum only available amounts.

Table 19: Recorded costs and available accounting values at MoLHUD

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Transport equipment 25 records; NBV 24/25	483.750	123.840*	340.560*	73.3%
Outside fixed-asset classification 2 records; NBV 2/2	3.600	0.000	0.000	n/a
Total 27 assets; NBV 26/27	487.350	123.840*	340.560*	73.3%

*Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.*

3.4 Results from blood banks

UgIFT financed the construction of the Arua and Hoima regional blood banks, which were completed and commissioned, and the rehabilitation of Soroti Regional Blood Bank. The three Blood Banks operate under Uganda Blood Transfusion Services (UBTS) and were verified.

Asset availability: The three regional blood banks held a total UgFT asset base of 602 recorded assets. The exercise recorded assets at the three regional blood banks as follows: Arua Regional Blood Bank held 324 assets, Hoima Regional Blood Bank had 163 and Soroti Regional Blood Bank had 115 assets. This subtotal excludes assets attributed to other institutions or locations.

Asset Condition and functionality

Assets at the regional blood banks were generally recorded as functional and in use: 578 (96.0%) had that status. Only Arua Regional Blood Bank had faulty assets, accounting for all 24 (4.0%) faulty assets in the three-bank total.

Marking and Identification

Of the 602 regional blood-bank assets, 76 (12.6%) had usable identifiers and 526 (87.4%) had no usable tag recorded. Twenty-six (4.3%) carried UgIFT or UGFT in the tag field and fifty (8.3%) carried another identifier. These tag-field counts do not confirm physical engraving.

Financial aspects

Available recorded value was UGX 1,503,720,926 and available net book value at 30 September 2026 was UGX 826,632,084. Available accumulated depreciation was UGX 553,688,842. Recorded cost is available for 589 of the 602 regional blood-bank records, and net book value is unavailable for thirteen. The available columns cover different populations; the financial reconciliation appendix gives the matched accounting population.

Table 20: Recorded value and net book value: Blood banks

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Arua Regional Blood Bank 324 records; NBV 311/324	1,153.115*	472.399*	557.316*	54.1%
Hoima Regional Blood Bank 163 records; NBV 163/163	312.991	48.561	264.430	84.5%
Soroti Regional Blood Bank 115 records; NBV 115/115	37.615	32.729	4.886	13.0%
Total 602 assets; NBV 589/602	1,503.721*	553.689*	826.632*	59.9%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.4.1 Arua Regional Blood Bank

Arua Regional Blood Bank accounts for 324 assets. Of these, 300 (92.6%) are classified as functional and in use, while 24 (7.4%) are classified as faulty and not in use. The faulty items require individual assessment for repair or replacement.

Marking and identification: Twenty-six assets (8.0%) have identifiers containing UgIFT or UGFT, 48 (14.8%) have another identifier and 250 (77.2%) have no usable identifier. Physical engraving still requires confirmation.

Financial value of assets: recorded costs total UGX 1,153,114,971 across 311 of 324 records. Accumulated depreciation totals UGX 472,399,460 and net book value totals UGX 557,315,511 at 30 September 2026. Net book value remains unavailable for 13 records. The table below gives the category breakdown and identifies any unavailable amounts.

Table 21: Asset categories at Arua Regional Blood Bank

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Medical, laboratory and research appliances 182 records; NBV 171/182	57.612*	41.213*	16.400*	28.5%
Furniture and fittings 65 records; NBV 63/65	192.104*	99.390*	92.715*	48.3%
ICT equipment 41 records; NBV 41/41	91.478	41.308	50.170	54.8%
Other classified assets 21 records; NBV 21/21	261.024	142.271	118.753	45.5%
Outside fixed-asset classification 11 records; NBV 11/11	123.400	0.000	0.000	n/a
Transport equipment 3 records; NBV 3/3	240.000	124.000	116.000	48.3%
Buildings and structures 1 records; NBV 1/1	187.496	24.218	163.278	87.1%
Total 324 assets; NBV 311/324	1,153.115*	472.399*	557.316*	54.1%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.4.2 Hoima Regional Blood Bank

Hoima Regional Blood Bank accounts for 163 assets, all classified as functional and in use (100.0%).

Marking and identification: No asset has an identifier containing UgIFT or UGFT. Two assets (1.2%) have other identifiers and 161 (98.8%) have no usable identifier. Physical engraving still requires confirmation.

Financial value of assets: recorded costs total UGX 312,990,807 across 163 of 163 records. Accumulated depreciation totals UGX 48,560,694 and net book value totals UGX 264,430,113 at 30 September 2026. All records have a calculated net book value. The table below gives the category breakdown and identifies any unavailable amounts.

Table 22: Asset categories at Hoima Regional Blood Bank

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Medical, laboratory and research appliances 152 records; NBV 152/152	54.192	37.973	16.219	29.9%
Other classified assets 6 records; NBV 6/6	6.840	3.544	3.296	48.2%

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Furniture and fittings 4 records; NBV 4/4	0.520	0.338	0.182	34.9%
Buildings and structures 1 records; NBV 1/1	251.439	6.705	244.734	97.3%
Total 163 assets; NBV 163/163	312.991	48.561	264.430	84.5%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

3.4.3 Soroti Regional Blood Bank

Soroti Regional Blood Bank accounts for 115 assets, all classified as functional and in use (100.0%).

Marking and identification: None of the 115 assets has a usable identifier. Physical engraving still requires confirmation.

Financial value of assets: recorded costs total UGX 37,615,148 across 115 of 115 records. Accumulated depreciation totals UGX 32,728,688 and net book value totals UGX 4,886,460 at 30 September 2026. All records have a calculated net book value. The table below gives the category breakdown and identifies any unavailable amounts.

Table 23: Asset categories at Soroti Regional Blood Bank

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Medical, laboratory and research appliances 103 records; NBV 103/103	32.599	28.131	4.468	13.7%
ICT equipment 8 records; NBV 8/8	4.416	4.048	0.368	8.3%
Furniture and fittings 4 records; NBV 4/4	0.600	0.550	0.050	8.3%
Total 115 assets; NBV 115/115	37.615	32.729	4.886	13.0%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

The photos below show some of the assets



Blood-bank building at Arua Regional Blood Bank, Arua City



Plasma snap freezer at Hoima Regional Blood Bank, Hoima City.



Blood bank refrigerator at Arua Regional Blood Bank, Arua City



Platelet agitator at Arua Regional Blood Bank, Arua City



Donor couches in the donor room at Hoima Regional Blood Bank, Hoima City



Blood-bank refrigerators and plasma snap freezer at Soroti Regional Blood Bank.

	
Benchtop centrifuge at Hoima Regional Blood Bank, Hoima City	Markings PEP II/UBTS/COMP/11/016 and UBTS/UGIFT/ARBB/UPS/001 on uninterruptible power supplies at Arua Regional Blood Bank, Arua City

3.5 Local Government level results

The programme list at the LG level contained 629 UgIFT facilities, of which 371 were Health Centres and 258 were Seed Secondary Schools. Supporting returns accounted for 590 entries and 39 had discrepancies requiring reconciliation. A total of 208,688 assets were recorded at Health Centres and school locations, of which 63,432 were for Health Centres and 145,256 were for schools. Of the 208,688 assets, 195,224 (93.5%) were recorded as functional and in use while 13,464 (6.5%) were recorded as faulty and not in use. A further 3,067 assets were attributed to hospitals and four to other local-government locations. The details are presented in sections 3.6 (Health Centres) and 3.7 (Seed Secondary Schools).

3.6 Health Centres

3.6.1 Availability of the assets

The verification findings indicate that health facilities had 63,432 recorded assets across the different categories which include clinical and laboratory equipment, furniture, maternity ward equipment, ICT equipment, buildings, land and other items. The register includes 7,746 items outside fixed-asset classification. Table 24 and Figure 17 present the assets by category.

Table 24: Availability of assets in Health Centres

Asset category	Records	Share
Medical, laboratory and research appliances	36,721	57.9%
Furniture and fittings	15,671	24.7%
Outside fixed-asset classification	7,746	12.2%
Buildings and structures	2,260	3.6%
Other classified assets	537	0.8%
ICT equipment	424	0.7%
Unclassified	64	0.1%
Transport equipment	5	0.0%

Asset category	Records	Share
Land	4 ¹	0.0%
Total	63,432	100.0%




Figure 17: Assets verified: Health centres

3.6.2 Asset condition and functionality

The findings indicate that of the 63,432 health-centre assets, 57,759 (91.1%) were recorded as functional and in use and 5,673 (8.9%) were recorded as faulty and not in use. Figure 18 and Table 25 present the condition of the assets. These two register categories do not establish separate current counts of items in store, broken items and other reasons for non-use.

¹ The four land entries relate to Kyamwinula Health Centre III (UGIFT-119332), Sop Sop Health Centre III (UGIFT-128460), Nalubembe Health Centre III (M161488) and Kabweri Health Centre III (M183544). Dimensions are stated only for Sop Sop, at 70 × 300 metres. The land appendix provides costs and further details. Title and tenure require confirmation.




Figure 18: Faulty assets at Health Centres by category

Table 25: Condition of assets: Health centres

Asset category	Records	Functional	Faulty
Medical, laboratory and research appliances	36,721	32,473	4,248
Furniture and fittings	15,671	14,988	683
Outside fixed-asset classification	7,746	7,231	515
Buildings and structures	2,260	2,144	116
Other classified assets	537	479	58
ICT equipment	424	374	50
Unclassified	64	62	2
Transport equipment	5	4	1
Land	4	4	0
Total	63,432	57,759	5,673

The field records describe health-centre assets that were not in use for other reasons, including those not delivered to the facility (still in stores at LGs), idle items, items with missing parts, lack of power, items not required at the facility, rooms or wards unavailable for installation, items held at another facility, items awaiting installation, lost or missing items and equipment unused because staff were not trained or no specialist was available to operate it. Examples include a wall-mounted blood-pressure machine at Butawata Health Centre III (Mubende District) recorded as not functional; a wheelchair at Aarapoo Health Centre III (Serere District) that had not been delivered; a patient screen at Ayer Health Centre III (Kole District) that was on the delivery note but not seen; a paediatric bed at Okwerodot Health Centre III (Kole District) supplied without a mattress; and an autoclave at Anamwany Health

Centre III (Amolatar District) unused for lack of electricity. The register's two condition categories do not provide a separate count for these reasons.

In terms of buildings and structures, health-centre records total 2,260, comprising 487 residential-building entries, 1,402 non-residential-building entries, 364 other-structure entries and seven water-supply-system entries. Residential buildings are staff houses and other buildings described as residential. Some entries require reclassification, so the record total does not establish a count of separate buildings. Table 26 presents the classifications.

Table 26: Health Centre records classified as buildings and structures

Recorded building classification	Records
BUILDINGS OTHER THAN DWELLINGS / NON RESIDENTIAL BUILDINGS	1,402
DWELLINGS / RESIDENTIAL BUILDINGS	487
STRUCTURES / OTHER STRUCTURES	364
STRUCTURES / WATER SUPPLY SYSTEMS	7

3.6.3 Asset marking and Identification

Of the 63,432 assets in Health Centres, 9,541 (15.0%) had usable identifiers and 53,891 (85.0%) had no usable tag recorded. It was noted that 3,824 (6.0%) carried UgIFT or UGFT in the tag field and 5,717 (9.0%) carried other identifiers, as depicted in Figure 19 and Table 27. These tag-field counts do not confirm physical engraving.




Figure 19: Health Centre assets with UgIFT or UGFT identifiers by category

Table 27: Identification of assets at Health centres

Asset category	Records	UgIFT text	Other identifier	No usable tag
Medical, laboratory and research appliances	36,721	1,786	2,826	32,109

Asset category	Records	UgIFT text	Other identifier	No usable tag
Furniture and fittings	15,671	1,484	1,888	12,299
Outside fixed-asset classification	7,746	356	689	6,701
Buildings and structures	2,260	45	179	2,036
Other classified assets	537	20	43	474
ICT equipment	424	133	32	259
Unclassified	64	0	54	10
Transport equipment	5	0	4	1
Land	4	0	2	2
Total	63,432	3,824	5,717	53,891

Financial Value of assets: The findings indicate that the available recorded value of assets was UGX 260,692,452,291 and the available net book value was UGX 189,403,577,197, while available accumulated depreciation was UGX 39,211,094,700 as at 30 September 2026. Table 28 gives the recorded value and net book value. Cost is available for 63,183 of 63,432 records; net book value is unavailable for 7,828. Available columns cover different populations; the financial reconciliation appendix gives the matched accounting population.

Table 28: Recorded and net book values at Health centres

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Medical, laboratory and research appliances 36,721 records; NBV 31,185/36,721	39,592.633*	14,080.055*	18,715.685*	57.1%
Furniture and fittings 15,671 records; NBV 13,869/15,671	15,109.270*	5,764.153*	6,584.582*	53.3%
Outside fixed-asset classification 7,746 records; NBV 7,746/7,746	479.803	0.000	0.000	n/a
Buildings and structures 2,260 records; NBV 2,027/2,260	203,954.138*	18,304.241*	163,802.803*	89.9%
Other classified assets 537 records; NBV 468/537	347.206*	172.492*	133.099*	43.6%
ICT equipment 424 records; NBV 244/424	929.345*	825.749*	85.256*	9.4%
Unclassified 64 records; NBV 56/64	134.958*	0.971*	0.485*	33.3%
Transport equipment 5 records; NBV 5/5	75.100	63.433	11.667	15.5%
Land 4 records; NBV 4/4	70.000	0.000	70.000	100.0%
Total 63,432 assets; NBV 55,604/63,432	260,692.452*	39,211.095*	189,403.577*	82.8%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

Recorded value is the cost in the verification records. For recognized assets with complete accounting figures, net book value is that cost less accumulated depreciation to 30 September 2026 and is not taken below zero. Available costs, depreciation and net book values cover different populations; the financial reconciliation appendix gives the matched accounting population.

The photos below show some of the facilities that are complete



Figure 20: Health centre building at Kibiri HC III, Makindye-Ssabagabo Municipal Council (Buganda)



Figure 21: Health centre buildings and covered walkway at Kihuukya HC III, Hoima City (Bunyoro)



Figure 22: Binocular microscope at Kihuukya HC III, Hoima City (Bunyoro)



Figure 23: Maternity block entrance and access ramp at Kamuli HC III, Tororo District (Bukedi)

The photos below show some of the facilities that are Incomplete



Figure 24: Unfinished laboratory building at a health centre, Sironko District (Bugisu)

The following three photographs show different views of Benet Health Centre III in Kween District. At the field visit on 27 August 2026, staff quarters were incomplete, another structure awaited completion and handover, and equipment was still in store.



Figure 25: Incomplete staff quarters at Benet Health Centre III, Kween District. Field visit 27 August 2026.



Figure 26: Interior awaiting completion at Benet Health Centre III, Kween District. Field visit 27 August 2026.



Figure 27: A further unfinished room at Benet Health Centre III, Kween District. Field visit 27 August 2026.

3.7 Seed Secondary Schools

3.7.1 Availability of the assets

The findings showed that schools had 145,256 recorded assets covering the following categories: school buildings, water facilities, furniture, computers and related equipment such as monitors, UPS units and keyboards; ICT equipment including printers, photocopiers, cameras and projectors; and other school assets such as laboratory items, electrical items, plant and machinery and sports equipment. Table 29 presents the details. The school group follows recorded locations and includes schools whose programme assignment requires confirmation.

Table 29: Availability of assets at schools

Asset category	Records	Share
Furniture and fittings	107,792	74.2%
ICT equipment	12,036	8.3%
Outside fixed-asset classification	9,081	6.3%
Buildings and structures	7,505	5.2%
Medical, laboratory and research appliances	5,604	3.9%
Other classified assets	2,716	1.9%
Unclassified	500	0.3%
Land	14	0.0%

Asset category	Records	Share
Transport equipment	8	0.0%
Total	145,256	100.0%

3.7.2 Asset condition and functionality

Out of 145,256 assets, 137,465 (94.6%) were recorded as functional and in use. The verification further established that 7,791 (5.4%) were recorded as faulty and not in use. Table 30 indicates the asset condition. These register categories do not establish separate current counts of items in store, broken items and other reasons for non-use.

Table 30: Condition of assets: schools

Asset category	Records	Functional	Faulty
Furniture and fittings	107,792	102,521	5,271
ICT equipment	12,036	10,404	1,632
Outside fixed-asset classification	9,081	8,692	389
Buildings and structures	7,505	7,220	285
Medical, laboratory and research appliances	5,604	5,498	106
Other classified assets	2,716	2,623	93
Unclassified	500	485	15
Land	14	14	0
Transport equipment	8	8	0
Total	145,256	137,465	7,791

Functional assets are recorded as in use and faulty assets as not in use. The two condition columns sum to the assets recorded. They do not establish separate counts of good items in store, broken items and other reasons for non-use.

School furniture and fittings (desks, tables, chairs, shelves and stools) is the largest category with 107,792 assets. Of these, 102,521 were recorded as functional and in use while 5,271 were recorded as faulty. ICT equipment had 10,404 assets recorded as functional and in use.

3.7.3 Asset marking and Identification

Of the 145,256 school assets, 35,601 (24.5%) had usable identifiers while 109,655 (75.5%) had no usable tag recorded. A total of 13,478 (9.3%) carried UgIFT or UGFT in the tag field and 22,123 (15.2%) carried other identifiers, as shown in Table 31. These tag-field counts do not confirm physical engraving.

Table 31: Identification of assets at schools

Asset category	Records	UgIFT text	Other identifier	No usable tag
Furniture and fittings	107,792	12,985	18,503	76,304
ICT equipment	12,036	315	2,426	9,295

Asset category	Records	UgIFT text	Other identifier	No usable tag
Outside fixed-asset classification	9,081	0	452	8,629
Buildings and structures	7,505	40	391	7,074
Medical, laboratory and research appliances	5,604	121	242	5,241
Other classified assets	2,716	17	96	2,603
Unclassified	500	0	10	490
Land	14	0	2	12
Transport equipment	8	0	1	7
Total	145,256	13,478	22,123	109,655

Movable assets exclude buildings, structures and land. The table groups recorded tag text as UgIFT or UGFT, another identifier or no usable tag. Buildings, structures and land are identified through property and site records rather than engraving.

3.8 Financial Value of school assets

The available recorded value was UGX 700,242,561,371, the available net book value was UGX 394,241,708,595 and available accumulated depreciation was UGX 104,574,530,246 as at 30 September 2026, as shown in Table 32. Cost is available for 144,445 of the 145,256 school records; net book value is unavailable for 14,807. Available columns cover different populations; the financial reconciliation appendix gives the matched accounting population.

Table 32: Recorded value and net book value: schools

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Furniture and fittings 107,792 records; NBV 97,305/107,792	22,612.957*	11,733.742*	7,406.367*	38.7%
ICT equipment 12,036 records; NBV 10,345/12,036	29,669.809*	15,836.227*	9,584.916*	37.7%
Outside fixed-asset classification 9,081 records; NBV 9,081/9,081	40,839.592	0.000	0.000	n/a
Buildings and structures 7,505 records; NBV 5,977/7,505	601,004.483*	74,561.320*	374,906.543*	83.4%
Medical, laboratory and research appliances 5,604 records; NBV 5,259/5,604	1,455.366*	864.426*	511.352*	37.2%
Other classified assets 2,716 records; NBV 2,448/2,716	2,488.189*	1,037.888*	1,224.696*	54.1%
Unclassified 500 records; NBV 16/500	610.010*	33.415*	141.245*	80.9%
Land 14 records; NBV 13/14	110.029*	0.000*	110.029*	100.0%

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Transport equipment 8 records; NBV 5/8	1,452.127	507.511*	356.561*	41.3%
Total 145,256 assets; NBV 130,449/145,256	700,242.561*	104,574.530*	394,241.709*	79.0%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

Recorded value is the cost in the verification records. For recognized assets with complete accounting figures, net book value is that cost less accumulated depreciation to 30 September 2026. Available costs, depreciation and net book values cover different populations; the financial reconciliation appendix gives the matched accounting population.

3.9 Completion Status of Facilities

The verification established that there were a number of facilities that were either completed or not completed. Table 33 provides the programme-list construction baseline and the documented outstanding-work findings separately.

Table 33: Programme-list construction baseline and documented outstanding works

Measure	Health centres	Schools	Total
Programme-list entries	371	258	629
Complete on the programme list	352	195	547
Ongoing on the programme list	19	63	82
Documented incomplete works	13	57	70
Documented handover or commissioning outstanding only	2	11	13

Counts are facilities. Programme-list completion labels and the documented outstanding-work findings may concern the same facilities and must not be added together. Outstanding-work counts are documented minimums.

Table 33 indicates that the programme list recorded 547 facilities as complete and 82 as ongoing before verification. The reviewed evidence identifies at least 70 facilities with incomplete works, comprising 57 schools and thirteen Health Centres, and another thirteen awaiting handover or commissioning, comprising eleven schools and two Health Centres. Some facilities were providing services while works remained incomplete. These findings and the programme-list completion labels describe different matters and must not be added together.

The photos below show some of the facilities that are complete



Figure 28: Classroom furnished with desks and a whiteboard at Gyagenda Memorial Seed Secondary School, Kalangala District (Buganda)




Figure 29: Books displayed on library shelves at Sibanga Seed School, Manafwa District (Bugisu)



Figure 30: ICT laboratory block and entrance ramp at Sisiyi Seed Secondary School, Bulambuli District (Bugisu)

The photos below show some of the facilities that are still under construction



Figure 31: Unfinished school block at Got Apwoyo Seed Secondary School, Nwoya District (Acholi)



Figure 32: Unfinished classroom block at Sidok Seed Secondary School, Kaabong District (Karamoja)



Figure 33: Latrine block under construction at Sidok Seed Secondary School, Kaabong District (Karamoja)



Figure 34: Building works and construction materials at Ndheh Seed Secondary School, Nebbi District (West Nile)



Figure 35: School block awaiting completion at Butungama Seed Secondary School, Ntoroko District (Tooro)



Figure 36: Building works at a seed secondary school, Kiboga District (Buganda)



Figure 37: Classroom block with earthworks in the foreground at Kihungya Seed Secondary School, Buliisa District (Bunyoro)



Figure 38: Biology laboratory under construction at a seed secondary school, Buliisa District (Bunyoro)



Figure 39: Unfinished laboratory interior at Kihungya Seed Secondary School, Buliisa District (Bunyoro)



Figure 40: Library interior under construction at Kihungya Seed Secondary School, Buliisa District (Bunyoro)



Figure 41: ICT laboratory interior under construction at Kitawoi Seed Secondary School, Kween District (Sebei)



Figure 42: Laboratory benches with cupboard doors not yet fitted, in a science laboratory block recorded as under construction, at King Solomon Seed Secondary School, Kagadi District (Bunyoro)



Figure 43: Empty computer laboratory at Kaptum Seed Secondary School, Kween District (Sebei), where the buildings had not been handed over and no ICT equipment had been received

3.10 Field Observations,

3.11 Location and Name changes

The verification exercise established that there were mismatches between information from the programme list and what was found on the ground. Out of 629 programme-list entries, 590 (93.8%) had supporting returns and 39 (6.2%) had discrepancies requiring reconciliation. These include entries on the programme list without matching returns or with conflicting location or facility-type information. Renamed facilities already matched to returns are not added to the 39 exceptions. Table 34 provides the details.

Table 34: Inconsistencies between the programme list and the facilities found

Outcome	Health centres	Schools	Total
Reported absent or not constructed	7	3	10
Outside UgIFT beneficiary scope	2	1	3
Exists but no UgIFT assets reported	2	3	5
UgIFT assets relocated	2	1	3
Represented by another programme entry	2	0	2
Follow-up without a separate on-site asset return	9	7	16
Total exceptions	24	15	39

Counts are programme-list facilities: 24 Health Centres and fifteen schools, giving 39 distinct exceptions. HC means Health Centre; SSS means Seed Secondary School. Renamed facilities already matched to returns are not added to this total.

3.12 UgIFT support to service delivery

Of the 284 health centres, 238 (83.8%) reported at least one benefit from the UgIFT support. Improved maternity and delivery services were reported by 117 (41.2%), and 51 (18.0%) reported more or safer births at the facility. Improved antenatal, immunisation, laboratory or other specific services were reported by 89 (31.3%), improved access to care or shorter distances by 71 (25.0%) and more patients attending by 61 (21.5%). More than half, 164 (57.7%), linked better services to the equipment and furniture supplied.

Of the 193 seed schools, 144 (74.6%) reported at least one benefit. A better learning environment, with classrooms, furniture and libraries, was reported by 74 (38.3%), and improved access to secondary education or shorter distances by 59 (30.6%). Practical science or ICT teaching improved at 39 schools (20.2%), and 37 (19.2%) reported higher enrolment. Forty schools (20.7%) also reported jobs and local economic benefits around the school. Figure 44 compares the benefits most often reported by the two types of facility.

Percentages use 284 health-centre and 193 school responses. A facility could report several benefits. These are respondents' accounts of service changes; the exercise did not measure a causal effect. The school response attributed to Kagganda Health Centre was excluded because its identity was not confirmed.




Figure 44: Programme Benefits

3.12.1 Gaps and Challenges

The main gaps identified by the facilities include; Percentages use 477 facility responses unless a facility type is specified; categories overlap.

- i. Insufficient Power supply which was reported by 201 facilities (42.1%), including 44.4% of Health Centre respondents and 38.9% of school respondents;
- ii. Inadequate Staffing which was reported by 32.1% of the facilities (153 of 477).
- iii. Inadequate space or infrastructure reported by 31.7% of the facilities (151 of 477).
- iv. Insecurity or absence of fencing reported by 27.0% of the facilities (129 of 477).
- v. Limited maintenance support was raised by 22.2% of the facilities (106 of 477).
- vi. Inadequate staff houses reported by 22.0% of the facilities (105 of 477).
- vii. Poor water supply reported by 20.1% of the facilities (96 of 477).

- viii. inadequate training of staff to operate the equipment reported by 28.9% of the health centres (82 of 284), and 1.6% of schools (three of 193).
- ix. Incomplete or delayed works, handover or commissioning reported by 28.0% of Seed Secondary School respondents (54 of 193) and 10.2% of Health Centre respondents (29 of 284).
- x. Equipment not installed, not assembled or delivered incomplete was raised by 17.6% of the facilities (84 of 477).




Figure 45: Service gaps and challenges

4 Asset management

4.1 Maintenance and repairs

Maintenance keeps UgIFT assets working for the services they were bought to support. Most of the verified assets are furniture, clinical equipment and computers in daily use at Health Centres and seed schools, where wear and breakage are to be expected. Routine checks, a record of faults and a dependable route for repair decide whether a broken item returns to use quickly or stays out of service. During the verification, each facility was asked how it maintains, repairs, services or replaces UgIFT assets and whether it keeps a regular record of their functionality or breakdown.

Repair arrangements. Of the 469 facilities that described their maintenance arrangements, 260 (55.4%) met repairs at facility level, from their own funds or with their own staff. Health Centres named Primary Health Care funds (94 of 278, 33.8%), while schools named the capitation or Universal Secondary Education grant, parents' contributions or the school budget (52 of 191, 27.2%). Busaale Health Centre III in Kayunga used Primary Health Care funds for repairs, and Kagumba Seed Secondary School in Kamuli had repaired broken furniture during the second term. A facility could describe more than one arrangement.

Support from outside the facility was cited by 152 facilities (32.4%): district offices, mainly the District Health Officer, 85 (18.1%); regional referral hospital workshops or national teams 52 (11.1%); hired technicians and artisans 27 (5.8%); and contractors or suppliers under defects liability, guarantee or warranty 12 (2.6%). Major medical equipment repairs depended on this support. Todora Health Centre III in Nwoya worked through the District Health Officer and the Gulu Regional Referral Hospital technical team, Avogera Health Centre III in Buliisa received support from Hoima Regional Referral Hospital, and Bundimulanga Health Centre III in Bundibugyo obtained a team through the District Health Officer.

In all, 97 facilities (20.7%), 59 of them schools, had not yet needed maintenance because the assets were new, not yet handed over or the buildings were still under construction, and 36 (7.7%) reported no repair arrangement, with broken items set aside or not repaired. Funds for maintenance and repair were reported as insufficient, particularly for major repairs, by 32 of the 505 facilities that described maintenance or challenges (6.3%). At Kyankaramata Health Centre III in Kyenjojo, Primary Health Care funds met minor repairs, but the cost of major repairs was a constraint.

Figure 46 compares these arrangements at Health Centres and seed schools. Health Centres relied more on outside technical support (41.4% of health centres against 19.4% of schools), while schools more often had not yet needed maintenance (30.9% against 13.7%).




Figure 46: Most facilities met repairs from their own funds or staff

Frequency. Few facilities worked to a fixed maintenance interval. Of the 494 programme-list facilities that described how they maintain UgIFT assets or check their condition, 50 (10.1%) did so at a fixed interval. Of these 50, 14 (28.0%) worked annually, 11 (22.0%) monthly, 10 (20.0%) quarterly, 9 (18.0%) every school term, 3 (6.0%) twice a year and 3 (6.0%) weekly or daily, as Figure 47 shows. A further 18 facilities (3.6%) described routine or scheduled servicing without a set interval, mostly scheduled visits by regional referral hospital maintenance teams, and 61 (12.3%) repaired items as the need arose. Ngwedo Seed Secondary School in Buliisa engaged a caretaker every month and used the Directorate of Industrial Training for furniture repairs, while Busaale reviewed asset condition every quarter.




Figure 47: Annual, monthly and quarterly checks were the most common stated intervals

Records. Of the 463 facilities that answered, 318 (68.7%) kept a regular record of asset functionality or breakdowns, 36 (7.8%) kept a partial or informal record, 80 (17.3%) kept none and 29 (6.3%) had not yet started because the assets were new or the facility was not yet operating. Of the 478 facilities that answered, 355 (74.3%) held a record of the UgIFT assets they received, 40 (8.4%) held a partial record, such as delivery notes only or a general register that does not identify UgIFT items, and 83 (17.4%) held none. Kagumba Health Centre III in Kamuli kept an asset condition book, a simple practice that other facilities can adopt.

4.2 Obsolete and Unserviceable Assets

Two wall-mounted aneroid blood-pressure machines at Nyanja Health Centre III, UgIFT-012842 and UgIFT-012843, were reported as spoilt, beyond repair and requiring replacement. Disposal approval or completion has not been confirmed.

A certified inventory of obsolete assets and an approved disposal schedule have not been established. Faulty equipment should be assessed individually for repair, replacement or disposal.

4.3 Missing and Unrecorded Assets

Assets reported stolen, items not received, equipment with missing accessories and items that could not be accessed during the visit require different follow-up. These circumstances cannot be combined into a single count of losses.

For example, the incubator at Buwembe Health Centre III (UgIFT-114904) and the ENT instrument set at Rubingo Health Centre III (UgIFT-188911) were reported not received. The wheelchair at Bukimanayi Health Centre III (UgIFT-115669) was not seen, and the officer in charge could not confirm whether it had been redistributed. Check delivery and transfer records before concluding that these assets were lost.

At Paloga Seed Secondary School, two monitors were reported stolen, while the others remained in use. At Bukiiro Seed Secondary School, accounts of 16 system units conflict: they were described as both present and functional and as stolen. Their status requires confirmation. At Ogur Seed Secondary School, furniture in locked rooms could not be verified because keys were unavailable; this is an access limitation, not evidence of loss.

The number of assets omitted from facility registers has not been established. A missing local asset register, an inaccessible item and a stolen asset should remain separate findings. Further examples and the required checks are set out in the asset reconciliation appendix.

5 Recommendations

Recommendation. Facility managers and school governing bodies should keep the local and regional repair arrangements that already work and adopt a fixed routine: a condition check at least every school term in schools and every quarter in health centres, and a full count of UgIFT assets each year. Each facility should keep a condition book or fault list naming each item requiring action, the responsible person and the agreed completion date; the 36 facilities with no repair arrangement and the 80 with no functionality or breakdown record should set these up first.

District health and education offices should review unresolved repairs each quarter and arrange technical assistance, and regional referral hospital workshops should include UgIFT equipment in their scheduled visits. Annual maintenance plans should separate minor repairs from major repairs such that the minor repairs be met from Primary Health Care funds or school grants, while major repairs can be handled through district or national funding.

Recommendation. Facility managers, district health and education officers, engineers and technical teams should prioritise unsafe furniture, electrical concerns and failed equipment needed for essential services. Withdraw unsafe items, obtain technical assessments and verify safe operation after repair. The broken down and not functional assets should be assessed in order of their effect on care and teaching, beginning with clinical equipment and the school furniture that makes up most of the broken down assets; items beyond economic repair should receive a formal disposal decision. At national level, the Office of the Prime Minister should decide on repair or replacement of its three laptops recorded as faulty, and Uganda Blood Transfusion Services (UBTS) should repair or replace the six blood-pressure machines recorded as faulty at Arua Regional Blood Bank. Keep damaged assets separate from usable assets awaiting installation so that each receives the appropriate action.

Recommendation. LG Accounting Officers, engineers, health and education officers and contractors should coordinate outstanding buildings, utilities, furniture and equipment through site-specific completion plans for each of the 83 documented facilities with works or handover outstanding, comprising seventy with incomplete works and thirteen awaiting handover or commissioning. These are documented minimums. Installation should follow confirmation that rooms, power, water and security are ready. Stored assets described as new or in good condition should be issued to the rooms where they are needed, and each asset waiting for power or installation should have a named date for connection and testing. Protect services already operating during construction. There should be complete testing and signing off before handover or closing each action.

Recommendation. District health officers, facility managers, suppliers and regional technical teams should provide practical training for staff who use specialist equipment, starting with the Health Centres that linked idle equipment to a lack of skills, including oxygen equipment users, for example, at Bubago and Sop Sop and staff requiring orientation at Avogera. Handover should include a demonstration, basic maintenance guidance and a named route for technical support. Future supply contracts should make on-site demonstration to the staff who will use the equipment, a condition of acceptance and staffing reviews should take account of the equipment each health centre now holds.

Recommendation. Institution asset managers and LG finance, health and education officers should engrave all the verified assets with UgIFT markings and confirm their locations and custodians. Assets carrying another marking only should receive the programme identifier at their next check. Resolve the continuing allocation of equipment e.g at Todora, Paraa and Masafu through signed transfer or receipt documentation, bring assets held at district stores to their facilities once rooms are ready, and complete delivery of the items still with suppliers.

The Ministry of Works and Transport should retain the completed tracing record and keep the confirmed custodians and locations current. Losses should be reported and investigated under the public finance

rules, and every facility should hold a list of the UgIFT assets it received, showing each item, its engraving and its custodian. Maintain site, ownership and handover records for buildings and land.

Recommendation. The Ministry of Finance, Planning and Economic Development, with the Ministry of Health, the Ministry of Education and Sports and the local governments concerned, should approve a corrected programme list after rectifying the inconsistencies. The corrected list should then guide decisions wherever planned locations differed from what teams found.

5.1 Actions to address the reported service gaps

Gap	Responsible officers	Action	Evidence of completion
Power	LG engineers and facility managers	Assess electrical loads and complete safe grid or suitable alternative supply before testing and issuing idle equipment.	Connection and electrical test records
Staffing	District service authorities and sector ministries	Match staffing needs to operating rooms and equipment; deploy qualified staff through approved staffing and budget processes.	Approved deployment and duty rosters
Space	LG engineers and sector departments	Inspect room suitability, identify overcrowded services and sequence building completion or adaptations around service needs.	Room allocation and completion records
Security	Accounting Officers and facility governing bodies	Prioritise vulnerable stores and ICT rooms; provide secure storage, access controls and risk-based fencing.	Security inspection and custodian logs
Maintenance	Facility managers and district technical teams	Set funded maintenance schedules, record faults and escalate major repairs to the responsible workshop or supplier.	Fault register and closed repair orders
Staff housing	LG planners, engineers and sector departments	Identify housing constraints affecting attendance; complete contracted quarters and plan additional accommodation where justified.	Occupancy and outstanding-work schedules
Water	District water officers and facility managers	Restore reliable water and test storage, supply and sanitation connections before putting dependent equipment into use.	Water availability and system test records
Training	Sector technical teams and suppliers	Demonstrate operation, safety and basic care to named users; confirm competence and provide a support contact.	Training attendance and competency sign-off
Works	Accounting Officers, engineers and contractors	Agree site-specific defects and completion lists, milestones and handover requirements; verify each closure on site.	Inspection certificates and signed handover
Installation and delivery	Procurement units, suppliers and facility managers	Reconcile delivery notes, obtain missing parts, install equipment in ready rooms and complete acceptance tests.	Delivery reconciliation and acceptance tests

Annexures Appendices

Appendix A Financial reconciliation and valuation limitations

The financial reporting date is 30 September 2026. Year-to-date depreciation covers 1 July to 30 September 2026. Amounts below are in Uganda shillings, rounded to the nearest shilling after the totals are calculated. Only available amounts are added; blank cells and entries marked Pending calculation are not treated as zero. Each record has one unit, so no further quantity multiplier is applied.

Financial measure	Available records	Unavailable records	Available total UGX
Recorded cost	227,938	1,086	996,812,628,890
Accumulated depreciation	206,012	23,012	165,185,197,307
Year-to-date depreciation	206,012	23,012	10,793,939,755
Net book value	206,008	23,016	595,801,587,531

The cost, depreciation and net book value totals do not all cover the same records. A direct comparison is possible for 180,730 records classified CAPITALIZED or construction in progress (CIP), where all three amounts are available. Their recorded cost of UGX 760,986,784,838 less accumulated depreciation of UGX 165,185,197,307 gives net book value of UGX 595,801,587,531. For this group, net book value is 78.3% of cost. This is the share of recorded cost that has not been depreciated; it does not measure physical condition, service performance or market value.

Reconciliation of available amounts	UGX
Available recorded cost, all accounting treatments	996,812,628,890
Less known costs on records whose NBV remains unavailable	190,742,908,682
Less positive recorded costs on expensed or non-recognized treatments	45,082,935,370
Recorded cost of the assets with complete accounting information	760,986,784,838
Less accumulated depreciation of those assets	165,185,197,307
Net book value of those assets	595,801,587,531

There are 21,978 records with a known cost but no calculated net book value. A further 5,336 records have positive costs but are treated as expenses or are not recognized as assets under the accounting treatment applied. Their costs must be excluded from the comparison above. This explains why subtracting all available depreciation from the full recorded cost does not give the reported net book value.

Extent of existing cost estimates

Basis of recorded cost	Records	Recorded cost UGX
Comparable assets within the same government	26,922	122,474,661,776
Comparable assets in other governments	139,671	699,262,256,528

Basis of recorded cost	Records	Recorded cost UGX
Other available costs	61,345	175,075,710,586
Total available costs	227,938	996,812,628,890

Costs for 166,593 items were estimated by comparison with other assets, totalling UGX 821,736,918,304, or 82.44% of available recorded cost. These estimates require supporting valuation evidence. The other available costs also require acquisition or valuation records before they can be accepted as verified amounts. Costs remain missing for a further 1,086 items.

Construction in progress requires particular care. Of 298 CIP records, 275 carry zero cost, 19 have positive cost totalling UGX 1,168,217,300 and four have missing cost. The reported CIP balance is therefore not a measure of the full value of unfinished works or the amount required to finish them. These are asset records, not 298 distinct incomplete facilities.

Depreciation includes the service month and is limited to cost less salvage value. Year-to-date depreciation is the increase in accumulated depreciation since the start of the financial year. All recorded salvage values are zero. The underlying dates and cost evidence require confirmation before the balances can be treated as verified amounts.

There are 23,154 fully depreciated items, including 22,161 still marked in use. These assets need a review of their condition and remaining useful life. A zero net book value alone is not a reason to regard an asset as failed, disposed of or due for replacement. The financial tables use the existing accounting classifications. Errors, such as diagnostic equipment classified as buildings, need supporting evidence and correction before category totals can be used as physical inventories.

Appendix B Service date exceptions and supporting evidence

Service-date entries across all assets

Service-date entry	Records	Share
Full date from 27 June 2017 to 30 September 2026	197,721	86.3%
Full date before 27 June 2017	3,345	1.5%
Month and year only	2,987	1.3%
Year only	7,701	3.4%
Year or financial-year period	455	0.2%
Commissioning status or other text	16,815	7.3%
Total asset records	229,024	100.0%

Categories are mutually exclusive; rounded percentages may not total 100.0%.

The cases below illustrate service-date problems and the decisions required. They are examples rather than a complete list of all date exceptions. Asset references and facility names are provided to support follow-up.

Asset reference	Location and service date	Finding and action
UGIFT-217326	UNSPECIFIED 2009-08-20	Source records purchase timing but leaves service date blank. Purchase does not establish commissioning.

Asset reference	Location and service date	Finding and action
UGIFT-010050	Nkokonjeru Health Centre III 2012-03-01	Service field absent or blank. No supported replacement date established.
UGIFT-010342	Bukatube Health Centre III 2016-05-01	Source records purchase timing but leaves service date blank. Purchase does not establish commissioning.
UGIFT-044388	Maaji Seed Secondary School 2014-06-24	Source records purchase timing but leaves service date blank. Purchase does not establish commissioning.
UGIFT-050677	Labongo Amida Seed Secondary School 2014-01-01	Service field absent or blank. No supported replacement date established.
UGIFT-114049	Sikuda Seed Secondary School 2012-07-13	Source states 13/7/2012 and Sikuda Primary School. Confirm legacy status, funding and school attribution.
UGIFT-118560	Kyamwinula Health Centre III 2012-03-01	Service field absent or blank. No supported replacement date established.
UGIFT-179828	Makokoto Seed Secondary School 2014-01-01	Service field absent or blank. No supported replacement date established.
UGIFT-196249	Nyamarwa Seed Secondary School 2014-01-01	Service field absent or blank. No supported replacement date established.
UGIFT-197564	Namungo Seed Secondary School 2014-01-01	Service field absent or blank. No supported replacement date established.

The shared 1 January 2014 value covers 260 wooden-chair records at Labongo Amida, 266 at Makokoto, 303 at Nyamarwa and 203 at Namungo. The original returns for these groups provide no service date. The sampled Kyamwinula source likewise lacks a service-date field and provides no full date to justify the stated date of 1 March 2012. The sampled Nkokonjeru return expressly states that receipt or service timing was not recorded. The dates therefore remain unresolved; the source material does not support replacement dates.

Rules for an approved register correction

Enter a full calendar date only when the evidence shows when the identified asset became available for use. Keep the source's original wording and level of detail in the supporting record. A month, year, financial year or commissioning status must not be entered as though it were a full date.

Leave the date field blank in the corrected register where a full date cannot be supported. Record the reason, original value and source reference separately. Keep any work-in-progress or undelivered status visible even when the date is blank.

Where the source supports an early date, establish whether the asset predates UgIFT or has been assigned to the wrong beneficiary or programme. Do not simply move the year forward or remove the asset from the register. Record the approved decision about its ownership and programme assignment.

Before approving changes, compare purchase and service dates, check repeated entries and confirm which physical units they describe. A date may be applied to a whole batch only where the documents identify both the batch and the relevant event. Similar item names or dates at another facility are not sufficient evidence.

For each approved change, record the original and revised values, supporting evidence, decision, responsible officer and review date. Recalculate depreciation, net book value and any recoverable

amount based on net book value. Retain independently supported recoverable amounts separately. Check the resulting balances and outstanding exceptions before migration to IFMIS.

Appendix C Definitions used in the analysis

The condition descriptions in section 2.5 distinguish physically faulty assets from usable items in store or awaiting installation. The quantitative tables use the current register codes: 215,504 assets marked Functional and in use, and 13,520 marked Faulty and not in use. All entries marked not in use carry the Faulty code in these totals, including usable stored or uninstalled items; the 13,520 therefore does not represent a count of physically broken assets.

The definitions below explain how quantities, condition and financial values are presented. Unresolved receipt, ownership and classification matters are included in the relevant schedules for follow-up.

Term	Meaning in this report
Asset quantities	Each entry represents one recorded unit. Totals include capitalized, expensed and unresolved entries; receipt and ownership exceptions require confirmation.
Institution and location	Assets are grouped by the institution and beneficiary to which they are attributed. Transfers, substitutions and uncertain programme assignments require reconciliation.
Asset categories	The categories describe the existing accounting classification. Known errors require correction before the categories can be treated as confirmed physical inventories.
Recorded cost	The available cost in Uganda shillings. Some amounts are estimates. A missing amount remains unresolved and is distinguished from a recorded zero.
Service and purchase dates	The service date is when the asset became available for use. The purchase date is a separate event and does not establish the service date.
Useful life and salvage value	Useful life is the period used for depreciation. Salvage value is the amount expected to remain at the end of that period. Neither determines when an asset physically fails.
Depreciation	Accumulated depreciation is the cost allocated over the asset's accounting life to date. Year-to-date depreciation covers 1 July to 30 September 2026. Pending calculations remain unavailable.
Net book value	Recorded cost less accumulated depreciation for assets recognized for accounting purposes. Comparisons use the same records with all required amounts available.
Recoverable amount	An independently supported recoverable amount must be distinguished from a value based on net book value. The latter does not constitute an independent impairment valuation.
Asset identification	Asset references, programme markings, serial numbers and vehicle registrations help establish identity. Shared identifiers and missing markings require physical and custody checks.
Condition and use	Functional and Faulty are the two reported condition classes. Reasons for non-use are examined separately to determine whether installation, repair, replacement or disposal is appropriate.
Complete accounting information	Assets classified CAPITALIZED or construction in progress, with cost, accumulated depreciation and net book value all available. These provide the basis for direct financial reconciliation.

The analysis distinguishes the thirteen asset-holding MDAs, the three regional blood banks, health centres, schools, hospitals and other local-government locations. Institution totals, programme-list facilities and interview respondents represent different populations and should not be used interchangeably.

Asset numbers are missing for 1,923 entries, while 34 state Not engraved. Three linked asset-number entries disagree: one at Birembo Health Centre III and two at Namungo Seed Secondary School. There are also 355 repeated asset-number values and 323 repeated serial-number values within individual institution books. Quantities and supporting records should be checked before any assets are counted as duplicates.

Principal references

Programme chronology: World Bank UgIFT Additional Financing programme paper, section I, paragraph 1, printed page 1.

Accounting policy context: Government of Uganda Asset Accounting Policies and Guidelines 2023, sections 3.3.5.2, 5.5, 5.7 and 5.9; pages 49, 67 and 68.

Field photographs and reports describe conditions at the time of the visits. Photographs alone cannot confirm functionality, completion, programme ownership or current condition.

Appendix D Programme list exception roster

The 39 entries below explain gaps or differences between the programme list and the available asset returns. Reported absence is not an independent finding that a facility does not exist. A receiving facility already on the list is counted once.

ID	Programme-list entry and LG	Outcome
H205	Olok HC II Pader	Reported absent or not constructed
H190	Alik HCII Lira	Reported absent or not constructed
H197	Acimi HC II Oyam	Reported absent or not constructed
H195	Acokara HCII Oyam	Reported absent or not constructed
H200	Ariba HC II Oyam	Reported absent or not constructed
H070	Busia Eastern Division Busia MC	Reported absent or not constructed
S010	Eastern Division Tororo MC	Reported absent or not constructed
S012	Central Division Jinja City	Reported absent or not constructed
S216	Kishangara seed school Ibanda	Reported absent or not constructed
H010	Butoloogo HC II Kasanda	Reported absent or not constructed
H193	Alira HCII Oyam	Outside UgIFT scope
H086	Buyinda HC II Kalire	Outside UgIFT scope

ID	Programme-list entry and LG	Outcome
S237	Kiziranfumbi Seed School Kikuube	Outside UgIFT scope
H149	Pandwong HC II Kitgum MC	No UgIFT assets reported
S214	Bumbaire Seed School Bushenyi	No UgIFT assets reported
S215	Kyamuhunga Bushenyi	No UgIFT assets reported
S221	Kashenshero Mitooma	No UgIFT assets reported
H282	Rwamujojo HC II Sheema MC	No UgIFT assets reported
H231	Alangi Zombo	Assets relocated
H233	Ther-uru HC II Zombo	Assets relocated
S208	Abanga Zombo	Assets relocated
H213	Loinya HC II Maracha	Already represented elsewhere
H054	Bussi HC II Wakiso	Already represented elsewhere
H044	Butalangu HC II Nakaseke	Follow-up without on-site return
H043	Semuto HC II Nakaseke	Follow-up without on-site return
S087	Kikamulo Nakaseke	Follow-up without on-site return
S088	Nakaseke Seed School Nakaseke	Follow-up without on-site return
H045	Kiralamba HC II Nakasongola	Follow-up without on-site return
S089	Nakitoma Nakasongola	Follow-up without on-site return
H370	Kyondo HC II Bundibugyo	Follow-up without on-site return
H373	Kabingo HCII Kasese	Follow-up without on-site return
H048	Kyera HCII Sembabule	Follow-up without on-site return

ID	Programme-list entry and LG	Outcome
H047	Ntete HCII Sembabule	Follow-up without on-site return
H031	Kyabakuza HCII Masaka	Follow-up without on-site return
S059	Kichwamba Kabarole	Follow-up without on-site return
S058	Karago TC Fort-Portal City	Follow-up without on-site return
S004	Ngoma Nakaseke	Follow-up without on-site return
S080	Lwengo Seed School Lwengo	Follow-up without on-site return
H227	Lodonga TC Yumbe	Follow-up without on-site return

Appendix E Documented outstanding works and handover

This schedule lists the 70 facilities with documented incomplete works and the 13 additional facilities awaiting handover or commissioning. It is a minimum list of documented cases, not a certification of the remaining facilities. A facility may operate while a block or ancillary structure remains unfinished.

ID	Facility and LG	Outstanding matter
H145	Omot Health Centre III Agago	Incomplete works
H112	Bukibologoto Health Centre III Bulambuli	Incomplete works
H181	Adagmon Health Centre III Dokolo	Incomplete works
H008	Mamba Health Centre III Gomba	Incomplete ancillary works
H009	Ngomamene Health Centre III Gomba	Incomplete ancillary works
H312	Maregamo Health Centre III Kisoro	Incomplete works
H152	Moyok Health Centre III Kween	Handover or commissioning
H155	Kaptum Health Centre III Kween	Incomplete works
H156	Benet Health Centre III Kween	Incomplete works
H356	Mutungo Health Centre III Makindye-Ssabagabo MC	Incomplete ancillary works

ID	Facility and LG	Outstanding matter
H366	Lama Health Centre III Moyo	Incomplete works
H355	Matugga Health Centre III Nansana MC	Incomplete ancillary works
H367	Tekulu Health Centre III Omoro	Incomplete works
H368	Abwoch Health Centre III Omoro	Incomplete works
H228	Amanyiri Health Centre III Yumbe	Handover or commissioning
S141	Alerek Seed Secondary School Abim	Handover or commissioning
S021	Kotomor Seed Secondary School Agago	Incomplete works
S022	Lamiyo Seed Secondary School Agago	Incomplete works
S027	Akwon Seed Secondary School Amolatar	Incomplete works
S145	Looro Seed Secondary School Amudat	Incomplete works
S157	Asamuk Seed Secondary School Amuria	Incomplete works
S024	Amuru Town Seed Secondary School Amuru	Handover or commissioning
S030	St Peters Aroi Seed Secondary School Arua	Incomplete works
S005	Kakule Seed Secondary School Budaka	Handover or commissioning
S007	Bushiribo Seed Secondary School Bududa	Incomplete works
S011	Mpiita Seed Secondary School Bugweri	Incomplete works
S014	Senendet Seed Secondary School Bukwo	Incomplete works
S046	Kihungya Seed Secondary School Buliisa	Incomplete works
S054	Burondo Seed Secondary School Bundibugyo	Incomplete works
S055	Kabango Seed Secondary School Bundibugyo	Incomplete works

ID	Facility and LG	Outstanding matter
S250	Kisuba Seed Secondary School Bundibugyo	Incomplete works
S056	Katugunda Seed Secondary School Bunyangabu	Incomplete works
S057	Nsuura Seed Secondary School Bunyangabu	Incomplete works
S096	Sikuda Seed Secondary School Busia	Handover or commissioning
S009	Muhula Seed Secondary School Butaleja	Incomplete works
S025	Patiko Seed Secondary School Gulu	Incomplete works
S230	Kidukuru Seed Secondary School Hoima	Handover or commissioning
S019	Sidok Seed Secondary School Kaabong	Incomplete works
S159	Aperikira Seed Secondary School Kaberamaido	Incomplete ancillary works
S047	Burora Seed Secondary School Kagadi	Handover or commissioning
S048	King Solomon Seed Secondary School Kagadi	Incomplete works
S049	Kitegwa Community Seed Secondary School Kagadi	Incomplete works
S232	St Catherine Kicucura Seed Secondary School Kagadi	Incomplete works
S060	Bwesumbu Seed Secondary School Kasese	Incomplete works
S001	Lwamata Town Council Seed Secondary School Kiboga	Incomplete works
S050	Kyangwali Seed Secondary School Kikuube	Handover or commissioning
S040	Lake Mburo Seed Secondary School Kiruhura	Incomplete works
S051	Kigumba Town Seed Secondary School Kiryandongo	Incomplete works
S254	Kanara Seed Secondary School Kitagwenda	Handover or commissioning
S149	Rengen Seed Secondary School Kotido	Incomplete works

ID	Facility and LG	Outstanding matter
S164	Kumi Seed Secondary School Kumi	Incomplete ancillary works
S131	Kaptum Seed Secondary School Kween	Incomplete works
S132	Kitawoi Seed Secondary School Kween	Incomplete works
S133	Moyok Seed Secondary School Kween	Incomplete works
S075	Ntwetwe Seed Secondary School Kyankwanzi	Incomplete works
S256	Rwentuha Seed Secondary School Kyegegwa	Incomplete works
S061	Kyarusenzi Seed Secondary School Kyenjojo	Incomplete works
S257	Kigaraale Seed Secondary School Kyenjojo	Incomplete works
S258	Kyembogo Seed Secondary School Kyenjojo	Incomplete works
S026	Padibe Seed Secondary School Lamwo	Incomplete works
S015	Butta Seed Secondary School Manafwa	Incomplete works
S016	Sisuni Seed Secondary School Manafwa	Incomplete works
S135	Khabutoola Seed Secondary School Manafwa	Incomplete works
S136	Sibanga Seed Secondary School Manafwa	Handover or commissioning
S151	Rupa Seed Secondary School Moroto	Incomplete ancillary works
S200	Dufile Seed Secondary School Moyo	Incomplete works
S085	Kigando Seed Secondary School Mubende	Incomplete works
S020	Moruita Seed Secondary School Nakapiripirit	Incomplete works
S153	Nakapiripirit Seed Secondary School Nakapiripirit	Incomplete works
S018	Mukuto Seed Secondary School Namisindwa	Incomplete works

ID	Facility and LG	Outstanding matter
S154	Iriiri Seed Secondary School Napak	Handover or commissioning
S033	Mamba Seed Secondary School Nebbi	Incomplete works
S034	Ndhew Seed Secondary School Nebbi	Incomplete works
S201	Atego Seed Secondary School Nebbi	Incomplete works
S062	Butungama Seed Secondary School Ntoroko	Incomplete works
S063	Kibuuku Seed Secondary School Ntoroko	Incomplete ancillary works
S035	Got Apwoyo Seed Secondary School Nwoya	Incomplete works
S028	Okum Seed Secondary School Otuke	Incomplete works
S102	Olok Seed Secondary School Pallisa	Incomplete ancillary works
S170	Kamuda Seed Secondary School Soroti	Incomplete works
S105	Malaba Seed Secondary School Tororo	Handover or commissioning
S209	Atyak Seed Secondary School Zombo	Incomplete works
S210	Kango Seed Secondary School Zombo	Incomplete ancillary works

Two additional locations outside this programme-list schedule, have outstanding works or commissioning: Bukuuku Community Seed Secondary School has staff quarters and a kitchen under construction; Kibuzigye Seed Secondary School has a kitchen recorded as completed and operational but not yet commissioned. Their programme-list attribution requires reconciliation.

Appendix F Facility interview scope and denominators

The interview analysis counts each programme-list facility once per topic. Multiple returns for a facility are reconciled before analysis. Answers about another institution, statements that do not answer the question and unclassifiable replies are excluded from the relevant denominator. The Mbirizi school response attributed to Kagganda Health Centre is excluded from health-centre analysis pending correction of the identity. Receiving-facility responses are linked to the appropriate programme entry.

Measure	Health centres	Schools	Total
Service benefits and challenges	284	193	477
Maintenance arrangements	278	191	469

Measure	Health centres	Schools	Total
Maintenance or condition-check frequency	294	200	494
Classified functionality or breakdown records	282	181	463
Classified records of assets received	281	197	478

A benefit or challenge percentage uses the respondents to that question, not all 629 programme-list entries. Topic categories overlap. The broader challenge measure includes both an explicitly described problem and a request for its remedy; it should not be confused with the narrower count of explicit complaints. The 50 fixed-interval responses combine maintenance and condition-check information. Forty-four facility responses share wording with another return, so the findings should be read as accounts reported by facilities, rather than independent measurements of impact.

Appendix G Asset reconciliation examples

The cases below require delivery, custody or condition checks. They do not provide a national total of losses or disposals. Where a report concerns a batch of equipment, the affected items still need to be identified.

Facility and item	Asset reference	Finding and action
Kijuna Health Centre III Oxygen Therapy Apparatus. Minimum 45L cylinder	UGIFT-003939	Oxygen therapy apparatus lacks regulators/accessories. This concerns missing parts, not the whole asset.
Nyanja Health Centre III B.P. Machine (Aneroid wall mounted)	UGIFT-012842	Two machines, UGIFT-012842 and UGIFT-012843, were reported beyond repair. Disposal approval remains unconfirmed.
Paloga Seed Secondary School Desktop Computer	UGIFT-052080	Two monitors were reported stolen, while the others remained in use. Confirm which items were affected.
Ogur Seed Secondary School Desks	UGIFT-057485	Furniture in locked rooms could not be verified because keys were unavailable. Confirm its location and condition.
Buwembe Health Centre III Incubator	UGIFT-114904	Incubator reported not received. Check delivery records before concluding that it was lost.
Bukimanayi Health Centre III Wheel Chair	UGIFT-115669	Wheelchair not seen; possible redistribution unconfirmed. Establish its location.
Ikumbya Seed Secondary School Desktop Computer	UGIFT-140448	Reported quantities: 29 received, 12 verified, 10 stolen and two faulty. Reconcile receipt, transfer and loss records.
Kitojo Health Centre III Microscope Binocular	UGIFT-150498	Microscope reportedly not received although status says Functional. Resolve the contradiction.
Bukiro Seed Secondary School System Unit	UGIFT-159973	Accounts of 16 system units conflict: described as both present and functional and as stolen. Confirm their status.
Rubingo Health Centre III Instrument set, ENT Basic for HCIII	UGIFT-188911	ENT instrument set reportedly not received. Reconcile supplier and facility receipt records.

Appendix H Photographic schedule

The photographs illustrate facilities, equipment and outstanding works at the time of the visits. They should be read alongside the findings on condition, use and completion. A photograph alone does not establish that equipment was functional or that a facility was ready for handover.

Facility	Photographic subject
Majanji Health Centre III	Delivery bed with a torn mattress cover at a health centre, Busia District (Bukedi).
Lungulu Seed Secondary School	Boxed computers and related equipment in a seed school store, Nwoya District (Acholi).
Malaba Seed School	UgIFT identification on a desk at a seed school, Tororo District (Bukedi).
Got Apwoyo Seed Secondary School	Unfinished school block at Got Apwoyo Seed Secondary School, Nwoya District (Acholi).
Lwamata Town Council Seed Secondary School	Building works at a seed secondary school, Kiboga District (Buganda).
Butungama Seed Secondary School	School block awaiting completion at Butungama Seed Secondary School, Ntoroko District (Tooro).
Bukibologoto Health Centre II	Cracked health centre block above collapsed ground, Bulambuli District (Bugisu).
Bundege Health Centre III	Stained and peeling ceiling at a health centre, Sironko District (Bugisu).
Napak Seed Secondary School	Stacked desks, chairs and stools at a seed secondary school, Napak District (Karamoja).
Butungama Seed Secondary School	Laboratory stools and other school furniture in storage, Ntoroko District (Tooro).
Kibiri Health Centre III	Boxed pulse oximeters at a health centre, Makindye-Ssabagabo Municipal Council (Buganda).
Ndhew Seed Secondary School	Building works and construction materials at Ndhew Seed Secondary School, Nebbi District (West Nile).
Simu Pondo Health Centre III	Unfinished laboratory building at a health centre, Sironko District (Bugisu).
Namboko Seed Secondary School	Broken desk frame at a seed secondary school, Namisindwa District (Bugisu).
Sibanga Seed School	Books displayed on library shelves at Sibanga Seed School, Manafwa District (Bugisu).
Kamuli HC III	Maternity block entrance and access ramp at Kamuli HC III, Tororo District (Bukedi).
Kyabasara Health Centre III	Hospital beds and screens stacked in storage at a health centre, Kagadi District (Bunyoro).
Kihungya Seed Secondary School	Biology laboratory under construction at a seed secondary school, Buliisa District (Bunyoro).
Older Butiaba Health Centre III facility	Flood-affected older health facility at Butiaba, Buliisa District (Bunyoro).
Kaptum Seed Secondary School	Empty computer laboratory at a seed secondary school, Kween District (Sebei).

Facility	Photographic subject
Kalemungole HC III	Programme engraving on a weighing scale at Kalemungole HC III, Moroto District (Karamoja).
Kalemungole HC III	Wheelchair with programme marking at Kalemungole HC III, Moroto District (Karamoja).
Sidok Seed Secondary School	Unfinished classroom block at Sidok Seed Secondary School, Kaabong District (Karamoja).
Sidok Seed Secondary School	Latrine block under construction at Sidok Seed Secondary School, Kaabong District (Karamoja).
Kihungya Seed Secondary School	Unfinished laboratory interior at Kihungya Seed Secondary School, Buliisa District (Bunyoro).
Kihungya Seed Secondary School	Library interior under construction at Kihungya Seed Secondary School, Buliisa District (Bunyoro).
King Solomon Seed Secondary School	School engraving on wooden furniture at King Solomon Seed Secondary School, Kagadi District (Bunyoro).
King Solomon Seed Secondary School	Boxed projector and other equipment at King Solomon Seed Secondary School, Kagadi District (Bunyoro).
Budde Seed Secondary School	Programme and school engraving on a chair at Budde Seed Secondary School, Butambala District (Buganda).
Sisiyi Seed Secondary School	ICT laboratory block and entrance ramp at Sisiyi Seed Secondary School, Bulambuli District (Bugisu).
Majanji HC III	Pedal suction unit in packaging at Majanji HC III, Busia District (Bukedi).
Bumufuni Seed Secondary School	Computer sets stacked in a store at Bumufuni Seed Secondary School, Bulambuli District (Bugisu).
Kitawoi Seed Secondary School	ICT laboratory interior under construction at Kitawoi Seed Secondary School, Kween District (Sebei).
Moyok HC III	Institutional engraving on equipment at Moyok HC III, Kween District (Sebei).
Kibiri HC III	Health centre building at Kibiri HC III, Makindye-Ssabagabo Municipal Council (Buganda).
Gyagenda Memorial Seed Secondary School	Classroom furnished with desks and a whiteboard at Gyagenda Memorial Seed Secondary School, Kalangala District (Buganda).
Kihungya Seed Secondary School	Classroom block with earthworks in the foreground at Kihungya Seed Secondary School, Buliisa District (Bunyoro).
Kihuukya HC III	Health centre buildings and covered walkway at Kihuukya HC III, Hoima City (Bunyoro).
Kihuukya HC III	Binocular microscope at Kihuukya HC III, Hoima City (Bunyoro).
King Solomon Seed Secondary School	Laboratory benches with cupboard doors detached at King Solomon Seed Secondary School, Kagadi District (Bunyoro).
Iriiri Seed Secondary School	Computer and library block interior with furniture and stored items at Iriiri Seed Secondary School, Napak District (Karamoja).

Facility	Photographic subject
Kamoru HC III	Microscope bearing local facility identification at Kamoru HC III, Kotido District (Karamoja).
Aperikira Seed Secondary School	Engraving reading APESSS MOES/UGIFT/KABE/SPLRS/2023-24/001 on a desk at Aperikira Seed Secondary School, Kaberamaido District (Teso)
Arua Regional Blood Bank	Completed blood bank building at Arua Regional Blood Bank, Arua City (West Nile)
Arua Regional Blood Bank	Markings PEP II/UBTS/COMP/11/016 and UBTS/UGIFT/ARBB/UPS/001 on uninterruptible power supplies at Arua Regional Blood Bank, Arua City (West Nile)
Hoima Regional Blood Bank	Donor couches in the donor room at Hoima Regional Blood Bank, Hoima City (Bunyoro)
Hoima Regional Blood Bank	Benchtop centrifuge at Hoima Regional Blood Bank, Hoima City (Bunyoro)
Arua Regional Blood Bank	Blood bank refrigerator at Arua Regional Blood Bank, Arua City (West Nile)
Arua Regional Blood Bank	Platelet agitator at Arua Regional Blood Bank, Arua City (West Nile)
Benet Health Centre III	Incomplete staff quarters at Benet Health Centre III, Kween District. Field visit 27 August 2026.
Benet Health Centre III	Interior awaiting completion at Benet Health Centre III, Kween District. Field visit 27 August 2026.
Benet Health Centre III	A further unfinished room at Benet Health Centre III, Kween District. Field visit 27 August 2026.
Hoima Regional Blood Bank	Freezer at Hoima Regional Blood Bank.
Soroti Regional Blood Bank	Refrigerators at Soroti Regional Blood Bank

Appendix I Land records and ownership evidence

Eighteen entries are classified as land, including four at health centres. Ownership, area, tenure and valuation require supporting documents. The table lists these entries for follow-up by the responsible institutions.

Asset reference	Location	Item	Cost UGX m	Available evidence
UGIFT-119332	Kyamwinula Health Centre III	Land	20.000	Functional.
UGIFT-128460	Sop Sop Health Centre III	70X300M	20.000	Functional. Good and In Use.
UGIFT-177218	Luwube Muslim Seed Secondary School	Land	Unavailable	Functional.
UGIFT-183077	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.

Asset reference	Location	Item	Cost UGX m	Available evidence
UGIFT-183078	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183079	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183080	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183081	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183082	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183083	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183084	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183085	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183086	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
UGIFT-183087	Kigorobyia Seed Secondary School	Land	0.912	Functional. Only a partial service date is available; the exact date requires confirmation.
M161436	Kabweri Seed Secondary School	School Land	50.000	Functional.
M161488	Nalubembe Health Centre III	Hospital Land	15.000	Functional.
M183485	Kasasira Seed Secondary School	School Land	50.000	Functional.

Asset reference	Location	Item	Cost UGX m	Available evidence
M183544	Kabweri Health Centre III	Hospital Land	15.000	Functional.

Costs include nil amounts and estimates.

Appendix J Additional assets and classification checks

Hospitals on local-government books: 3,067 records. These are included in the report total and shown separately from Health Centres and schools.

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Medical, laboratory and research appliances 2,843 records; NBV 2,632/2,843	1,436.617	738.099*	546.884*	42.6%
Outside fixed-asset classification 145 records; NBV 145/145	1.000	0.000	0.000	n/a
Furniture and fittings 68 records; NBV 10/68	52.427	3.696*	7.832*	67.9%
Buildings and structures 6 records; NBV 4/6	396.408	35.986*	356.923*	90.8%
Other classified assets 3 records; NBV 3/3	1.010	0.662	0.348	34.5%
ICT equipment 2 records; NBV 1/2	0.552*	0.506*	0.046*	8.3%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

Other local-government or unassigned locations: 4 records. These are included in the report total and shown separately from Health Centres and schools.

Asset category and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Transport equipment 4 records; NBV 4/4	431.136	279.424	151.712	35.2%

Amounts are in UGX million, rounded to three decimals. * Available amounts only; one or more amounts are missing or pending calculation. NBV coverage is given for each category. NBV/cost compares complete accounting records and does not measure physical condition. n/a means a comparable ratio is unavailable.

Review the classification of diagnostic sets listed under buildings and structures. Confirm item descriptions, account mapping, ownership and useful life before migration to IFMIS.

Appendix K Financial analysis by asset type

The following tables present financial values by asset type for each ministry, regional blood bank, Health Centres and schools. They separate laptops, printers, furniture, medical equipment and other items while retaining the full institution totals. Recorded costs, accumulated depreciation and net book values agree with the broader financial analysis in the report.

Items are grouped by their descriptions, with accounting categories used where the description is insufficient. Each record represents one unit. A desktop-computer description may refer to a system unit or an incomplete set; separately listed monitors, CPUs, keyboards and mice are therefore shown as

components. Accessories and supplies are included even where they are not recognized as fixed assets. Unclear descriptions are reported separately. Some descriptions differ from their accounting categories: for example, Van de Graaff generators and strip cups classified as transport are grouped here as laboratory items. Their accounting classifications require correction.

Amounts are in UGX million at 30 September 2026, rounded to three decimals. An asterisk means the total includes available amounts only; Unavailable means none of the amounts for that measure can be calculated. NBV coverage shows how many records have a net book value. The NBV/cost ratio uses only CAPITALIZED or CIP records with cost, depreciation and net book value all available. It shows the share of cost not yet depreciated, not physical condition or market value. n/a means there is no positive cost on that comparable basis.

MoFPED

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Computer components: monitors, CPUs, keyboards and mice 70 records; NBV 66/70	338.617	284.293*	54.084*	16.0%
Chairs and seats 69 records; NBV 69/69	92.869	59.383	33.486	36.1%
Other records outside fixed-asset classes 54 records; NBV 54/54	6.564	0.000	0.000	n/a
Laptops and notebooks 40 records; NBV 34/40	261.360	150.858*	55.542*	26.9%
Software and licences 31 records; NBV 30/31	147.147*	147.147*	0.000*	0.0%
Desktop and unspecified computer records 26 records; NBV 26/26	135.854	123.120	12.734	9.4%
UPS systems 25 records; NBV 25/25	30.723	19.554	11.168	36.4%
Desks and benches 21 records; NBV 21/21	32.238	26.346	5.891	18.3%
Vehicles and other transport 21 records; NBV 20/21	4,550.385*	3,046.016*	1,504.369*	33.1%
Tablets 17 records; NBV 17/17	39.244	26.163	13.081	33.3%
Printers and photocopiers 15 records; NBV 13/15	234.901	156.781*	52.077*	24.9%
Digital phones and TELA handsets 14 records; NBV 14/14	10.290	10.290	0.000	0.0%
Projectors 14 records; NBV 14/14	124.300	124.300	0.000	0.0%
Servers and network equipment 10 records; NBV 10/10	70.000	60.667	9.333	13.3%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Cabinets, cupboards and shelves 9 records; NBV 9/9	11.930	10.339	1.591	13.3%
Other records classified as ICT 9 records; NBV 9/9	32.317	32.262	0.054	0.2%
Accessories and protective items 6 records; NBV 0/6	18.640	Unavailable	Unavailable	n/a
Paper shredders and binding machines 3 records; NBV 3/3	10.800	9.360	1.440	13.3%
Water dispensers 3 records; NBV 3/3	2.040	1.870	0.170	8.3%
Audio-visual, survey and other ICT equipment 1 record; NBV 1/1	54.100	23.443	30.657	56.7%
Total 458 records; NBV 438/458	6,204.318*	4,312.194*	1,785.678*	29.3%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoWT

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Computer components: monitors, CPUs, keyboards and mice 48 records; NBV 40/48	62.259	23.859*	31.200*	56.7%
UPS systems 14 records; NBV 10/14	13.076	5.001*	6.539*	56.7%
Desktop and unspecified computer records 8 records; NBV 4/8	22.016	15.961*	2.455*	13.3%
Printers and photocopiers 8 records; NBV 6/8	67.483	50.979*	14.704*	22.4%
Laptops and notebooks 5 records; NBV 5/5	40.080	17.368	22.712	56.7%
Audio-visual, survey and other ICT equipment 1 record; NBV 1/1	54.100	23.443	30.657	56.7%
Other or insufficiently described items 1 record; NBV 0/1	Unavailable	Unavailable	Unavailable	n/a
Tablets 1 record; NBV 1/1	0.900	0.390	0.510	56.7%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Vehicles and other transport 1 record; NBV 1/1	196.018	189.484	6.534	3.3%
Total 87 records; NBV 68/87	455.932*	326.485*	115.311*	26.1%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoES

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Digital phones and TELA handsets 9,324 records; NBV 9,324/9,324	10,847.924	7,774.569	3,073.355	28.3%
Tablets 1,001 records; NBV 1,001/1,001	1,995.347	1,591.326	404.021	20.2%
Laptops and notebooks 456 records; NBV 456/456	2,043.788	1,206.684	837.104	41.0%
Printers and photocopiers 2 records; NBV 2/2	38.070	34.897	3.172	8.3%
Total 10,783 records; NBV 10,783/10,783	14,925.128	10,607.477	4,317.652	28.9%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MAAIF

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Tablets 819 records; NBV 819/819	623.690	429.317	194.373	31.2%
Accessories and protective items 784 records; NBV 778/784	306.274*	82.589*	163.388*	66.4%
Computer components: monitors, CPUs, keyboards and mice 340 records; NBV 340/340	823.828	247.120	576.612	70.0%
Laptops and notebooks 49 records; NBV 49/49	481.164	158.325	322.839	67.1%
Printers and photocopiers 21 records; NBV 21/21	72.534	21.760	50.774	70.0%
Printer supplies and consumables 15 records; NBV 15/15	12.674	0.000	0.000	n/a
Software and licences 5 records; NBV 5/5	8.000	5.467	2.533	31.7%
Other records classified as ICT 4 records; NBV 4/4	20.992	6.298	14.694	70.0%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Vehicles and other transport 4 records; NBV 4/4	500.040	425.034	75.006	15.0%
Audio-visual, survey and other ICT equipment 3 records; NBV 2/3	3.829*	1.149*	2.680*	70.0%
Projectors 1 record; NBV 1/1	3.532	3.002	0.530	15.0%
Total 2,045 records; NBV 2,038/2,045	2,856.557*	1,380.060*	1,403.430*	50.4%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoH

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Accessories and protective items 148 records; NBV 148/148	134.418	0.000	0.000	n/a
Printer supplies and consumables 50 records; NBV 50/50	40.950	0.000	0.000	n/a
Laptops and notebooks 23 records; NBV 23/23	137.277	72.714	64.563	47.0%
Motorcycles 23 records; NBV 23/23	418.000	202.556	215.444	51.5%
Printers and photocopiers 6 records; NBV 6/6	67.278	33.406	33.872	50.3%
Paper shredders and binding machines 4 records; NBV 4/4	4.831	2.415	2.415	50.0%
Servers and network equipment 4 records; NBV 4/4	12.800	6.400	6.400	50.0%
Vehicles and other transport 2 records; NBV 1/2	371.136	123.712*	61.856*	33.3%
Total 260 records; NBV 259/260	1,186.690	441.202*	384.551*	46.6%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

OPM

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laptops and notebooks 10 records; NBV 10/10	53.535	48.182	5.354	10.0%
Total 10 records; NBV 10/10	53.535	48.182	5.354	10.0%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoWE

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Tablets 2,368 records; NBV 2,348/2,368	1,453.253	764.511*	551.862*	41.9%
Computer components: monitors, CPUs, keyboards and mice 320 records; NBV 320/320	2,583.075	763.466	563.609	42.5%
UPS systems 166 records; NBV 166/166	372.850	215.868	156.982	42.1%
Laptops and notebooks 31 records; NBV 31/31	298.532	179.917	118.615	39.7%
Audio-visual, survey and other ICT equipment 27 records; NBV 4/27	116.932*	54.943*	53.157*	49.2%
Printers and photocopiers 16 records; NBV 16/16	117.205	65.334	51.870	44.3%
Projectors 5 records; NBV 5/5	56.552	32.989	23.563	41.7%
Servers and network equipment 4 records; NBV 4/4	12.400	7.233	5.167	41.7%
Other records classified as ICT 2 records; NBV 2/2	19.183	8.380	10.803	56.3%
Total 2,939 records; NBV 2,896/2,939	5,029.982*	2,092.642*	1,535.627*	42.3%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoGLSD

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laptops and notebooks 8 records; NBV 6/8	36.120	13.260*	14.860*	52.8%
Tablets 2 records; NBV 0/2	10.060	Unavailable	Unavailable	n/a
Total 10 records; NBV 6/10	46.180	13.260*	14.860*	52.8%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

NEMA

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Desktop and unspecified computer records 4 records; NBV 4/4	16.000	12.000	4.000	25.0%
Printers and photocopiers 2 records; NBV 2/2	30.824	20.841	9.983	32.4%
Total 6 records; NBV 6/6	46.824	32.841	13.983	29.9%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

PPDA

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laptops and notebooks 3 records; NBV 3/3	27.630	11.973	15.657	56.7%
Printers and photocopiers 1 record; NBV 1/1	1.825	0.791	1.034	56.7%
Tablets 1 record; NBV 1/1	0.699	0.303	0.396	56.7%
Total 5 records; NBV 5/5	30.154	13.067	17.087	56.7%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

OAG

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laptops and notebooks 16 records; NBV 16/16	188.795	61.597	127.198	67.4%
Printers and photocopiers 2 records; NBV 2/2	39.978	9.995	29.984	75.0%
Vehicles and other transport 2 records; NBV 2/2	160.000	40.000	120.000	75.0%
Total 20 records; NBV 20/20	388.774	111.592	277.182	71.3%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoLG

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Computer components: monitors, CPUs, keyboards and mice 4 records; NBV 3/4	16.000	3.400*	8.600*	71.7%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laptops and notebooks 4 records; NBV 4/4	39.134	10.173	28.961	74.0%
Desktop and unspecified computer records 2 records; NBV 2/2	8.000	1.467	6.533	81.7%
Printers and photocopiers 2 records; NBV 2/2	31.667	21.111	10.556	33.3%
Vehicles and other transport 1 record; NBV 1/1	248.520	248.520	0.000	0.0%
Total 13 records; NBV 12/13	343.320	284.671*	54.650*	16.1%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

MoLHUD

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Motorcycles 25 records; NBV 24/25	483.750	123.840*	340.560*	73.3%
Accessories and protective items 2 records; NBV 2/2	3.600	0.000	0.000	n/a
Total 27 records; NBV 26/27	487.350	123.840*	340.560*	73.3%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Arua Regional Blood Bank

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laboratory and blood-processing equipment 48 records; NBV 48/48	13.809	11.009	2.800	20.3%
Refrigerators, freezers and cold storage 32 records; NBV 32/32	10.807	8.304	2.503	23.2%
Power, water and other service equipment 30 records; NBV 29/30	389.062*	145.262*	120.399*	45.3%
Other records classified as medical or laboratory 29 records; NBV 20/29	6.487*	4.812*	1.675*	25.8%
Scales and balances 24 records; NBV 24/24	8.332	5.908	2.424	29.1%
Beds, cots, mattresses and couches 21 records; NBV 21/21	7.850	5.394	2.455	31.3%
Desktop and unspecified computer records 17 records; NBV 17/17	48.150	17.438	30.713	63.8%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Other furniture and fittings 16 records; NBV 16/16	3.100	1.602	1.498	48.3%
Cabinets, cupboards and shelves 15 records; NBV 15/15	7.840	3.799	4.041	51.5%
Other medical and laboratory items 14 records; NBV 13/14	4.191*	2.305*	1.886*	45.0%
Other records outside fixed-asset classes 9 records; NBV 9/9	0.000	0.000	0.000	n/a
Tables 8 records; NBV 8/8	6.800	3.513	3.287	48.3%
Blood-pressure equipment 7 records; NBV 7/7	2.034	0.811	1.224	60.2%
Laptops and notebooks 7 records; NBV 7/7	3.864	3.321	0.543	14.0%
Chairs and seats 6 records; NBV 6/6	2.676	1.350	1.326	49.5%
Sterilization, disinfection and waste items 5 records; NBV 5/5	1.817	0.968	0.849	46.7%
Microscopes 4 records; NBV 4/4	1.432	1.026	0.406	28.3%
Other records classified as ICT 4 records; NBV 4/4	5.964	3.081	2.883	48.3%
Servers and network equipment 4 records; NBV 4/4	13.600	6.177	7.423	54.6%
Desks and benches 3 records; NBV 3/3	1.500	0.775	0.725	48.3%
Other records classified as furniture 3 records; NBV 3/3	168.468	87.042	81.426	48.3%
Printers and photocopiers 3 records; NBV 3/3	7.552	3.552	4.000	53.0%
UPS systems 3 records; NBV 3/3	1.656	1.076	0.580	35.0%
Vehicles and other transport 3 records; NBV 3/3	240.000	124.000	116.000	48.3%
Accessories and protective items 2 records; NBV 0/2	Unavailable	Unavailable	Unavailable	n/a
Audio-visual, survey and other ICT equipment 2 records; NBV 2/2	4.860	4.455	0.405	8.3%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Patient support and clinical furniture 2 records; NBV 2/2	0.716	0.370	0.346	48.3%
Other records classified as buildings 1 record; NBV 1/1	187.496	24.218	163.278	87.1%
Projectors 1 record; NBV 1/1	2.982	0.795	2.187	73.3%
Stools 1 record; NBV 1/1	0.070	0.036	0.034	48.3%
Total 324 records; NBV 311/324	1,153.115*	472.399*	557.316*	54.1%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Hoima Regional Blood Bank

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Laboratory and blood-processing equipment 60 records; NBV 60/60	21.211	14.837	6.374	30.1%
Scales and balances 30 records; NBV 30/30	9.790	7.213	2.577	26.3%
Refrigerators, freezers and cold storage 28 records; NBV 28/28	10.986	7.117	3.869	35.2%
Power, water and other service equipment 14 records; NBV 14/14	8.864	5.534	3.330	37.6%
Beds, cots, mattresses and couches 12 records; NBV 12/12	4.463	3.124	1.339	30.0%
Patient support and clinical furniture 6 records; NBV 6/6	2.147	1.503	0.644	30.0%
Sterilization, disinfection and waste items 6 records; NBV 6/6	2.189	1.533	0.657	30.0%
Other records classified as medical or laboratory 3 records; NBV 3/3	1.116	0.781	0.335	30.0%
Other furniture and fittings 2 records; NBV 2/2	0.716	0.191	0.525	73.3%
Cabinets, cupboards and shelves 1 record; NBV 1/1	251.439	6.705	244.734	97.3%
Stools 1 record; NBV 1/1	0.070	0.023	0.047	66.7%
Total 163 records; NBV 163/163	312.991	48.561	264.430	84.5%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Soroti Regional Blood Bank

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Other medical and laboratory items 38 records; NBV 38/38	12.549	11.503	1.046	8.3%
Laboratory and blood-processing equipment 18 records; NBV 18/18	4.235	3.882	0.353	8.3%
Scales and balances 15 records; NBV 15/15	4.595	2.693	1.902	41.4%
Refrigerators, freezers and cold storage 14 records; NBV 14/14	4.295	3.937	0.358	8.3%
Beds, cots, mattresses and couches 12 records; NBV 12/12	4.463	4.091	0.372	8.3%
Blood-pressure equipment 8 records; NBV 8/8	4.416	4.048	0.368	8.3%
Patient support and clinical furniture 4 records; NBV 4/4	1.432	1.312	0.119	8.3%
Other records classified as medical or laboratory 3 records; NBV 3/3	1.074	0.984	0.089	8.3%
Power, water and other service equipment 2 records; NBV 2/2	0.200	0.183	0.017	8.3%
Sterilization, disinfection and waste items 1 record; NBV 1/1	0.358	0.095	0.262	73.3%
Total 115 records; NBV 115/115	37.615	32.729	4.886	13.0%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Health centres

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Other medical and laboratory items 12,797 records; NBV 11,017/12,797	12,859.916*	4,227.785*	6,523.271*	60.7%
Beds, cots, mattresses and couches 7,473 records; NBV 6,400/7,473	13,138.484	4,799.540*	5,751.624*	54.5%
Patient support and clinical furniture 6,895 records; NBV 5,826/6,895	3,843.920	1,425.673*	1,822.683*	56.1%
Resuscitation, oxygen and suction equipment 5,014 records; NBV 4,375/5,014	8,004.034*	3,102.561*	3,749.447*	54.7%
Sterilization, disinfection and waste items 4,719 records; NBV 4,658/4,719	564.976	166.216*	174.780*	51.3%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Cabinets, cupboards and shelves 4,144 records; NBV 3,615/4,144	3,374.608	1,295.940*	1,614.235*	55.5%
Other records classified as medical or laboratory 3,762 records; NBV 3,295/3,762	5,956.768*	1,682.465*	2,613.657*	60.8%
Chairs and seats 2,959 records; NBV 2,695/2,959	1,121.407	544.232*	467.327*	46.2%
Desks and benches 2,439 records; NBV 2,233/2,439	898.270	387.384*	404.560*	51.1%
Other records outside fixed-asset classes 1,887 records; NBV 1,887/1,887	43.771	0.000	0.000	n/a
Scales and balances 1,838 records; NBV 1,557/1,838	927.968*	370.819*	391.460*	51.4%
Power, water and other service equipment 1,719 records; NBV 1,491/1,719	1,205.043*	531.372*	501.107*	48.5%
Accessories and protective items 1,511 records; NBV 1,110/1,511	299.405	86.303*	91.401*	51.4%
Buildings, components and site infrastructure 1,319 records; NBV 1,177/1,319	192,676.460*	16,224.082*	154,922.816*	90.5%
Blood-pressure equipment 1,297 records; NBV 1,114/1,297	422.750	178.413*	185.553*	51.0%
Stools 739 records; NBV 666/739	255.022	117.896*	106.699*	47.5%
Laboratory and blood-processing equipment 600 records; NBV 524/600	1,125.611*	426.348*	557.458*	56.7%
Refrigerators, freezers and cold storage 592 records; NBV 508/592	1,980.863	677.673*	988.100*	59.3%
Microscopes 395 records; NBV 338/395	696.639	271.695*	330.860*	54.9%
Tables 308 records; NBV 308/308	60.226	52.862	7.364	12.2%
Audio-visual, survey and other ICT equipment 243 records; NBV 64/243	122.539*	47.904*	56.261*	54.0%
Other records classified as buildings 242 records; NBV 226/242	9,605.390*	1,690.046*	7,701.724*	82.0%
Other records classified as furniture 193 records; NBV 186/193	36.816*	20.369*	16.448*	44.7%
Other or insufficiently described items 82 records; NBV 72/82	460.850*	32.003*	295.445*	90.2%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Servers and network equipment 72 records; NBV 72/72	559.039	559.039	0.000	0.0%
Other furniture and fittings 45 records; NBV 45/45	1.580	1.002	0.578	36.6%
Computer components: monitors, CPUs, keyboards and mice 33 records; NBV 33/33	73.079	52.195	20.884	28.6%
Desktop and unspecified computer records 32 records; NBV 32/32	16.136	12.097	4.039	25.0%
Printers and photocopiers 28 records; NBV 28/28	95.870	95.802	0.069	0.1%
UPS systems 21 records; NBV 21/21	29.400	29.400	0.000	0.0%
Other records classified as ICT 16 records; NBV 14/16	37.619*	27.633*	9.986*	26.5%
Land records 6 records; NBV 5/6	104.905	0.896*	74.104*	98.8%
Laptops and notebooks 3 records; NBV 3/3	8.073	4.478	3.596	44.5%
Motorcycles 3 records; NBV 3/3	74.000	62.333	11.667	15.8%
Projectors 3 records; NBV 3/3	9.765	5.391	4.374	44.8%
Other records classified as transport 2 records; NBV 2/2	1.100	1.100	0.000	0.0%
Digital phones and TELA handsets 1 record; NBV 1/1	0.150	0.150	0.000	0.0%
Total 63,432 records; NBV 55,604/63,432	260,692.452*	39,211.095*	189,403.577*	82.8%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Schools

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Chairs and seats 37,948 records; NBV 32,808/37,948	32,414.137	6,082.224*	24,913.392*	80.4%
Stools 25,504 records; NBV 24,573/25,504	4,186.113	1,306.123*	2,739.639*	67.7%
Desks and benches 22,358 records; NBV 20,177/22,358	18,803.478	2,710.851*	6,873.881*	71.7%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Tables 16,472 records; NBV 14,157/16,472	32,313.571	4,749.847*	26,531.642*	84.8%
Other medical and laboratory items 5,509 records; NBV 5,265/5,509	33,128.711*	8,368.224*	19,661.304*	70.1%
Buildings, components and site infrastructure 4,782 records; NBV 4,034/4,782	345,990.827*	38,130.369*	187,574.763*	83.1%
Other records classified as medical or laboratory 4,356 records; NBV 4,043/4,356	1,152.670*	657.041*	430.864*	39.6%
Desktop and unspecified computer records 3,769 records; NBV 3,270/3,769	12,010.788	6,417.939*	3,751.758*	36.9%
Computer components: monitors, CPUs, keyboards and mice 3,231 records; NBV 2,844/3,231	7,933.239	4,018.894*	2,782.603*	40.9%
Other records outside fixed-asset classes 3,226 records; NBV 3,226/3,226	111.014	0.000	0.000	n/a
Cabinets, cupboards and shelves 3,077 records; NBV 2,878/3,077	3,678.681	784.281*	2,773.997*	78.0%
UPS systems 2,916 records; NBV 2,544/2,916	3,131.398	1,745.665*	951.050*	35.3%
Other records classified as furniture 2,697 records; NBV 2,440/2,697	577.819*	253.127*	173.344*	40.6%
Power, water and other service equipment 2,500 records; NBV 2,405/2,500	1,599.132*	694.524*	644.366*	48.1%
Books, stationery and other supplies 1,374 records; NBV 1,374/1,374	40,624.635	0.135	0.315	70.0%
Other records classified as buildings 1,222 records; NBV 999/1,222	127,813.514*	23,815.406*	86,027.617*	78.3%
Servers and network equipment 1,189 records; NBV 1,086/1,189	3,252.573*	1,662.756*	1,162.473*	41.1%
Other or insufficiently described items 870 records; NBV 317/870	26,803.085*	980.915*	25,378.016*	96.3%
Other records classified as ICT 509 records; NBV 443/509	1,603.073*	723.534*	677.750*	48.4%
Audio-visual, survey and other ICT equipment 460 records; NBV 377/460	1,257.649*	730.112*	348.377*	32.3%
Other furniture and fittings 400 records; NBV 398/400	47.534*	25.823*	21.361*	45.3%

Asset type and coverage	Recorded cost	Accumulated depreciation	Net book value	NBV / cost
Projectors 287 records; NBV 243/287	790.656	300.143*	340.593*	53.2%
Printers and photocopiers 240 records; NBV 199/240	704.566	288.316*	306.530*	51.5%
Scales and balances 136 records; NBV 134/136	43.697*	25.916*	17.423*	40.2%
Accessories and protective items 74 records; NBV 73/74	67.756*	58.137*	9.619*	14.2%
Microscopes 59 records; NBV 54/59	23.834	15.110*	3.814*	20.2%
Beds, cots, mattresses and couches 52 records; NBV 52/52	13.000	11.556	1.444	11.1%
Land records 14 records; NBV 13/14	110.029*	0.000*	110.029*	100.0%
Laptops and notebooks 9 records; NBV 7/9	34.413	11.854*	19.159*	61.8%
Refrigerators, freezers and cold storage 7 records; NBV 7/7	2.823	2.567	0.256	9.1%
Software and licences 2 records; NBV 2/2	9.810	1.635	8.175	83.3%
Sterilization, disinfection and waste items 2 records; NBV 2/2	0.200	0.178	0.022	11.1%
Blood-pressure equipment 1 record; NBV 1/1	0.321	0.086	0.235	73.3%
Laboratory and blood-processing equipment 1 record; NBV 1/1	0.300	0.000	0.000	n/a
Patient support and clinical furniture 1 record; NBV 1/1	0.375	0.000	0.000	n/a
Printer supplies and consumables 1 record; NBV 1/1	6.784	1.131	5.654	83.3%
Tablets 1 record; NBV 1/1	0.358	0.113	0.245	68.3%
Total 145,256 records; NBV 130,449/145,256	700,242.561*	104,574.530*	394,241.709*	79.0%

Amounts in UGX million. * Available amounts only. NBV/cost compares the same complete records.

Appendix L Responses to reviewer comments

The table below summarises the issues raised, the corresponding findings and any further action required.

Comment	Subject	Disposition
Older 59	MoFPED broken assets	Current Functional/Faulty codes recalculated; status and source remarks distinguished in the MoFPED section.
Older 64	Financial analysis by asset type	Financial schedules by classification and by detailed asset type provided for every MDA, each blood bank, health centres and schools, with costs, depreciation, NBV and a matched NBV/cost ratio.
Older 68	MoWT percentages	Counts and denominators refreshed from the current MoWT book.
Older 74	MoES condition and identification	Separate current status and identifier tables retained and refreshed.
Older 78	MAAIF condition and identification	Separate current tables and full-record denominators supplied.
Older 81	MoH other assets	Binding machines, shredders and helmet records reconciled to the current book. Three named power items traced to Kyamwinula on the Tororo Municipal Council book; programme attribution and the further three implied items remain unresolved.
Older 94	NEMA percentages	Recomputed against the current NEMA book.
Older 96	PPDA costs	Current recorded values used, with cost-estimate and date limitations disclosed.
Older 99	OAG percentages	Current condition and tag-field percentages calculated consistently.
Older 103	Photocopier terminology	The MoLG figure uses Photocopiers. Shared identifiers are disclosed to avoid treating two asset records as two confirmed physical items.
Older 144	School identification table	Redundant movable-assets column removed; category population and identifier fields reconciled.
Older 177	Facility reconciliation	39 distinct exceptions reconciled; renamed matched sites excluded from that exception total.
Newer 102	Blood-bank analysis	Arua, Hoima and Soroti have separate availability, status, identification and category-finance analyses.
Newer 111	Land detail	The four health-centre land entries are listed with recorded costs and available evidence.
Newer 127	Additional health photographs	Three views of Benet Health Centre III show unfinished works during the visit on 27 August 2026.
Newer 175	Obsolete and unserviceable assets	Two blood-pressure machines at Nyanja Health Centre III were reported beyond repair. Disposal approval remains unconfirmed.
Newer 176	Missing and unrecorded assets	Examples distinguish items not received, access restrictions, stolen components, missing parts and conflicting accounts.
Newer 179	Recommendation per challenge	The action schedule covers all ten challenge themes, responsible officers and evidence required to confirm completion.