VisionAI Industrial Inspection Report

Id: 8376e300aca8445b939588820a2b2dcf


Status: FAIL

Summary: The left pin is improperly bent, and the right pin is damaged and deformed.

Alignment: Not requested

Elapsed: 21.671

Annotated inspection image



Detected regions (SAM mask area is not necessarily true defect area)

#	Type	Area (px)	Area (mm2)
1	Deformation	10415	Not calibrated
2	Damage	6997	Not calibrated